

SIEMENS

**SINUMERIK 840C
SIMODRIVE 611-D**


Diagnostics Guide

07.97 Edition

User Documentation

SINUMERIK 840C/OEM Version for Windows

General Documentation




Brochure

Catalog NC 36


Catalog NC Z

User/Manufacturer/Service Documentation



Link to SINEC L2-DP with Module
 • IM 328-N, Slave
 • IM 329-N, Master and Slave

User Documentation



Operator's Guide
 • OEM Version for Windows
 • Standard Diagnostics Guide

Programming Guide


User's Guide
 Graphic Progr. System
 • Drilling/Boring and Milling Parts 1+2
 • Turning Parts 1+2
 • On PC
 • Environment Description 840C

Cycles,
 Programming Guide

Measuring Cycles
 Version 20
 User's Guide

User's Guide
 Simulation – Milling
 and Turning

Manufacturer Documentation



Interface:
 • Signals
 • Connection Conditions

Function Block
 Packages,
 Function Macros


Quick Reference,
 Planning PLC 135
 WB/WB2/WD
 S5-HLL

SINUMERIK
 WS 800A
 • CL800 Cycle Language
 • User's Guide

Planning Guide
 Graphic
 Programming
 System

OEM Version
 for Windows
 • User's Guide
 • Alarm Dialog for PC

Manufacturer Documentation




Description of
 Functions
 Safety Integrated

Computer Link
 • SINT
 • SIN PS 231
 • SIN PS 315

Computer Link
 • Message Frame Description
 • General Description

Service Documentation



Installation Guide
 • Instructions
 • Lists
 • Difference Description
 Windows

Measuring Cycles
 Version 20
 Start-up Guide

Spare Parts List

SINUMERIK 840C SIMODRIVE 611–D

Diagnostics Guide User Documentation

Valid for

Control	Drive
SINUMERIK 840C/CE (Standard/Export version)	SIMODRIVE 611–D
Software Version	Software Version
1.x	
2.x	
3.x	1.x
4.x	2.x
5.x	3.x
6.x	4.x

Alarms

1

Diagnostics on the PLC

2

Error Display on CPU

3

Errors with Function Macros

4

Parameterization Errors Spindle/Axis

5

Printing history

Brief details of this edition and previous editions are listed below.

The status of each edition is shown by the code in the "Remarks" column.

Status code in the "Remarks" column:

A New documentation.

B Unrevised reprint with new Order No.

C Revised edition with new status.

If factual changes have been made on the page since the last edition, this is indicated by a new edition coding in the header on that page.

Edition	Order No.	Remarks
09.95	6FC5198-5AB40-0BP0	A
04.96	6FC5198-5AB40-0BP1	C
08.96	6FC5198-5AB40-0BP2	C
07.97	6FC5198-6AB40-0BP0	C

This manual is included in the documentation on CD-ROM (**DOCONCD**)

Edition	Order No.	Remarks
09.97	6FC5 198-6CA00-0BG0 (Read)	C
09.97	6FC5 198-6CB00-0BG0 (Print)	C
09.97	6FC5 198-6CC00-8BG0 (Net)	C

For further information visit our Internet address:
<http://www.aut.siemens.de/sinumerik>

This publication was produced with Interleaf V 5.4

The reproduction, transmission or use of this document or its contents is not permitted without express written authority. Offenders will be liable for damages. All rights, including rights created by patent grant or registration of a utility model or design, are reserved.

© Siemens AG 1996, 1997. All rights reserved.

Other functions not described in this documentation might be executable in the control. This does not, however, represent an obligation to supply such functions with a new control or when servicing.

We have checked that the contents of this document correspond to the hardware and software described. Nonetheless, differences might exist and therefore we cannot guarantee that they are completely identical. The information contained in this document is, however, reviewed regularly and any necessary changes will be included in the next edition. We welcome suggestions for improvement.

Subject to change without prior notice.

Preliminary notes

This Guide serves as a reference work. It allows the machine tool user:

- to assess irregularities during operation at the machine correctly
- to obtain information about the response of the system to the irregularity
- to make use of the options for continuing operation after the irregularity

Scope

This description lists the diagnostics options of the PLC and the alarms of the MMC, NCK, servo and drive (SIMODRIVE 611-D) areas.

Sequence

In the Diagnostics Guide the alarms are sorted in ascending order of alarm numbers. The numbers are not necessarily contiguous.

Safety



Danger

Please assess the condition of your plant carefully against the description of the alarm that has occurred. Eliminate the cause of the alarm and acknowledge it as described. If alarms are ignored, danger to the machine, workpiece, stored settings, and in certain cases, to your health, could result.

Contents

1	Alarms	1-1
1.1	Alarm groups	1-1
1.2	Alarm numbers/cancellation of alarms	1-2
1.3	Display of the alarms in the alarm line	1-4
1.4	Display of the alarms as dialog box	1-6
1.5	Priority of alarms	1-8
1.5.1	Alarm description	1-8
1.6	Dialog text	1-218
1.6.1	Notes for the operator	1-218
1.6.2	Listing of dialog texts	1-218
2	Diagnostics on the PLC	2-1
2.1	Error numbers (ACCU 3 high byte, DB 1 DW 160)	2-1
2.2	Additional error information (ACCU 3 low byte, DB 1 DW 161-163)	2-7
3	Error Display on CPU	3-1
4	Errors with Function Macros	4-1
5	Parameterization Errors Spindle/Axis	5-1



1 Alarms

1.1 Alarm groups


NC alarms

The alarms are divided into alarm groups.


- General alarms
- Computer link alarms
- Axis-specific alarms
- Spindle-specific alarms
- Channel-specific alarms



PLC alarms





MMC alarms



1.2 Alarm numbers/cancellation of alarms

Alarm number	Kind of alarm
1	General alarms
2 to 15	General alarms
16 to 36	Computer link alarms
43 to 110	General alarms
1000 to 1211 1240 to 1251	Axis-specific alarms
1280 to 1371	Axis-specific alarms
1440 to 1971	Axis-specific alarms
2000 to 2193	General alarms
2250 to 2263	Spindle-specific alarms
2270 to 2273	Spindle-specific alarms
2280 to 2283	Spindle-specific alarms
3000 to 3220	General alarms
4000 to 4299 5000 to 5299	Cycle alarms
6000 to 9999	PLC error messages or PLC operational messages
10000 to 12031	Axis-specific alarms
20000 to 20309	Spindle-specific alarms
100000 to 169999	MMC alarms
200000 to 209999	PLC dialogs
210000 to 219999	Free area
300000 to 399999	611D alarms

Key	Effect of cancelling alarms
 Acknowledgement	An active NC program is not aborted but only stopped. After eliminating the error, it is possible to continue execution of the NC program from the point at which it was stopped.
 Reset	Execution of an active NC program is aborted. After eliminating the error, the NC program must be restarted.
POWER ON	Execution of the active NC program is aborted. After eliminating the error, the NC program must be restarted and the reference points must be reapproached. Caution! On switching off the control, the contents of the NCK part program memory are lost.

POWER ON means switching off the control and switching it on again.

Please note the information provided by the machine tool manufacturer.

1.3 Display of the alarms in the alarm line

1.3 Display of the alarms in the alarm line

Messages from the monitoring system are displayed in the alarm line. Existing comments are overwritten by alarm texts. The alarm line is the second display line from the top.

Alarm line				Delete error condition			
Machine	Parameter	Programm.		Services	Diagnosis		
						POWER ON	
AUTOMATIC		Program stop				M. grp.: 1 Channel: 1	
Actual values			Distances to go		Program pointer		
X	10.789		100.000		%1234	N1234	
Y	5.231				L1234	P12	N1234
Z	210.643		10.000				
			200.000				

There are three types of display representation for alarm messages: Types A, B and C.

Example of display representation Type A: Alarm display in sequence order

Machine	Parameter	Programm.		Services	Diagnosis	
10243 ORD 5 X Illegal pulse multiplication						

max. 6 characters for alarm number

max. 5 characters for ordinal number
The ordinal number shows the order in which the alarms have occurred.

max. 40 characters for explanatory text
(for single-line alarm)
max. 100 characters (for two-line alarm)

1.3 Display of the alarms in the alarm line

Example of display Alarm display in block number order
representation Type B:

Machine	Parameter	Programm.		Services	Diagnosis	
3000 1 N0045 General programming error						

Diagram illustrating the structure of the alarm message:

- max. 5 characters for alarm number (3000)
- 1 character for channel number (1)
- max. 5 characters for block number (N0045)
 E.g.: the error has occurred in block N0045.
- max. 38 characters for explanatory text (for single-line alarm) (General programming error)

Example of display
representation Type C:

Machine	Parameter	Programm.		Services	Diagnosis	
6000	Hydraulic oil min.					

Diagram illustrating the structure of the alarm message:

- max. 4 characters for alarm number (6000)
- max. 47 characters for explanatory text (for single-line alarm) (Hydraulic oil min.)

1.4 Display of the alarms as dialog box

1.4 Display of the alarms as dialog box

The machine tool manufacturer can configure whether the alarm messages are displayed in the alarm line or in a dialog box. MMC messages are displayed as a dialog box.

There are 3 types of dialog box:

Dialog box with empty softkey bar

The dialog must be acknowledged from a configured application.

Machine	Parameter	Programm.	Services	Diagnosis
				12:17
JOG		Program reset		Mode Gp 1 Channel 1
Actual value		REPOS offset	Program pointer	
X 0.000		0.000	PART	
Y 0.000		0.000	% 13 N 0	
Z 0.000		0.000	L 0 P 0 N 0	
			L 0 P 0 N 0	
			L 0 P 0 N 0	
206001 Data in Siemens branch cannot be stored				
Act. value		ons		
F= 0.00 100%		F= 0.00M		T = M =
S 1= 0 50%		S 1= 0		D = M =
				H = M =
		G functions		

Fig. 1.1 Example 1 dialog box

*Dialog box with OK
softkey*

The dialog box can be acknowledged with the OK key.

Machine	Parameter	Programm.	Services	Diagnosis
				12:08
JOG		Program reset		Mode Gp 1 Channel 1
Actual value		REPOS offset		Program pointer
X	0.000	0.000	PART	
Y	0.000	0.000	% 13	
Z	0.000	0.000	N 0	
Act. value		206001 Data in Siemens branch cannot be stored		ons
F=	0.00 100%	F=	0.00M	T = M =
S 1=	0 50%	S 1=	0	D = M =
				H = M =
				G functions
				OK

Fig. 1.2 Example 2 dialog box

*Dialog box with
OK softkey and
HIDE softkey*

The dialog box can either be acknowledged with the OK key or it can be with the HIDE softkey without being acknowledged.

Machine	Parameter	Programm.	Services	Diagnosis
				12:14
JOG		Program reset		Mode Gp 1 Channel 1
Actual value		REPOS offset		Program pointer
X	0.000	0.000	PART	
Y	0.000	0.000	% 13	
Z	0.000	0.000	N 0	
Act. value		206001 Data in Siemens branch cannot be stored		ons
F=	0.00 100%	F=	0.00M	T = M =
S 1=	0 50%	S 1=	0	D = M =
				H = M =
				G functions
				Hide OK

Fig. 1.3 Example 3 dialog box

1.5 Priority of alarms

Only one alarm can be displayed in the alarm line and the following priorities apply:

Priority range	Alarm type
0 – 100	Power on
101 – 200	Reset
201 – 300	Cancel
301 – 500	Message
301 – 500	PLC alarm
1000	Diagnosis

Within the alarm groups, the priority is in accordance with the alarm number or priority range, i.e. the lowest alarm number/priority range has the highest priority. The alarm priorities can be configured by the machine tool manufacturer.



An arrow on the right in the alarm line indicates that further alarms exist. These alarms are displayed if you select the alarm overview display in the DIAGNOSIS area.

1.5.1 Alarm description

The alarms are described in a uniform style. The column alarm heading boxes show the alarm number, alarm text and the means of cancellation.

Alarm number	Alarm text	Means of cancel.
Scan:	Specifies in which state the alarm occurs.	
Effect:	Specifies the sphere of influence of processing.	
Explanation:	States the reasons for the alarm.	
Remedy:	Instructions for eliminating the alarm state.	

1	Battery: Data loss at power off!	Acknowledgement key
<i>Scan</i>	POWER ON Cyclic	
<i>Effect</i>	Data is not battery-backed after power off. During operation: Do not interrupt the production process. Data will be lost if the control is switched off. Run-up: Data has been lost. Obligatory re-installation is activated.	
<i>Explanation</i>	Backup battery is empty.	
<i>Remedy</i>	Replace the battery when the control is switched on If data has been lost the whole NCK/PLC unit must be re-installed.	
2	Overtemperature	Acknowledgement key
<i>Scan</i>	POWER ON Cyclic	
<i>Effect</i>	The second temperature monitoring threshold has been triggered because the ambient temperature is too high. NC program is not interrupted.	
<i>Explanation</i>	Safe functioning of the hardware can no longer be guaranteed, serious damage to hardware may result. Processing is not interrupted directly. A contact is opened on the CSB which the NC user must use to take the appropriate measures.	
<i>Remedy</i>	A low temperature level will eliminate the error. Switch off control (hardware damage possible).	
3	Fan failure	Acknowledgement key
<i>Scan</i>	POWER ON Cyclic	
<i>Effect</i>	Fan monitoring is triggered because of incorrect fan functioning.	
<i>Explanation</i>	Safe functioning of the hardware can no longer be guaranteed, serious damage to hardware may result. Processing is not interrupted directly. A contact is opened on the CSB which the NC user must use to take the appropriate measures.	
<i>Remedy</i>	Eliminate the fan fault, e.g. by replacing the fan. Switch off control (hardware damage possible).	
4	System of units not allowed	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> • POWER ON • After modification of NC machine data 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC READY • Interlocking of NC START • Interlocking of Mode Group Ready • Machining stops 	
<i>Exlanation</i>	An illegal combination of machine data MD 18000 display resolution and MD 5002 input resolution has been selected. Both data must use the same system of units For rotary axes with a position control resolution smaller than $= 0.5 \cdot 10^{-4}$ degrees, the function bit "High-resolution rotary axis" must be set.	
<i>Remedy</i>	Check and correct machine data combinations. Then cancel the alarm with POWER ON.	
5	Power failure protection / data loss	Acknowledgement key
<i>Scan</i>	POWER ON	
<i>Effect</i>	The power failure protection integrated in the software could not be executed correctly because of a hardware fault.	
<i>Explanation</i>	Data loss in the NCK unit. Obligatory re-installation is activated.	
<i>Remedy</i>	The whole NCK unit must be re-installed. Eliminate hardware fault.	

1.5.1 Alarm description

6	Start-up due to system error	Acknowledgement key
<i>Scan</i>	POWER ON	
<i>Effect</i>	Start-up of the control shows that a fatal error was present before reset/power off (e.g. obligatory re-installation is activated. Alarm 5 can be set in conjunction with alarm 6. EPROM error, DRAM error, processor exceptions).	
<i>Explanation</i>	Re-installation is necessary as data loss or corruption is to be expected (no data consistency).	
<i>Remedy</i>	<p>The NCK unit must be completely re-installed.</p> <p>Cause of error can be eliminated as follows:</p> <ul style="list-style-type: none"> a) Replace hardware b) Report the software error leading to the processor exception to the manufacturer of the control. 	
7	15 V undervoltage	Acknowledgement key
<i>Scan</i>	POWER ON Cyclic	
<i>Effect</i>	Activates 15V voltage monitoring	
<i>Explanation</i>	Safe operation of the NC is no longer possible so NC Ready is cancelled.	
<i>Remedy</i>	Eliminate hardware fault	
8	Wrong axis/spindle assignment	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> • After modification of machine data • On POWER ON 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Removal of Mode Group Ready • NC Ready relay drops out • Machining stops 	
<i>Explanation</i>	<p>The NC machine data for axis assignment MD200* or spindle assignment MD400* have been input incorrectly or transposed.</p> <p>If error in MD 461* C axis definition:</p> <ul style="list-style-type: none"> • C axis must not be fictitious (MD 564*, bit 6) • C axis must be defined (MD 564*, bit 7) • Mode group numbers of C axis and spindle must be same (MD 360*, MD 453*) 	
<i>Remedy</i>	<p>Check and correct machine data for axis and spindle assignment.</p> <p>Cancel alarm with POWER ON.</p>	
9	Not enough memory for UMS	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> • At POWER ON in normal mode, not in start-up mode 	
<i>Effect</i>	None	
<i>Explanation</i>	The RAM area reserved on the NC is too small for the UMS address lists for the modified system area.	
<i>Remedy</i>	Describe fewer elements (displays/texts) in modified system area (merge).	
<i>Note</i>	Applies up to SW 2 only	
9	Overflow in altered system area	POWER ON
<i>Scan</i>	When powering up the control	
<i>Effect</i>	The UMS does not function	
<i>Explanation</i>	In the UMS, an altered system area has been configured that exceeds the memory area.	
<i>Remedy</i>	Configure UMS properly	
<i>Note</i>	Applies as from SW 4	

10	UMS error	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> At POWER ON 	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START 	
<i>Explanation</i>	The UMS loaded in NCK has a faulty internal structure.	
<i>Remedy</i>	Reinstall UMS on hard disk.	
<i>Note</i>	Applies up to SW 2 only	
10	Startup after software upgrade	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> At POWER ON 	
<i>Effect</i>	<ul style="list-style-type: none"> The NCK–internal static memory has been deleted. 	
<i>Explanation</i>	There are two causes for the alarm: <ul style="list-style-type: none"> A new NCK software version has been loaded (only when booting for the first time after software upgrade) The NCK–internal static RAM has failed (e.g. because of an empty back–up battery); alarm 5 is then displayed additionally. 	
<i>Remedy</i>	The complete NCK unit must be started up again.	
<i>Note</i>	Applies as from SW 6	
11	Undervoltage on secondary side	Cancel
<i>Scan</i>	POWER ON Cyclic	
<i>Effect</i>	Short circuit on secondary side or overloading of 5V voltage Caution: The error may have been signalled during initial start-up without the error being present (hardware wiring).	
<i>Explanation</i>	When the error occurs the shutdown routine is activated to achieve a safe state. Restart: Data loss has occurred, obligatory re-installation is activated	
<i>Remedy</i>	Eliminate the hardware error Re-install	
20	Cam activation wrong	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC start Interlocking of Mode Group Ready 	
<i>Explanation</i>	Software cams can only be used for linear axes.	
<i>Remedy</i>	Correct the PLC user program	
26	Part program block >120 char. V.24	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> On reading data into the NC via the computer link 	
<i>Effect</i>	<ul style="list-style-type: none"> Computer link transmission interrupted Last block declared invalid 	
<i>Explanation</i>	The part program block that has been read in contains more than 120 characters. Only the characters actually stored are counted (no spaces, no CR, etc.)	
<i>Remedy</i>	Divide the block into two or more blocks. The number of the faulty block is displayed.	
<i>Note</i>	Applies up to SW 2 only	

1.5.1 Alarm description

27	Data input disabled V.24	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> On reading data into the NC via the computer link 	
<i>Effect</i>	No data has been read in	
<i>Explanation</i>	<ul style="list-style-type: none"> The "Cycle lock" interface signal (DB 48 D0.11) is present An attempt has been made to read in NC machine data in normal mode An attempt has been made to transfer UMS data to the NC although the UMS was not enabled or not plugged in. 	
<i>Remedy</i>	<ul style="list-style-type: none"> Reset DB 48 DW 0 bit 11 via PLC STATUS Enter new NC machine data 	
<i>Note</i>	Applies up to SW 2 only	
29	Block >254 characters V.24	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> On reading tool data into the NC via the computer link 	
<i>Effect</i>	<ul style="list-style-type: none"> Computer link transmission interrupted Last block declared invalid 	
<i>Explanation</i>	The block read in has more than 254 characters (counting all characters read in, including blanks, CR, LF, etc.)	
<i>Remedy</i>	Divide the block into two or more blocks. The number of the faulty block is displayed.	
<i>Note</i>	Applies up to SW 2 only	
30	Part program memory overflow V.24	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> While reading programs in via the computer link of the NC 	
<i>Effect</i>	<ul style="list-style-type: none"> Computer link transmission interrupted Last block declared invalid 	
<i>Explanation</i>	The maximum memory space for part programs is already assigned	
<i>Remedy</i>	<ul style="list-style-type: none"> Delete old programs to release memory for the reading in of new programs. The number of the faulty block is displayed. 	
<i>Note</i>	Applies up to SW 2 only	
31	No more part program input V.24	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> On reading in via computer link 	
<i>Effect</i>	No data has been read in	
<i>Explanation</i>	The part program memory available has been used up.	
<i>Remedy</i>	<ul style="list-style-type: none"> Read and delete old part programs no longer required in order to provide more memory. 	
<i>Note</i>	Applies up to SW 2 only	
32	Data format error V.24	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> On reading data into the NC via the computer link 	
<i>Effect</i>	<ul style="list-style-type: none"> Computer link transmission interrupted Last block declared invalid 	
<i>Explanation</i>	<ul style="list-style-type: none"> The number of decades used after an address is not permissible The decimal point occurs in the wrong place Part programs or subroutines are not defined or concluded correctly (check header) 	
<i>Remedy</i>	Check the program to be read in. The number of the faulty block is displayed.	
<i>Note</i>	Applies up to SW 2 only	

33	Programs different V.24	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> On reading part programs into the NC memory via the computer link of the NC 	
<i>Effect</i>	No data is read in/stored	
<i>Explanation</i>	If a new program is to be read in with the same program number as one already stored in the NC, the program to be read in is compared. If they are different, an NC alarm occurs. The point of disagreement is shown in the data input display. The new program is not stored.	
<i>Remedy</i>	Delete the old program or rename it in the NC so that the new program can be read in.	
<i>Note</i>	Applies up to SW 2 only	
43	PLC–CPU not ready for operation	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> Cyclic or on Restart 	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Interlocking of Mode Group Ready Interlocking of NC Ready relay Processing is terminated 	
<i>Explanation</i>	<ul style="list-style-type: none"> Hardware or software error in PLC or general data interface link PLC machine data error or not in agreement with user program Error in the PLC user program Selection of error fine coding 	
<i>Remedy</i>	<ul style="list-style-type: none"> Remove cause of error Check detailed error coding in PLC service menu Read out ISTACK Ascertain cause of error using the error list in the installation lists 	
45	Cam signal output wrong	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Interlocking of Mode Group Ready 	
<i>Explanation</i>	Incorrect values in NC MD 310, 311 Interface output via MIXED I/O selected without the corresponding hardware	
<i>Remedy</i>	Slot in the MIXED I/O before switching on the control.	
46	Invalid TO parameter number	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> After altering machine data and then formatting user memory or when powering up if MD 13 (as from SW 4 MD 60006) is not correct. 	
<i>Effect</i>	Function not usable <ul style="list-style-type: none"> Interlocking of NC START 	
<i>Explanation</i>	On installation, a value greater than 32 or less than 10 has been specified for machine data 13, "Number of TO parameters". "Extended tool parameter for type 50..59" deselected: 10 – 32 "Extended tool parameter for type 50..59" selected: 10 – 32	
<i>Remedy</i>	<ul style="list-style-type: none"> Correct machine data Format user memory or, in General Reset mode, format the area for the TO data 	

1.5.1 Alarm description

47	Wrong TO assignment lists	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> At POWER ON after modifying machine data 	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START 	
<i>Explanation</i>	<ul style="list-style-type: none"> Value of machine data 210, "Number of TO areas", is greater than 4 TO start numbers in NC MD211 to 214 have not been entered in ascending order Input value in channel-specific NC MD 1040 to 1043 is greater than the number of TO areas under MD 210 or is specified as 0 in the TO area 	
<i>Remedy</i>	<ul style="list-style-type: none"> Correct machine data Where appropriate format user memory if machine data were input correctly or format the TO data in General Reset mode POWER ON 	
48	Data link to PLC not ready	POWER ON
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Interlocking of NC Ready relay Interlocking of Mode Group Ready Machining stops 	
<i>Explanation</i>	During the start-up synchronization or data exchange between interface-CPU (IFC) and PLC CPU an error was established, leading to the alarm. Data exchange between NC and PLC is still possible but the link to the programmer via the interface is not possible.	
<i>Remedy</i>	Error fine coding can give information on further error sources; in addition, check whether alarm 43 is present.	
<i>Note</i>	Applies up to SW 2 only	
49	NC in general reset	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	None	
<i>Explanation</i>	The software has recognized that the control is in general reset mode.	
<i>Remedy</i>	Leave general reset mode	
50	Flex. memory incorrectly configured	POWER ON
50	Insufficient memory for block buffer	POWER ON
<i>Scan</i>	On pressing NC Start	
<i>Effect</i>	Interlocking of machining Interlocking of "NC Start"	
<i>Explanation</i>	<ol style="list-style-type: none"> The channel-specific machine data 6100* that defines the number of block buffers in a channel is not in the permissible range. No memory has been made available (MD 60014) for loading of drive software (MD 60003 or 60004). 	
<i>Remedy</i>	Check and correct the values of the machine data.	
<i>Note</i>	Alarm Insufficient memory for block buffer (with SW 4 and higher) Alarm Flex. memory incorrectly configured (with SW 5.4 and higher)	
57	Drive link failure	POWER ON
<i>Scan</i>	Cyclic	
<i>Effect</i>	Interlocking of NC Ready, NC Start, Mode Group Ready, NC Stop	
<i>Explanation</i>	Internal software error or ring programming for GI or gantry axes.	
<i>Remedy</i>	<ul style="list-style-type: none"> Eliminate ring programming for GI or gantry axes Notify service 	

60	Internal software error	POWER ON
<i>Scan</i>	Cyclic	
<i>Effect</i>	Computer stops, machining stops, interlocking of NC Start	
<i>Explanation</i>	The software has recognized an internal error but cannot rectify it.	
<i>Remedy</i>	Notify service.	
67	1st computer link not ready for operation	POWER ON
<i>Scan</i>	Cyclic or after POWER ON	
<i>Effect</i>	Message frame transfer between host computer and NC is not possible	
<i>Explanation</i>	Host computer and NC are not synchronized owing to an incorrect input or a fault in the interface module. This means that message frame transfer is not possible.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check programming of interface module • Check machine data settings for computer link • Check whether host computer is ready or connected 	
68	2nd computer link not ready for operation	POWER ON
<i>Scan</i>	Cyclic or after POWER ON	
<i>Effect</i>	Message frame transfer between host computer and NC is not possible	
<i>Explanation</i>	Host computer and NC are not synchronized owing to an incorrect input or a fault in the interface module. This means that message frame transfer is not possible.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check programming of interface module • Check machine data settings for computer link • Check whether host computer is ready or connected 	
70	Define at least one channel	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> • At POWER ON 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Interlocking of Mode Group Ready • Interlocking of NC Ready relay • Machining not possible 	
<i>Explanation</i>	At start-up, an incorrect assignment of machine data was made. The NC will not work without channel assignment.	
<i>Remedy</i>	Check and correct machine data for channel assignment <ul style="list-style-type: none"> • POWER ON 	
71	Too many real axes	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> • At POWER ON 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Interlocking of Mode Group Ready • Interlocking of NC Ready relay • Machining stops • Surplus axes are not shown on the service display 	
<i>Explanation</i>	More real axes than are permitted were defined in axis-specific machine data bits 564* at the time of start-up. The machine data MD 60013 (memory for real axes) is not within the permissible range or has been set too small.	
<i>Remedy</i>	Correct axis-specific machine data bits 564*. Correct MD 60013.	

1.5.1 Alarm description

72	Too many fictitious axes	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> At POWER ON or warm restart 	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Interlocking of Mode Group Ready Interlocking of NC Ready relay Machining stops 	
<i>Explanation</i>	More fictitious axes than are permitted were defined in axis-specific machine data bits 564* during installation.	
<i>Remedy</i>	Correct axis-specific machine data bits 564*.	
73	Axis preset in wrong mode group	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> At POWER ON or warm restart 	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Interlocking of Mode Group Ready Interlocking of NC Ready relay Machining not possible 	
<i>Explanation</i>	At start-up, an incorrect assignment of NC machine data was made or the assignment of axis selector switch with 2 machine control panels is incorrect or a wrong axis is set in the program.	
<i>Remedy</i>	Check and correct NC machine data "Axis valid in mode group". <ul style="list-style-type: none"> Correct program POWER ON 	
74	Too many drives	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> At POWER ON or warm restart 	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Interlocking of Mode Group Ready Interlocking of NC Ready relay Machining stops Surplus axes do not appear in the service display 	
<i>Explanation</i>	The total number of spindles and real axes defined during installation is greater than permitted.	
<i>Remedy</i>	Correct axis-specific machine data bits 564* and spindle-specific machine data bits 521*.	
75	Max. number of meas. circuits exceeded	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> At POWER ON or warm restart 	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Interlocking of Mode Group Ready Interlocking of NC Ready relay Machining stops Surplus axes do not appear in the service display 	
<i>Explanation</i>	Output of alarm if too many axes and spindles are defined.	
<i>Remedy</i>	Reduce the number of axes (MD 564*) and spindles (MD 512*).	
<i>Note</i>	Axes/spindles that are not assigned to a measuring circuit are included in the number of measuring circuits.	
77	Mode group no. of axis invalid	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> At POWER ON 	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Interlocking of Mode Group Ready Interlocking of NC Ready relay Interlocking of machining 	
<i>Explanation</i>	Check and correct machine data for axis assignment and spindle assignment.	
<i>Remedy</i>	<ul style="list-style-type: none"> Check and correct machine data for "Axis valid in mode group" Perform POWER ON 	

78	Mode group no. of spindle invalid	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> At POWER ON 	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Interlocking of Mode Group Ready Interlocking of NC Ready relay Interlocking of machining 	
<i>Explanation</i>	Check and correct machine data for axis assignment and spindle assignment.	
<i>Remedy</i>	<ul style="list-style-type: none"> Check and correct machine data for "Mode group of spindle" Perform POWER ON 	
79	Mode group no. of channel invalid	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> At POWER ON 	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Interlocking of Mode Group Ready Interlocking of NC Ready relay Interlocking of machining 	
<i>Explanation</i>	An incorrect assignment (e.g. channel gap) has been made in the channel-specific machine data for "Channel valid in mode group".	
<i>Remedy</i>	<ul style="list-style-type: none"> Check machine data Perform POWER ON 	
80	Error in C axis definition	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> At POWER ON and warm restart 	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Interlocking of Mode Group Ready Interlocking of NC Ready relay Machining stops If C axes and spindles are incorrectly assigned, the spindle does not appear in the service display. 	
<i>Explanation</i>	The C axes assigned to the spindles were either defined as non-existent or fictitious during installation, or the spindle and assigned C axis mode groups are not identical.	
<i>Remedy</i>	Check and correct axis-specific machine data bits 564*, axis-specific machine data 360* and spindle-specific machine data 453* and 461*.	
84	Coupled motion grouping defined wrong	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> At POWER ON At warm restart 	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Interlocking of Mode Group Ready Interlocking of machining 	
<i>Explanation</i>	An illegal coupled axis grouping has been set for the assignment of coupled axes in machine data, e.g.: <ul style="list-style-type: none"> The axes do not belong to the same mode group The axes have different position control resolutions The axes are of different types (linear axis/rotary axis) The axes are declared as being not present The axes are fictitious The leading axis is defined as a coupled axis 	
<i>Remedy</i>	Correct machine data using the "Coupled motion" function and perform a warm restart (see Start-up Guide).	

1.5.1 Alarm description

85	Coupled-motion combination wrong	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> • POWER ON • Warm restart 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Interlocking of Mode Group Ready • Interlocking of machining 	
<i>Explanation</i>	An undefined combination has been input in NC machine data for the coupled axis combination.	
<i>Remedy</i>	Correct machine data and perform a warm restart (see Start-up Guide).	
87	Illegal software limit switch	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> • After altering machine data 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Interlocking of Mode Group Ready • Interlocking of machining 	
<i>Explanation</i>	An excessively large value has been entered in the NC machine data for the software limit switch. The maximum traversing range of the individual axes results from the axis-specific position control resolution set and the input resolution. With alarm 87, the control has automatically entered the maximum permissible value in the appropriate NC machine data.	
<i>Remedy</i>	Check machine data for software limit switch and where appropriate correct.	
<i>Note</i>	Applies up to SW 2 only	
88	Interpolation greater than 3D	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> • When executing part programs in AUTOMATIC or MDA 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Interlocking of machining 	
<i>Explanation</i>	More than 3 axes have been programmed in one block in the part program block of the NC, or the "5D" function is not active.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Modify part program • Do not execute more than 2 programs at once 	
89	More than two 3D interpolations	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> • When executing part program blocks in AUTOMATIC or MDA 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Machining stops 	
<i>Explanation</i>	More than 3 axes have been programmed in more than 2 channels in the NC in one program block in each case.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Modify program • Do not execute more than 2 programs at once 	
90	Customer UMS invalid	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> • At POWER ON when UMS bit is set 	
<i>Effect</i>	Interlocking of NC START until alarm is acknowledged. Standard UMS is loaded.	
<i>Explanation</i>	Customer UMS faulty or >512 KB.	
<i>Remedy</i>	Check customer UMS.	
<i>Note</i>	Applies up to SW 2 only	
91	ID no. in UMS header faulty	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> • At POWER ON and with activated UMS data 	
<i>Effect</i>	Interlocking of NC START until alarm is acknowledged.	
<i>Explanation</i>	The programmed ID number in the UMS header, which is evaluated by the system software, is incorrect or has been read incorrectly because the UMS submodules were plugged in incorrectly.	
<i>Remedy</i>	Check WS 800A software version.	
<i>Note</i>	Applies up to SW 3 only	

91	UMS invalid	POWER ON
<i>Scan</i>	At POWER ON and activated UMS data	
<i>Effect</i>	Interlocking of NC START until alarm is acknowledged.	
<i>Explanation</i>	The configured identifying number in the UMS header, evaluated by the system software, is incorrect or no UMS has been loaded because the memory reserved for this (MD 60000) is smaller than the UMS to be loaded.	
<i>Remedy</i>	Check MD 60000 or install the correct UMS.	
<i>Note</i>	Applies as from SW 4	
93	Wrong UMS selector	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> At POWER ON and with activated UMS data 	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START until alarm is acknowledged. 	
<i>Explanation</i>	The address lists preset by the NC workstation do not contain the set selectors required for error-free processing of a UMS.	
<i>Remedy</i>	Check the system software of the NC workstation, or have it checked.	
94	Wrong UMS identifier	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> At POWER ON and with activated UMS data 	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START until alarm is acknowledged. 	
<i>Explanation</i>	An incorrect identifier is programmed in the UMS.	
<i>Remedy</i>	Check UMS and NC workstation software.	
95	Wrong number in GSB	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> At POWER ON and with activated UMS data 	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START until alarm is acknowledged. 	
<i>Explanation</i>	Numbers have been used in the modified system area (GSB) which are outside the reserved areas.	
<i>Remedy</i>	Check the numbers used in the modified system area.	
96	Language in UMS not available	Acknowledgement key
<i>Scan</i>	At UMS analysis (POWER ON of control not during start-up)	
<i>Effect</i>	UMS is connected in its basic language	
<i>Explanation</i>	Two-language UMS does not contain the language activated in the control	
<i>Remedy</i>	Put correct UMS in control	
<i>Note</i>	Applies up to SW 1 only	
101	Prewarning replace battery	Acknowledgement key
<i>Scan</i>	POWER ON Cyclic	
<i>Effect</i>	Battery monitoring is activated if battery voltage falls below the advance warning voltage threshold.	
<i>Explanation</i>	The working process is not interrupted User is advised to replace the backup battery to avoid the risk of data loss – see alarm 1.	
<i>Remedy</i>	Replace battery when control is switched on	

1.5.1 Alarm description

102	Prewarning overtemperature	Acknowledgement key
<i>Scan</i>	POWER ON Cyclic	
<i>Effect</i>	The first temperature monitoring threshold on the CBS module is activated because the ambient temperature is too high	
<i>Explanation</i>	User is given advance warning. The working process is not interrupted.	
<i>Remedy</i>	A lower temperature level is required to eliminate the fault	
103	Initializing error NCK FB	POWER ON
<i>Scan</i>	When powering up the control	
<i>Effect</i>	Interlocking of NC START Follow-up mode Removal of Mode Group Ready	
<i>Explanation</i>	The initialization routine of the NCK FB has returned a value which is not equal to zero. The return value is output in the alarm as block number N.	
<i>Remedy</i>	Check the NCK FB.	
<i>Continuation</i>	The alarm is initiated when powering up the control. No program can be started. Acknowledge alarm by POWER ON.	
<i>Note</i>	<ul style="list-style-type: none"> Alarm 103 is output only if appropriately configured by the machine manufacturer. An error has occurred in the safety NCK-FB. For more information and remedy, refer to the manufacturer's documentation. Applies as from SW 5.4. Applies as from SW 5.4. 	
104	Error in machine data	
<i>Scan</i>	When powering up the control After a warm start After changing a machine data	
<i>Effect</i>	Interlocking of NC START Follow-up mode Removal of Mode Group Ready	
<i>Explanation</i>	A machine data contains an implausible value. The machine data error is output in the alarm as block number N.	
<i>Remedy</i>	Evaluate the block number and correct the corresponding machine data.	
<i>Continuation</i>	The alarm is initiated when powering up the control. No program can be started. Acknowledge alarm by POWER ON.	
<i>Note</i>	Applies as from SW 5.4	
105	Error in NCK FB	
<i>Scan</i>	During cyclic operation of control	
<i>Effect</i>	Interlocking of NC START Follow-up mode Removal of Mode Group Ready Interruption of machining	
<i>Explanation</i>	The cyclic routines of the NCK FB have returned a value which is not equal to zero.	
<i>Remedy</i>	Evaluate the block number and check the NCK FB.	
<i>Continuation</i>	No program can be started. Acknowledge alarm by POWER ON.	
<i>Note</i>	<ul style="list-style-type: none"> Alarm 105 is output only if appropriately configured by the machine manufacturer. An error has occurred in the safety NCK-FB. For more information and remedy, refer to the manufacturer's documentation. Applies as from SW 5.4 	

110 Checksum error safe monitorings POWER ON

Scan When powering up the control

Effect Interlocking of NC START

Explanation The MDs for the safety system are protected by a checksum after acceptance of the control. The alarm indicates that the current checksum no longer matches the stored checksum, i.e. either an MD value has been changed without authorization or a data is defective.

Remedy Check the MDs. Inspect the safety functions again. Have the checksum calculated again.

Continuation The alarm is initiated when powering up the control. No program can be started. Alarm acknowledgement only possible by POWER ON.

Note Applies as from SW 5.4

111 Error in collision monitoring data POWER ON

Scan At POWER ON

Parameters: Block number (4-digit) Nxxx:
 3rd and 4th digit: Number of protection zone 00–09 = Protection zone 1–20
 1st and 2nd digit: Error identifier (see explanation)
 Nibble 3,4=Error identifier:
 01=Motion axis does not exist
 02=Motion axes not in same mode group
 03=Error in monitoring relation
 04=Protection zone dimensions not available (all dimensions=0)
 05=Negative protection zone dimension
 06=Protection zones not defined in same plane

Effect Machining standstill;
 interlocking of machining (NC Start);
 BAG–BB=0; NC–Ready=0

Explanation Error identifiers

01=Motion axis does not exist

A non-existing axis has been specified in the machine data 3800*, 3802*, 3804*.

02=Motion axes not in same mode group

Axes that are not in same mode group have been specified In the machine data 3800*, 3802*, 3804*.

03=Error in monitoring reference

The mutual deselection of the protection zone monitoring in the MD bits 38803+s*3 has not been executed correctly.

Deselection of monitoring of protection zone 2 in the machine data of protection zone 1 causes the deselection of monitoring of protection zone 1 in the machine data of protection zone 2, i.e. deselection must always be carried out mutually.

04=Protection zone dimensions not available

The protection zone dimensions specified in the machine data 3812*, 3814*, 3816* are all=0.

05=Negative protection zone dimension

At least one of the protection zone dimensions specified in the machine data 3812*, 3814*, 3816* is negative. But only positive dimensions are allowed.

06=Protection zones not defined in same plane

The protection zone specified is 2-dimensional. It is related to another 2-dimensional protection zone, which is defined in another plane. But 2-dimensional protection zones that are in a monitoring relation must lie in the same plane.

1st possibility:

The plane of the protection zone defined in the machine data 3812*, 3814*, 3816* is not identical with the planes of the other protection zones to be monitored.

2nd possibility:

The protection zone should not monitor the protection zones in other planes, i.e. the protection zone relation must be corrected in the machine data bits 38803 – 38815 (monitoring relation).

Remedy Correct machine data and execute POWER ON.

Note Applies as from SW 6

1.5.1 Alarm description

100*	Leadscr. err. comp.-illegal grid spacg.	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> • After POWER ON 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Interlocking of Mode Group Ready 	
<i>Explanation</i>	<p>Leadscrew error compensation with rotary axes in NC machine data "Distance between 2 values" has been entered for the appropriate axis with a value which cannot be divided into 360 degrees to give an integer, i.e. grid spacing is not equal; e.g.</p> <ul style="list-style-type: none"> • Correct: NC-MD= 10 (rotary axis) • Results in: $360/10 = 36$ grid points • Incorrect: NC-MD= 11 • Would give: $360/11 = 32,7$ grid points <p>The compensation value chosen is too large compared with the distance between two leadscrew error compensation points (valid for rotary and linear axes).</p>	
<i>Remedy</i>	<p>Modify NC machine data "Distance between 2 values" – check NC MD 324* and 328*.</p> <ul style="list-style-type: none"> • The compensation value in NC MD 328* must be less than NC MD 324*. 	
104*	Speed setpoint value warning limit responded	Reset key
<i>Scan</i>	<ul style="list-style-type: none"> • Cyclic 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START 	
<i>Explanation</i>	<p>For analog measuring circuit: The DAC set value entered is higher than in NC machine data 268* "Maximum setpoint speed (DAC)". It is not possible to increase the set value further.</p>	
<i>Remedy</i>	<ul style="list-style-type: none"> • Traverse more slowly • Check actual values (encoder) • Check NC machine data "Maximum setpoint speed (DAC)" • Check the drive actuator 	
112*	Zero-speed control	Reset key
<i>Scan</i>	<ul style="list-style-type: none"> • When accelerating • When stopped • When clamping • When decelerating (delay) 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Interlocking of Mode group READY • Setpoint 0 • The control enable is removed after the time stored in NC machine data "Control enable cutout delay" has elapsed • Follow-up operation 	
<i>Explanation</i>	<ul style="list-style-type: none"> • The following error could not be cleared faster than the time entered in NC machine data "Control enable cutout delay" during positioning • On clamping, the limit defined in NC machine data "Zero speed monitoring" was exceeded • A mechanically clamped axis has been pushed out of position • Fault in the control device (actuator), at the tachometer, at the motor, in the CNC measuring circuit hardware or at/on the pulse encoder • Incorrect specification on assigning the set value output • At start-up: wrong position control direction 	
<i>Remedy</i>	<ul style="list-style-type: none"> • NC machine data "Zero speed monitoring" must be greater than "Coarse exact positioning limit" • NC machine data "Control enable cutout delay" must be large enough for the following error to be removed within this time (only applies if NC machine data "Zero speed monitoring delay" = 0) • NC machine data "Zero speed monitoring delay" must be large enough for the following error of the individual axis to be removed within the time entered • Check actual values (encoder) and position control direction 	

116*	Contour monitoring	Reset key
<i>Scan</i>	In all modes <ul style="list-style-type: none"> • When decelerating • When accelerating • At velocities greater than in NC machine data "Contour threshold speed" 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Interlocking of Mode Group Ready • Setpoint 0 • The control enable is removed after the time stored in NC machine data "Control enable cutout delay" has elapsed • Follow-up operation 	
<i>Explanation</i>	<ul style="list-style-type: none"> • At a velocity greater than in NC machine data "Contour threshold speed", the NC machine data "Tolerance band contour monitoring" was exceeded • When accelerating or decelerating the axis has not reached the new speed within the time defined by the K_V factor 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Increase NC machine data "Tolerance band contour monitoring" • Check K_V (servo gain) factor • Check the optimization of the speed controller • Check the actual values (pulse encoder) • Check the free movement of the axes • Reduce acceleration 	
120*	Axis specification illegal	Reset key
<i>Scan</i>	<ul style="list-style-type: none"> • At POWER ON 	
<i>Effect</i>	<ul style="list-style-type: none"> • Axis is not processed • Controller disable for the relevant axis • Mode Group Ready removed • Interlocking of NC START 	
<i>Explanation</i>	<ul style="list-style-type: none"> • Specification of MD200x or MD384x in the relevant axis missing. Example: MD2000 = 01020101 and MD384 = 00000000 • Specification of module number in MD200x or MD384 is greater than the number of measuring circuit modules present. Example: MD2000 = 04010000 and 3 measuring circuit modules are plugged in. • Specification of the connection number in MD200x or MD384 is greater than the number of connections on the relevant module. Example: MD3840 = 02070000; the 2nd measuring circuit module is a SPC module and therefore has only 6 connections. • Connection number for an input is assigned to an output and vice versa. Example: MD3840 = 01030000; the 1st measuring circuit module is a HMS module and connection number 3 there is an input connection. • Input or output assignment is not compatible with the plug-in submodule. Example: MD2000 = 01040101; the 1st measuring circuit module is a HMS module with output submodule Servo-Command 6FX1132-5BAxx on its submodule slot 1. 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check and correct MD200x and MD384x of the relevant axis. Both these machine data must be specified or must be zero. In addition, they must agree with the hardware configuration. 	
<i>Note</i>	Applies up to SW 2 only	
128*	Measuring circuit not available	POWER ON
<i>Scan:</i>	<ul style="list-style-type: none"> • At POWER ON 	
<i>Effect</i>	<ul style="list-style-type: none"> • Axis is not processed • Control disable for the axis concerned • NC Ready 2 removed • Interlocking of NC START • Interlocking of Mode Group Ready • Interlocking of NC RDY relay 	
<i>Explanation</i>	<ul style="list-style-type: none"> • MD200x or MD384x indicates an empty slot on a measuring circuit module containing submodules. Example: MD3840 = 01090000; the 1st measuring circuit module is a HMS module with submodule slot 2 empty. • Measuring circuit module removed or defective. 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Compare and correct MD200x or MD384x with hardware configuration. 	

1.5.1 Alarm description

132*	Closed-loop system hardware axis	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> • Cyclic 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Interlocking of Mode Group Ready • Setpoint = 0 • The control enable is removed after the time stored in NC machine data "Control enable cutout delay" has elapsed • Follow-up operation 	
<i>Explanation</i>	<p>The measuring circuit difference signals.</p> <ul style="list-style-type: none"> • Are not in phase • Have a fault to earth • Are completely missing 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check whether the measuring circuit connector has been plugged in • By plugging in the measuring circuit short-circuit connector it is possible to check whether the measuring circuit group is in working order • Check the difference signals using an oscilloscope • Replace the encoders • Check NC MD 200*, 384* <p>The alarm can only be cancelled by POWER ON.</p>	
136*	Contamination measuring system axis	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> • Cyclic 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Interlocking of Mode Group Ready • Machining stops 	
<i>Explanation</i>	<ul style="list-style-type: none"> • On measuring systems with a contamination signal (e.g. EXE) an error is sent to the NC from the measuring system. 	
<i>Remedy</i>	Check the measuring system in accordance with the manufacturer's instructions.	
140*	Pulse code monitoring	Reset key
<i>Scan</i>	<ul style="list-style-type: none"> • Cyclic 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of Mode Group Ready • Interlocking of NC START • Alarm leads to machining stop 	
<i>Explanation</i>	<ul style="list-style-type: none"> • Transmission errors or noise from encoder 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check encoder, cable, connector 	
144*	Zero mark monitoring responded	Reset key
<i>Scan</i>	<ul style="list-style-type: none"> • Cyclic 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START 	
<i>Explanation</i>	Transmission errors, noise or excessive speed have caused pulses to be lost relating to an encoder revolution	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check encoder pulses • Check transmission path • Switch off monitoring system briefly with MD 1820* bit 1=0 	
148*	SW limit switch plus	Reset key
<i>Scan</i>	<ul style="list-style-type: none"> • With each axis movement 	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining stops • Interlocking of NC START 	
<i>Explanation</i>	<ul style="list-style-type: none"> • The software limit switch only becomes active after approach to reference point. • Depending on the PLC interface signal "Second software limit switch active", the first or the second limit switch has been approached. 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Traverse away from the limit switch in the opposite direction in JOG mode. • Check the values in machine data for software limit switches. 	

152*	SW limit switch minus	Reset key
<i>Scan</i>	<ul style="list-style-type: none"> On each axis movement 	
<i>Effect</i>	<ul style="list-style-type: none"> Machining stops Interlocking of "NC START" 	
<i>Explanation</i>	<ul style="list-style-type: none"> The software limit switch becomes active only after reference point approach has taken place. The first or second software limit switch has been approached, according to the PLC interface signal "Second software limit switch active". 	
<i>Remedy</i>	<ul style="list-style-type: none"> Travel away from the software limit switch in the opposite direction using JOG mode. Check NC machine data for 1st software limit switch minus or 2nd software limit switch minus. 	
156*	Speed set val. alarm limit responded	Reset key
<i>Scan</i>	Cyclic	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Interlocking of Mode Group Ready Setpoint 0 The control enable is removed after the time stored in NC machine data "Control enable cutout delay" has elapsed Follow-up operation 	
<i>Explanation</i>	<ul style="list-style-type: none"> A higher set speed value has been output within the control than set in NC machine data "Threshold for drive errors". The motor could not follow the setting of the speed set value. On installation: wrong position control direction 	
<i>Remedy</i>	<ul style="list-style-type: none"> Check whether the value in NC machine data "Threshold for drive errors" is greater than the value in NC machine data "Max. speed setpoint (DAC)" Check the drive Check the position control direction Check the speed set value cable Check actual values (encoder) 	
160*	Drift too high	Reset key
<i>Scan</i>	Where there is semi-automatic drift compensation and changes to MDs	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START "Position not yet reached" is displayed No traversing movement is possible 	
<i>Explanation</i>	<ul style="list-style-type: none"> The drift to be compensated by the NC automatically has risen beyond approximately 500 mV. 	
<i>Remedy</i>	<ul style="list-style-type: none"> Carry out drift compensation in NC machine data "Drift compensation" Check whether the drift on the drive unit has been set correctly 	
164*	Coupled-motion axis programmed	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> Machining is interrupted Interlocking of NC START 	
<i>Explanation</i>	The axis-specific alarm appears if a coupled axis is assigned several times in one part program block or if an axis is "Leading axis" and coupled axis at the same time in one part program block.	
<i>Remedy</i>	<ul style="list-style-type: none"> Check and correct program 	
168*	Servo enable traversing axis	Reset key
<i>Scan</i>	With each axis movement	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Interlocking of Mode Group Ready Setpoint 0 The control enable is removed after the time stored in NC machine data "Control enable cutout delay" has elapsed Follow-up operation 	
<i>Explanation</i>	The axis-specific controller enable has been removed by the PLC during a traversing movement.	
<i>Remedy</i>	<ul style="list-style-type: none"> Check the PLC program 	

1.5.1 Alarm description

172*	Working area limitation plus	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Machining stops 	
<i>Explanation</i>	The working area limitation specified in the setting data has been reached.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check the working area limitation in the setting data • Check the program • Program G26 with different values 	
176*	Working area limitation minus	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining stops • Interlocking of NC START 	
<i>Explanation</i>	The working area limitation minus preset in the setting data of the NC has been reached.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check the working area limitation in the setting data • Check the machining program • Program G25 with different values 	
180*	Axis active in several channels	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Machining stops 	
<i>Explanation</i>	When executing two or more programs in different channels at the same time, one axis has been programmed in both programs (channels).	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check both programs • Insert L999 or @714 • Stop a channel by pressing NC STOP 	
<i>Note</i>	Channel-specific	
188*	HW limit switch plus	Reset key
<i>Scan</i>	Cyclic	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Direction key in the direction of approach disabled • Machining stops 	
<i>Explanation</i>	The limit switch is approached in the plus direction or triggered by other errors.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Travel away in the opposite direction • Check PLC user program • Check limit switches 	
192*	HW limit switch minus	Reset key
<i>Scan</i>	Cyclic	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining stops • Interlocking of NC START • Direction key disabled in approach direction 	
<i>Explanation</i>	The machine limit switch in the minus direction has been approached or has been activated by other errors.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Travel away in the opposite direction in JOG mode • Check limit switches • Check PLC user program 	

196*	Coupled-motion axis assigned twice	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Machining is interrupted 	
<i>Explanation</i>	<ul style="list-style-type: none"> 2 leading axes have been programmed whose coupled axes are the same. Axis X → Axis Y Axis Z → Axis Y 2 leading axes have been programmed with one leading axis also being the coupled axis of the other leading axis. Axis X → Axis Y Axis Y → Axis Z 	
<i>Remedy</i>	<ul style="list-style-type: none"> Correct program 	
2000	Emergency Stop	POWER ON
<i>Scan</i>	Cyclic	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Setpoint 0 Follow-up operation as internal setting 	
<i>Explanation</i>	The "EMERGENCY STOP" signal is output to the NC from the PLC.	
<i>Remedy</i>	<ul style="list-style-type: none"> Check with PLC STATUS Check whether "EMERGENCY STOP" cam has been approached or "EMERGENCY STOP" button has been actuated Check the PLC user program 	
<i>Note</i>	On selecting Start-up mode, there is always an Emergency Stop message.	
2021	Contour violation with tool radius compensation	Reset key
<i>Scan</i>	When executing a part program, with active TRC Not: in the selection block in the deselection block	
<i>Effect</i>	The tool radius compensation has recognized a contour violation. Processing of the part program is interrupted (depending on MD 5024, bit 0), the alarm is cancelled with RESET.	
<i>Explanation</i>	<ul style="list-style-type: none"> The contour calculation results in a traversing movement which is opposite to the programmed movement (e.g. when machining an internal circle, where the milling radius is larger than the circle radius). Between two blocks in the TRC plane, too many blocks have been programmed outside the TRC plane (see also Programming Guide, Section 11.11). In this case, the block number displayed indicates the 4th block outside the TRC plane. 	
<i>Remedy</i>	<ul style="list-style-type: none"> Check program specifications Deselect compensation at the respective point and select it again Check used tool against the specifications (tool radius too large?) 	
<i>Note</i>	<ul style="list-style-type: none"> Alarm is displayed with reference to block and channel. 	
2022	Plane not defined for TO type	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Machining stops 	
<i>Explanation</i>	On selecting a D No. of tool type 50..59, the CRC plane and the length compensations were not defined with G16.	
<i>Remedy</i>	Define CRC plane and length compensations with G16!	
<i>Note</i>	Applies as from SW 4	
<i>Note</i>	Alarm is displayed with reference to block and channel	

1.5.1 Alarm description

2023	Invalid type of tool	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START 	
<i>Explanation</i>	A tool has been selected with unknown tool type (0, >59), or a tool of type 50..59 has been selected, even though the tool offset memory has been formatted with fewer than 12 parameters.	
<i>Remedy</i>	Enter a permissible tool type for the selected tool.	
<i>Note</i>	Applies as from SW 4	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2031	Weighting factor too large/small	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Machining stops • Deletion of part setpoint 	
<i>Explanation</i>	The actual axis velocity has become so large, as a result of recalculation with the specified weighting factor, that the maximum permissible velocity with the axis-specific position control resolution set has been exceeded.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check NC machine data "Weighting factor" (MD 388*) • Program a lower velocity • Reduce the feedrate or rapid override 	
2036	G35 pitch decrease too high	Reset key
<i>Scan</i>	When thread cutting	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Machining stops 	
<i>Explanation</i>	The lead decrease in the thread is so large that a lead greater than or equal to 0 would result at the end of the thread.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Program a smaller lead decrease or a shorter thread 	
<i>Note</i>	Channel-specific	
2037	Programmed S value too high	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	None; for information only	
<i>Explanation</i>	<ul style="list-style-type: none"> • The programmed spindle speed in AUTOMATIC/MDA is too high. • Resulting velocity too high for thread, see Installation and Start-up Guide, Section 10.2. 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Program lower spindle speed 	
2038	Path feed too great	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining is interrupted • Interlocking of NC START • Axes go into follow-up mode, servo-enable is cancelled 	
<i>Explanation</i>	The axis velocity has been made so large by the programmed path feedrate that the maximum permissible axis velocity with the position control resolution set has been exceeded.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Program a smaller path feedrate • Check interpolation combinations in the part program block 	
<i>Note</i>	Channel-specific	

2039	Reference point not reached	Acknowledgement key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of "NC START" 	
<i>Explanation</i>	The reference point has not been approached by at least one axis and NC START has been pressed in MDA or AUTOMATIC mode. Nockensignale wurden aktiviert, ohne daß für diese "Referenzpunkt erreicht" war.	
<i>Remedy</i>	<ul style="list-style-type: none"> Approach reference point The alarm does not occur if the NC machine data "NC START without reference point" is set 	
2040	Program disabled	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> Machining stop 	
<i>Explanation</i>	The program (MPF, SPF) called has not been enabled for processing.	
<i>Remedy</i>	Enable	
<i>Note</i>	Alarm is displayed with reference to channel	
2041	Program does not exist in memory	Reset key
<i>Scan</i>	When specifying a program number and then pressing NC START	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Machining stops 	
<i>Explanation</i>	<ul style="list-style-type: none"> The preselected program is not in the memory A non-existent subroutine is called in the main program The contour for the stock removal cycle does not exist Select "Overview" 	
<i>Remedy</i>	<ul style="list-style-type: none"> Check prgram 	
<i>Note</i>	Channel-specific	
2042	Parity error in memory	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Machining stops 	
<i>Explanation</i>	One or more characters in the memory have been corrupted so that they can no longer be recognized <ul style="list-style-type: none"> These characters are displayed in the "Correction block" or in the part program under "Programming" as "?" 	
<i>Remedy</i>	<ul style="list-style-type: none"> Clear part program block and re-enter 	
<i>Note</i>	Channel-specific	
2043	Program error in transformation	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Machining is interrupted 	
<i>Explanation</i>	<ul style="list-style-type: none"> Programming actual axes with transformation selected Programming fictitious axes with transformation deselected Selecting transformation although transformation has already been selected Programming traversing movements in the selection block of transformation 	
<i>Remedy</i>	<ul style="list-style-type: none"> Correct program 	
<i>Note</i>	Channel-specific	

1.5.1 Alarm description

2044	Error execution external	Reset key
<i>Scan</i>	When starting a program from external	
<i>Effect</i>	NC START is interrupted	
<i>Explanation</i>	<p>The alarm is displayed</p> <ul style="list-style-type: none"> • When the selected program from external is already being processed in another channel • When an interface (file transfer) is to be addressed in several channels • When an interface is to be addressed which is already busy • When an interface is to be addressed while an alarm is present • When "Location receiver" or "Logical peer receiver" are unknown at the beginning of the file transfer. 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check machine data 130* • Check the active interfaces • Check machine data 5148 – 5152 	
2046	Block > 120 characters	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Machining stops 	
<i>Explanation</i>	An "Lf" in the memory is corrupted so that a block of more than 120 characters has resulted.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Insert "Lf" without deleting the whole block 	
<i>Note</i>	Channel-specific	
2047	Option not available	Reset key
<i>Scan</i>	After presetting or programming a function which is not present	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Machining stops 	
<i>Explanation</i>	A function has been programmed which is not included in the function set of the control.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Correct program • Check NC machine data • Have Service Dept. check function options 	
<i>Note</i>	Channel-specific	
2048	Circle end point error	Reset key
<i>Scan</i>	When processing a circle block in AUTOMATIC or MDA	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Machining stops 	
<i>Explanation</i>	<ul style="list-style-type: none"> • The programmed circle end point is not on the circle. • The end point is further out than the limit input in NC machine data "Circle end point monitoring" 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Correct program 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2049	Axis/spindle converter not available	Reset key
<i>Scan</i>	After presetting or programming the axis/spindle converter function which has not been implemented	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Machining stops 	
<i>Explanation</i>	The axis/spindle converter function has been programmed which is not included in the function set of the control.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Correct program • Check NC-MD • Have Service Dept. check function options 	
<i>Note</i>	Alarm is displayed with reference to channel	

2050	Rotary axis path is too small with G98	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining stops • Interlocking of NC start 	
<i>Explanation</i>	The traversed distance to go of the rotary axis in G98 is so small (or 0) that it is not possible to calculate a path feedrate for the linear axes to be traversed.	
<i>Remedy</i>	Check the programmed values in the block. If the rotary axis has to traverse a distance to go, path feed (G94) should be used in this block.	
<i>Note</i>	Alarm is displayed with reference to channel	
2056	Travel through transformation center	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Machining is interrupted 	
<i>Explanation</i>	With TRANSMIT transformation selected, a part program block which brings about a movement directly through the transformation centre has been programmed.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check program • Check whether the function "Travel through transformation center" can be used. 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2057	Thread/revolutional feedrate missing	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining is not started or is terminated • Interlocking of NC START 	
<i>Erläuterung</i>	<ul style="list-style-type: none"> • A thread has been programmed with G33, G34, G35 although this function has not been implemented in the control. • Revolutional feedrate G95 has been programmed • With 840 T, the NC machine data "Revolutional feedrate" has not been set • A program not included in the function set of the control has been programmed 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check program • Check NC machine data • Have function options upgraded. 	
	Alarm is displayed with reference to block and channel.	
2058	3D interpolation missing	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining stops • Interlocking of NC START 	
<i>Explanation</i>	More than two axes have been programmed in one block in a program, or a function has been selected which may result in additional axes from the programming, e.g. when setting the coordinate rotation	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check program • Have function option retrofitted if possible 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2059	Programming error with G92	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining is not started or is terminated • Interlocking of NC START 	
<i>Explanation</i>	<ul style="list-style-type: none"> • An illegal address letter has been used • The unit and working diameter factor is ZERO 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check program block • Check machine data 	
<i>Note</i>	Alarm is displayed with reference to block and channel	

1.5.1 Alarm description

2060	Programming error with TO or ZO	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining is interrupted • Interlocking of NC START 	
<i>Explanation</i>	<ul style="list-style-type: none"> • Tool type is 0 (i.e. no tool) • A tool offset number which is not present has been selected • The values in the zero offsets or tool offsets selected are too large 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check and correct specifications of tool offsets and zero offsets • Check and correct program 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2061	General programming error	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining is stopped or is not started • Interlocking of NC START 	
<i>Explanation</i>	<ul style="list-style-type: none"> • The programmed distance to go has exceeded the permissible distance to go. This is dependent on the input resolution, for example. • G63 was not programmed together with G01 (G63 has no effect with G0). • An axis for which mirroring is active has been programmed with G220 or @736. • A thread block has been programmed with thread lead 0 or distance to go 0. • G02/G03 has been programmed together with G63. 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check the program part and correct the incorrect setting • Check the input resolution selected 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2062	Feed is missing	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining stops • Interlocking of NC START 	
<i>Explanation</i>	<ul style="list-style-type: none"> • Revolutionary feedrate G95 greater than 50 mm/min. has been programmed • No revolutionary feedrate has been programmed • No feedrate value (F value) has been programmed • Feedrate is missing for soft approach and retraction • Setting in machine data MD 280* for max. speed of an axis has been given the value 0 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check settings in program block • Check machine data settings • Cancel alarm using RESET key 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2063	Thread pitch too large	Reset key
<i>Scan</i>	When thread cutting with G33	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining stops • Interlocking of NC START 	
<i>Explanation</i>	<ul style="list-style-type: none"> • The thread lead can be specified in the program under I, J or K. The programmed set value exceeds the permissible value depending on the preset display resolution. 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Correct program block whose block number and channel number are specified in the alarm display • Cancel alarm using RESET 	
<i>Note</i>	Alarm is displayed with reference to block and channel	

2064	Wrong programming of rounding axis	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Programmed path is not exited • Machining stops 	
<i>Explanation</i>	If a rotary axis is rounded to a half or whole degree, then the control monitors whether the rounding has been maintained for the programmed positions.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Program correct position in the rotary axis • Check the machine data "Whole/half degree" and "Rotary axis" • Check whether the interface signal "Clear distance to go" has been set, in which case no automatic rounding takes place. 	
<i>Note</i>	In the JOG modes, the control automatically rounds to valid values. In AUTOMATIC or MDA, the control only monitors the programmed positions without itself carrying out rounding.	
<i>Note</i>	Alarm is displayed with reference to block and channel	

2065	Progr. position behind SW limit switch	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Programmed path is not traversed • Machining stops 	
<i>Explanation</i>	The programmed end point of the block is beyond the software limit switch.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Correct program • Machine data "1st software limit switch plus" • Machine data "1st software limit switch minus" • Machine data "2nd software limit switch plus" • Check machine data "2nd software limit switch minus" depending on the PLC interface signal "2nd software limit switch active" 	
<i>Note</i>	Alarm is displayed with reference to block and channel	

2066	Thread increase/decrease too high	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Machining stops 	
<i>Explanation</i>	A thread or lead increase or decrease of more than 16 mm/revolution (0.6 inches/revolution) has been programmed.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Program smaller lead increase/decrease 	
<i>Note</i>	Alarm is displayed with reference to block and channel	

2068	Position behind working area limitation	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Programmed path is not traversed • Machining stops 	
<i>Explanation</i>	The programmed end point of the block is beyond the working area limitation.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Correct program 	
<i>Note</i>	Alarm is displayed with reference to block and channel	

1.5.1 Alarm description

2069	5D tool length comp. not possible	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining is interrupted or not performed • Interlocking of NC START 	
<i>Explanation</i>	<ul style="list-style-type: none"> • Cutter radius compensation has been selected • No linear interpolation has been selected • Function is not enabled • Machine data have been entered incorrectly • Export version 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check program • Check machine data 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2070	5D interpolation missing	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Machine stops • Interlocking of NC START 	
<i>Explanation</i>	More than three axes have been programmed in one block in a program, or a function has been selected which may result in additional axes from the programming, e.g. when specifying the coordinate rotation.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check program • Have function option retrofitted if possible 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2072	Wrong input value contour definition	Reset key
<i>Scan</i>	When working in AUTOMATIC or MDA	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining is not performed or is terminated • Interlocking of NC START 	
<i>Explanation</i>	When programming, an input which cannot be calculated was specified for contour definition calculation.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check program and correct input values • Cancel alarm using "RESET" 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2073	No intersection contour definition	Reset key
<i>Scan</i>	When working in AUTOMATIC	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining is not performed or is terminated • Interlocking of NC START 	
<i>Explanation</i>	In calculating the contour definition with the programmed values, no intersection results.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check program settings • Cancel alarm using "RESET" 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2074	Wrong angle value contour definition	Reset key
<i>Scan</i>	When working in AUTOMATIC or MDA	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Machining stops 	
<i>Explanation</i>	<ul style="list-style-type: none"> • Angle > or = 360 degrees has been programmed • Value of angle for the contour described is meaningless 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check and correct program settings • Cancel alarm using "RESET" 	
<i>Note</i>	Alarm is displayed with reference to block and channel	

2075	Wrong radius angle contour definition	Reset key
<i>Scan</i>	When working in AUTOMATIC or MDA	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Machining stops 	
<i>Explanation</i>	<ul style="list-style-type: none"> Radius value too large Radius value not permitted with the contour described 	
<i>Remedy</i>	<ul style="list-style-type: none"> Check program Cancel alarm using Reset 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2076	Wrong G02/G03 contour definition	Reset key
<i>Scan</i>	When working in AUTOMATIC or MDA	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Machining stops 	
<i>Explanation</i>	Circle direction with the contour described is not possible	
<i>Remedy</i>	<ul style="list-style-type: none"> Correct program Cancel alarm using "RESET" 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2077	Wrong block sequence contour def	Reset key
<i>Scan</i>	When processing part programs in AUTOMATIC	
<i>Effect</i>	<ul style="list-style-type: none"> Machining is terminated Interlocking of NC START 	
<i>Explanation</i>	<p>In calculating the contour definition several blocks are required.</p> <ul style="list-style-type: none"> Block sequence cannot be correct Inadequate information is available (under-defined) 	
<i>Remedy</i>	<ul style="list-style-type: none"> Check program Cancel alarm using Reset 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2078	Wrong input parameters contour def.	Reset key
<i>Scan</i>	When processing part programs in AUTOMATIC or MDA	
<i>Effect</i>	<ul style="list-style-type: none"> Machining stops Interlocking of NC START 	
<i>Explanation</i>	<ul style="list-style-type: none"> Programmed parameter sequence is not permitted Parameter sequence is incomplete with the contour described <p>Example: N10... X60 B15 L_F (Z axis missing) N20... X90 B10 L_F</p>	
<i>Remedy</i>	<ul style="list-style-type: none"> Check program Cancel alarm using Reset 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2081	Block not allowed with TRC	Reset key
<i>Scan</i>	When processing in AUTOMATIC	
<i>Effect</i>	<ul style="list-style-type: none"> Machining is stopped Interlocking of NC START 	
<i>Explanation</i>	<p>With TRC selected, the following functions may not be programmed: G33, G34, G35, G58, G59, G92, @714 and all the functions that trigger an @714. e.g. G74, G200</p>	
<i>Remedy</i>	<ul style="list-style-type: none"> Program G40 beforehand Deselection of TRC with G41, G42 D00 	
<i>Note</i>	Alarm is displayed with reference to block and channel	

1.5.1 Alarm description

2082	TRC plane cannot be defined	Reset key
<i>Scan</i>	When processing a part program in AUTOMATIC	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining is stopped • Interlocking of NC START 	
<i>Explanation</i>	The axes of the TRC plane selected do not exist.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Machine data "Abscissa for prog. G16" • Machine data "Ordinate for prog. G16" • Machine data "Applicate for prog. G16" • Select correct plane using G16 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2083	Contour violation with TRC	Reset key
<i>Scan</i>	When TRC is selected in AUTOMATIC	
	Not: in the selection block	
	in the deselection block	
<i>Effect</i>	A contour violation may have occurred on the workpiece. The program is continued if MD 5024, bit 0, is set or machining is aborted. This also depends on whether the alarm has been acknowledged with the Acknowledgement key or the Reset key.	
<i>Explanation</i>	The calculated compensation results in a direction of travel that is opposite to the programmed direction.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check the program • Deselect the compensation at a suitable point and reselect 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2087	Coordinate rotation/ZO not allowed	Reset key
<i>Scan</i>	When working in AUTOMATIC or MDA	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Machining is interrupted 	
<i>Explanation</i>	<ul style="list-style-type: none"> • After selecting coordinate rotation (G54 to G59) a circular movement (G02, G03) was programmed in the following block. • After selecting coordinate rotation (angle $\neq 0$ degrees) the settable zero offset (G54 to G57) was changed. • After selecting coordinate rotation (angle $\neq 0$ degrees) the plane (G16, G17, G18, G19) was changed. 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Correct program • The plane can only be changed if the angle of rotation is 0 degrees. • The settable zero offset (G54 to G57) can only be changed if the angle of rotation is 0 degrees. • Set angle of rotation in the settable zero offsets (G54 to G57) to 0 degrees and work only with G58 and G59. 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2160	Illegal scale factor	Reset key
<i>Scan</i>	When working in AUTOMATIC or MDA	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Machining is interrupted 	
<i>Explanation</i>	The scale factor has exceeded the valid range of values: <ul style="list-style-type: none"> + P is negative + P = 0 + P > 99.99999 	
<i>Remedy</i>	Note the valid range of values for scale factor: (P = 0.00001 to 99.99999)	
<i>Note</i>	Alarm is displayed with reference to block and channel	

2161	Illegal scale modification	Reset key
<i>Scan</i>	When working in AUTOMATIC or MDA	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Machining is interrupted 	
<i>Explanation</i>	With a scale factor of $\gg 1$, an axis position was programmed which was so large that internal representation is no longer possible.	
<i>Remedy</i>	<ul style="list-style-type: none"> Check programmed axis position Reduce scale factor 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2171	Approach not possible	Reset key
<i>Scan</i>	When working in AUTOMATIC or MDA	
<i>Effect</i>	<ul style="list-style-type: none"> Machining is interrupted 	
<i>Explanation</i>	In the block after approach, no axis for the selected plane (G16, G17, G18, G19) has been programmed, so that a vector to the tangential approach cannot be calculated. <ul style="list-style-type: none"> In the selection block, or in the following block for soft approach, @714 has been programmed. 	
<i>Remedy</i>	<ul style="list-style-type: none"> Correct program (G147, G247, G347), programming at least one axis of the selected plane in the block after the approach. 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2172	Retraction not possible	Reset key
<i>Scan</i>	When working in AUTOMATIC or MDA	
<i>Effect</i>	<ul style="list-style-type: none"> Machining is interrupted 	
<i>Explanation</i>	In the block before retraction no axis for the selected plane (G16, G17, G18, G19) has been programmed, so that a vector to the tangential exit cannot be calculated. <ul style="list-style-type: none"> In the deselection block or in the previous block @714 has been programmed G48 programmed without previous selection More than 5 axes are traversed in the deselection block because 1 axis has been added to the plane. 	
<i>Remedy</i>	<ul style="list-style-type: none"> Correct program (G148, G248, G348, G48), programming at least one axis of the selected plane in the block before the retraction movement. 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2173	Approach/retraction plane wrong	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> Machining is interrupted 	
<i>Explanation</i>	<ul style="list-style-type: none"> A plane change is programmed in the block after selection (G16, G17, G18, G19) A plane change is programmed in the deselection block 	
<i>Remedy</i>	<ul style="list-style-type: none"> Correct program (plane change) 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2184	M fct. for C axis switchover not allowed	CANCEL
<i>Scan</i>	Cyclic	
<i>Effect</i>	None	
<i>Explanation</i>	M function for C axis ON/OFF (MD 260, MD 261) has been given a value reserved by the system.	
<i>Remedy</i>	Enter the correct value	

1.5.1 Alarm description

2189	Transformation not defined	Reset key
<i>Scan</i>	On transformation selection	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Machining stops 	
<i>Explanation</i>	<ul style="list-style-type: none"> • The type of transformation is not defined • The transformation axes are in different mode groups • The option of selecting transformation is not available • Transformation has been selected in an illegal channel • Transformation is defined several times or wrongly • Transformation data block has been declared invalid by alarm 3087 (error in transformation data) 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check transformation data block • Check program • Order option • Check channel number 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2190	Transformation axes assigned	Reset key
<i>Scan</i>	On transformation selection	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Machining stops 	
<i>Explanation</i>	A transformation has been selected whose actual axes are also used in another channel in a parallel transformation.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Wait until transformation is deselected in the parallel channel • Check program 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2191	Transformation in zero	Reset key
<i>Scan</i>	On selecting transformation in AUTOMATIC or MDA	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Machining is interrupted 	
<i>Explanation</i>	Transformation was selected at a time when one or more axes involved in transformation have the actual position ZERO. When selecting TRANSMIT, the X axis (transverse axis) must not have the actual position ZERO.	
<i>Remedy</i>	Before selecting transformation, set the actual axes of the transformation to be selected to permissible actual positions. (With TRANSMIT set the X axis to $X \neq 0$)	
<i>Note</i>	Alarm is displayed with reference to block and channel	
2192	Following error comp. not possible	Reset key
<i>Scan</i>	At the beginning of a threading block, if the option has been selected.	
<i>Effect</i>	Machining is stopped and NC START is interlocked	
<i>Explanation</i>	The servo gain (K_V) factors of the axes involved in thread cutting are too small.	
<i>Remedy</i>	Check the servo gain factors of the axes involved in thread cutting and correct if necessary—	
2193	Wrong axis/spindle operation	Reset key
<i>Scan</i>	When switching over from C axis to spindle	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining stops • Interlocking of NC START 	
<i>Explanation</i>	A spindle has been programmed in C axis mode or a C axis has been programmed in spindle mode	
<i>Remedy</i>	Change C axis/spindle mode	
<i>Note</i>	Applies up to SW 2	

2194	There is no FIFO	Reset key
<i>Scan</i>	After POWER ON or warm start	
<i>Effect</i>	<ul style="list-style-type: none"> Function is not executed Interlocking of NC START 	
<i>Explanation</i>	FIFO has been assigned to a channel but has not been activated.	
<i>Remedy</i>	<ul style="list-style-type: none"> Correct program Check NC MD Have service personnel check the function option Have function option retrofitted 	
<i>Note</i>	Applies up to SW 2	
2195	Too many FIFO channels defined	Reset key
<i>Scan</i>	At POWER ON or warm restart	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Machining not possible 	
<i>Explanation</i>	The FIFO memory can be assigned to a maximum of two channels	
<i>Remedy</i>	<ul style="list-style-type: none"> Check NC MD 	
<i>Note</i>	Applies up to SW 2	
2260	Incorrect parameters "Ext. stop"	Reset key
<i>Scan</i>	When configuring G421–6.	
<i>Effect</i>	Machining stops	
<i>Explanation</i>	<ol style="list-style-type: none"> Axis/spindle already involved in extended stopping and retraction. Axis/spindle already involved through G422/5/6 in extended stopping and retraction. 	
<i>Remedy</i>	Check and modify programming/parameterization.	
<i>Note</i>	Applies as from SW 4. Alarm is displayed with reference to channel	
2500	Program is being edited	Acknowledgement key
<i>Scan</i>	At NC START	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Machine stops 	
<i>Explanation</i>	NC START calls a program which is in the process of being edited	
<i>Remedy</i>	Terminate editing	
2501	Program is being read-in	Acknowledgement key
<i>Scan</i>	At NC START	
<i>Effect</i>	<ul style="list-style-type: none"> Function is not executed Interlocking of NC START 	
<i>Explanation</i>	NC START calls a program which is in the process of being read in through the computer link or from disk from the MMC.	
<i>Remedy</i>	Wait for the end of the read-in process	
2502	Program already exists	Reset key
<i>Scan</i>	When starting a program from external	
<i>Effect</i>	<ul style="list-style-type: none"> NC START is interrupted 	
<i>Explanation</i>	<p>The alarm is displayed</p> <ul style="list-style-type: none"> If a program with the same program no. as the program to be processed externally is already in the part program memory. 	
<i>Remedy</i>	<ul style="list-style-type: none"> Rename or delete the program which already exists 	
<i>Note</i>	Channel-specific	

1.5.1 Alarm description


2503	Not enough memory available	Reset key
<i>Scan</i>	When starting a program from external	
<i>Effect</i>	<ul style="list-style-type: none"> NC START is interrupted 	
<i>Explanation</i>	<p>The alarm is displayed</p> <ul style="list-style-type: none"> When the memory set in MD30 is not available for the program to be processed externally. 	
<i>Remedy</i>	<ul style="list-style-type: none"> Make sufficient part program memory available (delete part programs) Lower value in MD30 	
<i>Note</i>	Channel-specific	
2504	Emergency retract triggered	Reset key
<i>Scan</i>	Cyclic in the servo cycle when LINK_ON for the following axis (from servo).	
<i>Effect</i>	Machining interrupt, interlocking of NC START; removal of Mode Group Ready.	
<i>Explanation</i>	<p>The threshold MD "Emergency retraction threshold" programmed for monitoring of synchronism has been exceeded and emergency retraction triggered.</p> <p>Prerequisite: Enable by means of PLC IS "Emergency retraction enabled".</p>	
<i>Remedy</i>	Inspect the drives; check the velocity and acceleration limit values of the following axis/spindle; check the emergency retraction threshold; check the link factors.	
<i>Note</i>	Applies as from SW 3. Alarm is displayed with reference to channel	
2505	Error in NCK FB	
<i>Scan</i>	During cyclic operation of control	
<i>Effect</i>	<p>Interlocking of NC START</p> <p>Follow-up mode</p> <p>Removal of Mode Group Ready</p> <p>Interruption of machining</p>	
<i>Explanation</i>	The machine data for the SGE/SGA input/output allocations (46000 – 47999) have been entered incorrectly. The incorrect MD No. is output in the alarm as block no. Nxxxxx.	
<i>Remedy</i>	Correct the indicated machine data.	
<i>Continuation</i>	No program can be started. Acknowledge alarm by RESET.	
<i>Note</i>	<ul style="list-style-type: none"> The alarm 2505 is only output if configured correspondingly by the machine manufacturer. An error has occurred in the Safety–NCK–FB. For explanation and remedy, please refer to the machine manufacturer's documentation. Applies as from SW 5.4 	
2506	Extended function outp. in target block	
<i>Scan</i>	During block preprocessing in AUTOMATIC or MDA	
<i>Effect</i>	Interlocking of NC–START	
<i>Explanation</i>	The target block during block preprocessing cannot be a G511/G522 block, as the output of accumulated miscellaneous functions and the extended output of the G511/G522 block collide functionally.	
<i>Remedy</i>	Select another target block.	
<i>Note</i>	Channel-specific reset alarm (as from SW 5.4), alarm is displayed with reference to channel	

3000**General programming error****Acknowledgement key***Explanation*

- A general programming error which cannot properly be explained has been made in one block in the program.
- Division by 0
- A G function which does not exist has been programmed
- An R parameter which does not exist has been programmed
- No +, -, /, " has been programmed in the R parameter chaining
- Range of values has been exceeded with R parameter calculation
- Number of decades exceeded (M, S, T, D, H, L, P, F)
- Subroutine number of passes P not programmed directly behind L
- Main block ":" programmed in subroutine
- Two decimal points programmed
- Decimal point programmed with M, S, T, D, H, L, P
- More than 8 decades programmed
- The programmed axis values exceed the travel range limits with the set input resolution
- Auxiliary functions D, F, S or T are programmed with a minus sign.
- SW 3 and higher, block search to a spline interpolation coefficient block
- The F word in G501 exceeds the value range or is negative.

Remedy

- Check the incorrect block in the "Correction block" display
- The cursor is placed on the incorrect word, if possible
- The block number of the incorrect block is positioned behind the alarm number in the alarm line.
- Correct the F word accordingly.

Example:*Note*

Alarm is displayed with reference to channel

1.5.1 Alarm description

3001	Number of geometry parameters > 5	Acknowledgement key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining stops 	
<i>Explanation</i>	<ul style="list-style-type: none"> • More than 2 radii or more than 2 angles have been programmed in the block • More than 5 geometry parameters such as axes, interpolation parameters, radii, angles, etc. have been programmed in the block 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check the faulty block in the "Correction block" display • If possible the cursor is positioned in front of the faulty word • The number of the faulty block is after the alarm number in the alarm line <p>Example:</p> <p>3000 1 N0010 General programming error</p> <p>3000 – Alarm number</p> <p>1 – Channel number</p> <p>N0010 – Block number "N10" containing errors.</p>	
<i>Note</i>	Alarm is displayed with reference to block and channel	

3002	Polar coordinates/radius error	Acknowledgement key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining stops • Interlocking of NC START 	
<i>Explanation</i>	<ul style="list-style-type: none"> • When programming circle/radius, full circle programmed. • For cylindrical interpolation if: <ul style="list-style-type: none"> – Calculated interpolation parameters in the C axis are too large or P factor is too small – P factor or axial distance to go of the rotary axis for cylindrical interpolation too large 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check the faulty block in the "Correction block" display • If possible the cursor is positioned in front of the faulty word • The number of the faulty block is after the alarm number in the alarm line 	

3003 Invalid address programmed**Acknowledgement key**

Scan When executing a part program

Effect • Machining stops

Explanation An address has been programmed other than that entered in NC machine data.

The error can also occur when invalid values for G functions are entered in the channel-specific MD as from 108* (delete position specification for G channel-specific functions).

Example:

Wrong: **N20 G0 C100 L_F** (rapid traverse for fourth axis)
However, the fourth axis is defined by the address Q in the NC machine data.

Correct: **N20 G0 Q100 L_F**

Remedy • Check the faulty block in the "Correction block" display
• If possible, the cursor is positioned in front of the faulty word
• The number of the faulty block is after the alarm number in the alarm line

Note Alarm is displayed with reference to block and channel

3004 Error in CL800 programming**Acknowledgement key**

Effect Machining stops

Explanation Formal errors

- Machining stops
- Incorrectly entered characters (0...9 and a...f are possible)
- @ number is greater than the decades for a text-type message
- @ number or @ function not implemented with SINUMERIK 840
- @ number or @ function cannot be programmed in CL800 or are not defined

Input errors with address letters and numerical values

- Incorrect address letters (K, R and P are permitted)
- Number of decades too high (max. K 8 decades permitted)
- Number of decades too high (max. R 4 decades permitted)
- Number of decades too high (P 4 decades permitted)
- R parameter number not defined or too high
- Point programmed in R parameter number
- Point programmed in P parameter number
- Incorrect number of words

Input errors with specific @ functions:

Program branching

- Error in the block number (programmed point, block number greater than four decades)

Data transfer system line – R parameter

- Constant or R parameter contents programmed too large for information such as: axis number, channel number, TO area, NC/PLC machine data, NC setting data, D number, P number, group for zero offsets, preset "COARSE/FINE" alarm number
- Bit number too large (0 to 7 are permitted)
- System line non-existent
- Incorrect value input for system line

Mathematical and logical functions

- Value selected too high for square root (+/- 00 000 001...99 999 999 permitted)
- Incorrect angle selected for sine (-360 (0) + 360 permitted)
- Two constants used for:
Angle from two vector components, OR, EXOR, AND, NAND
- Incorrect characters input for logical functions (0, 1 permitted)
(Only bits and bytes) (max. eight bits)

NC specific functions

- Incorrect address letter used for number of axes
- Number of axes selected too high (max. 3 axes permitted per block)
- No axis name programmed (0)

Note Alarm is displayed with reference to block and channel

1.5.1 Alarm description

3005	Error in contour definition	Acknowledgement key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining stops 	
<i>Explanation</i>	<p>The coordinates in the contour description have been defined so that there is no intersection.</p> <ul style="list-style-type: none"> • Too many geometry values have been programmed 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check the faulty block in the "Correction block" display • If possible the cursor is positioned in front of the faulty word • The number of the faulty block is after the alarm number in the alarm line 	
<i>Note</i>	Alarm is displayed with reference to block and channel	

3006	Wrong block structure	Acknowledgement key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining stops • Interlocking of NC START 	
<i>Explanation</i>	<ul style="list-style-type: none"> • Approach to reference point with program and specification of the wrong G function or more than one axis, or an impermissible axis. • Wrong thread lead parameters with G33 • More than 3 M functions in the block • More than 1 S function in the block • More than 1 T function in the block • More than 1 H function in the block • More than 4 auxiliary functions in the block • More than 6 axes + geometry parameters • More than 5 axes with G00, G01, G02, G03 • More than 2 axes with G10, G11, G12, G13, G110, G111, G112 • More than one radius/angle with G10, G11, G12, G13, G110, G111, G112 • Negative radius with G10, G11, G12, G13, G110, G111, G112 • First programming of polar coordinates G10, G11, G12, G13 or angle/radius • More than two axes with G02, G03 (circle radius programming) • G04 programmed with addresses other than X, F or S • G04 is not programmed in the block by itself • M19 S is programmed with other functions • Incorrect circle parameters with G02, G03 axes • Axis missing with circle radius programming • Before the first G110 block in the program, a G10/G11 block must have been programmed • G110 may not be programmed with axes • Incorrect programming in connection with G176 freeze function • Either too few measured value memories or none at all have been defined for G720/721/722 via the flexible memory configuration • On G511/G522 <ul style="list-style-type: none"> – An F word does not immediately follow G511/G522 – G511/G522 is superfluous, because neither a miscellaneous function nor a program coordination command or an F word output to the PLC is programmed. 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check the faulty block in the "Correction block" display • If possible the cursor is positioned in front of the faulty word • The number of the faulty block is after the alarm number in the alarm line • Re G511/G522 <ul style="list-style-type: none"> – Place the F word immediately after G511/G522 – Delete G511/G522 F... 	
<i>Note</i>	Alarm is displayed with reference to block and channel	

3007	Error in programming setting data	Acknowledgement key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining stops 	
<i>Explanation</i>	<ul style="list-style-type: none"> • M19 without S word • Spindle not present • Illegal setting data programmed, e.g. G92 X... Y..., G92 D, T, A, I, J • Error in parameterization of handwheel pulse weighting for G27 (SD 564*) 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check the faulty block in the "Correction block" display • If possible the cursor is positioned in front of the faulty word • The number of the faulty block is after the alarm number in the alarm line 	
<i>Note</i>	Alarm is displayed with reference to block and channel	

3008	Subroutine error	Acknowledgement key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining stops 	
<i>Explanation</i>	<ul style="list-style-type: none"> • M17 not in the subroutine • M02, M30 in the subroutine • M17 in the main program • More than 3 subroutine levels 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check the faulty block in the "Correction block" display • If possible the cursor is positioned in front of the faulty word • The number of the faulty block is after the alarm number in the alarm line • SW 3 and higher, number of permissible subroutine levels exceeded • Subroutine call in the block with M2, M30 or M17 	
<i>Note</i>	Alarm is displayed with reference to block and channel	

3009	Program disabled	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> • On NC START, or when editing a program during machining 	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining stops 	
<i>Explanation</i>	<ul style="list-style-type: none"> • Pressing "NC START" calls a program which was disabled by being opened, by "Copy" or by "Rename". While a program is being edited it may not be called by "NC START". 	
<i>Remedy</i>	Once editing is complete, the locked program must be enabled.	
<i>Note</i>	Alarm is displayed with reference to block and channel	

3010	Intersection error	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> • When executing a part program 	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining stops 	
<i>Explanation</i>	<p>A mistake has been discovered during reference processing in conjunction with the calculation of intersection. Possible causes are:</p> <ul style="list-style-type: none"> • Contour program without G00, G01, G03 • Contour program with "Empty buffer memory" (@714) • Programmed axes are not the same as the plane selected • No intersection found • Stock removal path circular • R parameter number not available 	
<i>Remedy</i>	Check program in which contour is stored.	
<i>Note</i>	Alarm is displayed with reference to block and channel	

1.5.1 Alarm description

3011	Axis twice or too many axes	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> When executing a part program 	
<i>Effect</i>	<ul style="list-style-type: none"> Machining stops 	
<i>Explanation</i>	<ul style="list-style-type: none"> An axis has been programmed twice in the same block More than five axes have been programmed 	
<i>Remedy</i>	<ul style="list-style-type: none"> Check the faulty block in the "Correction block" display If possible the cursor is positioned in front of the faulty word The number of the faulty block is after the alarm number in the alarm line 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
3012	Block does not exist in memory	Reset key
<i>Scan</i>	<ul style="list-style-type: none"> On block search or jumps in the part program 	
<i>Effect</i>	<ul style="list-style-type: none"> Machining stops Interlocking of "NC START" 	
<i>Explanation</i>	<ul style="list-style-type: none"> On block search, the block number is not available in the program. On jumping in the program, the programmed block number cannot be found. Program which does not conclude with M30, M17 The alarm is displayed <ul style="list-style-type: none"> if a forward jump has been programmed outside the maximum memory area with "Execution from external". (The target of the jump cannot be read in to the available memory area) when backward jumps or jumps to the present block location have been programmed 	
<i>Remedy</i>	<ul style="list-style-type: none"> Check the part program as regards the correct block number target or the correct program conclusion with M30/M02 or M17. <ul style="list-style-type: none"> Increase maximum memory for "Execution from external" (MD 30) Reduce jump distance Delete backward jumps or jumps to the present block location. 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
3014	Axis disabled in channel	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> When executing a part program 	
<i>Effect</i>	<ul style="list-style-type: none"> Machining stops 	
<i>Explanation</i>	The programmed axis is disabled for this channel by means of the NC machine data "Axis not valid for channel 1, 2, 3 or 4".	
<i>Remedy</i>	<ul style="list-style-type: none"> Observe the programming notes of the machine manufacturer. Correct machine data if necessary. 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
3015	Main block not in memory	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> On automatic block search 	
<i>Effect</i>	<ul style="list-style-type: none"> Processing is not started 	
<i>Explanation</i>	No main block was found in front of the target block during an automatic block search.	
<i>Remedy</i>	<ul style="list-style-type: none"> Check target block Use another block search 	
<i>Note</i>	Channel-specific Applies up to SW 2 only	

3016	Error in external data input	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> On entering data from the PLC to the NC 	
<i>Effect</i>	<ul style="list-style-type: none"> Machining stops 	
<i>Explanation</i>	With external data input from PLC and NC: <ul style="list-style-type: none"> The code is incorrect The value is too high The dimension ID is not valid 	
<i>Remedy</i>	<ul style="list-style-type: none"> Check PLC program 	
3017	Part program available twice	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> At POWER ON 	
<i>Effect</i>	<ul style="list-style-type: none"> Machining stops 	
<i>Explanation</i>	The UMS contains a part program which is already stored in the part program memory of the NC (with the same ID).	
<i>Remedy</i>	<ul style="list-style-type: none"> Delete or rename the program in the part program memory Use a different UMS 	
<i>Note</i>	Applies up to SW 2 only	
3018	Distance to contour too large	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> With AUTO interrupt in the circle block and travelling away from the point of interruption 	
<i>Effect</i>	<ul style="list-style-type: none"> Machining stops Additional alarm 2048 	
<i>Explanation</i>	If AUTOMATIC mode is interrupted while processing a circle block and the axes are positioned in a range, for example for tool change, outside the permissible tolerance for reapproach (scratching) (MD9), this alarm is triggered. To prevent incorrect positioning, the additional alarm 2048 – circle end point error – is set. Reapproach is only possible after a Reset.	
<i>Remedy</i>	Cancel alarms and perform a block search as far as the point of interruption. If necessary, check whether the MD9 setting can be made larger.	
<i>Note</i>	Alarm is displayed with reference to channel	
3020	Option not available	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> On specifying a non-existent function 	
<i>Effect</i>	<ul style="list-style-type: none"> Function is not processed 	
<i>Explanation</i>	A function not included or not enabled in the control has been programmed or selected.	
<i>Remedy</i>	<ul style="list-style-type: none"> Have function option retrofitted or set function enable bit. 	
<i>Note</i>	Alarm is displayed with reference to channel	
3021	Contour violation with tool radius comp.	Acknowledgement key
<i>Scan</i>	When executing a part program, with active TRC <p>Not:</p> <ul style="list-style-type: none"> In the selection block In the deselection block 	
<i>Effect</i>	A contour violation has occurred on the workpiece. The program is continued, nevertheless (see MD 5024, bit 0). The alarm can be cancelled with the acknowledge key.	
<i>Explanation</i>	<ul style="list-style-type: none"> The contour calculation results in a traversing movement which is opposite to the programmed movement (e.g. when machining an internal circle, where the milling radius is larger than the circle radius). Between two blocks in the TRC plane, too many blocks have been programmed outside the TRC plane (see also Programming Guide, Section 11.11). In this case, the block number displayed indicates the 4th block outside the TRC plane. 	
<i>Remedy</i>	<ul style="list-style-type: none"> Check programming. Deselect correction at a suitable point and select it again. Check tool used against specifications (tool radius too large?). 	
<i>Note</i>	<ul style="list-style-type: none"> Alarm is displayed with reference to channel In the case of an error, the block number indicated refers to the 4th block outside the compensation plane (TRC). See Programming Guide Section 11.1. 	

1.5.1 Alarm description

3022	Too many spindles programmed	Reset key
<i>Scan</i>	<ul style="list-style-type: none"> When executing part program blocks in AUTOMATIC or MDA 	
<i>Effect</i>	<ul style="list-style-type: none"> Function is not executed 	
<i>Explanation</i>	Only one spindle may be programmed in any one part program block.	
<i>Remedy</i>	Divide spindle programming into two or more blocks.	
3023	Wrong spindle position in setting data	Reset key
<i>Scan</i>	The alarm is output if M19 is programmed without an S value with MDA or in a part program and if an illegal value is set in the spindle setting data for oriented spindle stop (M19).	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Machining stops 	
<i>Explanation</i>	An illegal value has been entered in the spindle setting data for oriented spindle stop (M19).	
<i>Remedy</i>	Enter legal value in setting data permissible range 0 – 359.99	
3024	Display description missing	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> On display selection 	
<i>Effect</i>	<ul style="list-style-type: none"> Selected display does not appear 	
<i>Explanation</i>	Using a programmed softkey, an attempt has been made to select a display not available in the UMS or system memory.	
<i>Remedy</i>	With the aid of the NC workstation, the programmed display number and softkey function must be checked.	
3025	Display description has errors	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> On display selection 	
<i>Effect</i>	<ul style="list-style-type: none"> Selected display does not appear 	
<i>Explanation</i>	On checking the display information an error has been discovered, e.g.: <ul style="list-style-type: none"> The programmed display type is unknown Block increment for the extended table display is incorrect (must always be 1 for absolute display) 	
<i>Remedy</i>	Check the display description with the NC workstation, in particular the information for data group, data type and format.	
3026	Fixed-text component too large	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> On display selection via softkey 	
<i>Effect</i>	<ul style="list-style-type: none"> Not all fixed texts are displayed 	
<i>Explanation</i>	The programmed fixed text part in the display description is too large.	
<i>Remedy</i>	Using the NC workstation, reduce the fixed text part of the display or split up the contents over several displays.	
3027	Graphics section too large	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> On display selection 	
<i>Effect</i>	<ul style="list-style-type: none"> No graphics display 	
<i>Explanation</i>	The programmed graphics part in the display description is too large (max. 4 Kbytes).	
<i>Remedy</i>	Using the NC workstation, reduce the fixed text part of the display or split up the contents over several displays.	

3029	Window beyond configuring area	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> On display selection 	
<i>Effect</i>	Display build-up is aborted when the window of a display being configured is outside the configuring area.	
<i>Explanation</i>	Additional subdisplays can be configured in a screen. The subdisplay windows can be moved in the configuring area. As a result the window may have been moved outside the configuring area → configuring error.	
<i>Remedy</i>	Configure the window movement so that it does not leave the configuring area (see also alarm 3037).	
3030	Cursor memory not available	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> On display selection 	
<i>Effect</i>	The display selected is treated as though there were no cursor memory.	
<i>Explanation</i>	The cursor memory programmed in the selected display is incorrect (illegal number, or too large).	
<i>Remedy</i>	Redefine cursor memory with NC workstation, since the cursor memory has the task, when a display is recalled, of putting the cursor back where it was when the display was removed.	
3031	Too many part programs	
<i>Scan</i>	On display selection	
<i>Effect</i>	Slower display build-up and processing time may result.	
<i>Explanation</i>	The configuring engineer has called up too many display descriptions with part program parts	
<i>Remedy</i>	Only incorporate a maximum of 5 part programs in the display descriptions if possible. The alarm need not be acknowledged as it is only for information.	
<i>Note</i>	Applies to SW 1 only	
3031	Error: NCK softkey text to MMC	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> When selecting the menu 	
<i>Effect</i>	<ul style="list-style-type: none"> The softkey text is not displayed 	
<i>Explanation</i>	An error has occurred while transferring the softkey text from NCK to MMC.	
<i>Remedy</i>	Activate notebook for I code and send message to System support together with notebook entry (system program change required)	
<i>Note</i>	Applies as from SW 2	
3032	Variable component too large	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> When selecting a display with a softkey 	
<i>Effect</i>	<ul style="list-style-type: none"> None 	
<i>Explanation</i>	The programmed variable display part of the display description is too large.	
<i>Remedy</i>	<ul style="list-style-type: none"> Check display with NC workstation, and if necessary regenerate Reduce variable display part 	
3033	There is no display text	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> Cyclic 	
<i>Effect</i>	<ul style="list-style-type: none"> Display text not displayed 	
<i>Explanation</i>	The display text generated at the NC workstation has not been transferred to the link list.	
<i>Remedy</i>	Check the link list and relink to the NC workstation; watch out for linking errors.	

1.5.1 Alarm description

3034	There is no special text	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> On display selection 	
<i>Effect</i>	<ul style="list-style-type: none"> Special text not displayed 	
<i>Explanation</i>	<p>The following texts have not been inserted or have been inserted incorrectly:</p> <ul style="list-style-type: none"> Menu texts Dialog texts Mode texts 	
<i>Remedy</i>	Check the display generated with NC workstation and where appropriate regenerate.	
3035	Indirect addressing faulty	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> Cyclic 	
<i>Effect</i>	<ul style="list-style-type: none"> Variable values/texts not displayed 	
<i>Explanation</i>	<ul style="list-style-type: none"> The display description for indirect addressing is incorrect. This affects the details in the display header for <ul style="list-style-type: none"> data group, data type, data number and data block. Information for number of indirect elements of the list/display (IEL) is incorrect. Variable text is selected but status or offset is not cancelled. Variable value has been selected but status not cancelled. 	
<i>Remedy</i>	<p>Check the information for</p> <ul style="list-style-type: none"> Start of range pointer, Length of range pointer and Cursor pointer <p>and check their relationship to one another</p> <ul style="list-style-type: none"> Check deselection of status or offset 	
3036	Variable status faulty	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> Cyclic 	
<i>Effect</i>	<ul style="list-style-type: none"> Status taken from display description 	
<i>Explanation</i>	In the display description form variable status, which can only be selected by the PLC, an incorrect data group has been specified or variable status has not been cancelled.	
<i>Remedy</i>	The display description must be modified with the aid of the NC workstation.	
3037	User window faulty	Acknowledgement key
<i>Scan</i>	On control power-up	
<i>Effect</i>	Displays to be shown in incorrect user windows are not displayed.	
<i>Explanation</i>	User windows can be defined in the UMS. These must lie within the configuring area, otherwise an alarm is given.	
<i>Remedy</i>	Check and correct user window in the UMS.	
3038	Double call of display	Acknowledgement key
<i>Scan</i>	On selecting the display	
<i>Effect</i>	Display build-up is aborted with the display that is repeatedly called in the same path.	
<i>Explanation</i>	In a display, additional subdisplays can be configured which themselves can have subdisplays. If a display is called which does not correspond to a display already configured, recursion results. This is prevented by aborting the display build-up and issuing an alarm.	
<i>Remedy</i>	Avoid subdisplay linking which can lead to recursion.	

3039	No multichannel display option	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> • Cyclic 	
<i>Effect</i>	<ul style="list-style-type: none"> • Fixed display parts only are displayed 	
<i>Explanation</i>	If data which is reserved for multi-channel display is configured in a display, it can be displayed correctly only if the multi-channel display option is available.	
<i>Remedy</i>	Set multi-channel display option.	
3040	Field/variable cannot be displayed	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> • Cyclic 	
<i>Effect</i>	<ul style="list-style-type: none"> • Not all variable values/texts are displayed 	
<i>Explanation</i>	<ul style="list-style-type: none"> • Field/variable incorrectly configured (data group not available) • Field/variable programmed with too few places • Field/variable overflow (value range exceeded) • Format error; format cannot be changed • Illegal pointer 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check field/variable with NC workstation and if appropriate delete and re-enter. <p>If the alarm occurs with standard displays then the value range has been exceeded.</p>	
3041	Too many fields/variables	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> • Cyclic 	
<i>Effect</i>	<ul style="list-style-type: none"> • Not all values/texts are displayed 	
<i>Explanation</i>	<ul style="list-style-type: none"> • The display description is too long so that the internal buffer is no longer adequate for processing the display. • More than one display (main displays/secondary displays) have been configured with data selector. 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Using the NC workstation, the desired information must be reduced or divided amongst more than one display. A maximum number of fields/variables cannot be specified since the fields/variables have different formats and positions. • Configure only one display with data selector in conjunction with other displays. 	
3042	Error in dynamic graphics section	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> • Cyclic 	
<i>Effect</i>	<ul style="list-style-type: none"> • Dynamic graphics (columns) not entirely displayed 	
<i>Explanation</i>	The column graphics configured at the NC workstation are too extensive. A maximum of 4 Kbytes are available for the whole cyclic part of the display (variable part of display including dynamic graphics) for all displays and insets.	
<i>Remedy</i>	Reconfigure the display at the NC workstation, reduce the variable display parts and dynamic graphics.	
3043	Error: NCK fixed display to MMC	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> • On display selection 	
<i>Effect</i>	<ul style="list-style-type: none"> • Not all fixed texts are displayed 	
<i>Explanation</i>	An error has occurred during transmission of fixed texts e.g.: delete window, fixed texts, etc. from NCK to MMC.	
<i>Remedy</i>	Activate notebook for I code and send message to <ul style="list-style-type: none"> • System Support (system program change required) 	
3044	Error: NCK display update to MMC	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> • Cyclic 	
<i>Effect</i>	<ul style="list-style-type: none"> • No dynamic display parts are displayed 	
<i>Explanation</i>	An error has occurred during transmission of dynamic display parts such as variable values/texts from the NCK to MMC.	
<i>Remedy</i>	Activate notebook for I code and send message together with notebook entry to <ul style="list-style-type: none"> • System Support (system program change required) 	

1.5.1 Alarm description

3045	Error: NCK fixed graphics to MMC	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> On selecting the display 	
<i>Effect</i>	<ul style="list-style-type: none"> Not all fixed graphics parts of the display description are shown on the screen 	
<i>Explanation</i>	An error has occurred during transmission of the graphics part of the display from NCK to MMC.	
<i>Remedy</i>	Activate notebook for I code and send message together with notebook entry to System Support (system program change required)	
3046	Faulty variable	Acknowledgement key as from SW 5.4: POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> On selecting the display 	
<i>Effect</i>	<ul style="list-style-type: none"> Not all variable values/texts are displayed 	
<i>Explanation</i>	In the display description, a variable text has been programmed without an end identifier because of an error in the NC workstation software. This produces a transfer format error.	
<i>Remedy</i>	<ul style="list-style-type: none"> Check NC workstation <p>The error must be at the point of interruption of the subsequent elements which are no longer displayed.</p>	
3047	Read data selector from harddisk	Acknowledgement key as from SW 5.4: POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> Cyclic if there is no response from the MMC approximately 5 seconds after the harddisk has requested the data selector. 	
<i>Effect</i>	The data selector does not switch over to the disk directory.	
<i>Explanation</i>	There is no response from the MMC to the request for the data selector from the harddisk.	
<i>Remedy</i>	Switch the control off and then on again.	
3061	Processing sections cannot be loaded	Acknowledgement key
<i>Scan</i>	When processing a program with execution from external in AUTOMATIC while reloading a section	
<i>Effect</i>	Processing stops	
<i>Explanation</i>	The program section which is to be read in no longer fits in the circular buffer for execution from external	
<i>Remedy</i>	<p>The program can be continued with NC START although processing may be interrupted when the program is re-loaded.</p> <p>Increase the size of the circular buffer for execution from external</p>	
<i>Note</i>	Applies to SW 2 only	
3072	Alarm text not available	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> If an alarm occurs without alarm text 	
<i>Effect</i>	<ul style="list-style-type: none"> None 	
<i>Explanation</i>	<ul style="list-style-type: none"> When generating cycles, alarms have been provided for which no text was programmed NC alarms which are not provided with a text in the system have been triggered 	
<i>Remedy</i>	<p>Look at the complete listing of alarm displays and check off alarm numbers without text.</p> <p>With cycle alarms, program an appropriate text.</p> <p>With system alarms, notify your Systems Support.</p>	
<i>Note</i>	Applies to SW 1 only	
3073	Error: NCK input line to MMC	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> On input 	
<i>Effect</i>	<ul style="list-style-type: none"> Input line is not displayed 	
<i>Explanation</i>	An error has occurred during transmission of the input line from NCK to MMC.	
<i>Remedy</i>	Activate notebook for I code and send message together with notebook entry to System Support (system program change required)	

3081	CRC not selected at approach/retraction	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> When executing a part program 	
<i>Effect</i>	Machine stop does not occur but the program is executed without the approach element.	
<i>Explanation</i>	<ul style="list-style-type: none"> CRC/TNRC (G41/G42) was not selected in or before the approach block. CRC/TNRC was not deselected in or after the exit block. Soft approach/exit is only possible when CRC/TNRC is selected because it is only then possible to calculate the programmed compensation movement exactly. 	
<i>Remedy</i>	<ul style="list-style-type: none"> Correct program (G41/G42) Program with G41/G42 DO if necessary 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
3084	Illegal working area limitation	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> Cyclic 	
<i>Effect</i>	The control automatically enters the maximum possible value in accordance with the traversing range in the working area limitation.	
<i>Explanation</i>	A value outside the permissible traversing area of the respective axis has been entered in the minimum or maximum axis-specific working area limitation.	
<i>Remedy</i>	<ul style="list-style-type: none"> Check input Check program (G25, G26, @..) For maximum traversing range, refer to table (combination of axis-specific position control resolution and input resolution) 	
<i>Note</i>	Channel-specific Applies up to SW 2 only	
3085	NC–CPU time watchdog	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> Cyclic 	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START Interlocking of Mode Group Ready Interlocking of machining Interlocking of NC Ready relay 	
<i>Explanation</i>	<p>The NC–CPU is overloaded with respect to time by a parallel program operation or by the selection of functions such as</p> <ul style="list-style-type: none"> Transformation (TRANSMIT, etc.) Coupled axis motion GI ring links 	
<i>Remedy</i>	<ul style="list-style-type: none"> Increase IPO/servo cycles, check the GI configuration. 	
<i>Note</i>	Channel-specific	
3086	Illegal transformation selection	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> On selecting or deselecting transformation via the command channel of the PLC 	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC Start 	
<i>Explanation</i>	An illegal value has been transferred from the PLC via the command channel. Evaluation is in the error byte in the PLC.	
<i>Remedy</i>	Check PLC user program	
3087	Error in transformation data	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> At POWER ON On warm restart 	
<i>Effect</i>	<ul style="list-style-type: none"> Selected transformation data block is locked 	
<i>Explanation</i>	An NC machine data with an illegal value is present in the selected transformation data block. The invalid NC machine data number is entered in the block number of alarm 3087.	
<i>Remedy</i>	<ul style="list-style-type: none"> Check NC machine data for transformation data (block number of alarm 3087) 	
<i>Note</i>	Alarm is displayed with reference to block and channel	

1.5.1 Alarm description

3088	F collapse at block change	Acknowledgement key
<i>Scan</i>	Processing in a channel with FIFO memory	
<i>Effect</i>	None	
<i>Explanation</i>	The programmed feedrate is too high. The control has not yet prepared the next block for processing.	
<i>Remedy</i>	<ul style="list-style-type: none"> Decrease feedrate Program G171 (to bridge the critical point with a rapid block change) 	
3091	Reduction on SW prelimit switch	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> In AUTOMATIC or MDA when processing a part program block or when positioning the axes in JOG 	
<i>Effect</i>	<ul style="list-style-type: none"> Speed reduction to the value set in the machine data 	
<i>Explanation</i>	The software prelimit switch has been exceeded and the axis speed is decelerated to the reduction speed (MD1). If a position behind the software prelimit switch is taken with rapid traverse G00, the alarm "Reduction on SW prelimit switch" is not output. But the reduction is executed.	
<i>Remedy</i>	<ul style="list-style-type: none"> Check the traversing block Check value in NC machine data 1100 "Prelimit switch" Position axis beyond the prelimit switch range and cancel the alarm by means of "Acknowledgement". 	
3092	Specified velocity too high	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> When traversing by the program in AUTOMATIC or MDA 	
<i>Effect</i>	<ul style="list-style-type: none"> Machining stops 	
<i>Explanation</i>	The specified speed (either programmed or by setting an override) is greater than the path speeds resulting from the maximum speeds of the axes In a circle block, the path velocity is reduced to the smallest velocity of the axes involved.	
<i>Remedy</i>	<ul style="list-style-type: none"> Program a lower path speed or check override Check NC machine data "Maximum velocity" Program a smaller spindle speed with G95 	
3093	G171 not allowed	Acknowledgement key
<i>Scan</i>	After programming G171	
<i>Effect</i>	<ul style="list-style-type: none"> Function is not executed 	
<i>Explanation</i>	G171 is illegal for the following reasons: <ul style="list-style-type: none"> No FIFO has been assigned to the current channel "FIFO" has not been activated. 	
<i>Remedy</i>	<ul style="list-style-type: none"> Program a lower path speed or check override Check NC machine data "Maximum speed" Program a smaller spindle speed with G95 	
<i>Note</i>	Channel-specific Applies up to SW 2	
3094	Error in compensation data	Acknowledgement key
<i>Scan</i>	On POWER ON/warm restart	
<i>Effect</i>	Interpolatory compensation (IKA) is not executed, an IKA already active is ended.	
<i>Explanation</i>	It is not possible to convert the error curves because the input data are incorrect. <ul style="list-style-type: none"> Only one of the start and end pointers is 0. Both must be 0 or $\neq 0$. End pointer is not greater than start pointer Within an error curve section, the interpolation position (n+1) is less than or equal to the interpolation position (n) The straight line slope within an error curve section is ≥ 45 degrees 	
<i>Remedy</i>	Correct the compensation data	

3095 Handwheel 1 – wire breakage Acknowledgement key

- Scan** • Cyclic
- Effect** • It is no longer possible to traverse the axes in the normal way using the handwheel.
- Explanation** • The alarm is only relevant for handwheels with differential signal evaluation
- Remedy** • Check the handwheels
Eliminate the hardware fault
• If necessary, connect wire jumper on CSB, if handwheel is not connected, to avoid triggering alarm

3096 Handwheel 2 – wire breakage Acknowledgement key


- Scan** • Cyclic
- Effect** • It is no longer possible to traverse the axes in the normal way using the handwheel.
- Explanation** • The alarm is only relevant for handwheels with differential signal evaluation
- Remedy** • Check the handwheels
Eliminate the hardware fault
• If necessary, connect wire jumper on CSB, if handwheel is not connected, to avoid triggering alarm.

3097 Illegal handwheel function Acknowledgement key

- Scan** G27 programmed with active DRF
Setting data 564* not provided with values
- Effect** • Interlocking of NC START
- Remedy** Deselect DRF
- Note** Alarm is displayed with reference to channel

3098 Error in IKA input/output data CANCEL

- Scan** On changing input/output assignment of the IKA with inactive relationship (input screen or @40C), not G411.
- Effect** None
- Explanation** A check is made to determine whether the input/output assignment of an IKA relationship contains permissible data, and in particular whether the pairs T2/T20, T25/T25, T3/T33 contain compatible values. An error fine coding ensues relating to block and channel number as follows:



- Error fine coding:
- 1; Error = "Wrong group"
 - 2; Error = "Illegal type of axis"
 - 3; Error = "Wrong axis number"
 - 4; Error = "Axis not available"
 - 5; Error = "Not a real axis"
 - 6; Error = "Wrong R parameter number"
 - 7; Error = "Illegal type of axis"

- Remedy** Enter the correct values

1.5.1 Alarm description

3100	Transfer buffer already assigned	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> During computer link operation 	
<i>Effect</i>	<ul style="list-style-type: none"> No data transfer between NC and host computer 	
<i>Explanation</i>	This alarm is not displayed but only sent from the NC to the host computer when data is to be transferred from the computer but the transfer buffer is still occupied.	
3101	Program not in memory	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> When calling a program via computer link 	
<i>Effect</i>	<ul style="list-style-type: none"> None 	
<i>Explanation</i>	A program has been requested for read-out but is not located in the NC memory. This alarm is not displayed in the message line but is only indicated in the operator display.	
<i>Remedy</i>	<ul style="list-style-type: none"> Check whether program request is correct 	
3102	Data input disabled FTR	Acknowledgement key
<i>Scan</i>	When reading in programs via FTR	
<i>Effect</i>	FTR is aborted	
<i>Explanation</i>	<ul style="list-style-type: none"> You have tried to read in a part program via FTR which has already been edited and executed NC internally. "Execution from external" <p>A program with the same number as the program to be executed from external already exists</p>	
<i>Remedy</i>	Stop execution or delete program in the case of "Execution from external".	
3110	Wrong block structure for axis-specific override (2nd step)	Acknowledgement key
<i>Scan</i>	When G160 and G161 commands are not programmed alone in a block	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of NC START 	
<i>Remedy</i>	<ul style="list-style-type: none"> Alter the part program 	
<i>Note</i>	Applies to SW 2 only	
3111	Wrong block struct. for delete dist-to-go	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> When @736 has not been programmed after the programmed axis movements If the axis concerned has not been programmed 	
<i>Explanation</i>	<ul style="list-style-type: none"> Interlocking of NC START 	
<i>Remedy</i>	<ul style="list-style-type: none"> Alter the part program 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
3112	Wrong block structure for reciprocation	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> Reciprocation incorrectly programmed (syntax, reciprocation parameters) Too many reciprocation movements in the block 	
<i>Explanation</i>	<ul style="list-style-type: none"> Interlocking of NC START 	
<i>Remedy</i>	<ul style="list-style-type: none"> Alter the part program 	
<i>Note</i>	Applies to SW 2 only	

3113	Error on accessing mixed I/O or CSB	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> MIXED I/O module does not exist or is faulty 	
<i>Explanation</i>	<ul style="list-style-type: none"> Attempt made to output to CSB without output driver (wrong hardware) or defective CSB output driver, NC MD 312–321 refer to non-existent modules or inputs. Interlocking of NC START PLC attempts to read from a non-existing module via fast data channel 	
<i>Remedy</i>	<ul style="list-style-type: none"> Slot in MIXED I/O module Check MIXED I/O module Replace the CSB module Correct NC MD 312 to 321 	
3157	Stop in thread	Acknowledgement key
<i>Explanation</i>	<ul style="list-style-type: none"> During thread cutting a stop has occurred in the revolution feedrate which has destroyed the thread. 	
<i>Remedy</i>	<ul style="list-style-type: none"> Check axis-specific feedrate lock (DB32) 	
3158	PLC number not allowed	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> On selecting via softkey in a configured display 	
<i>Effect</i>	<ul style="list-style-type: none"> None 	
<i>Explanation</i>	Configured field shows a non-existent PLC number; SINUMERIK 840C has only 1 PLC.	
<i>Remedy</i>	<ul style="list-style-type: none"> Check assignments using NC workstation and correct 	
3159	There is no data block	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> On selecting via softkey in a configured display 	
<i>Effect</i>	<ul style="list-style-type: none"> None 	
<i>Explanation</i>	Configured field indicates a non-existent data block.	
<i>Remedy</i>	<ul style="list-style-type: none"> Check assignments using NC workstation and correct 	
3164	Axis conversion error	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> While executing in AUTOMATIC, MDA or Teach In mode 	
<i>Effect</i>	<ul style="list-style-type: none"> Machining stops Interlocking of NC START 	
<i>Explanation</i>	<ul style="list-style-type: none"> The alarm is displayed in channel and block. Wrong entries in axis converter list (SD) <ul style="list-style-type: none"> Axis name not entered Axis does not exist 	
<i>Remedy</i>	Correct axis converter list	
<i>Note</i>	Alarm is displayed with reference to block and channel	
3166	Program coordination wrong	Acknowledgement key
<i>Scan</i>	While executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> Machining stops 	
<i>Explanation</i>	Addressed channel has not been defined or is not enabled	
<i>Remedy</i>	Change channel addressing Define or enable channel	
<i>Note</i>	Alarm is displayed with reference to block and channel	

1.5.1 Alarm description

3167	T/H word not acknowledged	Acknowledgement key
<i>Scan</i>	Cyclic	
<i>Effect</i>	None	
<i>Explanation</i>	<ul style="list-style-type: none"> The target channel is not enabled in the PLC MD (signals from channel) Routing in target channel has not yet been acknowledged by the user 	
<i>Remedy</i>	The current routing and/or error must be acknowledged through the PLC program before the next routing is assigned.	
3200	Program coordination syntax wrong	Acknowledgement key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	Interlocking of machining	
<i>Explanation</i>	Syntax error: invalid command mnemonics invalid modification parameters	
<i>Remedy</i>	Correct the faulty command	
<i>Note</i>	Alarm is displayed with reference to block and channel	
3201	Program coord. too many parameters	Acknowledgement key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	Interlocking of machining	
<i>Explanation</i>	More command parameters have been programmed than are permitted in the command description.	
<i>Remedy</i>	Correct the faulty command	
<i>Note</i>	Channel-specific	
3202	Program coordination area violation	Acknowledgement key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	Interlocking of machining	
<i>Explanation</i>	One or more command parameters violate the permitted lower and upper limit values	
<i>Remedy</i>	Correct the faulty command	
<i>Note</i>	Alarm is displayed with reference to block and channel	
3203	Program coord. illegal character	Acknowledgement key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	Interlocking of machining	
<i>Explanation</i>	Illegal separators are in the coordination command.	
<i>Remedy</i>	Correct the faulty command	
<i>Note</i>	Alarm is displayed with reference to block and channel	
3204	Program coord. command incomplete	Acknowledgement key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	Interlocking of machining	
<i>Explanation</i>	Parameters or closing brackets are missing in the programmed command or channel no. = 0	
<i>Remedy</i>	Correct the faulty command	
<i>Note</i>	Alarm is displayed with reference to block and channel	

3205	Program coord. R parameter error	Acknowledgement key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	Interlocking of machining	
<i>Explanation</i>	<ul style="list-style-type: none"> An error occurred while programmed R parameters were being substituted 	
<i>Remedy</i>	Correct the faulty command	
<i>Note</i>	Alarm is displayed with reference to block and channel	
3206	Program coord. symbol. paras. not allowed	Acknowledgement key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	Interlocking of machining	
<i>Explanation</i>	With the exception of the R parameters, no symbol. parameters are permitted	
<i>Remedy</i>	Correct the faulty command	
<i>Note</i>	Alarm is displayed with reference to block and channel	
3220	Change from G176 → G175	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> When executing a part program 	
<i>Effect</i>	<ul style="list-style-type: none"> Activated freeze function is terminated leading to G175 function. 	
<i>Explanation</i>	During an activated freeze function for angle of rotation, zero offset or length compensation, the ZO group was changed or the D No. was changed, an angle of rotation offset was activated or a G53 programmed. These functions result in termination of the "Freeze" function and a change to the G175 function.	
<i>Remedy</i>	<ul style="list-style-type: none"> Check program blocks and correct 	
<i>Note</i>	Channel-specific	
3225	Invalid plane specification	Acknowledgement key
<i>Scan</i>	Before executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> Processing stops 	
<i>Explanation</i>	The plane assignment (cube) and the axis definitions in the channel do not correspond.	
<i>Remedy</i>	Check NC MD 548* 550*552*	
<i>Note</i>	Alarm is displayed with reference to channel	
3226	Invalid G function initial setting	Acknowledgement key
<i>Scan</i>	Before processing the first block in AUTOMATIC or MDA	
<i>Effect</i>	<ul style="list-style-type: none"> Processing stops 	
<i>Explanation</i>	Invalid G function initial settings positions have been entered in the channel-specific machine data.	
<i>Remedy</i>	Check NC MD 108* to 122*	
<i>Note</i>	Alarm is displayed with reference to channel	
3233	Approach reference point not allowed	Reset key
<i>Scan</i>	In "AUTOMATIC interrupted" state.	
<i>Effect</i>	No referencing possible.	
<i>Explanation</i>	If a program is interrupted with the NC STOP key or when changing from AUTOMATIC to JOG mode, it must not be possible to activate the submode of JOG, REFPOINT. (Safety function)	
<i>Remedy</i>	<ul style="list-style-type: none"> Reference in program (G74) Abort program and reference using keys 	

1.5.1 Alarm description

3234	There is no target block	Acknowledgement key
<i>Scan</i>	When block search function is being applied	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining stops • Interlocking of NC START 	
<i>Explanation</i>	Block being sought is not in the part program or is to be found after M30	
<i>Remedy</i>	Check entered block number	
<i>Note</i>	Applies as from SW 2	
<i>Note</i>	Alarm is displayed with reference to channel	
3235	End of program missing	Acknowledgement key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	Machining stops	
<i>Explanation</i>	The program end M30 is missing in the part program.	
<i>Remedy</i>	Check the part program	
<i>Note</i>	Channel-specific	
3236	Illegal pole specification	Acknowledgement key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining stop • Interlocking of NC START 	
<i>Explanation</i>	Illegal pole programming with polar coordinates when: <ul style="list-style-type: none"> • G110, G111, G112 programmed without having specified a pole plane • Programmed pole plane with G110, G111, G112 does not correspond to the current pole plane • G110, G111, G112 programmed with axes and with angles and radii • Pole displacement (by way of G9 programming) with G10, G11, G12, G13 does not correspond to the current pole plane • G10, G11, G12, G13 programmed for the first time without axis specification • G10, G11, G12, G13 programmed for the first time with G91 • G91 programmed before the angle 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check the incorrect block in the "Correction block" display. • The cursor is positioned in front of the incorrect word, if possible. 	
<i>Note</i>	Alarm is displayed with reference to block and channel	
3237	Program is being edited	Acknowledgement key
<i>Scan</i>	When starting read-out via the computer link	
<i>Effect</i>	Part program is not output	
<i>Explanation</i>	The control tries to output via the computer link a part program which is in the process of being edited.	
<i>Remedy</i>	Terminate editing and repeat read-out process	
3238	Program being read-in	Acknowledgement key
<i>Scan</i>	When starting read-out via the computer link	
<i>Effect</i>	Part program is not read out	
<i>Explanation</i>	The control tries to output via the computer link a part program which is in the process of being read in via the computer link	
<i>Remedy</i>	Wait for the end of the read-in process and repeat read-out.	

3239	EPROM cycle overwritten by SPF	POWER ON
<i>Scan</i>	When reading in subroutines via the computer link	
<i>Effect</i>	Cycle replaced by subroutine	
<i>Explanation</i>	At least one subroutine has been read in which has the same number as an existing cycle. The cycle can therefore no longer be called from a part program. The first cycle to be overwritten is displayed in the N number.	
<i>Remedy</i>	Delete the read in subroutine to save the cycle. To prevent overwriting generally, set MD 5147, bit 3 to 1 on file transfer.	
<i>Note</i>	Channel-specific	
3240	Subroutine not read-in	Acknowledgement key
<i>Scan</i>	When reading in subroutines via computer link	
<i>Effect</i>	At least one subroutine has not been read	
<i>Explanation</i>	The control has attempted to read in at least one subroutine which has the same number as an existing UMS cycle. The first subroutine not to be read in is displayed in the N number.	
<i>Remedy</i>	If the UMS cycle is to be replaced by a subroutine, the MD 5147, bit 3 must be set to 0 on file transfer.	
<i>Note</i>	Channel-specific	
3260	Incorrect parameters "Ext. overstore"	Reset key
<i>Scan</i>	On decoding G421–6.	
<i>Effect</i>	Decoding stop	
<i>Explanation</i>	When programming G421–6, it is found that the required behaviour requested through the program has been locked by the machine data parameterization.	
<i>Remedy</i>	Perform no programming or check MD parameterization.	
<i>Note</i>	Applies as from SW 4	
<i>Note</i>	Alarm is displayed with reference to channel	
3261	Workpiece not available	Reset key
<i>Scan</i>	At Power On and active MD "Load workpiece last active after Power On"	
<i>Effect</i>	The workpiece selected in the program pointer cannot be transferred from MMC to NCK.	
<i>Explanation</i>	In the volatile NCK part program memory, a workpiece directory has been opened and not saved to harddisk before Power Off. After Power On, it is therefore not possible to transfer the workpiece entered in the program pointer from harddisk to the NCK part program memory.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Select existing workpiece • Preselect part program for execution (which means that the program pointer will automatically be assigned to the workpiece belonging to the preselected part program). 	
<i>Note</i>	Applies as from SW 4	
<i>Note</i>	Alarm is displayed with reference to channel	

1.5.1 Alarm description

3262	Error in NCK FB	Acknowledgement key
<i>Scan</i>	During cyclic operation of control	
<i>Effect</i>	None	
<i>Explanation</i>	The cyclic routines of the NCK FB have returned a value which is not equal to zero, and have requested the CANCEL alarm class. The return value is output in the alarm as block number N.	
<i>Remedy</i>	Evaluate the block number and check the NCK FB.	
<i>Continuation</i>	Acknowledge the alarm with the Acknowledgement key	
<i>Note</i>	<ul style="list-style-type: none"> Alarm 3262 is output only if appropriately configured by the machine manufacturer. An error has occurred in the safety NCK-FB. For more information and remedy, refer to the manufacturer's documentation. Applies as from SW 5.4. 	
3263	Impermissible axis position	Acknowledgement key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	Interlocking of NC START Machining stops	
<i>Explanation</i>	The position of the material entry coordinate is outside the travel range of the block.	
<i>Remedy</i>	Modify the part program.	
<i>Continuation</i>	Acknowledge the alarm with the Acknowledgement key	
<i>Note</i>	Applies as from SW 5.4	
<i>Note</i>	Alarm is displayed with reference to channel	
3264	NC STOP is effective at the end of block	
<i>Scan</i>	When pressing NC STOP with active G04 S..., G14 and G24 with set MD bit "No NC STOP in the dwell block".	
<i>Effect</i>	NC-STOP is delayed until the end of block	
<i>Explanation</i>	NC STOP has been pressed in a dwell block in which NC STOP is not to become effective. Processing of the dwell block continues, NS STOP becomes effective only at the end of the block.	
<i>Remedy</i>	The message is deleted when the NC STOP has become effective at the end of the block or when the NC STOP request has been cancelled with NC START.	
<i>Note</i>	<ul style="list-style-type: none"> Alarm channel-specific Applies as from SW 5.4 	
3265	IKA link disconnected	Cancel key
<i>Scan</i>	Cyclically in IPO cycle	
<i>Effect</i>	Feed stop of "slave axis" (IKA output variable)	
<i>Explanation</i>	The IKA link has been disconnected because the IKA output variable (normally an axis) was stopped for safety reasons (e.g. feed disable, follow-up mode, override, controller enable).	
<i>Remedy</i>	Remove the reason for the feed stop. Caution: If the reason for the feed stop is no longer present, the IKA link is automatically reactivated. As a result, the "following error" that has been built up in the meantime is reduced again. The "reduction" is executed with the modification limit of the IKA.	
<i>Note</i>	Applies as from SW 6	
3280	NC start disable	Acknowledgement key
<i>Scan</i>	On NC START	
<i>Effect</i>	None	
<i>Explanation</i>	Interlocking of NC START set internally. User has operated NC START.	
<i>Remedy</i>	Change to the required operating mode or enable the function (e.g. Teach in).	

3281	Set-up disable	POWER ON
<i>Scan</i>	While operating the manual travel keys	
<i>Effect</i>	None	
<i>Explanation</i>	Set-up disable has been set internally. The user wishes to move an axis with the manual travel keys.	
<i>Remedy</i>	Change to the required operating mode or enable the function (e.g. Teach in).	
3282	Data not available	Acknowledgement key
<i>Scan</i>	While reading in machine data or setting data into the NCK	
<i>Effect:</i>	None	
<i>Explanation</i>	A machine data or setting data which does not exist (or which no longer exists in the present software version) has been read in.	
<i>Remedy</i>	Remove invalid machine data or setting data from file.	
4000	Delete alarm	
:	:	
:	:	
4220	Parallel straight lines	
	This area is reserved for measuring cycle messages. The messages are listed in the publication SINUMERIK 840C MEASURING CYCLES.	
1000*	Terminal assigned more than once	POWER ON as from SW 2: Reset key
<i>Scan</i>	<ul style="list-style-type: none"> When inputting machine data for axis assignment 	
<i>Effect</i>	No machining of the axes for which the connection number concerned has been assigned more than once <ul style="list-style-type: none"> Servo disable for the axis concerned Mode Group Ready removed Interlocking of NC START Interlocking of NC RDY relay 	
<i>Explanation</i>	<ul style="list-style-type: none"> A connection number of a measuring circuit module has been specified more than once under MD200x or MD384x. Example: MD3840 = 01060000, MD3845 = 01060000. Connection number 6 of the 1st measuring circuit module has thus been assigned more than once. 	
<i>Remedy</i>	<ul style="list-style-type: none"> Check and correct MD200x or MD384x 	
<i>Note</i>	Applies up to SW 2	
1000*	Terminal assigned more than once	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> Cyclic for digital drives if double assignment of setpoint output via MD is permissible. 	
<i>Effect</i>	<ul style="list-style-type: none"> As before 	
<i>Explanation</i>	<ul style="list-style-type: none"> Two NC axes assigned the same digital setpoint output are being controlled at the same time. This simultaneous output of setpoints at the same drive is not allowed. 	
<i>Remedy</i>	<ul style="list-style-type: none"> One of the NC axes must be disconnected from the control loop (servo enable, follow-up mode, parking axis). 	
<i>Note</i>	Applies as from SW 3	

1.5.1 Alarm description

1004*	Permissible feed/limit frequency exceeded	Reset key
<i>Scan</i>	Cyclic	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Interlocking of Mode Group Ready • Setpoint 0 • Servo enable is cancelled after the time in NC MD "Cutout delay" • Follow-up mode 	
<i>Explanation</i>	<p>The maximum value set in the NC MD "Encoder frequency" has been exceeded.</p> <p>Is only activated for C axes to spindles (assignment via NC MD 461*).</p> <p>If the service number 309 is indicated here, the reason for the alarm is a format overflow, which can be avoided by reduction of the resolution.</p>	
<i>Remedy</i>	Check feedrate and NC MD "Encoder limit frequency" MD 308*.	
1008*	Speed controller limitation	Reset key
<i>Scan</i>	POWER ON and warm restart	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Interlocking of Mode Group Ready <p>Alarm causes machining stop</p>	
<i>Explanation</i>	<ul style="list-style-type: none"> • Speed alarm limit has been reached 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check current controller • Set speed control loop to a slower rate • Increase parameters • Check mechanical parts 	
1012*	Parameterization error drive MD (SW 3)	Reset key
1012*	Parameterization error NC–MD (SW 4 and higher)	Reset key
<i>Scan</i>	<ul style="list-style-type: none"> • At POWER ON and warm restart 	
<i>Effect</i>	<ul style="list-style-type: none"> • Corresponding axes switched to follow-up operation • Machining stops • Interlocking of NC START • Mode Group Ready is removed 	
<i>Explanation</i>	<p>Setting error in the NC machine data, e.g.</p> <ul style="list-style-type: none"> • Too large a ratio between interpolator clockrate and position control clockrate, because MD160>8 • Too large an internal K_V (servo gain) factor by specification of <ul style="list-style-type: none"> – K_V factor (252*) – Multigain (260*) – Pulse weighting • Ratio of cycle rate (MD165) to setting for fine interpolation (MD160) or check of MD584* "Identifier of auxiliary axes" is not a whole number • Incorrect measuring system adjustment with MD364* to MD368* (values chosen too large) • General parameter error in a drive MD • An illegal value has been entered for the pulse multiplication in connection with the high-resolution measuring system. Permissible values are: 1, 2, 4, 8, 16, 32, 64 and 128. • Error in parameterization of the SI machine data. 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check and new input of the corresponding machine data. • The AXIS service display shows the service number for the parameterization errors and therefore the exact cause.(see Diagnostics Guide, Section Parameterization errors spindle/axis). 	
<i>Note</i>	<ul style="list-style-type: none"> • Alarm "Parameterization error drive MD": up to SW 3 • Alarm "Parameterization error NC–MD": as from SW 4 	

1016*	MS switchover not possible	Reset key
<i>Scan</i>	When the PLC requests a measuring system switchover	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Interlocking of Mode Group Ready • Setpoint 0 • Servo enable is withdrawn after the time in NC–MD “Cutout delay controller enable” has elapsed • Follow-up mode 	
<i>Explanation</i>	<ul style="list-style-type: none"> • The difference between measuring system 1 and measuring system 2 is greater than the tolerance specified in MD 1216*. 	
<i>Remedy</i>	<p>Check the mechanical parts and find out the reason for the differences in the measuring value acquisition via the 1st and the 2nd measuring system.</p> <p>Check sign change actual value 2nd measuring system MD 1824* bit 4, if necessary.</p>	
1028*	Unable to set reference dimension	Reset key
<i>Scan</i>	Negative edge of signal DB32, DL K+1, bit 6, (“Set reference dimension”)	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlock of NC Start • Setpoint 0 • No servo enable • Follow-up mode 	
<i>Explanation</i>	If the “Set reference dimension” could not be performed (axis not stationary), the “Reference point reached” signal is no longer set and also the axis-specific RESET alarm 1028* “Unable to set reference dimension” is triggered.	
<i>Remedy</i>	Make sure that the axes are stationary.	
1040*	Absolute encoder defective	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Interlocking of Mode Group Ready • Machining stops 	
<i>Explanation</i>	If a SIPOS absolute encoder with absolute submodule is fitted and the absolute encoder function is selected in MD 1808*, bit 0, the absolute position is requested by the control on POWER ON. If it is not possible to transmit an absolute position from the encoder without any errors, this alarm is released.	
<i>Remedy</i>	Check the encoder hardware (encoder, cable, connectors, absolute submodule). The SIPOS encoder must remain stationary during transmission of the absolute value, the axis must therefore be held by the brake if necessary.	
1044*	Battery absolute module	Acknowledgement key
<i>Scan</i>	Cyclic, every 10 minutes	
<i>Effect</i>	None	
<i>Explanation</i>	The SIPOS encoder has a battery back-up on the absolute submodule so that the absolute position is not lost even when switched off. The remaining capacity of this battery is checked by the absolute module approximately every 10 minutes and an alarm is released if a critical minimum limit is reached.	
<i>Remedy</i>	Replace the battery on the absolute module (see SIPOS absolute encoder description)	
1052*	Drive fault	Reset key
<i>Scan</i>	<ul style="list-style-type: none"> • 611–D alarm 300100 “Drive link off” • Power On / Reset alarms (ZK1) from 611–D 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Interlocking of Mode Group Ready • Setpoint 0 • Servo enable cancelled after the time set in NC MD “Switchoff delay servo enable” has passed (not with alarm “Drive link off”) • Follow-up mode • 611–D status signals “Drive ready” and “Drive connected” are reset 	
<i>Explanation</i>	<ul style="list-style-type: none"> • Further detailed information on the cause are given in the MMC diagnosis display 	
<i>Note</i>	Applies as from SW 3	

1.5.1 Alarm description

1056*	Programmed axis is slave	Reset key
<i>Scan</i>	<ul style="list-style-type: none"> • Setpoint specified for a slave axis • Travel to fixed stop with a slave axis 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Follow-up mode • Cancellation of Mode Group Ready • Processing interrupt 	
<i>Explanation</i>	The designated axis is coupled to its master axis through a speed setpoint coupling. Setpoints should therefore not be specified.	
<i>Remedy</i>	Setpoints should not be specified for the slave axis.	
<i>Note</i>	Applies as from SW 4.4	
1064*	Output not available	POWER ON
<i>Scan</i>	Setpoint incorrectly assigned	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Interlocking of Mode Group Ready • Interlocking of NC Ready • Setpoint 0 • No servo enable • Follow up mode 	
<i>Explanation</i>	A digital setpoint output which does not exist has been assigned	
<i>Remedy</i>	Check the setpoint assignment machine data	
<i>Note</i>	Applies as from SW 3	
1068*	Drive fault	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> • 611-D alarms <ul style="list-style-type: none"> – Drive configuration faulty – Ramp-up error (error on 611-D ramp-up. Adjusting data has caused errors) – Fault along transmission line 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Interlocking of Mode Group Ready • Interlocking of NC Ready • Setpoint 0 • Servo enable cancelled after the time set in NC MD "Switch off delay servo enable" has passed • Follow-up mode 	
<i>Explanation</i>	<ul style="list-style-type: none"> • Further detailed information on the cause in MMC diagnosis display 	
<i>Note</i>	Applies as from SW 3	
1076*	Measure hardware	Reset key
<i>Scan</i>	Once only after incorrect operator action/function selection	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining stops • NC Start disable • Removal of Mode Group Ready 	
<i>Explanation</i>	<ul style="list-style-type: none"> • Invalid measuring circuit assignment • Pushbutton 2 programmed for SPC/HMS • Alternating edges programmed for SPC/HMS • Positive edge programmed for SPC/HMS • Measuring system change during extended measurement 	
<i>Remedy</i>	Check and rectify possible causes of error.	

1164*	Emergency retraction triggered	Reset key
<i>Scan</i>	Cyclic in servo cycle when LINK ON is set for following axis (from servo).	
<i>Effect</i>	Machining interrupted, interlocking of NC START; Mode Group Ready cancelled;	
<i>Explanation</i>	The threshold MD "Emergency retraction threshold" programmed for synchronism monitoring has been exceeded and "Emergency retraction triggered". Condition: enable via PLC interface signal emergency retraction enabled.	
<i>Remedy</i>	Check the drives; check the speed and acceleration limit values of the following axis/spindle; check the emergency retraction threshold; check the link factors.	
<i>Note</i>	Applies as from SW 3	
1168*	Overlay of FA not enabled	Acknowledgement key
<i>Scan</i>	Path defined for following axis (NCK).	
<i>Effect</i>	Setpoint not output, i.e. overlay not executed.	
<i>Explanation</i>	Overlaid offset of following axis although the PLC interface signal "Enable FA overlay" has not been set.	
<i>Remedy</i>	Traverse the following axis with the fictitious leading axis or set PLC interface signal "Enable FA overlay"	
<i>Note</i>	Applies as from SW 3	
1172*	Speed limit exceeded	Acknowledgement key
<i>Scan</i>	Cyclic in servo cycle when LINK ON has been set for the following axis (from servo)	
<i>Effect</i>	No reaction, machining not interrupted; the speed of the following axis is limited to the programmed maximum value; the setpoint determined by the compensatory controller is not used in the calculation.	
<i>Explanation</i>	The maximum value set for the following axis/spindle has been exceeded. Synchronism is in danger.	
<i>Remedy</i>	Reduce feedrate or speed of leading axes. Check the speed limit value. Check the link factors.	
<i>Note</i>	Applies as from SW 3	
1176*	Acceleration limit exceeded	Acknowledgement key
<i>Scan</i>	Cyclic in servo cycle when LINK ON has been set for the following axis and MD bit "Suppression of acceleration limitation" is not set (from servo).	
<i>Effect</i>	No reaction. Machining is not interrupted; when interface signal "Acceleration limitation synchronous" is set; travel is continued at maximum acceleration; any suppressed partial setpoints are traversed afterwards; If interface signal "Acceleration limit synchronous" has not been set; any suppressed partial setpoints are not traversed. The setpoint determined by the compensatory controller is not used in the calculation.	
<i>Explanation</i>	The maximum value programmed for the following axis has been exceeded. Synchronism is in danger.	
<i>Remedy</i>	Reduce the acceleration of the leading axes. Check the acceleration limit value. Check the link factors. Set MD bit "Suppress acceleration limitation".	
<i>Note</i>	Applies as from SW 3	
1180*	Following spindle corrected autom.	Reset key
<i>Scan</i>	An error has occurred that has cancelled "Mode Group Ready".	
<i>Scan</i>	Cyclic in servo cycle when LINK ON is set	
<i>Effect</i>	Machining is interrupted. Interlocking of NC START: switchover to actual position link.	
<i>Explanation</i>	An error has occurred for an axis/spindle in the mode group which usually causes a switch over to follow-up mode. As long as the following axis is not affected by the fault, the link is maintained until "Delay controlled follow-up" has been executed.	
<i>Remedy</i>	Remove error from faulty axis/spindle.	
<i>Note</i>	Applies as from SW 3	

1.5.1 Alarm description

1192*	Centering edge violated	Acknowledgement key
<i>Scan</i>	Cyclic in IPO cycle when LINK ON and PLC interface signal "Semi-automatic centring is active" are set.	
<i>Effect</i>	Interlocking of NC START, any movement towards edges already recognized are suppressed.	
<i>Explanation</i>	The alarm is set when the axis tries to traverse across an edge that has already been recognized or if PLC interface signal "Semi-automatic centring on" and "First edge approached" have been set without first traversing the following axis.	
<i>Remedy</i>	Move following axis away from the edge (in opposite direction to approach direction: if necessary remove interface signal "x edge approached" traverse at least 1 increment between interface signal "Semi-automatic centring on" and "First edge approached").	
<i>Note</i>	Applies as from SW 3 up to SW 4.3	
1192*	No synchronous/switching positions defined	Reset key
<i>Scan</i>	When synchronizing or switching on in relation to a position from PLC.	
<i>Effect</i>	Interlocking of NC START, MACHINING STOP	
<i>Explanation</i>	An attempt has been made to synchronize master and slave axes/spindles from PLC, or to switch on with reference to a position, without there being any valid switching or synchronizing positions. Synchronization or switching on with reference to a position is therefore not possible.	
<i>Remedy</i>	For example, specified positions through the GI input display.	
<i>Note</i>	Applies as from SW 4.4	
1196*	Reconfiguration not allowed	Acknowledgement key
<i>Scan</i>	When RECONFIGURING with G function (G401), i.e. when adding, removing a leading axis or changing the link structure or on CLEAR configuration (from NCK)	
<i>Effect</i>	Interlocking of NC START	
<i>Explanation</i>	"Reconfiguration allowed" is not set (MD 1844, bit 1)	
<i>Remedy</i>	Correct input, set MD bit	
<i>Note</i>	Applies as from SW 3	
1200*	Division wrong	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> • Cyclic 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Machining is interrupted 	
<i>Explanation</i>	<p>The "Division from PLC" function is not possible because:</p> <ul style="list-style-type: none"> • NC machine data "Number of divisions" has an invalid value • NC machine data "Absolute division increment" has an invalid value • NC machine data "Division offset" has an invalid value • Indexing axis has been defined as a rounding axis, which is impermissible. 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check and correct the relevant machine data. 	
1204*	Traversing range limits exceeded	Reset key
<i>Scan</i>	<ul style="list-style-type: none"> • Cyclic (only with linear axes) 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Machining is interrupted • Set value 0 (abrupt, no deceleration ramp) 	
<i>Explanation</i>	If no software limit switches or working area limitations are active, it is theoretically possible to exceed the maximum possible traversing range (set by the combination of axis-specific position control resolution and input resolution). As this would lead to traversing errors, however, the traversing range limit is monitored and, when it is exceeded, alarm 1204* is set.	
<i>Remedy</i>	Traverse back into the permissible range in the opposite direction using INC or JOG mode.	

1208*	Link factor KF not allowed	Acknowledgement key
<i>Scan</i>	When entering a new link factor via the G function (from NCK).	
<i>Effect</i>	Command is not executed, the previous link factor is maintained. Interlocking of NC start.	
<i>Explanation</i>	Denominator J=0 is programmed, link factor incorrectly programmed, following axis not programmed.	
<i>Remedy</i>	Correct link factor	
<i>Note</i>	Applies as from SW 3	
1212*	Overwriting of pos. not allowed	Acknowledgement key
<i>Scan</i>	When programming a position with G1 command.	
<i>Effect</i>	G command is not executed: interlocking of NC START	
<i>Explanation</i>	G1 positions must not be overwritten (enabled with MD 1844 *, bit 3)	
<i>Remedy</i>	Correct input	
<i>Note</i>	Applies as from SW 3	
1216*	Reconfiguration/deletion not allowed	Reset key
<i>Scan</i>	When RECONFIGURING with G function (G401), i.e. when a leading axis is added or removed or when the link structure is altered or on DELETE CONFIGURATION (from NCK)	
<i>Effect</i>	Interlocking of NC START, NC STOP, i.e. channel is stopped: command is not executed: JOG mode still possible.	
<i>Explanation</i>	RECONFIGURATION or DELETE CONFIGURATION is not possible until LINK OFF has been set. RECONFIGURATION is only possible after DELETE CONFIGURATION. Program a new configuration block (G401); following axis already exists.	
<i>Remedy</i>	First set LINK OFF for the G1 grouping in question.	
<i>Note</i>	Applies as from SW 3	
1220*	G1 configuration not allowed	Acknowledgement key
<i>Scan</i>	When programming DEFINE CONFIGURATION with G function. (From NCK)	
<i>Effect</i>	Command is not executed. Interlocking of NC START	
<i>Explanation</i>	Possible causes: <ul style="list-style-type: none"> • Do leading and following axes have a position measuring system (encoders)? • Is the following axis linked to itself as a leading axis? • Can the axis be a following axis (MD 1844*)? • Link structure switchover not permissible (MD 1844*) • Link type for the LA/LS not allowed (MD 1456*/496*)? • The following axes must always be real available axes, i.e. a measuring circuit (POS encoder) must be defined. A measuring circuit must be defined for leading axes/spindles with link structure K2 (actual position link). • Leading axes/spindles and following axis are not in the same mode group. • Not exactly one leading spindle defined for following spindle. • One of the axes in the G1 grouping is a fictitious transformation axis. • No synchronous positions have been defined for on-the-fly synchronization. 	
<i>Remedy</i>	Check configuration	
<i>Note</i>	Applies as from SW 3	
1224*	Change of KF not allowed	Acknowledgement key
<i>Scan</i>	When a new link factor is entered via G function (from NCK).	
<i>Effect</i>	The command is not executed, the previous link factor is kept. Interlocking of NC START	
<i>Explanation</i>	The link factor default setting must not be changed (MD 1844*).	
<i>Remedy</i>	Change default setting if necessary.	
<i>Note</i>	Applies as from SW 3	

1.5.1 Alarm description

1228*	Link factor KF not allowed	Reset key
<i>Scan</i>	When entering a new link factor via G function (from NCK).	
<i>Effect</i>	Command is not executed, the previous link factor remains. Interlocking of NC START; NC STOP. Channel stop; JOG mode still possible.	
<i>Explanation</i>	The entered link factor does not lie within the range $0.00000001 \leq /KF/ \leq 10.000000$ or denominator J = 0 or the individual values are so high that internal overflows are the result.	
<i>Remedy</i>	Correct or shorten link factor KF	
<i>Note</i>	Applies as from SW 3	
1232*	Change of link factor KF not allowed	Reset key
<i>Scan</i>	When entering a new link factor via G function (from NCK).	
<i>Effect</i>	Command is not executed, the previous link factor remains. Interlocking of NC START; NC STOP. Channel stop; JOG mode still possible.	
<i>Explanation</i>	The link factor default setting must not be changed (MD 1844*).	
<i>Remedy</i>	Change default setting if necessary.	
<i>Note</i>	Applies as from SW 3	
1236*	GI configuration not allowed	Reset key
<i>Scan</i>	When programming DEFINE CONFIGURATION via G function. (From NCK)	
<i>Effect</i>	Command is not executed. Interlocking of NC START; NC STOP, channel stopped; JOG mode still possible.	
<i>Explanation</i>	Possible causes: <ul style="list-style-type: none"> • Do leading and following axes have a position measuring system (encoders)? • Is the following axis linked to itself as a leading axis? • Can the axis be a following axis (MD 1844*)? • Link structure switchover not permissible (MD 1844*) • Link type for the LA/LS not allowed (MD 1456*/496*)? • The following axes must always be real available axes, i.e. a measuring circuit (POS encoder) must be defined. A measuring circuit must be defined for leading axes/spindles with link structure K2 (actual position link). • Leading axes/spindles and following axis are not in the same mode group. • Not exactly one leading spindle defined for following spindle. • One of the axes in the GI grouping is a fictitious transformation axis. • No synchronous positions have been defined for on-the-fly synchronization. 	
<i>Remedy</i>	Check configuration	
<i>Note</i>	Applies as from SW 3	
1240*	Following axis not defined	Reset key
<i>Scan</i>	When programming an axis as a following axis which is not defined as such (from NCK).	
<i>Effect</i>	G command is not executed. Interlocking of NC START; NC STOP, channel is stopped; JOG mode still possible.	
<i>Explanation</i>	A GI grouping with the stated axis defined as a following axis does not exist.	
<i>Remedy</i>	Correct input.	
<i>Note</i>	Applies as from SW 3	
1244*	Axis not in C axis mode	Reset key
<i>Scan</i>	The following axis is a C axis, is however not in axis mode.	
<i>Effect</i>	G command is not executed Interlocking of NC START; NC STOP, channel is stopped; JOG mode still possible.	
<i>Explanation</i>	For all GI commands except G401, C axis mode must also be set for the C axis which is to be programmed as a following axis. When G401 is programmed, a GI grouping must not also be defined for the assigned spindle.	
<i>Remedy</i>	Correct input.	
<i>Note</i>	Applies as from SW 3	

1248*	Leading axis not defined	Reset key
<i>Scan</i>	When programming an axis as a following axis or a spindle as a leading spindle which are not defined as such. (from NCK)	
<i>Effect</i>	Command is not executed. Interlocking of NC START; NC STOP, channel stopped: JOG mode still possible.	
<i>Explanation</i>	A GI grouping with the stated axis defined as a leading axis does not exist.	
<i>Remedy</i>	Correct input.	
<i>Note</i>	Applies as from SW 3	
1252*	Overwriting of GI position not allowed	Reset key
<i>Scan</i>	When programming a position with GI command.	
<i>Effect</i>	GI command is not executed. Interlocking of NC START; NC STOP, channel stopped: JOG mode still possible.	
<i>Explanation</i>	The GI positions cannot be overwritten (enable with MD 1844*, bit 3)	
<i>Remedy</i>	Correct input	
<i>Note</i>	Applies as from SW 3	
1256*	Retraction axis is following axis	Reset key
<i>Scan</i>	On decoding the retraction command	
<i>Effect</i>	None	
<i>Explanation</i>	Alarm occurs when a following axis is defined as retraction axis because the link is violated by the retraction. Also, the overlay must be enabled by the PLC.	
<i>Remedy</i>	Select another retraction axis.	
<i>Note</i>	Applies as from SW 4	
1260*	Retraction axis in several channels	Reset key
<i>Scan</i>	With configuration G425/6	
<i>Effect</i>	Machining interrupt	
<i>Explanation</i>	An axis has been programmed as retraction axis that has already been selected in another channel for retraction.	
<i>Remedy</i>	Remove axis from the retraction block.	
<i>Note</i>	Applies as from SW 4	
1264*	Sel./desel. endl. rot. axis illegal	Reset key
<i>Scan</i>	On decoding	
<i>Effect</i>	Machining interrupt	
<i>Explanation</i>	An endlessly rotating rotary axis programmed for a retraction operation should be switched over to normal axis operation.	
<i>Remedy</i>	Before deselecting the endless rotary axis, write a G block without this rotary axis.	
<i>Note</i>	Applies as from SW 4	
1268*	IKA path reconfiguration illegal	Reset key
<i>Scan</i>	When programming G401/G411	
<i>Effect</i>	Interlocking of NC Start Interlocking of NC Stop	
<i>Explanation</i>	<ul style="list-style-type: none"> An IKA path has been defined that is already configured. An attempt has been made to delete with G411 an IKA path that is still active. 	
<i>Remedy</i>	Activate an IKA path that is not yet configured. On deselection: Switch IKA inactive.	

1.5.1 Alarm description

1272*	Error in IKA path input/output	Reset key
<i>Scan</i>	When programming G401/411/G412	
<i>Effect</i>	Interlocking of NC Start, NC Stop	
<i>Explanation</i>	If an input/output value is specified with G410/G411/412 that does not correspond to the configuration or is not permissible, this alarm is triggered.	
<i>Remedy</i>	Specify input/output correctly or omit I/O designation with G410.	
1276*	Illegal software limit switch	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> • After changing MD 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Interlocking of Mode Group Ready • Interlocking of machining stops 	
<i>Explanation</i>	An impermissibly high value has been entered in the software limit switch NC MD. The maximum traversing range of the individual axes is determined by the set axis-specific position control resolution and the input resolution. The control entered the maximum permissible value in the relevant NC MD when alarm 87 was triggered.	
<i>Remedy</i>	Check software limit switch machine data and correct if necessary.	
<i>Note</i>	Applies as from SW 3	
1280*	Illegal working area limitation	Acknowledgement key
<i>Scan</i>	<ul style="list-style-type: none"> • Cyclic 	
<i>Effect</i>	The control automatically enters the maximum possible value for the traversing range in the working area limitation.	
<i>Explanation</i>	A value has been entered in the minimum or maximum axis-specific working area limitation which is outside the permissible traversing range of the axis in question.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check input • Check program (G25, G26, @..) • Take maximum traversing range from table (combination of axis-specific position control resolution and input resolution). 	
<i>Note</i>	Applies as from SW 3	
1284*	Fixed stop not reached	Reset key
<i>Scan</i>	In the block or on every block change	
<i>Effect</i>	<ul style="list-style-type: none"> • Alarm is triggered • Machining stops 	
<i>Explanation</i>	Alarm 1284* is output when the fixed stop is not between the starting and target position in the selection block and no R parameter has been programmed for function acknowledgement in the selection block.	
<i>Remedy</i>	Ensure that the fixed stop is between the starting and target position in the selection block. Also enter the R parameter number for the function acknowledgement in the selection block.	
<i>Note</i>	Applies as from SW 3	
1288*	No fixed stop axis	Reset key
<i>Scan</i>	In a block or on every block change	
<i>Effect</i>	<ul style="list-style-type: none"> • Programmed path in block is not traversed • Machining stops 	
<i>Explanation</i>	The function, Move Against Fixed Stop, has been selected for an axis which cannot traverse to the fixed stop.	
<i>Remedy</i>	Select the function Move Against Fixed Stop for an axis which is able to. Set MD 1804* for the axis which is to move against the fixed stop.	
<i>Note</i>	Applies as from SW 3	

1292*	Axis at fixed stop	Reset key
<i>Scan</i>	In a block or on every block change	
<i>Effect</i>	Path programmed in block is not traversed	
<i>Explanation</i>	The axes which have moved to the fixed stop cannot be included in an interpolation grouping while the function Move Against Fixed Stop is active.	
<i>Remedy</i>	Deselect the function move against fixed stop for the axis which is to be part of an interpolation grouping.	
<i>Note</i>	Applies as from SW 3	
1296*	Clamping tolerance exceeded	Reset key
<i>Scan</i>	While moving against fixed stop	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Setpoint 0 • No servo enable • Follow-up mode 	
<i>Explanation</i>	The alarm is triggered if the fixed stop is moved away from by more than the tolerance set in MD 1284*.	
<i>Remedy</i>	Check parameter settings	
<i>Note</i>	Applies as from SW 3	
1300*	Progr. axis is not a rotary axis	CANCEL
<i>Scan</i>	When executing AUTOMATIC, MDA and TEACH IN	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Machining stop 	
<i>Explanation</i>	G[...]103, G[...]104, G[...]105, G[...]119, G195, G295 not programmed in connection with a rotary axis.	
<i>Remedy</i>	Correct the block!	
<i>Note</i>	Applies as from SW 4; alarm is channel-specific and block-specific!	
1304*	Axis turning endlessly	Reset key
<i>Scan</i>	On block search with calculation	
<i>Effect</i>	<ul style="list-style-type: none"> • Cancellation of the block search 	
<i>Explanation</i>	An endlessly rotating rotary axis is programmed as contouring axis although the axis is still rotating endlessly.	
<i>Remedy</i>	Stop the endlessly rotating rotary axis and start the block search again.	
<i>Note</i>	Applies as from SW 4; alarm is channel-specific and block-specific!	
1308*	Error in progr. of sim. axis	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining abort 	
<i>Explanation</i>	The "Endlessly rotating rotary axis" is programmed with G[..]119P[..].. without the endless rotation being switched on.	
<i>Remedy</i>	Correct the block!	
<i>Note</i>	Applies as from SW 4; alarm is channel-specific and block-specific!	
1312*	Error in progr. of sim. axis	CANCEL
<i>Scan</i>	When executing a part program	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining abort 	
<i>Explanation</i>	The "Endlessly rotating rotary axis" has been incorrectly programmed.	
<i>Remedy</i>	Correct the block!	
<i>Note</i>	Applies as from SW 4; alarm is channel-specific and block-specific!	

1.5.1 Alarm description

1316*	Programmed position behind SW limit switch	Reset key
<i>Scan</i>	When executing a part program	
<i>Effect</i>	Processing stops at indicated block.	
<i>Explanation</i>	The programmed end point of the displayed axis (incl. the active offsets) lies behind the software limit switch.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Correct program • Check MD "1st and 2nd software limit switch plus/minus" • Check PLC interface signal "2nd software limit switch active" 	
	Alarm is displayed axis-specifically, for the block and channel in question.	
<i>Note</i>	Alarm applies as from SW 5	
1320*	Axis not in C axis mode	CANCEL
<i>Scan</i>	When traversing a C axis that is in spindle mode.	
<i>Effect</i>	Axis is not traversed.	
<i>Explanation</i>	A C axis has been programmed in spindle mode. The alarm is only output if MD 5025.5 is set.	
<i>Remedy</i>	Switch C axis to C axis mode.	
1324*	Tolerance for safe standstill exceeded	POWER ON
<i>Scan</i>	After selection of safe standstill After initiation of STOP C, D, E and expired timer	
<i>Effect</i>	Display of the alarm Initiation of STOP B and A	
<i>Explanation</i>	The axis has moved too far from the set position, i.e. further than permitted in MD 4180*: (standstill tolerance for safe operation).	
<i>Remedy</i>	Check the tolerance of the standstill monitoring: If the value does not match the accuracy and dynamic control response of the axis → increase the tolerance. If the value matches the accuracy and dynamic control response of the axis → inspect the machine for damage and repair the damage.	
<i>Note</i>	Applies as from SW 5.4.	
1328*	Safe speed exceeded	Reset key
<i>Scan</i>	After selection of safe speed	
<i>Effect</i>	Display of the alarm Initiation of STOP C, D, E (depending on configuration)	
<i>Explanation</i>	The axis has moved too quickly, i.e. faster than permitted in MD 4184*, 4188*, 4192*, 4196*: (limit value for safe speed 1, 2, 3, 4).	
<i>Remedy</i>	If no apparent operating error occurred: Check the input value of the MD, check the SGEs: of the 4 available speeds, was the correct one selected? If MDs and SGEs are correct, inspect the machine for damage and repair the damage.	
<i>Note</i>	Applies as from SW 5.4.	
1332*	Safe end position exceeded	Reset key
<i>Scan</i>	After enabling of the safe end position function	
<i>Effect</i>	Display of the alarm Initiation of STOP C, D, E (depending on configuration)	
<i>Explanation</i>	The axis has traveled beyond the end position entered in MD 4200*, 4204*: (upper limit for safe end position 1, 2) or MD 4208*, 4212*: (lower limit for safe end position 1, 2).	
<i>Remedy</i>	If no apparent operating error occurred: Check the input value of the MD, check the SGEs: of the 2 end positions, was the correct one selected? If MDs and SGEs are correct, inspect the machine for damage and repair the damage.	
<i>Continuation</i>	Cancel the user enable for this axis. Then activate the RESET key. The program is aborted and the alarm is cleared. Move the axis into the valid travel range in JOG mode. When the error in the NC program has been remedied and the position of the axis has been checked, the user enable can be reactivated and the program started.	
<i>Note</i>	Applies as from SW 5.4.	

1336*	Failure in a monitoring channel	Reset key
<i>Scan</i>	After selection of at least one safety function	
<i>Effect</i>	Display of the alarm NC START interlock STOP F STOP B and A on active SI function	
<i>Explanation</i>	The comparison of both monitoring channels has uncovered a difference between the input data or the monitoring results. One of the monitoring functions is no longer operating reliably, i.e. safe monitored operation is no longer possible.	
<i>Remedy</i>	Find the difference between the monitoring channels. The error code that indicates the cause appears in the following machine data: on 840C MD 301: diagnostics for STOP F (SI service display) on 611D MD 1395: diagnostics for STOP F (SI drive display) The meaning of the error code can be found in the error code table for STOP F on the 840C. It is possible that the safety-related machine data are no longer identical (load them again if necessary) or that the SGEs do not have the same signal level (measure again or check in the SI service display). If no such error is found, an error may have occurred in the CPU, such as a corrupt memory cell. This error can be transient (remedied by POWER ON) or permanent (reoccurs after POWER ON, in this case replace the hardware).	
<i>Continuation</i>	Remedy the error, and press the RESET key. The program is aborted. If safe monitoring was active, STOP B was also initiated automatically. In this case, it is necessary to switch the control off and on (POWER ON).	
<i>Note</i>	Applies as from SW 5.4.	

1.5.1 Alarm description

Table: Error codes for STOP F on 840C

No.	Name	Explanation	Cause, Remedy
0	No error	There is no error in this channel, however an error may have occurred in another channel.	Find the cause in the other channel and interpret the error code
1	Result list 1	Differences in the evaluation of the safe standstill/safe speed/safe end position functions in the NCK and drive monitoring channel	e.g. through unbalanced activation of the functions via the SGEs
2	Result list 2	Differences in the evaluation of the SN function in the NCK and drive monitoring channel	Check the tolerance of the cams
3	Actual position value	The difference between the actual position value in the NCK and drive monitoring channel is greater than the actual value cross-comparison tolerance specified in MD 4256* or MD 1342	Incorrect encoder evaluation (check MDs) different standstill positions stored
4	No cross-comparison	—	—
5	Function enables	MD 4500*, 4504* and MD 1301 are not identical	Enter the same MD values
6	Limit value for SG1	MD 4184* and MD 1331 are not identical	Enter the same MD values
7	Limit value for SG2	MD 4188* and MD 1331 are not identical	Enter the same MD values
8	Limit value for SG3	MD 4192* and MD 1331 are not identical	Enter the same MD values
9	Limit value for SG4	MD 4196* and MD 1331 are not identical	Enter the same MD values
10	Standstill tolerance	MD 4180* and MD 1330 are not identical	Enter the same MD values
11	Upper limit SE1	MD 4200* and MD 1334 are not identical	Enter the same MD values
12	Lower limit SE1	MD 4208* and MD 1335 are not identical	Enter the same MD values
13	Upper limit SE2	MD 4204* and MD 1334 are not identical	Enter the same MD values
14	Lower limit SE2	MD 4212* and MD 1335 are not identical	Enter the same MD values
15	Safe cam 1+ (+ Tolerance)	MD 4216* + MD 4248* and MD 1336 + MD 1340 are not identical	Enter the same MD values
16	Safe cam 1+	MD 4216* and MD 1336 are not identical	Enter the same MD values
17	Safe cam 1– (+ Tolerance)	MD 4232* + MD 4248* and MD 1337 + MD 1340 are not identical	Enter the same MD values
18	Safe cam 1–	MD 4232* and MD 1337 are not identical	Enter the same MD values
19	Safe cam 2+ (+ Tolerance)	MD 4220* + MD 4248* and MD 1336 + MD 1340 are not identical	Enter the same MD values
20	Safe cam 2+	MD 4220* and MD 1336 are not identical	Enter the same MD values
21	Safe cam 2– (+ Tolerance)	MD 4236* + MD 4248* and MD 1337 + MD 1340 are not identical	Enter the same MD values
22	Safe cam 2–	MD 4236* and MD 1337 are not identical	Enter the same MD values
23	Safe cam 3+ (+ Tolerance)	MD 4224* + MD 4248* and MD 1336 + MD 1340 are not identical	Enter the same MD values
24	Safe cam 3+	MD 4224* and MD 1336 are not identical	Enter the same MD values
25	Safe cam 3– (+ Tolerance)	MD 4240* + MD 4248* and MD 1337 + MD 1340 are not identical	Enter the same MD values
26	Safe cam 3–	MD 4240* and MD 1337 are not identical	Enter the same MD values
27	Safe cam 4+ (+ Tolerance)	MD 4228* + MD 4248* and MD 1336 + MD 1340 are not identical	Enter the same MD values
28	Safe cam 4+	MD 4228* and MD 1336 are not identical	Enter the same MD values
29	Safe cam 4– (+ Tolerance)	MD 4244* + MD 4248* and MD 1337 + MD 1340 are not identical	Enter the same MD values
30	Safe cam 4–	MD 4244* and MD 1337 are not identical	Enter the same MD values
31	Position tolerance	MD 4256* and MD 1342 are not identical	Enter the same MD values
32	Reference position tolerance	MD 4252* and MD 1344 are not identical	Enter the same MD values
33	Time/velocity switchover	MD 4264* and MD 1351 are not identical	Enter the same MD values
34	Tolerance time/ SGE switchover	MD 4260* and MD 1350 are not identical	Enter the same MD values

1.5.1 Alarm description

No.	Name	Explanation	Cause, Remedy
35	Delay time pulse deletion	MD 4268* and MD 1356 are not identical	Enter the same MD values
36	Time for pulse deletion check	MD 4272* and MD 1357 are not identical	Enter the same MD values
37	Transition time STOP C to SBH	MD 4276* and MD 1352 are not identical	Enter the same MD values
38	Transition time STOP D to SBH	MD 4280* and MD 1353 are not identical	Enter the same MD values
39	Transition time STOP E to SBH	MD 4284* and MD 1354 are not identical	Enter the same MD values
40	Stop reaction after SG	MD 4508*.4, 4508*.5 and MD 1361 are not identical	Enter the same MD values
41	Stop reaction after SE	MD 4508*.2, 4508*.3 and MD 1362 are not identical	Enter the same MD values
42	Shut-down speed pulse deletion	MD 4288* and MD 1360 are not identical	Enter the same MD values
43	Memory test stop reaction	—	—
44	Position actual value+limit value SG1	Position actual value (error code 3) different or MD 4184* and MD 1331[0] not equal (error code 6)	—
45	Position actual value–limit value SG1	Position actual value (error code 3) different or MD 4184* and MD 1331[0] not equal (error code 6)	—
46	Position actual value+limit value SG2	Position actual value (error code 3) different or MD 4188* and MD 1331[1] not equal (error code 7)	—
47	Position actual value–limit value SG2	Position actual value (error code 3) different or MD 4188* and MD 1331[1] not equal (error code 7)	—
48	Position actual value+limit value SG3	Position actual value (error code 3) different or MD 4192* and MD 1331[2] not equal (error code 8)	—
49	Position actual value–limit value SG3	Position actual value (error code 3) different or MD 4192* and MD 1331[2] not equal (error code 8)	—
50	Position actual value+limit value SG4	Position actual value (error code 3) different or MD 4196* and MD 1331[3] not equal (error code 9)	—
51	Position actual value–limit value SG4	Position actual value (error code 3) different or MD 4196* and MD 1331[3] not equal (error code 9)	—
52	Standstill position + tolerance	Position actual value (error code 3) different or MD 4180* and MD 1330 not equal (error code 10)	—
53	Standstill position – tolerance	Position actual value (error code 3) different or MD 4180* and MD 1330 not equal (error code 10)	—
54	Position actual value+ n_x +tolerance	Position actual value (error code 3) different or MD 4292* and MD 1346 not equal (error code 75) or MD 4256* and MD 1342 not equal (error code 31)	—
55	Position actual value+ n_x	Position actual value (error code 3) different or MD 4292* and MD 1346 not equal (error code 75)	—
56	Position actual value– n_x	Position actual value (error code 3) different or MD 4292* and MD 1346 not equal (error code 75)	—
57	Position actual value– n_x –tolerance	Position actual value (error code 3) different or MD 4292* and MD 1346 not equal (error code 75) or MD 4256* and MD 1342 not equal (error code 31)	—
58	Stop request	MD 1301 bit 6 is not 0	—
59	SG correction factor 1	MD 1301 bit 5 is not 0	—
60	SG correction factor 2	MD 1301 bit 5 is not 0	—
61	SG correction factor 3	MD 1301 bit 5 is not 0	—
62	SG correction factor 4	MD 1301 bit 5 is not 0	—
63	SG correction factor 5	MD 1301 bit 5 is not 0	—
64	SG correction factor 6	MD 1301 bit 5 is not 0	—
65	SG correction factor 7	MD 1301 bit 5 is not 0	—
66	SG correction factor 8	MD 1301 bit 5 is not 0	—
67	SG correction factor 9	MD 1301 bit 5 is not 0	—
68	SG correction factor 10	MD 1301 bit 5 is not 0	—
69	SG correction factor 11	MD 1301 bit 5 is not 0	—
70	SG correction factor 12	MD 1301 bit 5 is not 0	—
71	SG correction factor 13	MD 1301 bit 5 is not 0	—
72	SG correction factor 14	MD 1301 bit 5 is not 0	—

1.5.1 Alarm description

No.	Name	Explanation	Cause, Remedy
73	SG correction factor 15	MD 1301 bit 5 is not 0	–
74	SG correction factor 16	MD 1301 bit 5 is not 0	–
75	Velocity limit n_x	MD 4292* and MD 1346 not equal	Enter MDs equal
76	Stop reaction with SG1	MD 4508*.4, 4508*.5 and MD 1361 not equal	Enter MDs equal
77	Stop reaction with SG2	MD 4508*.4, 4508*.5 and MD 1361 not equal	Enter MDs equal
78	Stop reaction with SG3	MD 4508*.4, 4508*.5 and MD 1361 not equal	Enter MDs equal
79	Stop reaction with SG4	MD 4508*.4, 4508*.5 and MD 1361 not equal	Enter MDs equal
80	SI modulo value for SN	MD 1367 is not 0	Enter MDs equal
81	Speed tolerance for SBR	MD 4296* and MD 1348 not equal	Enter MDs equal
1000	Control timer expired	The SGE modification timer did not expire within the time of the control timer (i.e. too many switching operations in SGEs).	e.g. contact problems (loose contact)
1001	Control timer initialization error	The SGE modification timer did not start the control timer.	–
1002	User enable timer expired	Different status of user enable from drive and NCK	–
1003	Reference tolerance violated	The comparison of stored standstill position and current position has a greater deviation than specified in MD 4252*: actual value tolerance (referencing) or MD 1344	–
1004	Plausibility violation of user enable	The user enable has been specified for an axis which is – already referenced – not yet referenced	–
1005	Pulses already deleted on test stop selection	The "pulses are deleted" signal is already active on test stop selection	Test stop selection on pulse enable error during wiring of the "pulses are deleted" SGE
1006	Error on SGA forced dynamic response	An error was detected on the cyclic check of the SGAs.	–
1007	Breakdown of the communication between PLC and drive	If the drive releases a breakdown in communication, either the PLC or the NC has broken down.	
1008	Erroneous data transfer between PLC and drive	The data transfer of the SGEs/SGAs between PLC and drive is guaranteed by a checksum. In the event of an error, the calculated checksum does not coincide with the transferred checksum. If the stop is released by the drive, either the PLC or the NC has broken down.	
Note: If the value 12 is stored in this value, the cross-comparison has detected a difference in the MD for lower limit SE1 in the NCK and drive monitoring channel.			

1340* Axis has not been referenced safely*Scan* After selection of SE/SN*Effect* Display of the alarm
The "axis has been referenced safely" SGA is not enabled
The safe end positions are not active
The safe cams are output, but are not safe*Explanation* 1. The axis has not been referenced, or
2. The user enable for this axis is missing or has been canceled. This can occur, for example, if the axis is moved after the machine is switched off, with the result that the standstill position, which was stored before the machine was switched off, is no longer correct.*Remedy* for 1. Reference the axis
for 2. Activate the user enable
The alarm disappears automatically when the enable has been activated*Warning!* If the axis has not been referenced safely, and the user enable is not active:
• The safe cams are active but not yet safe
• The safe end positions are not yet active*Note* Applies as from SW 5.4.**1344* Test stop running***Scan* After selection of at least one safety function*Effect* Display of the alarm*Explanation* The correct operation of the shut-down path is tested by enabling the "test stop selection" SGE.*Remedy* One is not necessary. It is used exclusively to inform the operator. The alarm disappears automatically when the delay time defined in MD 4272*: (time for checking pulse deletion) expires, if the control detects pulse deletion, i.e. if the test was successfully completed.*Note* Applies as from SW 5.4.**1348* Stop E triggered****Reset key***Scan* After selection of SG, SE*Effect* Interlocking of NC START
Initiation of ESR
Activation of SBH
Follow-up mode for all axes of this mode group
Removal of Mode Group Ready
Interruption of machining*Explanation* This alarm occurs with the alarms "safe speed exceeded" or "safe position exceeded" (when configured accordingly in MD 4508* Bit 4: (STOP D/E selection for SG) or MD 4508* Bit 2: (STOP D/E selection for SE). It indicates the initiation of a configured ESR and the internal activation of safe standstill.*Remedy* Remedy the causes of "safe speed exceeded" or "safe end position exceeded" (see description of the alarms).*Continuation* Remedy the error and press the RESET key (the program is aborted and must be restarted).*Note* Applies as from SW 5.4.**1352* Stop D triggered****Reset key***Scan* After selection of SG, SE*Effect* Interlocking of NC START
Braking on the path
Activation of SBH
Interruption of machining*Explanation* This alarm occurs with the alarms "safe speed exceeded" or "safe position exceeded" (when configured accordingly in MD 4508* Bit 4: (STOP D/E selection for SG) or MD 4508* Bit 2: (STOP D/E selection for SE). It indicates the initiation of "braking on the path" and the internal activation of "safe standstill monitoring".*Remedy* Remedy the causes of "safe speed exceeded" or "safe end position exceeded" (see description of the alarms).*Continuation* Remedy the error and press the RESET key (the program is aborted and must be restarted).*Note* Applies as from SW 5.4.

1.5.1 Alarm description

1356*	Stop C triggered	Reset key
<i>Scan</i>	After selection of SG, SE	
<i>Effect</i>	Interlocking of NC START Follow-up mode for all axes of this mode group Removal of Mode Group Ready Interruption of machining	
<i>Explanation</i>	This alarm occurs with the alarms "safe speed exceeded" or "safe position exceeded" (when configured accordingly in MD 4508* Bit 4: (STOP D/E selection for SG) or MD 4508* Bit 2: (STOP D/E selection for SE). It indicates the initiation of "braking at the current limit" and the internal activation of the "safe standstill".	
<i>Remedy</i>	Remedy the causes of "safe speed exceeded" or "safe end position exceeded" (see description of the alarms).	
<i>Continuation</i>	Remedy the error and press the RESET key (the program is aborted and must be restarted).	
<i>Note</i>	Applies as from SW 5.4.	
1360*	Stop B triggered	POWER ON
<i>Scan</i>	After selection of SG, SE after selection of SBH After initiation of STOP C, D, E After initiation of STOP F and activated SBH/SG or SE, SN	
<i>Effect</i>	Interlocking of NC START Follow-up mode for all axes of this mode group Removal of Mode Group Ready Interruption of machining Pulse deletion after timer expires (SGA)	
<i>Explanation</i>	This alarm occurs with the alarm "tolerance for safe standstill exceeded" or alarm "STOP F triggered". It indicates the initiation of "braking at the current limit" and the internal activation of the timer for switchover to STOP A (see MD 4268*: (pulse deletion delay time).	
<i>Remedy</i>	Remedy the causes of "tolerance for safe standstill exceeded" or for "STOP F triggered" (see description of the alarms).	
<i>Continuation</i>	Not possible. Acknowledgement of the alarm only possible by POWER ON.	
<i>Note</i>	Applies as from SW 5.4.	
1364*	Stop A triggered	POWER ON
<i>Scan</i>	After selection of SBH After initiation of STOP B	
<i>Effect</i>	Interlocking of NC START Removal of Mode Group Ready Interruption of machining Immediate pulse deletion (SGA)	
<i>Explanation</i>	This alarm occurs with the alarm "tolerance for safe standstill exceeded" or as a result of STOP B or an unsuccessful test stop. It indicates the initiation of a "pulse deletion".	
<i>Remedy</i>	Remedy the causes of "tolerance for safe standstill exceeded" or for "STOP F triggered" (see description of the alarms).	
<i>Continuation</i>	Not possible. Acknowledgement of the alarm only possible by POWER ON.	
<i>Note</i>	Applies as from SW 5.4.	
1368*	Protection zone collision plus	RESET
<i>Scan</i>	Cyclic with active function "Collision monitoring"	
<i>Parameters</i>	Axis number	
<i>Effect</i>	Machining standstill; disabling of NC Start	
<i>Explanation</i>	Overlap of two protection zones has been recognized	
<i>Remedy</i>	Travel free and trigger mode group reset	
<i>Note</i>	Applies as from SW 6.	

1372*	Protection zone collision minus	RESET
<i>Scan</i>	Cyclic with active function "Collision monitoring"	
<i>Parameters</i>	Axis number	
<i>Effect</i>	Machining standstill; disabling of NC Start	
<i>Explanation</i>	Overlap of two protection zones has been recognized	
<i>Remedy</i>	Travel free and trigger mode group reset	
<i>Note</i>	Applies as from SW 6.	
1376*	Check absolute value encoder position	Cancel key
<i>Scan</i>	<ul style="list-style-type: none"> Loading of complete NC MD files Absolute value encoder available and range expansion of Endat absolute value encoder parameterized 	
<i>Effect</i>	None	
<i>Explanation</i>	Startup, which is to be performed by loading an NC MD file, has possibly not yet been terminated on an axis with absolute value encoder. The start-up engineer must then decide whether further startup steps have to be carried out. This alarm remains present even after Power Off.	
<i>Remedy</i>	<ul style="list-style-type: none"> Bring axes to closed-loop control mode (terminate possible initial clear mode) and check the actual position displayed. If the actual position is not correct (e.g. after loss of data in SRAM through hardware replacement), startup steps must be carried out. Acknowledge alarm (not possible in initial clear mode!) 	
2000*	LEC – grid spacing illegal	POWER ON
<i>Scan</i>	Cyclic	
<i>Effect</i>	Removal of NC START	
<i>Explanation</i>	In the case of the spindle (e.g. synchronous spindle mode), a modulo value has been entered for the axis concerned which cannot be divided exactly into 360°, which means that the grid spacing is not equal.	
<i>Remedy</i>	Check NC MD* 3440*	
<i>Note</i>	Applies as from SW 3	
2001*	Speed setpoint warning limit responded	Reset key
<i>Scan</i>	Cyclic	
<i>Effect</i>	Interlocking of NC START	
<i>Explanation</i>	<ul style="list-style-type: none"> The setpoint on the DAC is higher than entered in NC MD 268* "Max. speed setpoint (DAC)". It is not possible to increase the setpoint any further. The alarm 2001* "Speed setpoint warning limit" can occur when an M19 positioning is requested while the drive unit is not ready (e.g. setpoint cable break: actuator switched off; actuator not enabled by PLC). An incorrect feedback polarity has been parameterized in the spindle positioning mode (sign error). 	
<i>Remedy</i>	<ul style="list-style-type: none"> Traverse at slower speed Check the actual values (encoder) Check NC MD "Max. speed setpoint (DAC)" Check the drive actuator 	

1.5.1 Alarm description

2003*	Zero speed monitoring	Reset key
<i>Scan</i>	<ul style="list-style-type: none"> • When accelerating • When at zero speed • When clamped • When decelerating (delay) 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlock of NC START • Interlock of Mode Group Ready • Setpoint 0 • Servo enable is removed on expiry of the time in NC-MD "Cutoff delay servo enable" • Follow-up mode 	
<i>Explanation</i>	<ul style="list-style-type: none"> • When positioning, the following error could not be eliminated faster than the time given in NC-MD "Cutoff delay servo enable". • When clamped, the limit defined in the NC-MD "Zero speed monitoring" has been exceeded. • Mechanically clamped spindle has been pushed out of position. • Error on the activating device, on the tachometer, on the motor, in the mechanical construction, in the CNC measuring circuit hardware or on/in the encoder. • Wrong setpoint output assignment specified • When starting up: wrong sense of position control 	
<i>Remedy</i>	<ul style="list-style-type: none"> • NC-MD "Zero speed monitoring" must be greater than NC-MD "Exact stop limit coarse". • NC-MD "Cutoff delay servo enable" must be great enough for the following error to be eliminated within this time (applies only when NC-MD "Delay zero speed monitoring" = 0). • NC-MD "Delay zero speed monitoring" must be great enough for the following error of the various spindles to be eliminated within the time entered. • Check actual values (encoder) and sense of position control. 	
2007*	There is no measuring circuit	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> • On POWER ON 	
<i>Effect</i>	<ul style="list-style-type: none"> • Spindle is not processed • Servo disable of spindle concerned • Removal of Mode Group Ready • Interlocking of NC START • Interlocking of NC RDY relay 	
<i>Explanation</i>	<ul style="list-style-type: none"> • MD 400* and/or MD 460* indicates an empty submodule slot on a measuring circuit module with submodules. Example: MD 460* = 01090000, the first measuring circuit module is an HMS module with empty submodule slot 2. • Measuring circuit module has been removed or is defective. 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Compare MD 400* and/or MD 460* with the hardware configuration and correct. 	
2008*	Closed-loop hardware spindle	POWER ON
<i>Scan</i>	Cyclic	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Setpoint relay drops out, setpoint 0 • Removal of Mode Group Ready • Spindle servo enable is removed after the time in MD "Delay for servo enable" has elapsed. 	
<i>Explanation</i>	<p>The measuring circuit difference signals</p> <ul style="list-style-type: none"> • are not in phase • have a short circuit to ground • are absent 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check whether the measuring circuit connector has been inserted • The measuring circuit short circuit connector can be slotted in to check whether the measuring circuit module is functioning correctly. • Check the difference signals with the oscilloscope • Replace the encoder/cable 	

2009*	Contamination measuring system spindle	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> • Cyclic 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Interlocking of Mode Group Ready 	
<i>Explanation</i>	<ul style="list-style-type: none"> • Where measuring systems have a contamination signal (e.g. EXE) an error is sent to the NC from the measuring system. 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check the measuring system against the manufacturer's specifications. 	
2010*	Pulse code monitoring	Reset key
<i>Scan</i>	<ul style="list-style-type: none"> • Cyclic 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of Mode Group Ready • Interlocking of NC START • Alarm causes machining stop 	
<i>Explanation</i>	<ul style="list-style-type: none"> • Transmission error or interference from encoder 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check encoder, cable, connector 	
2011*	Zero marks monitoring has responded	Reset key
<i>Scan</i>	<ul style="list-style-type: none"> • Cyclic, depending on the tolerance band set for the difference pulses 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Machining stops 	
<i>Explanation</i>	Pulses have been lost per encoder revolution, above the permitted tolerance band, due to transmission errors, interference or too high speed. The reference counter checks this zero mark.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check the encoder pulses • Check transmission path 	
2014*	Setpoint or actual speed alarm limit exceeded	Reset key
2014*	Speed setpoint value alarm limit responded	Reset key
<i>Scan</i>	Cyclic	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Interlocking of Mode Group Ready • Setpoint 0 • Servo enable is removed after the time in NC MD "Cutout delay servo enable" has elapsed • Follow-up mode 	
<i>Explanation</i>	<ul style="list-style-type: none"> • The motor could not follow the entered speed setpoint. • During start-up: incorrect position control direction, incorrect spindle multgain • The speed actual value exceeds the maximum spindle speed + tolerance <p>If the service number 309 is indicated here, the reason for the alarm is a format overflow, which can be avoided by reduction of the resolution. Another reason can also be the resolution of the C axis assigned.</p>	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check the drive • Check position control direction • Match spindle multgain (MD 468*) • Check speed setpoint cable • Check actual values (pulse encoder) • Increase spindle speed tolerance (MD 445*) • Increase acceleration time constant (MD 419* – 426*) 	
<i>Note</i>	<ul style="list-style-type: none"> • Alarm "Setpoint or actual speed alarm limit exceeded": up to SW 3 • Alarm "Speed setpoint alarm limit actuated": as from SW 4 	
2015*	Drift too high	Reset key
<i>Scan</i>	With input of NC MD 401* or with semi-automatic drift compensation (axis only)	
<i>Effect</i>	Interlocking of NC START	
<i>Explanation</i>	The entered drift is greater than approx. 500 mV. In the case of semi-automatic drift compensation, the drift to be compensated for by the NC has risen to above approx. 500 mV.	
<i>Remedy</i>	Check whether the drift has been compensated for correctly at the driving unit.	

1.5.1 Alarm description

2016*	Terminal assigned more than once	POWER ON as from SW 3: Reset key
<i>Scan</i>	<ul style="list-style-type: none"> During machine data input for spindle assignment 	
<i>Effect</i>	<p>No processing of the spindles of which the corresponding connection number has been assigned more than once.</p> <ul style="list-style-type: none"> Servo disable for the spindle in question 	
<i>Explanation</i>	<ul style="list-style-type: none"> Removal of Mode Group Ready Interlocking of NC START Interlocking of NC RDY relay 	
<i>Remedy</i>	<ul style="list-style-type: none"> A connection number of a measuring circuit module is entered several times in MD 400* and/or MD 460*. Example: MD 4600 = 01060000, MD 4605 = 01060000. Connection number 6 of the 1st measuring circuit module is thus assigned several times. Check and correct MD 400* and/or MD 460*. 	
2018*	Speed controller limitation	Reset key
<i>Scan</i>	Cyclic	
<i>Effect</i>	<ul style="list-style-type: none"> Interlocking of Mode Group Ready Interlocking of NC START Alarm causes machining to stop 	
<i>Explanation</i>	<ul style="list-style-type: none"> Speed controller limitation triggered 	
<i>Remedy</i>	<ul style="list-style-type: none"> Check current control. Set speed control loop slower. Check SIMODRIVE Check machine 	

2019*	Parameterization error NC MD	Reset key
2019*	Parameterization error NC–MD	Reset key
<i>Scan</i>	<ul style="list-style-type: none"> At POWER ON or warm restart 	
<i>Effect</i>	<ul style="list-style-type: none"> The spindles concerned are switched to follow-up mode Machining stops Interlocking of NC START Mode Group Ready removed 	
<i>Explanation</i>	<p>Input error in machine data, e.g.</p> <ul style="list-style-type: none"> Ratio of interpolator pulse to position control pulse too great because MD 160 > 80 Internal servo gain (K_V) factor too large due to <ul style="list-style-type: none"> Servo gain factor (469*) Multgain (468*) Pulse weighting No whole-number ratio between entry in MD 165 (timing ratio) and MD 160 (fine interpolation) Incorrect measuring system adaptation in MD 455* to MD 456* (values selected too large) General parameterization error of a drive MD 	
<i>Remedy</i>	<ul style="list-style-type: none"> The pulse multiplication value entered for the high-resolution measuring system is impermissible. The following values are permissible: 1, 2, 4, 8, 16, 32, 64 and 128. Check and new input of the corresponding machine data. Error in parameterization of the SI machine data. The SPINDLE service display displays the service number for parameterization errors and with it the exact cause (see Diagnostics Guide, Section Parameterization errors spindle/axis). 	
<i>Note</i>	<ul style="list-style-type: none"> Alarm "Parameterization error drive MD": up to SW 3 Alarm "Parameterization error NC–MD": as from SW 4 	
2021*	Spindle not synchronized	Reset key
<i>Scan</i>	On execution of an M19 command	
<i>Effect</i>	Machining stops	
<i>Explanation</i>	M19 was used to approach a spindle position, although the spindle had not yet been synchronized.	
<i>Remedy</i>	Synchronize the spindle; execute the M19 again.	
2028*	MD M19 not selected	Reset key
<i>Scan</i>	When executing in AUTOMATIC mode or input in MDA or external	
<i>Effect</i>	<ul style="list-style-type: none"> Machining stops <p>"M19 S..." has been programmed in the part program although this function is not implemented in the control.</p>	
<i>Explanation</i>	<ul style="list-style-type: none"> Check program 	
<i>Remedy</i>	<ul style="list-style-type: none"> Check NC MD 	

1.5.1 Alarm description

2029*	Drive fault	Reset key
<i>Scan</i>	<ul style="list-style-type: none"> • 611–D alarm 300100 “Drive link off” • Power On / Reset alarms (ZK1) from 611–D 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Interlocking of Mode Group Ready • Setpoint 0 • Setpoint enable is removed after the time set in NC MD “Switch off delay servo enable” (not with alarm “Drive link off”) • Follow up mode • 611–D status signals “Drive ready” and “Drive connected” are reset • Further detailed information on the cause in MMC diagnosis display 	
<i>Note</i>	Applies as from SW 3	
2030*	Spindle speed too high	Reset key
<i>Scan</i>	Only when NC MD “Encoder available” is set	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining stops • Interlocking of NC START • Interlocking of Mode Group Ready 	
<i>Explanation</i>	The spindle speed is higher than defined in the machine data or setting data.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Program a smaller S value • NC MD “Max spindle speed for 1st to 8th gearing” • NC MD “Tolerance band of max. spindle speed” • NC MD “Max. spindle speed” • Check PLC gear speed • Check G92 S... at “v = constant” • Check setting data of spindle speed limitation • Program G26 S... 	
2032*	Output not available	POWER ON
<i>Scan</i>	When setpoint incorrectly assigned	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Interlocking of Mode Group Ready • Interlocking of NC Ready • Setpoint 0 • No servo enable • Follow-up mode 	
<i>Explanation</i>	A digital setpoint output that does not exist has been assigned	
<i>Remedy</i>	Check the setpoint output machine data	
<i>Note</i>	Applies as from SW 3	
2033*	Drive fault	POWER ON
<i>Scan</i>	<ul style="list-style-type: none"> • 611–D alarms <ul style="list-style-type: none"> – Drive configuration description incorrect <ul style="list-style-type: none"> — Drive number — Drive type (FDD/MSD) — Module type (single-axis/double-axis module) – Ramp up error (error during 611–D rump-up, error during data matching) – Transmission line fault (CRC, bus timeout) 	
<i>Effect</i>	<ul style="list-style-type: none"> • Interlocking of NC START • Interlocking of Mode Group Ready • Interlocking of NC Ready • Setpoint 0 • Servo enable removed after time set in NC MD “Switchoff delay servo enable” has passed • Follow-up mode 	
<i>Remedy</i>	Additional detailed information about the cause is given in the MMC diagnosis display	
<i>Note</i>	Applies as from SW 3	

2057*	Emergency retraction triggered	Reset key
<i>Scan</i>	Cyclic in servo cycle, when LINK ON is set for the following spindle (from servo).	
<i>Effect</i>	Machining interrupted, interlocking of NC START; Mode Group Ready cancelled	
<i>Explanation</i>	The threshold MD "Emergency retraction threshold" programmed for synchronism monitoring has been exceeded and emergency retraction triggered. Prerequisite: Enable with PLC interface signal "Emergency retraction enabled".	
<i>Remedy</i>	Check the drives; check the speed and acceleration limit values of the following spindle; check the emergency retraction threshold; check the link factors.	
<i>Note</i>	Applies as from SW 3	
2058*	Overlay of following axis not enabled	Acknowledgement key
<i>Scan</i>	When path for following axis defined (NCK).	
<i>Effect</i>	Setpoint is not output, i.e. the overlay is not executed.	
<i>Explanation</i>	Overlaid offset of the following spindle although the PLC interface signal "Enable FA overlay" is not set.	
<i>Remedy</i>	Traverse a following axis with fictitious leading axis or set PLC interface signal "Enable FA overlay".	
<i>Note</i>	Applies as from SW 3	
2059*	Speed limit exceeded	Acknowledgement key
<i>Scan</i>	Cyclic in servo cycle, when LINK ON is set for following spindle (from servo)	
<i>Effect</i>	<ul style="list-style-type: none"> • No reaction • Machining is not interrupted <p>The speed of the following spindle is limited to the programmed maximum value; the setpoint determined by the compensatory controller is not included in the calculation.</p>	
<i>Explanation</i>	The maximum value programmed for the following spindle has been exceeded. Synchronism is at risk	
<i>Remedy</i>	<ul style="list-style-type: none"> • Reduce feedrate or speed of leading spindles • Check the speed limit value • Check the link factors 	
<i>Note</i>	Applies as from SW 3	
2060*	Acceleration limit exceeded	Acknowledgement key
<i>Scan</i>	Cyclic in servo cycle, when LINK ON is set for the following spindle and MD bit "Suppress acceleration limitation" (MD 526*) is not set (from servo).	
<i>Effect</i>	<ul style="list-style-type: none"> • No reaction • Machining is not interrupted <p>Interface signal "Acceleration limitation synchronous" is set, spindle continues to travel at maximum acceleration; any suppressed TSW are traversed afterwards. If interface signal "Acceleration limitation synchronous" is not set, suppressed partial setpoints are not traversed. The setpoint determined by the compensatory controller is not included in the calculations.</p>	
<i>Explanation</i>	Maximum value programmed for the following spindle has been exceeded. Synchronism is at risk.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Reduce the acceleration of the leading spindles • Check the acceleration limit value • Check the link factors 	
<i>Note</i>	Applies as from SW 3	

1.5.1 Alarm description

2061*	Aut. contr. corr. of following spindle	Reset key
<i>Cause</i>	An error has occurred which has cancelled "Mode group ready".	
<i>Scan</i>	Cyclic in servo cycle when LINK ON is set	
<i>Effect</i>	<ul style="list-style-type: none"> • Machining is interrupted • Interlocking of NC START • Switchover to actual position link 	
<i>Explanation</i>	An axis/spindle within the mode group is subject to an error which usually results in switchover to follow-up mode. As long as the following axis is not affected by this fault, the link is maintained until the "Delay controlled follow-up" has come to an end.	
<i>Remedy</i>	Rectify axis/spindle error.	
<i>Note</i>	Applies as from SW 3	
2065*	Reconfiguration not allowed	Acknowledgement key
<i>Scan</i>	With RECONFIGURATION using the G function (G401), i.e. when a leading axis is added or removed, the link structure is altered or with CLEAR CONFIGURATION (from NCK).	
<i>Effect</i>	Interlocking of NC START	
<i>Explanation</i>	Reconfiguration permitted not set (MD 525*, bit 1)	
<i>Remedy</i>	Correct input, set MD bit	
<i>Note</i>	Applies as from SW 3	
2066*	GI configuration not allowed	Acknowledgement key
<i>Scan</i>	When programming DEFINE CONFIGURATION with G function (from NCK).	
<i>Effect</i>	<ul style="list-style-type: none"> • Command is not executed • Interlocking of NC START 	
<i>Explanation</i>	Possible causes: <ul style="list-style-type: none"> • Do leading and following axes have a position measuring system (encoders)? • Is the following axis linked to itself as a leading axis? • Can the axis be a following axis (MD 1844*)? • Link structure switchover not permissible (MD 1844*)? • Link type for the LA/LS not allowed (MD 1456*/496*)? • The following axes must always be real available axes, i.e. a measuring circuit (POS encoder) must be defined. A measuring circuit must be defined for leading axes/spindles with link structure K2 (actual position link). • Leading axes/spindles and following axis are not in the same mode group. • Not exactly one leading spindle defined for following spindle. • One of the axes in the GI grouping is a fictitious transformation axis. • No synchronous positions have been defined for on-the-fly synchronization. 	
<i>Remedy</i>	Check configuration	
<i>Note</i>	Applies as from SW 3	
2067*	Change of KF not allowed	Acknowledgement key
<i>Scan</i>	When entering a new link factor via G function (from NCK).	
<i>Effect</i>	<ul style="list-style-type: none"> • Command is not executed, the previous link factor is maintained • Interlocking of NC START 	
<i>Explanation</i>	The link factor default setting must not be changed (MD 525*, bit 2).	
<i>Remedy</i>	Change default setting if necessary.	
<i>Note</i>	Applies as from SW 3	

2068*	Link factor KF illegal	Acknowledgement key
<i>Scan</i>	When entering a new link factor via G function (from NCK).	
<i>Effect</i>	<ul style="list-style-type: none"> • Command is not executed, the previous link factor is maintained • Interlocking of NC START 	
<i>Explanation</i>	Denominator J=0 programmed	
<i>Remedy</i>	Correct link factor	
<i>Note</i>	Applies as from SW 3	
2069*	Overwriting of position not allowed	Acknowledgement key
<i>Scan</i>	When programming a position with G1 command.	
<i>Effect</i>	<ul style="list-style-type: none"> • G command not executed • Interlocking of NC START 	
<i>Explanation</i>	G1 positions must not be overwritten (enable with MD 525*, bit 3)	
<i>Remedy</i>	Correct input	
<i>Note</i>	Applies as from SW 3	
2070*	Reconfiguration/deletion not allowed	Reset key
<i>Scan</i>	At RECONFIGURATION via G function (G401), i.e. addition, cancellation of a leading spindle or changing a coupling structure or on DELETE CONFIGURATION (from NCK).	
<i>Effect</i>	Interlocking of NC START; NC Stop, stopping of the channel, command is not executed, JOG mode still possible.	
<i>Explanation</i>	A RECONFIGURATION or DELETE CONFIGURATION is not allowed without being preceded by LINK_OFF. Reconfiguration not allowed (MD 525, bit 1) New configuration block; following spindle already exists	
<i>Remedy</i>	Precede by LINK_OFF for the specified G1 combination.	
2073*	Change of link factor KF illegal	Reset key
<i>Scan</i>	When entering a new link factor with G function (from NCK).	
<i>Effect</i>	Command is not executed, the previous link factor is maintained. Interlocking of NC Start; NC Stop, channel stopped: JOG mode still possible.	
<i>Explanation</i>	The link factor entered is not in the range $0.00000001 \leq /KF/ \leq 10.000000$ or denominator J=0 or the individual values are so large that internal overflows occur.	
<i>Remedy</i>	Correct the link factor KF.	
2074*	Change of link factor KF not allowed	Reset key
<i>Scan</i>	When entering a new link factor with G function (from NCK).	
<i>Effect</i>	<ul style="list-style-type: none"> • Command is not executed, the previous link factor is maintained • Interlocking of NC START • NC STOP • Channel is stopped: JOG mode still possible 	
<i>Explanation</i>	The link factor must not be switched over from the default setting (MD525*).	
<i>Remedy</i>	Change default setting if necessary.	

1.5.1 Alarm description

2075*	GI configuration not allowed	Reset key
<i>Scan</i>	When programming DEFINE CONFIGURATION with G function (from NCK).	
<i>Effect</i>	<ul style="list-style-type: none"> • Command is not executed • Interlocking of NC START • NC STOP • Channel stopped: JOG mode still possible 	
<i>Explanation</i>	Possible causes: <ul style="list-style-type: none"> • Do leading and following axes have a position measuring system (encoders)? • Is the following axis linked to itself as a leading axis? • Can the axis be a following axis (MD 1844*)? • Link structure switchover not permissible (MD 1844*) • Link type for the LA/LS not allowed (MD 1456*/496*)? • The following axes must always be real available axes, i.e. a measuring circuit (POS encoder) must be defined. A measuring circuit must be defined for leading axes/spindles with link structure K2 (actual position link). • Leading axes/spindles and following axis are not in the same mode group. • Not exactly one leading spindle defined for following spindle. • One of the axes in the GI grouping is a fictitious transformation axis. • No synchronous positions have been defined for on-the-fly synchronization. 	
<i>Remedy</i>	Check configuration	
<i>Note</i>	Applies as from SW 3	
2076*	Following spindle not defined	Reset key
<i>Scan</i>	When programming a spindle as a following spindle which has not been defined as such (from NCK).	
<i>Effect</i>	<ul style="list-style-type: none"> • G command is not executed • Interlocking of NC START • NC STOP • Channel stopped: JOG mode still possible 	
<i>Explanation</i>	A GI grouping with the stated axis as a following spindle does not exist.	
<i>Remedy</i>	Correct input.	
<i>Note</i>	Applies as from SW 3	
2077*	Spindle not in spindle mode	Reset key
<i>Scan</i>	The programmed following spindle has a C axis which has been selected for C axis mode.	
<i>Effect</i>	<ul style="list-style-type: none"> • Command is not executed • Interlocking of NC START • NC STOP • Channel stopped: JOG mode still possible 	
<i>Explanation</i>	When programming a following spindle which is assigned to a C axis, this C axis must be in spindle mode. This is not necessary with G401, but a GI grouping must not be defined for the C axis at the same time.	
<i>Remedy</i>	Correct mode/input.	
2078*	Leading spindle not defined	Reset key
<i>Scan</i>	When programming a spindle as a leading spindle or an axis as a leading axis which have not been defined as such (from NCK).	
<i>Effect</i>	<ul style="list-style-type: none"> • G command is not executed • Interlocking of NC START • NC STOP • Stop channel: JOG mode is still possible 	
<i>Explanation</i>	A GI grouping with the stated axis as a leading axis does not exist	
<i>Remedy</i>	Correct input.	
<i>Note</i>	Applies as from SW 3	

2079*	Overwriting of GI position not allowed	Reset key
<i>Scan</i>	When programming a position with GI command.	
<i>Effect</i>	<ul style="list-style-type: none"> • G command is not executed • Interlocking of NC START • NC STOP • Channel stopped: JOG mode still possible 	
<i>Explanation</i>	The GI positions must not be overwritten (enabled with MD 525*, bit 3)	
<i>Remedy</i>	Correct input.	
<i>Note</i>	Applies as from SW 3	
2080*	Wrong spindle assignment to channel	Reset key
<i>Scan</i>	When programming a position with GI command.	
<i>Effect</i>	<ul style="list-style-type: none"> • G command is not executed • Interlocking of NC START • NC STOP • Channel stopped: JOG mode still possible 	
<i>Explanation</i>	The GI command for the following spindle must only be programmed in the channel to which the spindle is assigned	
<i>Remedy</i>	Change channel or alter assignment.	
<i>Note</i>	Applies as from SW 3	
2081*	Retraction spindle is following spindle	Reset key
<i>Scan</i>	On decoding the retraction command	
<i>Effect</i>	None	
<i>Explanation</i>	Alarm occurs when a following spindle has been defined as retraction spindle because the link is violated by the retraction. Also, the overlay must be enabled by the PLC.	
<i>Remedy</i>	Select another retraction spindle.	
<i>Note</i>	Applies as from SW 4	
2082*	Retraction spindle in several channels	Reset key
<i>Scan</i>	On decoding G425/6	
<i>Effect</i>	Machining interrupt	
<i>Explanation</i>	A spindle has been programmed as retraction axis that has already been selected in another channel for retraction.	
<i>Remedy</i>	Remove spindle from the retraction block.	
<i>Note</i>	Applies as from SW 4	
2084*	IKA path reconfiguration not allowed	Reset key
<i>Scan</i>	When programming G401/G411	
<i>Effect</i>	Interlocking of NC Start Interlocking of NC Stop	
<i>Explanation</i>	<ul style="list-style-type: none"> • An IKA path has been defined that is already configured. • An attempt has been made to delete G411 – an IKA path that is still active. 	
<i>Remedy</i>	Activate an IKA path that is not yet configured. On deselecting: switch IKA inactive.	
2085*	Error in IKA path input/output	Reset key
<i>Scan</i>	When programming G410/G411/G412	
<i>Effect</i>	Interlocking of NC Start, NC Stop	
<i>Explanation</i>	If an input/output value is specified with G410/G411/G412 that does not correspond to the configuration or is not permissible, this alarm is triggered.	
<i>Remedy</i>	Specify input/output correctly or omit I/O designation with G410.	

1.5.1 Alarm description

2086*	Programmed spindle is slave	Reset key
<i>Scan</i>	<ul style="list-style-type: none"> • Setpoint specified for a slave spindle • Initiate oscillation mode for a slave spindle • M19 for a slave spindle 	
<i>Explanation</i>	<ul style="list-style-type: none"> • Interlocking of NC Start • Follow-up mode • Cancellation of Mode Group Ready • Processing interrupt 	
<i>Explanation</i>	The designated spindle is coupled to its master spindle through a speed setpoint coupling. Setpoints should therefore not be specified.	
<i>Remedy</i>	Setpoints should not be specified for the slave spindle.	
<i>Note</i>	Applies as from SW 4.4	
2087*	No synchronous/switching positions defined	Reset key
<i>Scan</i>	When synchronizing or switching on in relation to a position from PLC.	
<i>Effect</i>	Interlocking of NC START, MACHINING STOP	
<i>Explanation</i>	An attempt has been made to synchronize master and slave axes/spindles from PLC, or to switch on with reference to a position, without there being any valid switching or synchronizing positions. Synchronization or switching on with reference to a position is therefore not possible.	
<i>Remedy</i>	For example, specified positions through the GI input display or G403.	
<i>Note</i>	Applies as from SW 4.4	
2088*	Test stop running	Reset key
<i>Note</i>	Alarm description see 1344*	
2089*	Stop E triggered	Reset key
<i>Note</i>	Alarm description see 1348*	
2090*	Stop D triggered	Reset key
<i>Note</i>	Alarm description see 1352*	
2091*	Stop C triggered	Reset key
<i>Note</i>	Alarm description see 1356*	
2092*	Stop B triggered	Reset key
<i>Note</i>	Alarm description see 1360*	
2093*	Stop A triggered	Reset key
<i>Note</i>	Alarm description see 1364*	
2094*	Tolerance for safe standstill exceeded	POWER ON
<i>Note</i>	Alarm description see 1324*	
2095*	Safe speed exceeded	Reset key
<i>Note</i>	Alarm description see 1328*	

2096*	Safe end position exceeded	Reset key
<i>Note</i>	Alarm description see 1332*	
2097*	Failure in a monitoring channel	Reset key
<i>Note</i>	Alarm description see 1336*	
100001	Connection to keyboard faulty!	
<i>Scan</i>	When initializing and with every input	
<i>Effect</i>	Entries through operator panel no longer possible	
<i>Explanation</i>	Connection between operator panel and MMC CPU interrupted	
<i>Remedy</i>	Restore connection	
100002	Operator panel: buffer overflow	OK softkey
<i>Scan</i>	Permanent	
<i>Effect</i>	MMC crash	
<i>Explanation</i>	Operator panel signals are lost	
<i>Remedy</i>	None	
100003	Operator panel interface not ready	
<i>Scan</i>	Permanently	
<i>Effect</i>	Operator panel cannot be used	
<i>Explanation</i>	–	
<i>Remedy</i>	Power on	
100005	... (Alarm text is variable)	OK softkey
<i>Scan</i>	–	
<i>Effect</i>	Special error text	
<i>Explanation</i>	Depending on operation	
<i>Remedy</i>	–	
100006	The area ... is to be terminated	OK softkey
<i>Scan</i>	–	
<i>Effect</i>	Application is terminated	
<i>Explanation</i>	Memory required for another application. The operation can be aborted with softkey ABORT.	
<i>Remedy</i>	–	
100007	Area ... could not be terminated	OK softkey
<i>Scan</i>	–	
<i>Effect</i>	The application has not been terminated	
<i>Explanation</i>	Application is still active	
<i>Remedy</i>	Terminate application	

1.5.1 Alarm description

100008	... (Alarm text is variable)	OK softkey
<i>Scan</i>	–	
<i>Effect</i>	Special error text	
<i>Explanation</i>	Explained by context of operation	
<i>Remedy</i>	–	
100009	The area is terminated	OK softkey
<i>Scan</i>	–	
<i>Effect</i>	–	
<i>Explanation</i>	–	
<i>Remedy</i>	–	
101000	NCK system being loaded	
<i>Scan</i>	When NCK system is being loaded	
<i>Effect</i>	None	
<i>Explanation</i>	Message appears in the red bar when the system is being loaded	
<i>Remedy</i>	–	
101001	PLC system being loaded	
<i>Scan</i>	When PLC system is being loaded	
<i>Effect</i>	None	
<i>Explanation</i>	Message appears in the red bar when the system is being loaded	
<i>Remedy</i>	–	
101002	NCK software not available on hard disk	
<i>Scan</i>	–	
<i>Effect</i>	NCK is not powering-up: MMC powers up without NCK	
<i>Explanation</i>	<ul style="list-style-type: none"> Required data for loading not available in defined directory 	
<i>Remedy</i>	<ul style="list-style-type: none"> Install NCK software on MMC 	
101002	NCK user data being loaded	
<i>Scan</i>	When user data are being loaded.	
<i>Effect</i>	None	
<i>Explanation</i>	Data in user/NC/data directory being loaded	
<i>Remedy</i>		
<i>Note</i>	Alarm in SW 5 and higher	
101003	Checksum error when booting the NCK	
<i>Scan</i>	–	
<i>Effect</i>	NCK is not powering-up: MMC powers up without NCK	
<i>Explanation</i>	<ul style="list-style-type: none"> Faulty loaded file (wrong checksum or wrong format) 	
<i>Remedy</i>	<ul style="list-style-type: none"> POWER ON Re-install NC software, if necessary 	
<i>Note</i>	Applies for SW 2 only	

101003 User file not loaded*Scan* At system start*Effect* File in the user/NC/data directory is not loaded.*Explanation* No file operation (read, position, ...) could be performed on the user file ... or an error occurred during transfer. In the case of file operations, message 105011 is not issued (a reference to the faulty file operation).*Remedy* Correct the data in the user/NC/data directory.*Note* Alarm in SW 5 and higher**101003 Error in NCK/user/data load***Scan* At system start*Effect* Data in the directory user/NC/data are not loaded into the NCK*Explanation* –*Remedy* Correct data in the directory user/NC/data. Only GIA data (file name GIA) and IKA data (file names IKA1, IKA2, IKA3) should be stored there.*Note* Applies from SW 3 to SW 4.4**101004 MMC–NC data link not ready (log)***Scan* –*Effect* NCK is not powering-up: MMC powers up without NCK*Explanation*

- Software error in transport protocol
- Faulty loaded file

Remedy

- POWER ON
- Replace hardware, reinstall software

101005 Faulty load list on MM*Scan* –*Effect* NCK is not powering-up: MMC powers up without NCK*Explanation*

- Last file when booting is not NCK_SYS

Remedy

- Reinstall NCK software on MMC

101006 MMC–NC data link not ready*Scan* –*Effect* NCK is not powering-up: MMC powers up without NCK*Explanation*

- Internal software error in the data link at driver level

Remedy

- Install new software on MMC
- Replace hardware

101008 Remove EPROM submodule on NC–CPU*Scan* –*Effect* NCK is not powering-up: MMC powers up without NCK*Explanation* EPROM module is plugged on NC CPU 386*Remedy*

- See error message: replace CPU, if necessary (if no RESTART EPROM is plugged)

102000 Directory does not exist on harddisk**OK softkey***Scan*

- When displaying a data selector in MMC

Effect

- Reset to configured initial state of data selector

Explanation

- The data selector tries to display an area no longer available in the data management

Remedy –

1.5.1 Alarm description

102010	Configuring error	OK softkey
<i>Scan</i>	<ul style="list-style-type: none"> First display of a data selector in MMC 	
<i>Effect</i>	<ul style="list-style-type: none"> Empty display 	
<i>Explanation</i>	<ul style="list-style-type: none"> Possibly a consequential error, since data selector cannot work in the services, diagnosis, programming area 	
<i>Remedy</i>	<ul style="list-style-type: none"> Check/change configuration of UMS/FUMS. 	
102013	Only ... of ... elements displayed	OK softkey
<i>Scan</i>	When data selector is called	
<i>Effect</i>	Data only partially displayed	
<i>Explanation</i>	Quantity of displayed data limited internally	
<i>Remedy</i>	–	
103000	DUAL PORT RAM error!	
<i>Scan</i>	–	
<i>Effect</i>	–	
<i>Explanation</i>	Hardware problem or incorrectly installed by OEM	
<i>Remedy</i>	Replace hardware if necessary	
104000	Maximum line length reached	OK softkey
<i>Scan</i>	When inputting/inserting in the ASCII editor on MMC	
<i>Effect</i>	Operation is not executed	
<i>Explanation</i>	The maximum line length of the ASCII editor is exceeded	
<i>Remedy</i>	Shorter lines	
104001	Search text not found	OK softkey
<i>Scan</i>	When searching	
<i>Effect</i>	None	
<i>Explanation</i>	The ASCII editor in the MMC outputs a message that the search for a character string has not been successful.	
<i>Remedy</i>	–	
104002	File cannot be opened	OK softkey
<i>Scan</i>	When displaying an ASCII editor in MMC	
<i>Effect</i>	Empty display in ASCII editor	
<i>Explanation</i>	ASCII editor cannot find the file to be processed in the data management	
<i>Remedy</i>	None	
104004	Buffer is empty	OK softkey
<i>Scan</i>	ASCII editor when pasting from clipboard	
<i>Effect</i>	Operation is not executed	
<i>Explanation</i>	By operator action the ASCII editor is requested to paste from the clipboard into the file processed. The clipboard, however, is empty, not available or faulty. Possibly an operating error	
<i>Remedy</i>	<ul style="list-style-type: none"> Other operator action Fill clipboard 	

104005	Caution File has lines which are too long	OK softkey
<i>Scan</i>	When reading in file	
<i>Effect</i>	Line wrapround with LF	
<i>Explanation</i>	Line length > 128 characters (as from SW 4: > 256 characters)	
<i>Remedy</i>	–	
<i>Note</i>	Applies up to SW 4.5	
104005	File or harddisk failure	OK softkey
<i>Scan</i>	in ASCII editor	
<i>Effect</i>	Operation aborted.	
<i>Explanation</i>	An error has occurred in the editor during a write/read operation on the hard disk.	
<i>Remedy</i>	Perform chkdisk; replace MMC	
<i>Note</i>	Applies as from SW 5	
104006	The hard disk is full	OK softkey
<i>Scan</i>	When expanding the current file in ASCII editor	
<i>Effect</i>	Operation is aborted	
<i>Explanation</i>	The ASCII editor cannot generate any further internal auxiliary files	
<i>Remedy</i>	Reduce number of files on the hard disk.	
<i>Note</i>	Applies up to SW 4.4	
104006	File cannot be processed further	OK oftkey
<i>Scan</i>	ASCII editor	
<i>Effect</i>		
<i>Explanation</i>	Possible causes are 1. File is \geq 8 MB 2. File \geq 8 MB was processed further 3. Hard disk is full 4. Hard disk error	
<i>Remedy</i>	<ul style="list-style-type: none"> for 1, 3, 4: exit file without saving for 2: changes made up to this message can be saved. 	
<i>Note</i>	Applies as from SW 4.4	
104007	Line wrapround due to excessively long lines	OK softkey
<i>Scan</i>	When reading in file	
<i>Effect</i>	–	
<i>Explanation</i>	Line length > 128 characters (as from SW 4: > 256 characters)	
<i>Remedy</i>	–	
104008	Save not possible at present time	OK softkey
<i>Scan</i>	When saving file	
<i>Effect</i>	File is not saved	
<i>Explanation</i>	File is still open somewhere else (e.g. execution from harddisk)	
<i>Remedy</i>	Wait until execution has ended	

1.5.1 Alarm description

104009 File cannot be loaded into NCK**OK softkey***Scan* With SK Save and Load in NCK*Effect* Operation is aborted*Explanation* An error has occurred while loading the file into the NCK.
Possible causes: File type cannot be loaded into NCK;
incorrect keyswitch position;
no communication with NCK.*Note* Alarm in SW 5 and higher**105000 MMC power up***Scan* Power up*Effect* None*Explanation* Time of MMC power is up noted in log*Remedy* No error**105001 Too many alarms/messages****Acknowledgement key***Scan* –*Effect* New alarms are not displayed until alarms are acknowledged again*Explanation* An alarm is displayed although 50 unacknowledged alarms already exist*Remedy* POWER ON**105002 No communication to NCK!***Scan* Power up*Effect* MMC power up without NCK*Explanation* A more detailed error diagnostic is entered in the log with alarm 105011. Wrong MD, e.g. too short IPO cycles*Remedy* Check NCK driver, POWER ON**105003 NCK failed with error ...***Scan* Power up*Effect* Alarm 105005 is also output —> see alarm 105005*Explanation* [EPROM_ERROR]: EPROM error
[DRAM_ERROR]: DRAM error detected during power up
[DRAM_PROG_ERROR]: DRAM system program error*Remedy* POWER ON, replace NCK hardware if necessary**105004 NCK reset – please wait ...***Scan* Power up*Effect* System can temporarily not be operated*Explanation* NCK power up in progress*Remedy* Wait until NCK reset is completed and message disappears**105005 Please initiate NCK reset***Scan* Power up*Effect*

- NCK cannot be operated
- Interlocking of NC START

Explanation MMC crash and subsequent power up **does not** cause the operating program to be **interrupted**. For safety reasons an NCK RESET must be initiated at a suitable time.
An NCK system error has occurred. For more detailed diagnosis refer to messages 105003 or 105020.*Remedy* Initiate NCK RESET

105006	System crash – Please switch control off/on	POWER ON
105006	!!! System crash – reboot !!!	POWER ON
<i>Scan</i>	Power up	
<i>Effect</i>	MMC is rebooted after 5 seconds	
<i>Explanation</i>	Either applications or the operating system has crashed or there is an MMC hardware fault	
<i>Remedy</i>	POWER ON	
105007	Operator system initialization failed	POWER ON
<i>Scan</i>	Power up	
<i>Effect</i>	No power up of MMC	
<i>Explanation</i>	Internal system error during power up	
<i>Remedy</i>	Inform system service	
105008	Hardware error: ...	
<i>Scan</i>	–	
<i>Effect</i>	Alarm 105006 is also output —> see alarm 105006	
<i>Explanation</i>	DPR driver recognizes NMI because of a MMC hardware error: I/O channel check error or RAM parity error	
<i>Remedy</i>	POWER ON	
105009	UMS too large → UMS not loaded	OK softkey
<i>Scan</i>	Power up	
<i>Effect</i>	UMS does not load	
<i>Explanation</i>	The UMS (customer or Siemens UMS) cannot be loaded with the current memory configuration because it is set greater than in NC–MD 60000 (as from SW 4; up to SW 3, 512 kB fixed).	
<i>Remedy</i>	Change the memory configuration (as from SW 4); set MD 60000 accordingly.	
105010	Master control initialization failed!	POWER ON
<i>Scan</i>	Power up	
<i>Effect</i>	No power up of MMC	
<i>Explanation</i>	Internal system error during power up	
<i>Remedy</i>	Inform system service	
105011	Internal error: ...	OK softkey
<i>Scan</i>	–	
<i>Effect</i>	Alarms 105002, 105012 or 105013 are also output —> see these alarms	
<i>Explanation</i>	Internal system error	
<i>Remedy</i>	See alarms 105002, 105012 and 105013	
105012	Error in UMS → UMS not loaded	OK softkey
<i>Scan</i>	Power up	
<i>Effect</i>	UMS does not load	
<i>Explanation</i>	More detailed error diagnostics are entered in the log with message 105011	
<i>Remedy</i>	Check customer UMS, POWER ON	

1.5.1 Alarm description

105013	Standard UMS cannot be loaded	POWER ON
<i>Scan</i>	Power up	
<i>Effect</i>	The MMC system boots up without NCK	
<i>Explanation</i>	The Siemens configuration file NCMEMCFG.020 does not exist. When transferring the standard configuration, an error occurred or the NCK signals an error in memory configuration.	
<i>Remedy</i>	New system software	
105014	Operator panel initialization failed	POWER ON
<i>Scan</i>	Power up	
<i>Effect</i>	No power up of MMC	
<i>Explanation</i>	Operator panel cannot be initialized	
<i>Remedy</i>	Check whether serial driver has been loaded, POWER ON	
105015	There is no directory for temporary files!	POWER ON
<i>Scan</i>	Power up	
<i>Effect</i>	No power up of MMC	
<i>Explanation</i>	There is no directory for temporary files in the data management	
<i>Remedy</i>	Reload MMC software	
105017	Boot file ... cannot be loaded	OK softkey
<i>Scan</i>	When loading from NCK, PLC or SIMODRIVE 611-D	
<i>Effect</i>	–	
<i>Explanation</i>	–	
<i>Remedy</i>	–	
<i>Note</i>	Applies up to SW 4	
105017	System file not loaded	Acknowledgement key
<i>Scan</i>	While loading NCK/PLC or SIMODRIVE 611D.	
<i>Effect</i>	MMC powers up without NCK and message 105002 appears.	
<i>Explanation</i>	No file operation (read, position, ...) could be performed on system file ... or an error has occurred during transmission. Message 105011 – reference to incorrect file operation – also missing during file operation.	
<i>Remedy</i>	Notify system service.	
<i>Note</i>	Applies as from SW 5	
105018	Error in memory configuration → standard configuration loaded	OK softkey
<i>Scan</i>	–	
<i>Effect</i>	Boot with standard configuration	
<i>Explanation</i>	Memory configuration could not be loaded and initiated. Error in the customer configuration.	
<i>Remedy</i>	Create new customer configuration	
105020	NCK crash ... 10 following lines	POWER ON
<i>Scan</i>	Permanent	
<i>Effect</i>	The register dump for alarms 105031 – 105039 is written into the log Alarm 105005 has also been output → see alarm 105005	
<i>Explanation</i>	NCK has crashed and has saved register dump	
<i>Remedy</i>	Report register dump from alarm log to Siemens Service, POWER ON	

105030 Except... 386--Error... Task...

105031 CS: ... EIP: ...

105032 SS: ... ESP: ...

105033 EFLAGS: ...

105034 DS: ... ES: ...

105035 FS: ... GS: ...

105036 EAX: ... EBX: ...

105037 ECX: ... EDX: ...

105038 ESI: ... EDI: ...

105039 EBP: ... LDTR: ... CR0: ...

Scan Permanent

Effect See alarm 105020

Explanation Under these alarm numbers the register contents of the NCK crash is entered in the alarm list

Remedy See alarm 105020

Note:

These alarms are displayed only for a short period of time. They are entered in the alarm list.

105040 Wrong text number for message no. ...

Acknowledgement key

Scan Power up

Effect Text number 0 understood.

Explanation Error during conversion of ASCII files. A message has a text number greater than or equal to the number of texts.

Remedy Eliminate error in the alarm configuration.

Note SW 5 and higher

105041 Incorrect reference to message description for no. ...

Acknowledgement key

Scan Power up

Effect Reference to the first message description

Explanation Error during conversion of ASCII files. A message has a reference to a message line description greater than or equal to the number of message line descriptions.

Remedy Eliminate error in the alarm configuration

Note SW 5 and higher

1.5.1 Alarm description

105042	Incorrect reference to dialog description for no. ...	Acknowledgement key
<i>Scan</i>	Power up	
<i>Effect</i>	Reference set to the first dialog description.	
<i>Explanation</i>	Error during conversion of ASCII files. A message has a reference to a dialog description greater than or equal to the number of dialog descriptions.	
<i>Remedy</i>	Eliminate error in the alarm configuration	
<i>Note</i>	SW 5 and higher	
105043	Message no. ... neither dialog nor message	Acknowledgement key
<i>Scan</i>	Power up	
<i>Effect</i>	Value 0 understood.	
<i>Explanation</i>	Error during conversion of ASCII files. The third from last parameter of the message description is not 0 or 1 (0 for message line, 1 for dialog box)	
<i>Remedy</i>	Eliminate error in the alarm configuration.	
<i>Note</i>	SW 5 and higher	
105044	Syntax error in message configuration	Acknowledgement key
<i>Scan</i>	Power up	
<i>Effect</i>	Binary files have been read from the Siemens branch.	
<i>Explanation</i>	Error during conversion of ASCII files. The converter could not interpret the message attribute/message text files. The binary files from the Siemens branch have been read in.	
<i>Remedy</i>	Eliminate error in the alarm configuration.	
<i>Note</i>	SW 5 and higher	
105045	No communication to PLC	
<i>Scan</i>	Permanently	
<i>Effect</i>	MMC cannot communicate with PLC	
<i>Explanation</i>	Communication with PLC aborted after an error or time overrun	
<i>Remedy</i>	Check whether module is slotted in, notify Service.	
105046	PLC failed with error ...	
<i>Scan</i>	Permanently	
<i>Effect</i>	If the PLC signals an error, the error number is entered in the alarm log	
<i>Explanation</i>	Used for logging the PLC error number	
<i>Remedy</i>	Report error no. to Siemens, log module	
105047	PLC Reset – please wait ...	
<i>Scan</i>	Permanently	
<i>Effect</i>	No communication possible with PLC at the moment	
<i>Explanation</i>	This alarm is displayed while communication is started, e.g. after a link bus reset. It disappears after a short time	
<i>Remedy</i>	Wait	
105048	Text in ... not available	
<i>Scan</i>	After Power On	
<i>Effect</i>	A language which is not available has been set in the config file in the master control	
<i>Explanation</i>	Siemens settings apply	
<i>Remedy</i>	Set correct language and Power On	

105049 Operator panel interface ... faulty*Scan* After Power On*Effect* An interface which does not exist has been set in the config file of the master control*Explanation* Siemens settings apply*Remedy* Set correct interface and Power On**105050 Keyword unknown in line ... (master control)***Scan* After Power On*Effect* An unknown keyword is in the config file of the master control*Explanation* Line is ignored*Remedy* Correct and Power On**105051 Wrong value in ... line (master control)***Scan* After Power On*Effect* An incorrect value stands behind the keyword in the config file of the master control*Explanation* Interpreted as value 0*Remedy* Correct and Power On**105052 Text too long in line ... (master control)***Scan* After Power On*Effect* A string is too long in the config file of the master control*Explanation* Line is ignored*Remedy* Correct and Power On**105053 Missing value in line ... (master control)***Scan* After Power On*Effect* The value behind the keyword is missing in the config file of the master control*Explanation* Line is ignored*Remedy* Correct and Power On**105054 Too many masks in line ... (master control)***Scan* After Power On*Effect* There are too many masks for registering the alarms to be entered in the log in the config file of the master control*Explanation* Line is ignored*Remedy* Reduce number of masks and Power On**105055 Log ... created new****OK softkey***Scan* Power up*Effect* Old entries have been deleted.*Explanation* The existing log (alarm log = 1, service log = 2) could no longer be accessed.*Remedy* –*Note* Applies as from SW 4

1.5.1 Alarm description

105056 Log ... cannot be created**OK softkey***Scan* Power up*Effect* Power up without log*Explanation* It was not possible to create a log file (alarm log = 1, service log = 2) (disk defective or full).*Remedy* Check disk*Note* Applies as from SW 4**106000 Listing texts ... cannot be read***Scan* MMC power up*Effect* Listing texts cannot be used.*Explanation* An essential system file cannot be read.*Remedy* Notify service.*Note* Applies as from SW 4**106001 Listing ... being prepared***Scan* Selection of a listing*Effect* The selected listing is prepared just once.*Explanation* This text simply provides information and is intended to explain a delay that might occur. When selecting the same listing again, this does not have to be prepared again.*Remedy* Wait until the message disappears again.*Note* Applies as from SW 4**106002 ... is being read***Scan* File functions MDD*Effect* A data block is being read in from harddisk.*Explanation* This text simply provides information and is intended to explain a delay that might occur.*Remedy* Wait until the message disappears again.*Note* Applies as from SW 4**106003 ...: Error in data block ...***Scan* File functions MDD*Effect* A data block has not been completely read in.*Explanation* A data block read in from harddisk (so-called punched tape format) contains an error.*Remedy* Correct the error as far as possible and repeat the process.*Note* Applies as from SW 4**106004 ...: This data area on-line only****OK softkey***Scan* File functions MDD with user pictures.*Effect* This function is not possible.*Explanation* The selected data area can only be combined with data block selection 0 (i.e. always on-line). Storage on harddisk in punched tape format is not possible.*Remedy* Correct the error as far as possible and repeat the process.*Note* Applies as from SW 4

106005	Memory overflow	OK softkey
<i>Scan</i>	File functions MDD	
<i>Effect</i>	Function is aborted	
<i>Explanation</i>	The main memory (RAM) is full	
<i>Remedy</i>	End another application and repeat the process.	
<i>Note</i>	Applies as from SW 4	
106006	Harddisk full	OK softkey
<i>Scan</i>	File functions MDD	
<i>Effect</i>	Function is aborted	
<i>Explanation</i>	The harddisk is full	
<i>Remedy</i>	Delete another file and repeat the process.	
<i>Note</i>	Applies as from SW 4	
106007	MD error: ...	OK softkey
<i>Scan</i>	Individual fields with machine data	
<i>Effect</i>	Function is aborted	
<i>Explanation</i>	Input or configuring error	
<i>Remedy</i>	—	
<i>Note</i>	Applies as from SW 4	
110000	No data can be created here	OK softkey
<i>Scan</i>	FUNCTION / NEW	
<i>Effect</i>	—	
<i>Explanation</i>	No new data can be created by the user in the current directory	
<i>Remedy</i>	Select another directory	
110001	Please enter correct name	OK softkey
<i>Scan</i>	MANAGEMENT / COPY / PASTE / OK	
<i>Effect</i>	—	
<i>Explanation</i>	The entered name can only contain letters, numbers or underline. For part program %3 = MPF3<3 = SPF3. The length of the file name must be no more than 8 characters.	
<i>Remedy</i>	Correct the name	
110002	Name ... already exists	OK softkey
<i>Scan</i>	COPY / PASTE	
<i>Effect</i>	—	
<i>Explanation</i>	The entered name already exists for the data type	
<i>Remedy</i>	Enter a different name	
110003	Data cannot be created	OK softkey
<i>Scan</i>	COPY / PASTE / OK	
<i>Effect</i>	Data are not created	
<i>Explanation</i>	Data type can only be created once	
<i>Remedy</i>	Select a different data object type	

1.5.1 Alarm description

110004	No data selected	OK softkey
<i>Scan</i>	In the SERVICES area with data selection	
<i>Effect</i>	–	
<i>Explanation</i>	The data selector is positioned on the directory .. or -	
<i>Remedy</i>	Select with the cursor	
110005	No read access for this data	OK softkey
<i>Scan</i>	DATA MANAGEMENT / COPY / COPY / DATA IN-OUT / PRINT / START	
<i>Effect</i>	Data cannot be processed	
<i>Explanation</i>	No authorization for reading the selected data or printing exists for the set user class	
<i>Remedy</i>	Set a password, enable keyswitch	
110006	No write access at this point	OK softkey
<i>Scan</i>	DATA MANAGEMENT / NEW / OK / COPY / PASTE	
<i>Effect</i>	Data cannot be created/copied or written	
<i>Explanation</i>	No authorization to write the selected data exists for the set user class	
<i>Remedy</i>	Set a password, enable keyswitch	
110007	Data must not be deleted	OK softkey
<i>Scan</i>	MANAGEMENT / DELETE / OK	
<i>Effect</i>	Data are not deleted	
<i>Explanation</i>	No authorization to delete the selected data exists for the set user class, i.e. they cannot be deleted at all	
<i>Remedy</i>	Set a password, enable keyswitch	
110008	Selected data cannot be edited	OK softkey
<i>Scan</i>	MANAGEMENT / EDIT	
<i>Effect</i>	Editor is not started	
<i>Explanation</i>	The selected data cannot be edited (e.g. a directory)	
<i>Remedy</i>	Select alternative data	
110009	No interface file	OK softkey
<i>Scan</i>	–	
<i>Effect</i>	The interface is not parameterized and can therefore not be used.	
<i>Explanation</i>	See above	
<i>Remedy</i>	Select or create valid interface	
110010	Workpiece archiving in punch tape format only	OK softkey
<i>Scan</i>	DATA IN-OUT / DATA OUTPUT / WORKPIECES	
<i>Effect</i>	–	
<i>Explanation</i>	A workpiece or job list can only be archived in punch tape format	
<i>Remedy</i>	Select punch tape format via toggle field	

110011	There is no error log	OK softkey
<i>Scan</i>	Error log	
<i>Effect</i>	None	
<i>Explanation</i>	No error log was created for the previous data transfer	
<i>Remedy</i>	–	
110012	Selected data cannot be printed	OK softkey
<i>Scan</i>	DATA IN-OUT / PRINT	
<i>Effect</i>	–	
<i>Explanation</i>	Selected data cannot be printed	
<i>Remedy</i>	Select data (e.g. MPF ..) which can be printed	
110013	There is no job list for printer	OK softkey
<i>Scan</i>	DATA IN-OUT / PRINT / JOB LIST	
<i>Effect</i>	–	
<i>Explanation</i>	The printer has no job to process at the moment	
<i>Remedy</i>	–	
110015	Floppy was not formatted	OK softkey
<i>Scan</i>	DATA IN-OUT / FORMAT / OK	
<i>Effect</i>	Diskette not formatted	
<i>Explanation</i>	General error during formatting	
<i>Remedy</i>	Check disk drive/cable	
110016	Floppy is write-protected	OK softkey
<i>Scan</i>	DATA IN-OUT / DATA OUTPUT / ... / START (INSERT NEXT DISKETTE)OK DATA IN-OUT / FORMAT / OK	
<i>Effect</i>	Data are not stored or diskette is not formatted	
<i>Explanation</i>	The diskette tab is in the wrong position	
<i>Remedy</i>	Remove write-protection or insert another diskette	
110017	No floppy inserted	OK softkey
<i>Scan</i>	DATA IN-OUT / DATA OUTPUT / ... / START DATA IN-OUT / DATA INPUT / START (INSERT NEXT DISKETTE) OK DATA IN-OUT / FORMAT / OK	
<i>Effect</i>	–	
<i>Explanation</i>	There is no diskette in the floppy disk drive	
<i>Remedy</i>	Insert diskette	
110018	Interface ... not initialized	OK softkey
<i>Scan</i>	DATA IN-OUT / DEVICES / SELECTION	
<i>Effect</i>	Data transfer not possible	
<i>Explanation</i>	Interface incorrect or not parameterized	
<i>Remedy</i>	Select suitable interface file and reparameterize. If floppy selected, floppy drive must be connected to interface.	

1.5.1 Alarm description

110019	Observe error log	OK softkey
<i>Scan</i>	DATA IN-OUT / (INPUT OR OUTPUT)	
<i>Effect</i>	–	
<i>Explanation</i>	Errors occurred during data transfer. The data concerned are listed in the logs and must be checked. Cause: Data already exist, overwriting not desired. No read/write authorization when reading in again, incorrect punch tape format	
<i>Remedy</i>	Rectify the cause (if possible) and read in again	
110020	Floppy is not formatted	OK softkey
<i>Scan</i>	DATA IN-OUT / (INPUT OR OUTPUT) / START (INSERT NEXT DISKETTE) OK	
<i>Effect</i>	Data are not read in/written	
<i>Explanation</i>	The floppy is either not formatted or incorrectly formatted	
<i>Remedy</i>	Insert formatted diskette	
110021	Error on reading the archive	OK softkey
<i>Scan</i>	DATA IN-OUT / DATA INPUT / START	
<i>Effect</i>	Data are not read	
<i>Explanation</i>	Archive file is faulty	
<i>Remedy</i>	–	
110022	No workpiece selected	OK softkey
<i>Scan</i>	LOAD NC / SHOPFLOOR SHEET	
<i>Effect</i>	No display	
<i>Explanation</i>	Selected data are not workpieces	
<i>Remedy</i>	Select workpiece under LOCAL or GLOBAL	
110023	There are no comments for ...	OK softkey
<i>Scan</i>	LOAD NC / SHOPFLOOR SHEET / COMMENT	
<i>Effect</i>	–	
<i>Explanation</i>	No comment available for current workpiece	
<i>Remedy</i>	Enter comment in program	
110024	Archive list/job list is empty	OK softkey
<i>Scan</i>	DATA IN-OUT / DATA OUTPUT / ARCHIVE LIST	
<i>Effect</i>	No data are being read out	
<i>Explanation</i>	No object in the archive list can be accessed	
<i>Remedy</i>	Check archive list	
110025	Floppy is full	OK softkey
<i>Scan</i>	DATA IN-OUT / DATA OUTPUT / ... / START	
<i>Effect</i>	Wait	
<i>Explanation</i>	The diskette is full	
<i>Remedy</i>	Insert another diskette, continue by pressing the OK softkey	

110026	Archive not created or not found	OK softkey
<i>Scan</i>	DATA IN-OUT / DATA INPUT / START DATA IN-OUT / DATA OUTPUT / ... / START	
<i>Effect</i>	–	
<i>Explanation</i>	The archive has not been written or no archive has been found	
<i>Remedy</i>	Read in: Transfer another archive Read out: Check data/archive or job list/transfer format	
110027	... is not an archive file	OK softkey
<i>Scan</i>	DATA IN-OUT / DATA OUTPUT / ARCHIVE LIST	
<i>Effect</i>	–	
<i>Explanation</i>	The selected data is not an archive list	
<i>Remedy</i>	Select archive list with data selector	
110028	No machining operation for ...	OK softkey
<i>Scan</i>	LOAD NC / SHOPFLOOR SHEET / MACHINING OPERATION	
<i>Effect</i>	None	
<i>Explanation</i>	The selected workpiece does not have a machining operation	
<i>Remedy</i>	Create data	
110029	Not a hexadecimal number	OK softkey
<i>Scan</i>	DATA IN-OUT / DEVICES / EDIT / STORE	
<i>Effect</i>	Data cannot be stored	
<i>Explanation</i>	Hexadecimal number: a–f, A–F, 0–9	
<i>Remedy</i>	Correct	
110030	Not a decimal number	OK softkey
<i>Scan</i>	DATA IN-OUT / DEVICES / EDIT / STORE	
<i>Effect</i>	Data cannot be stored/softkey operation cannot be executed	
<i>Explanation</i>	Decimal number: 0–9 without sign	
<i>Remedy</i>	Correct	
110031	Interface still transmitting data	OK softkey
<i>Scan</i>	DATA IN-OUT / DEVICES / SELECTION	
<i>Effect</i>	Interface selection still being executed	
<i>Explanation</i>	Interface selection not possible during output (e.g. printing)	
<i>Remedy</i>	Delete print jobs or wait	
110032	Error in archive file	OK softkey
<i>Scan</i>	DATA IN-OUT / DATA INPUT / START	
<i>Effect</i>	Data are either not read in or are read in with errors	
<i>Explanation</i>	Archive list is faulty	
<i>Remedy</i>	Correct	

1.5.1 Alarm description

110033	Error on writing the archive	OK softkey
<i>Scan</i>	DATA IN-OUT / DATA OUTPUT / ... / START	
<i>Effect</i>	Data read out has been interrupted	
<i>Explanation</i>	Data is not evaluated by output medium (external device) (hardware fault)	
<i>Remedy</i>	Start again	
110034	Timeout ≥ 0 and ≤ 60 seconds	OK softkey
<i>Scan</i>	DATA IN-OUT / DEVICES / EDIT / STORE DATA IN-OUT / DEVICES / SELECTION	
<i>Effect</i>	Data cannot be stored/no device selection	
<i>Explanation</i>	Time must be in the specified range	
<i>Remedy</i>	Enter $0 \leq \text{time} \leq 60$ seconds	
110035	Wrong output medium parameterized	OK softkey
<i>Scan</i>	DATA IN-OUT / FORMAT DATA IN-OUT / PRINT	
<i>Effect</i>	None	
<i>Explanation</i>	Parameterized floppy cannot be formatted, print command cannot be sent to parameterized universal interface	
<i>Remedy</i>	Change interface parameterization	
110036	No data for ...	OK softkey
<i>Scan</i>	LOAD NC / SHOPFLOOR SHEET / WORK SCHEDULE / MACHINING OPERATION LOAD NC / SHOPFLOOR SHEET / WORK SCHEDULE LOAD NC / SHOPFLOOR SHEET / BLANK	
<i>Effect</i>	None	
<i>Explanation</i>	The corresponding data for the shopfloor sheet is not available	
<i>Remedy</i>	Create data	
110037	The hard disk is full	OK softkey
<i>Scan</i>	DATA MANAGEMENT / COPY / COPY / DATA IN-OUT / DATA INPUT / START / SAVE NC / SOURCE NC / START	
<i>Effect</i>	Data cannot be stored or created	
<i>Explanation</i>	–	
<i>Remedy</i>	Delete data no longer required	
110038	Syntax error in job list line ...	OK softkey
<i>Scan</i>	LOAD NC / START DATA IN-OUT / DATA OUTPUT / WORKPIECES / START	
<i>Effect</i>	Data are not archived/loaded into the NC	
<i>Explanation</i>	Syntax error in job list	
<i>Remedy</i>	Correct	
110039	Data cannot be copied	OK softkey
<i>Scan</i>	MANAGEMENT / COPY / PASTE / OK	
<i>Effect</i>	Data are not copied	
<i>Explanation</i>	General error, e.g. data type may exist only once	
<i>Remedy</i>	E.g. delete data beforehand	

110041	Error in NCK name	OK softkey
<i>Scan</i>	DATA IN-OUT / DATA INPUT / START	
<i>Effect</i>	Data in punch tape format are not read in their entirety	
<i>Explanation</i>	With data I/O in punch tape format the name is transmitted first. NCK data must begin with %MPF, %SPF, %TOA, %TEA, %SEA, %UMS, %RPA	
<i>Remedy</i>	Alter external data	
110042	Syntax error in UMS file	OK softkey
<i>Scan</i>	DATA IN-OUT / DATA INPUT / START	
<i>Effect</i>	UMS file has been read in incorrectly	
<i>Explanation</i>	Error in data	
<i>Remedy</i>	Change external data	
110043	Please use the proposed name	OK softkey
<i>Scan</i>	MANAGEMENT / NEW / OK	
<i>Effect</i>	Data are not created	
<i>Explanation</i>	–	
<i>Remedy</i>	Use the proposed name	
110044	Too many print jobs in queue	OK softkey
<i>Scan</i>	DATA IN-OUT / PRINT / START	
<i>Effect</i>	Data are not sent to printer	
<i>Explanation</i>	The number of print jobs allowed is limited	
<i>Remedy</i>	Wait for the next print job to be completed or remove a print job from the job list	
110045	...signals transmission fault	OK softkey
<i>Scan</i>	DATA IN-OUT / (DATA INPUT OR OUTPUT)	
<i>Effect</i>	Data have either not been transferred at all or only partially or incorrectly	
<i>Explanation</i>	General error	
<i>Remedy</i>	Check other station and cable, reselect interface	
110046	System error ...	OK softkey
<i>Scan</i>	None	
<i>Effect</i>	The last action has not been executed correctly	
<i>Explanation</i>	None	
<i>Remedy</i>	Inform system service	
110047	Interface is still active	OK softkey
<i>Scan</i>	–	
<i>Effect</i>	A data transmission session to this interface has not yet ended.	
<i>Explanation</i>	–	
<i>Remedy</i>	Terminate data transmission.	
<i>Note</i>	Applies as from SW 4.4	

1.5.1 Alarm description

110048	Interface signals overrun	OK softkey
<i>Scan</i>	DATA IN-OUT / DATA INPUT / START	
<i>Effect</i>	Data are not read in correctly	
<i>Explanation</i>	Hardware problem	
<i>Remedy</i>	–	
110049	Check interface parameterization	OK softkey
<i>Scan</i>	DATA IN-OUT / DATA INPUT / START	
<i>Effect</i>	Data are not read in correctly	
<i>Explanation</i>	Baud rate, parity, data length, number of stop bits incorrect	
<i>Remedy</i>	Alter interface data and reselect	
110050	Floppy is already full	OK softkey
<i>Scan</i>	DATA IN-OUT / DATA OUTPUT / ... / START (INSERT NEXT DISKETTE) OK	
<i>Effect</i>	Data are not are not archived	
<i>Explanation</i>	A full diskette has been inserted	
<i>Remedy</i>	Insert new diskette	
110051	... was not printed	OK softkey
<i>Scan</i>	DATA IN-OUT / PRINT SERIAL / START	
<i>Effect</i>	Not all of the specified object has been printed or it has not been printed at all	
<i>Explanation</i>	None	
<i>Remedy</i>	Check interface/printer	
110052	... signals timeout	OK softkey
<i>Scan</i>	(DATA INPUT OR OUTPUT)	
<i>Effect</i>	Data have not been read in or read out	
<i>Explanation</i>	No data were read in or collected in the parameterized time (TIMEOUT)	
<i>Remedy</i>	Check other station	
110053	End of transmission without end identifier	OK softkey
<i>Scan</i>	DATA IN-OUT / ... / ... / START	
<i>Effect</i>	Data are not read-in/written or only partially	
<i>Explanation</i>	E.g. end of data without M02 or end identifier	
<i>Remedy</i>	Check other station and cable	
110054	No punch tape format or it is faulty	OK softkey
<i>Scan</i>	DATA IN-OUT / DATA INPUT / START	
<i>Effect</i>	No reading-in	
<i>Explanation</i>	No punch tape format found in archive, archive does not have a PC format or transmission was started at the wrong time	
<i>Remedy</i>	Check external data	

110055	Too much data found	OK softkey
<i>Scan</i>	SERVICES / DATA OUTPUT	
<i>Effect</i>	There is still more data that cannot be accessed	
<i>Explanation</i>	The currently selected workpiece contains more data than can be displayed or processed (max 240 files)	
<i>Remedy</i>	Select low no. of files for output	
110056	PC format can be transmitted only with 8 data bits	OK softkey
<i>Scan</i>	DATA IN-OUT / ... / ... / START	
<i>Effect</i>	No data read-in or out	
<i>Explanation</i>	For reading in or out data in PC format the device must be parameterized with 8 data bits	
<i>Remedy</i>	Suitably parameterize interface	
110057	File not available	OK softkey
<i>Scan</i>	DATA IN-OUT / ... / ... / START	
<i>Effect</i>	File not read out	
<i>Explanation</i>	File is not available on MMC at the archiving time	
<i>Remedy</i>	Faulty archive list or time problem	
110058	Transfer aborted	OK softkey
<i>Scan</i>	DATA ON OFF / ... / ... / START	
<i>Effect</i>	Not all the data was transferred.	
<i>Explanation</i>	Abort occurred while file was being transferred.	
<i>Remedy</i>	Check cable and peer.	
110059	Cannot be transmitted in punch tape format	OK softkey
<i>Scan</i>	Archiving	
<i>Effect</i>	Data is not archived.	
<i>Explanation</i>	Only MPF, SPF, TOA, RPA, ZOA, UMS, SEA, TEA1, TEA2, TEA4 can be transmitted in LS format.	
<i>Remedy</i>	Select other data or archive in PC format	
110060	Stored in the clipboard	OK softkey
<i>Scan</i>	DATA IN-OUT / DATA INPUT / START	
<i>Effect</i>	The file was entered in the clipboard	
<i>Explanation</i>	The file could not be entered in the current directory (not possible, no authorization, file opened from PC editor)	
<i>Remedy</i>	Paste from clipboard into the desired archive location	
110061	No workpiece in job list line ...	OK softkey
<i>Scan</i>	LOAD NC / START	
<i>Effect</i>	Job list processing was interrupted	
<i>Explanation</i>	The workpiece name in the LOAD instruction does not exist	
<i>Remedy</i>	Change job list	

1.5.1 Alarm description

110062	... not found in job list	OK softkey
<i>Scan</i>	LOAD NC / START	
<i>Effect</i>	Job list processing was interrupted	
<i>Explanation</i>	The workpiece name in the LOAD instruction does not exist	
<i>Remedy</i>	Change job list	
110063	No workpiece can be created here	OK softkey
<i>Scan</i>	DATA IN-OUT / DATA INPUT / IN NEW WORKPIECE	
<i>Effect</i>	None	
<i>Explanation</i>	A workpiece cannot be created at the current location	
<i>Remedy</i>	Select the directory PC/USER/LOCAL or PC/USER/GLOBAL	
110064	Data type exists already	OK softkey
<i>Scan</i>	Data management / new Data management / insert from archive	
<i>Effect</i>	File is not created / copied	
<i>Explanation</i>	The data type can only be created once in the current location.	
<i>Remedy</i>	First delete the existing file	
110065	Not possible at present	OK softkey
<i>Scan</i>	When data is output through V24 and saved to hard disk at the same time, e.g. from a MPF in the programming. If file is processed in the PC editor.	
<i>Effect</i>	Data is not transmitted.	
<i>Explanation</i>	–	
<i>Remedy</i>	Wait until the save operation has been concluded in the ASCII editor.	
<i>Note</i>	Applies as from SW 4.4	
110066	Data in Siemens branch cannot be stored	OK softkey
<i>Scan</i>	Data management / new Data management / insert from archive	
<i>Effect</i>	File is not created / copied	
<i>Explanation</i>	File cannot be created in Siemens branch.	
<i>Remedy</i>	Move to user branch	
110067	Please enter correct archive name	OK softkey
<i>Scan</i>	Data input Data output	
<i>Effect</i>	Function is not processed	
<i>Explanation</i>	The archive name must have the syntax of a file name	
<i>Remedy</i>	Enter correct name	
110068	Interface ... is disabled	OK softkey
<i>Scan</i>	Data input Data output	
<i>Effect</i>	Function is not processed	
<i>Explanation</i>	The interface is busy with another application (PG SW, WOP, transfer job by PLC)	
<i>Remedy</i>	Wait until interface is free	

110069	Tool list not available	OK softkey
<i>Scan</i>	PROGRAMMING: shopfloor sheet / create TO file / OK	
<i>Effect</i>	TO file is not created	
<i>Explanation</i>	–	
<i>Remedy</i>	Create tool list	
110070	D number(s) exist more than once	OK softkey
<i>Scan</i>	PROGRAMMING: shopfloor sheet / create TO file / OK	
<i>Effect</i>	Data sets in TO file exist more than once	
<i>Explanation</i>	–	
<i>Remedy</i>	Process tool list	
110071	Computer link: error number ...	OK softkey
<i>Scan</i>	Computer link / error listing	
<i>Effect</i>	Error during transmission	
<i>Explanation</i>	Error number reported during transmission	
<i>Remedy</i>	–	
110100	There is no data/part program	OK softkey
<i>Scan</i>	LOAD NC/START	
<i>Effect</i>	Part program ... is not loaded	
<i>Explanation</i>	An item of data specified in the job list/part program is not available	
<i>Remedy</i>	Correct job list	
110101	There is no channel No./mode group/PLC No.	OK softkey
<i>Scan</i>	LOAD NC, SAVE NC	
<i>Effect</i>	Data is not saved or loaded	
<i>Explanation</i>	TOA, SEA4, RPA, ZOA (TOA, SEA4 > 0) RPA, ZOA ≥ 0	
<i>Remedy</i>	All data ≤ 4 (or 6 as from SW 4)	
110102	No read/write access for ...	OK softkey
<i>Scan</i>	Save NC / NC source / start	
<i>Effect</i>	Data object is not created on MMC or cannot be read	
<i>Explanation</i>	No read only / write rights for the set user class, e.g. because PLC is in stop or keyswitch not processed in PLC	
<i>Remedy</i>	Turn keyswitch to position < 3 or set password	
110103	Memory on NCK is full	OK softkey
<i>Scan</i>	LOAD NC or basic display in AUTOMATIC mode, LOAD WORKPIECE	
<i>Effect</i>	Part program will not be transferred	
<i>Explanation</i>	None	
<i>Remedy</i>	Delete part programs no longer needed from the NCK	

1.5.1 Alarm description

110104	Error in data/part-program ...	OK softkey
<i>Scan</i>	LOAD NC or AUTOMATIC basic display, LOAD WORKPIECE	
<i>Effect</i>	Data are not transferred or only partly	
<i>Explanation</i>	<ul style="list-style-type: none"> • NC data to be loaded have errors • Read error on hard disk when executing from hard disk 	
<i>Remedy</i>	Check data	
110105	Error during job processing	OK softkey
<i>Scan</i>	LOAD NC, SAVE NC or AUTOMATIC basic display, LOAD WORKPIECE	
<i>Effect</i>	–	
<i>Explanation</i>	–	
<i>Remedy</i>	–	
110107	NC data/part program cannot be created here	OK softkey
<i>Scan</i>	SAVE NC / NC SOURCE / START MANAGEMENT / COPY / PASTE DATA IN-OUT / BUFFER / INSERT	
<i>Effect</i>	Data are not saved, copied or inserted in buffer	
<i>Explanation</i>	The data cannot be stored in the current directory	
<i>Remedy</i>	Select a different directory	
110108	There is no workpiece . . .	OK softkey
<i>Scan</i>	(AUTOMATIC MODE)	
<i>Effect</i>	Workpiece will not be loaded	
<i>Explanation</i>	The workpiece required by the NCK does not exist in the MMC	
<i>Remedy</i>	Check entered names	
110109	Only workpieces/NCK data can be loaded	OK softkey
<i>Scan</i>	LOAD NC / START	
<i>Effect</i>	None	
<i>Explanation</i>	Only workpieces or NCK data can be loaded	
<i>Remedy</i>	Using the data selector, select a workpiece under LOCAL or GLOBAL or an NCK object under a workpiece or from NC data	
110110	No access to SPF0	OK softkey
<i>Scan</i>	SAVE NC / NC SOURCE / START	
<i>Effect</i>	SPF0 is not saved	
<i>Explanation</i>	The name SPF0 is not permissible	
<i>Remedy</i>	Deselect from SPF1	
110111	... being processed or cycle inhibit	OK softkey
<i>Scan</i>	SAVE NC / NC SOURCE / START / LOAD NC / START	
<i>Effect</i>	Data will not be saved to MMC or loaded in NCK	
<i>Explanation</i>	The part program either has cycle disable or is being processed	
<i>Remedy</i>	Remove disable or discontinue processing	
<i>Note</i>	Applies up to SW 2	

110112	... is not a correct NCK name	OK softkey
<i>Scan</i>	LOAD NC / START	
<i>Effect</i>	Data are not transferred to NC	
<i>Explanation</i>	Error in part program name, e.g. MPF_1	
<i>Remedy</i>	Correct name in MMC	
110113	No communication to NCK	OK softkey
<i>Scan</i>	(Power up) LOAD NC / START SAVE NC / NC SOURCE	
<i>Effect</i>	No data transfer	
<i>Explanation</i>	There is no connection to the NCK. A more detailed error diagnosis is entered in the alarm log with message 105011 and possibly 105030 to 105039. Incorrect MDs e.g. IPO cycles too short.	
<i>Remedy</i>	Inform system service	
110114	... transmitted incompletely	OK softkey
<i>Scan</i>	Abort AUTOMATIC basic display LOAD NC / START / ABORT SAVE NC / NC SOURCE / START / ABORT	
<i>Effect</i>	The file has not been transmitted in its entirety to the MMC or the NCK	
<i>Explanation</i>	It may no longer be possible to send the complete file to the NCK	
<i>Remedy</i>	Save the complete file from the NC again and/or transfer it completely to the NCK	
110115	... : Line is too long	OK softkey
<i>Scan</i>	LOAD NC / START	
<i>Effect</i>	Incomplete data transfer	
<i>Explanation</i>	Line may not contain more than 120 characters without blanks or 120 characters with blanks in the comments section.	
<i>Remedy</i>	Alter using editor	
<i>Note</i>	Applies up to SW 2	
110116	No data transmitted for ...	OK softkey
<i>Scan</i>	LOAD NC / ... / START / SAVE NC / ... / START	
<i>Effect</i>	–	
<i>Explanation</i>	No transferable data was selected	
<i>Remedy</i>	Select data that can be transmitted / correct job list	
110117	Wrong channel number	OK softkey
<i>Scan</i>	SAVE NC / ... / START	
<i>Effect</i>	No data transmission	
<i>Explanation</i>	The channel number must be $\geq 0 \leq 4$ (≥ 6 as from SW 4)	
<i>Remedy</i>	–	
110118	Storage of ... not allowed here	OK softkey
<i>Scan</i>	Save NC / NC source / start	
<i>Effect</i>	No data transmission	
<i>Explanation</i>	Parameter ... stands for NC name Part programs MFP/SPF can only be stored in a workpiece and GIA data can only be stored under NC data.	
<i>Remedy</i>	Position on/in a workpiece or in the case of GIA data to NC data using the data selector.	

1.5.1 Alarm description

110119	Data not transferred or incompletely	OK softkey
<i>Scan</i>	Computer link / save start Computer link / load start / OK	
<i>Effect</i>	Not all data transfers, the last file may be incomplete	
<i>Explanation</i>	Cause perhaps in error log	
<i>Remedy</i>	Rectify cause, restart transmission	
110120	Data cannot be read in	OK softkey
<i>Scan</i>	DATA INPUT START	
<i>Effect</i>	File has neither been read in the clipboard nor under the target path.	
<i>Explanation</i>	Cause (e.g. no write authorization, file opened by ASCII editor) can be seen in the error log	
<i>Remedy</i>	Eliminate cause. Restart data input.	
<i>Note</i>	Applies as from SW 4.4	
110121	Option not available	OK softkey
<i>Scan</i>	On computer link	
<i>Effect</i>	–	
<i>Explanation</i>	Computer link module not slotted in or not active	
<i>Remedy</i>	Activate computer link module (CP)	
110122	NCK password not set	OK softkey
<i>Scan</i>	When loading NCK data	
<i>Effect</i>	The selected data are not loaded	
<i>Explanation</i>	Password required for loading GIA data	
<i>Remedy</i>	Set password in diagnosis	
120000	Password set	OK softkey
<i>Scan</i>	When operating softkey, "Set password"; the password is correct and has been set.	
<i>Effect</i>	Files can be stored with ASCII editor. New files can be created or deleted. Backup can be executed.	
<i>Explanation</i>	–	
<i>Remedy</i>	–	
120001	Password reset	OK softkey
<i>Scan</i>	When operating softkey, "Reset password"; the password has been reset.	
<i>Effect</i>	Password protected files cannot be altered.	
<i>Explanation</i>	–	
<i>Remedy</i>	–	
120002	Wrong time/date given	OK softkey
<i>Scan</i>	When pressing the "Set clock" softkey	
<i>Effect</i>	–	
<i>Explanation</i>	Time or date entered incorrectly.	
<i>Remedy</i>	Check input fields Input values for	
	hour:	0 ... 23
	minute:	0 ... 59
	day:	1 ... 31
	month:	1 ... 12
	year:	1980 ... 1999

120003	No password set	OK softkey
<i>Scan</i>	You have tried to save a file or perform a backup.	
<i>Effect</i>	The files cannot be saved with the ASCII editor. No data can be created or deleted. No backup can be performed.	
<i>Explanation</i>	The password has not been set.	
<i>Remedy</i>	Enter and set the password in the screen form for this.	
120004	No logbook found	OK softkey
<i>Scan</i>	When operating the softkey, "Display logbook".	
<i>Effect</i>	–	
<i>Explanation</i>	Logbook in MMC area has been deleted illegally	
<i>Remedy</i>	Not possible by user	
120005	No data selected	OK softkey
<i>Scan</i>	The identifier ".." or "—" has been selected with the data selector and a softkey (e.g. "Edit") has been pressed.	
<i>Effect</i>	The next display cannot be called up.	
<i>Explanation</i>	Data has been selected which cannot be edited	
<i>Remedy</i>	Select a valid name with the data selector and press the softkey (e.g. "Edit") again.	
120006	Transfer error ...	OK softkey
<i>Scan</i>	The error occurred during data transfer (PLC/NC DATA).	
<i>Effect</i>	The data have either not been transmitted or have been transmitted incorrectly.	
<i>Explanation</i>	The value indicates a data transfer error if the cause cannot be output as a plaintext message.	
<i>Remedy</i>	Check settings on NC and check input fields and restart transmission.	
120007	No data presetting possible	OK softkey
<i>Scan</i>	Standard default setting could not be set.	
<i>Effect</i>	SIEMENS default setting is used.	
<i>Explanation</i>	–	
<i>Remedy</i>	Check path setting of data selector in SIEMENS branch; the path must also exist in the user branch.	
120008	No data storage possible here	OK softkey
<i>Scan</i>	No NC/PPLC data can be stored in the SIEMENS area.	
<i>Effect</i>	None	
<i>Explanation</i>	Only data transfer from the NCK in the user areas of the MMC is possible.	
<i>Remedy</i>	Select user area.	
120009	Password incorrect	OK softkey
<i>Scan</i>	An incorrect password has been entered.	
<i>Effect</i>	See alarm message 120003 "No password set"	
<i>Explanation</i>	None	
<i>Remedy</i>	Enter correct password, press "Return" key and the "Set" softkey.	

1.5.1 Alarm description

120010	Error while generating alarm log	OK softkey
<i>Scan</i>	Log could not be created.	
<i>Effect</i>	No log is displayed.	
<i>Explanation</i>	The master control creates the logs when demanded by diagnosis	
<i>Remedy</i>	Check the entry for the length of the logs in the configuration file of the master control and alter if necessary.	
120011	Error on creating service log	OK softkey
<i>Scan</i>	Log could not be created.	
<i>Effect</i>	No log is displayed.	
<i>Explanation</i>	The master control creates the logs when demanded by diagnosis	
<i>Remedy</i>	Check the entry for the length of the logs in the configuration file of the master control and alter if necessary.	
120012	... cannot be created	OK softkey
<i>Scan</i>	An error has occurred while creating the specified data object.	
<i>Effect</i>	The object will not be created or only partially.	
<i>Explanation</i>	–	
<i>Remedy</i>	Delete a file, possibly there are too many files in this directory. Check position of keyswitch and capacity of hard disk.	
120013	No write access at this point	OK softkey
<i>Scan</i>	You have tried to store a file in the SIEMENS branch, or to store NC data in the user branch when keyswitch not in position 1 or 2.	
<i>Effect</i>	Data cannot be stored.	
<i>Explanation</i>	Check the position of the keyswitch.	
<i>Remedy</i>	Leave editor using RECALL key.	
120014	... not available	OK softkey
<i>Scan</i>	The specified file (e.g. PCF17) has not been found in the NCK.	
<i>Effect</i>	None	
<i>Explanation</i>	Existing PLC error messages can only be saved in the NC.	
<i>Remedy</i>	Select a different program number for PCF file.	
120015	Operating system – error ...	OK softkey
<i>Scan</i>	An error has been caused in an operating system call during data transfer.	
<i>Effect</i>	System failure	
<i>Explanation</i>	Operating system error [0x4005] i.e.: no communication to NCK	
<i>Remedy</i>	Inform service	
120016	NCK password not set	OK softkey
<i>Scan</i>	An attempt has been made to transfer NC files to the NCK for which a password is required.	
<i>Effect</i>	File is not transferred.	
<i>Explanation</i>	None	
<i>Remedy</i>	Set the password on the NCK side.	

120017	Transmission aborted	OK softkey
<i>Scan</i>	The user has aborted data transfer with softkey.	
<i>Effect</i>	The data have not been transferred or only incompletely.	
<i>Explanation</i>	–	
<i>Remedy</i>	Select another file, restart transmission.	
<i>Note</i>	Applies as from SW 4.4	
120018	Error in channel no. / TO area	OK softkey
<i>Scan</i>	The channel no. or TO area entered is not permissible with the NC source specified.	
<i>Effect</i>	File is not transferred.	
<i>Explanation</i>	None	
<i>Remedy</i>	Correct number.	
120019	Name ... not allowed	OK softkey
<i>Scan</i>	An illegal file name has been entered.	
<i>Effect</i>	The file with the name is not created on the MMC side.	
<i>Explanation</i>	Letters A...Z, numbers 0...9 and the underscore character are permissible.	
<i>Remedy</i>	Please enter the correct name, e.g. ABC _123	
120020	There is no data/part program	OK softkey
<i>Scan</i>	The error occurred while a file was being transferred.	
<i>Effect</i>	File has not been transferred or only partially.	
<i>Explanation</i>	–	
<i>Remedy</i>	–	
120021	Error in NCK name	OK softkey
<i>Scan</i>	The error occurred while a file was being transferred.	
<i>Effect</i>	File has not been transferred or only partially.	
<i>Explanation</i>	The name for the NC is incorrect. It consists of an NC identifier (RPA for R parameter) and the channel number, e.g.: R parameter for channel 2 → name = RPA2	
<i>Remedy</i>	Correct the name and/or channel number	
120022	No read/write access for ...	OK softkey
<i>Scan</i>	The error occurred while transferring a file.	
<i>Effect</i>	File has not been transferred or only partially.	
<i>Explanation</i>	–	
<i>Remedy</i>	Set keyswitch for data.	
120023	Memory on NC is full	OK softkey
<i>Scan</i>	An error occurred during transfer of a file.	
<i>Effect</i>	File has not been transferred or only partially.	
<i>Explanation</i>	The NC part program is full.	
<i>Remedy</i>	If necessary, delete part programs from the memory.	

1.5.1 Alarm description

120024	Error in data/part program ...	OK softkey
<i>Scan</i>	The error occurred while transferring the file.	
<i>Effect</i>	File has not been transferred or only partially.	
<i>Explanation</i>	Syntax error in file structure. E.g.: % MPF in part program on MMC	
<i>Remedy</i>	Correct the file	
120025	Error during job processing	OK softkey
<i>Scan</i>	Error occurred while transferring the above file.	
<i>Effect</i>	File has not been transferred or only partially.	
<i>Explanation</i>	Check selected files	
<i>Remedy</i>	Restart transmission	
120026	Only possible in Reset	OK softkey
<i>Scan</i>	The error occurred while transferring the above file.	
<i>Effect</i>	File was not transferred or only incompletely.	
<i>Explanation</i>	The selected data can be transferred in RESET mode only.	
<i>Remedy</i>	Trigger NC Reset and transfer; start again.	
<i>Note</i>	Applies as from SW 4.4	
120027	Error in file structure	OK softkey
<i>Scan</i>	The error occurred while transferring the above file.	
<i>Effect</i>	File was not transferred or only incompletely.	
<i>Explanation</i>	Syntax error in the file structure. Data after end of list. An item of data follows M02.	
<i>Remedy</i>	Make the corrections in the file.	
<i>Note</i>	Applies as from SW 4.4	
120028	Cycle disable set	OK softkey
<i>Scan</i>	The error occurred while a file was being transferred.	
<i>Effect</i>	File has not been transferred or only partially.	
<i>Explanation</i>	The cycle disable can be set for several cycles.	
<i>Remedy</i>	Remove cycle disable for the cycles concerned.	
120029	No communication to NCK	
<i>Scan</i>	See alarm 110113	
<i>Effect</i>		
<i>Explanation</i>		
<i>Remedy</i>		
120030	Option not available	OK softkey
<i>Scan</i>	When activating the PG function	
<i>Effect</i>	S5 package for programming functions cannot be called up.	
<i>Explanation</i>	None	
<i>Remedy</i>	Activate option	

120031	Wrong option password	OK softkey
<i>Scan</i>	The password entered for the options is incorrect.	
<i>Effect</i>	The displayed options cannot be altered.	
<i>Explanation</i>	None	
<i>Remedy</i>	Enter correct password.	
120032	Error in options list ...	OK softkey
<i>Scan</i>	When activating option <Nxxx>.	
<i>Effect</i>	The option in question cannot be activated or deactivated.	
<i>Explanation</i>	None	
<i>Remedy</i>	Call service!	
120033	Help text ... not found	OK softkey
<i>Scan</i>	When operating the I key in the diagnosis alarm basic display.	
<i>Effect</i>	No alarm/message help texts displayed.	
<i>Explanation</i>	None	
<i>Remedy</i>	Copy the file "MELDINFO" from the standard branch (master control/ language) to user under Installation PC data with the softkey Preset. The file can then be edited in the user branch and also stored if the password is set.	
120034	The hard disk is full	OK softkey
<i>Scan</i>	PC data preset Save PLC program	
<i>Effect</i>	It is not possible to store or create the data.	
<i>Explanation</i>	–	
<i>Remedy</i>	Delete data not required.	
120035	PLC program ... cannot be created	OK softkey
<i>Scan</i>	Save PLC program	
<i>Effect</i>	The PLC user program could not be saved on the hard disk in the usual way.	
<i>Explanation</i>	–	
<i>Remedy</i>	–	
130000	Workpiece/file exists already	OK softkey
<i>Scan</i>	NEW / CREATE / mask for entering an object name	
<i>Effect</i>	No new object can be created	
<i>Explanation</i>	Workpiece or file already exists in the data management and cannot be created again.	
<i>Remedy</i>	Enter a new/different name	
130001	No element selected	OK softkey
<i>Scan</i>	PROGRAM or EDIT	
<i>Effect</i>	A file cannot be processed	
<i>Explanation</i>	Cursor is positioned on ".." or "–", the file that can be processed has not been selected	
<i>Remedy</i>	Select a file with the cursor	

1.5.1 Alarm description

130002	No file type selected	OK softkey
<i>Scan</i>	NEW / CREATE	
<i>Effect</i>	New file cannot be created	
<i>Explanation</i>	No element selected in the file type list for creating new files (system error)	
<i>Remedy</i>	New programming / data selector version	
130003	No write access for this file	OK softkey
<i>Scan</i>	EDIT	
<i>Effect</i>	File cannot be processed	
<i>Explanation</i>	A file has been chosen for which you have no authorization for making changes	
<i>Remedy</i>	Set keyswitch to > 0 setting; enter password in the diagnostics	
130004	No read access for this file	OK softkey
<i>Scan</i>	EDIT	
<i>Effect</i>	File cannot be processed	
<i>Explanation</i>	A file has been selected for which read access does not exist	
<i>Remedy</i>	Position key switch to position > 3; enter password in diagnosis	
130005	There is no standard job list	OK softkey
<i>Scan</i>	NEW / JOG LIST / CREATE → Create a new job list	
<i>Effect</i>	Job list cannot be created	
<i>Explanation</i>	The standard job list and/or the "EMPIRICAL VALUES" directory is missing from the data management. When a new job list is created, this is copied onto the new job list.	
<i>Remedy</i>	Inform system service	
130006	Job list does not exist	OK softkey
<i>Scan</i>	JOB LIST	
<i>Effect</i>	Job list cannot be processed	
<i>Explanation</i>	No job list exists under a workpiece	
<i>Remedy</i>	Create a job list under the workpiece node using the softkey NEW	
130007	Workpiece/file cannot be created	OK softkey
<i>Scan</i>	NEW / CREATE / mask for entering an object name	
<i>Effect</i>	No new workpiece or file can be created	
<i>Explanation</i>	Error in data management configuration memory too small Incorrect object name (error message from data management create function)	
<i>Remedy</i>	Create more memory New programming/data management version	
130008	Please select workpiece	OK softkey
<i>Scan</i>	PROGRAMMING	
<i>Effect</i>	Workpiece cannot be processed	
<i>Explanation</i>	Cursor positioned on "...", a workpiece has been selected which cannot be processed	
<i>Remedy</i>	Position the cursor on a workpiece name	

130009	Please state name	OK softkey
<i>Scan</i>	NEW / CREATE / mask for entering object name	
<i>Effect</i>	No new workpiece or file is created	
<i>Explanation</i>	No name was entered The name was not terminated with input	
<i>Remedy</i>	Enter a name or terminate input with input key	
130010	Only NCK-data/part programs can be edited	OK softkey
<i>Scan</i>	EDIT	
<i>Effect</i>	File cannot be processed	
<i>Explanation</i>	A file was not selected (recognizable by the length, length 0 also possible) for processing with the editor	
<i>Remedy</i>	Place the cursor on an element with a length entry	
130011	Select a workpiece for job list	OK softkey
<i>Scan</i>	JOB LIST	
<i>Effect</i>	Job list cannot be processed	
<i>Explanation</i>	The job list of the selected workpiece cannot be processed	
<i>Remedy</i>	Place the cursor on a workpiece	
130012	There is no programming system	OK softkey
<i>Scan</i>	PROGRAMMING	
<i>Effect</i>	Graphic programming not possible	
<i>Explanation</i>	Graphic programming system does not exist.	
<i>Remedy</i>	Install GRAPHIC PROGRAMMING SYSTEM option.	
130013	Name not allowed	OK softkey
<i>Scan</i>	NEW / CREATE / mask for entering file name	
<i>Effect</i>	No new object created	
<i>Explanation</i>	Syntax of entered name is incorrect, only alphanumeric characters and “_” permitted	
<i>Remedy</i>	Enter correct name	
130014	No workpiece/file may be created	OK softkey
<i>Scan</i>	Softkey NEW at top level “LOCAL” “GLOBAL”	
<i>Effect</i>	No new object created	
<i>Explanation</i>	The data management tree does not allow the creation of a directory on this level	
<i>Remedy</i>	–	
130015	Access denied	OK softkey
<i>Scan</i>	PROGRAMMING	
<i>Effect</i>	Workpiece cannot be processed	
<i>Explanation</i>	Incorrect keyswitch setting No authorization for processing workpiece	
<i>Remedy</i>	Turn keyswitch to setting 1 or 2; enter password in DIAGNOSIS	

1.5.1 Alarm description

130016	No more memory space available	OK softkey
<i>Scan</i>	NEW / CREATE	
<i>Effect</i>	Directory/file cannot be created	
<i>Explanation</i>	No memory left to create the directory/file	
<i>Remedy</i>	Workpieces/files which are no longer required can be deleted	
130017	Disk full! No graphical programming	OK softkey
<i>Scan</i>	PROGRAMMING	
<i>Effect</i>	Workpiece cannot be machined	
<i>Explanation</i>	No memory available to load programming system data	
<i>Remedy</i>	Workpieces/files which are no longer required can be deleted	
130018	File not available	OK softkey
<i>Scan</i>	EMPIRICAL VALUES	
<i>Effect</i>	Empirical values file cannot be processed	
<i>Explanation</i>	There is no empirical value file in the data management tree that can be copied into the user branch for processing.	
<i>Remedy</i>	Notify service	
130019	Data transfer in progress! Terminate?	Abort/OK softkey
<i>Scan</i>	–	
<i>Effect</i>	–	
<i>Explanation</i>	If an MMC CPU with 8 MB is available, the graphic programming system (WOP) must not be started while the V24 data transfer is in progress.	
<i>Remedy</i>	<ul style="list-style-type: none"> By pressing the OK softkey, the V24 data transfer is aborted. By pressing the ABORT softkey, WOP is not started. 	
<i>Note</i>	Applies as from SW 4.4	
130020	File has been altered! Lose change?	Abort/OK softkey
<i>Scan</i>	–	
<i>Effect</i>	–	
<i>Explanation</i>	File was exited after an alteration with RECALL and without softkey SAVE.	
<i>Remedy</i>	<ul style="list-style-type: none"> Press ABORT softkey if further changes are to be made in the edit mode. Press OK softkey if the changes are to be lost. 	
<i>Note</i>	Applies as from SW 4.4	

Note You will find below a list of all possible alarms and messages that can occur in the SIMULATION area.

The messages and alarms are self-explanatory or their explanation is obvious from the last operator action. The majority of alarms and messages point to a programming error in the blocks of the simulation program. An explanation of the programming functions is beyond the scope of this documentation. Please refer to the Programming Guide.

Some alarms and messages include an identifier %... in their formatting. These are replaced in the display by the cause, e.g.:

141497 "Workpiece %1 is being loaded"

Display:

141497 "Workpiece PART 3 is being loaded"

141102	"Error on workpiece selection !"
141104	"No program selected !"
141105	"Select. allowed only after end of prog./RESET"
141106	"Workpiece empty, please make new selection"
141107	"Program selection error! Reselect tool!"
141122	"Scale modification not allowed !"
141123	"Illegal scale value !"
141124	"Coordinate rotation not allowed !"
141130	"Turning allowed in perspective view only !"
141132	"Function not allowed with only one view"
141134	"Cut allowed with 3D and side view !"
141135	"Please select numerical input."
141136	"Representation no longer possible"
141137	"A cut is not possible in TURNING mode."
141140	"Please exit the vertical menu first"
141141	"No end-of-program (M02/M30/M17) programmed"
141142	"Program stop due to M0/M1."
141490	"Memory limitation, please terminate simulation!"
141495	"Parameter save in progress"
141496	"Initialize simulation"
141497	"Workpiece %1 is being loaded."
141498	"Internal error ! Result might be faulty !"
141499	"Internal error ! Please end simulation!"
142001	"No blank available !"
142002	"No tools set up !"
142003	"No workholder available !"
142004	"Error on loading machine data !"
142005	"Error on loading R parameters"
142006	"Error on loading the ZOA data !"

1.5.1 Alarm description

142007	"Error on loading the TOA data !"
142008	"Error on loading the SEA data !"
142009	"No operational data, default setting !"
142010	"No machined parts available !"
142011	"Too many points in contour %1 !"
142015	"Error on storing operational data !"
142020	"Error on loading the TOA data !"
142021	"Error on loading the TOA data !"
142022	"No D number in tool list !"
142025	"Programm %1 does not exist !"
142026	"Syntax error in job list !"
142027	"Job list could not be evaluated"
142030	"Axis in transmit data set not defined"
142031	"Axis in transmit data expected to be fictit."
142032	"Axis in transmit data set expected to be real"
142033	"Axis in transmit data set exists several times"
142034	"Non-assigned transmit MD incorrectly initialized"
142035	"No data set exists for TRANSMIT !"
143000	"Access via P address does not exist !"
143001	"Pointer in P cell invalid !"
143002	"R parameter address invalid on READING !"
143003	"R parameter address invalid on WRITING !"
143004	"TO area not available !"
143005	"There is no D compensation memory !"
143006	"No access to settable zero offset"
143007	"No access to progr. zero offset"
143008	"Specified angle No. not equal to 1 !"
143009	"No access to settable coordinate rotation"
143010	"No access to progr. coordinate rotation"
144051	"Circle end point error in circle programming"
144052	"Full circle with circle rad.prog. not allowed"
144053	"Radius too small for programmed circle"
144100	"Wrong input for contour definition !"
144101	"No intersection possible !"
144102	"Angle value not allowed !"
144103	"Radius value not allowed !"

144104	"Wrong selection G02/03 !"
144105	"Block sequence wrong !"
144106	"Values for contour definition faulty !"
144108	"Wrong axis programmed for cont. definition!"
144109	"Target position cannot be reached !"
144150	"Scale modification not allowed !"
144151	"Illegal scale value !"
144152	"Coordinate rotation not allowed !"
144200	"Smooth appr. + retraction cannot be selected!"
144201	"Not poss. to deselect smooth appr. + retr. !"
144202	"Wrong smooth approach and retraction plane !"
144203	"No TRC chosen on selecting smooth app.+retr.!"
144204	"No added axis with smooth appr. + retr. !"
144205	"Select/deselect TRC not possible !"
144206	"Contour violation TRC !"
144207	"Too many blocks programmed without path !"
144208	"No equidistant intersection available!"
144209	"Transform. not allowed with active TRC !"
144210	"No axis added with TRC !"
144211	"No added axis with TLC !"
144300	"Transmit grouping %1 in channel %2 illegal !"
144301	"Current transformation not deselected !"
144302	"Transformation type %1 not defined"
144304	"Axis %1 cannot be traversed with TRANSMIT !"
144305	"Feed is zero !"
144309	"Circle end point error in interpolation !"
144311	"G4 S progr., spindle not rotating !"
144312	"G96 S progr., leading spindle missing!"
144313	"Velocity limitation"
144316	"Rotary axis feed G98: G1 or G36 required !"
144318	"Path thru transformation centre not allowed"
144319	"Veloc. of transmit rotary axis too high"
144320	"Veloc. of transmit linear axis too high"
144350	"Axis %1 not possible. Only 3 axes at present"
144351	"Axis %2 not permitted in channel %1!"
144352	"Axis %2 disabled in channel %3!"

1.5.1 Alarm description

144353	"Spindle %2 not in rotary axis mode !"
144354	"Setting setpoint for axis %1 not allowed!"
144355	"Setting setpoint for axis %1 not allowed!"
144356	"Limit on software limit switch"
144357	"Spindle in other channel active !"
144358	"Rotary axis mode not possible for spindle !"
144359	"Spindle %1 currently being moved as an axis !"
144450	"@71x: Unable to read R parameters"
144451	"@71x: Unable to write R parameters"
144452	"@71x: Unable to copy R parameters"
144453	"@711: No direction straight line defined"
144454	"@711: No contour element stored in R para."
144455	"@711: No circle element stored in R para."
144456	"@711: Circle element exceeds 2 quadrants"
144457	"@711: No point of intersection available"
144458	"@710: %1 could not be opened"
144459	"@710: Wrong control parameter in R%1"
144460	"@710: NC block from contour %1 cannot be read"
144461	"@710: Invalid NC block in contour %1"
144462	"@710: Invalid ident. for direct. of rotation"
144463	"@710: NC block in contour %1 has error"
144464	"Circle not programmed in selected plane"
144465	"DIN: %1"
144501	"No more memory space available !"
144502	"No more memory space available !"
144504	"Error in '%1' geometry !"
146000	"DIN: ... %1 ..."
146001	"Overlong line cut off"
146002	"Block not concluded with Line Feed"
146003	"Jump destination %1 not found"
146004	"Program SPF%1 not available"
146005	"Too many SPFs: SPF%1 not opened"
146006	"M17 not allowed in MPF"
146007	"M02/M30 not allowed in SPF"
146010	"Comments/program coordination nested"
146011	"End of line in comments/program coordination"

146012	"Invalid character in block"
146013	"Too many characters in the block"
146014	"One point alone is not a permissible number"
146015	"Block too long: closing brackets inserted"
146020	"Only R parameters allowed here"
146021	"Only constant allowed here"
146022	"Only constant or R parameters allowed here"
146023	"Only the first sign is considered"
146024	"Illegal address extension"
146025	"Illegal value"
146026	"Illegal R parameter number"
146027	"Illegal R parameter number"
146028	"Illegal constant in @ function"
146029	"Sign in address extension not allowed"
146030	"Illegal constant"
146040	"=' is missing after target parameter"
146041	"'R' must be followed by number or '='"
146042	"Only 'R', 'P', or constant allowed here"
146043	"Division by ZERO"
146044	"Error in calculation"
146050	"Illegal beginning of word"
146051	"Too much information in the block"
146052	"Value must be an integer"
146053	"R parameter number not an integer"
146054	"Illegal word value"
146055	"Faulty word"
146060	"%1 word already programmed in block"
146061	"Too many M functions in the block"
146062	"Rap.aux.fct. not allowed because %1 value neg"
146063	"Address extension not allowed for %1 word"
146064	"Selected D number not available"
146065	"S word must follow M19"
146066	"Spindle number not allowed"
146067	"M function of Group %1 already programmed"
146068	"Meaning of P word not defined"
146069	"The block no. is not at the beginning of line"

1.5.1 Alarm description

146070	"Illegal axis address extension"
146071	"Address with extension not allowed"
146072	"Illegal address"
146073	"Address extension not allowed for dwell"
146074	"Value overflow (negative)"
146075	"Value overflow (positive)"
146076	"Main block allowed in program level 0 only"
146077	"P word must be directly behind G92"
146078	"P word must immediately follow L-word"
146079	"Word is not allowed after G%1"
146080	"G%1: I, J, K, IKA or IKP cannot be allocated"
146081	"G%1: Same spindle programmed more than once"
146082	"G%1: I before J is missing"
146083	"Multiple transform'n select/deselect in block"
146084	"Selection can only be made in deselected pos."
146085	"Valid transformation data set missing"
146100	"Further alarms in the block are suppressed"
146110	"Repeated selection of a G group not allowed"
146111	"Illegal G function"
146112	"Conflict: @706 <-> G53"
146113	"G%1: Block cannot be simulated"
146114	"G%1 interpreted as LF"
146115	"Smooth retraction requires G40"
146116	"G40 has already been set by WAB"
146117	"Function no longer effective"
146118	"Transmit cannot be simulated"
146120	"G%1 is not simulated"
146130	"@ function is not simulated"
146131	"@ function cannot be simulated exactly"
146132	"@ function for PLC is not simulated"
146133	"@ number not allowed"
146134	"Illegal @ function"
146135	"Value must be an integer here"
146136	"Value overflow"
146137	"Value must be a bit pattern here"
146138	"Not enough parameters for @ function"

146139	"End of line in @ parameter list"
146140	"Type of parameter illegal"
146141	"Illegal sign"
146142	"Only value 0 or 1 allowed here"
146143	"Only values 0 to 7 allowed here"
146144	"No. of machine/setting data not allowed"
146145	"Type of machine data/setting data illegal"
146146	"1st parameter: quantity must be positive"
146147	"Stack limit exceeded/not reached"
146148	"Source/target is in stack area"
146149	"Illegal MIB address"
146150	"MIB cell not initialized"
146151	"G group function non-modal"
146152	"R number for result of @713 not allowed"
146153	"Axis not defined"
146154	"No IPO parameter exists for axis"
146155	"@ expression contains errors"
146156	"Identifier in @3FF cannot be simulated"
146157	"Type in 3FF data group cannot be simulated"
146158	"No D number active – cycle alarm 4100"
146159	"Tool radius = 0 – cycle alarm 4101"
146160	"Cutter radius too large – cyc. alarm 4102"
146161	"Tool too wide – cycle alarm 4103"
146162	"No M03/M04 programmed – cycle alarm 4120"
146163	"Spindle not in tolerance – cycle alarm 4121"
146164	"Diam. of fin.part too small – cyc. alarm 4140"
146165	"Option not available – cycle alarm 4180"
146166	"Check definition R (Nxxx) – cycle alarm 4200"
146167	"Thread length too short – cycle alarm 4153"
146168	"Cycle alarm number not defined "
146169	"Only angle No.1 allowed"
146170	"Only axis 1 to 9 possible"
146171	"@ position in block invalid"
146200	"The axis is disabled according to axis MD"
146201	"G16 block allows only signs in axis word"
146202	"Axis already programmed in block"

1.5.1 Alarm description

146203	"After axis etc: do not change system of units"
146204	"Too many axes programmed in the block"
146205	"Too many radii and/or chamfers in the block"
146206	"Too many angles programmed in the block"
146207	"Too many interpolation parameters in block"
146208	"Only K parameters allowed here"
146209	"R parameter not allowed as spline coefficient"
146210	"Spline coefficient must be an integer"
146211	"X word not allowed"
146212	"Dwell already programmed in block"
146213	"Stop angle has been corrected 'modulo 360'"
146214	"Negative S value for speed not allowed"
146215	"Too many components for contour def. in block"
146216	"G92 S/ G96 S allowed for leading spindle only"
146217	"Illegal axis setpoint"
146218	"Illegal rotary axis setpoint"
146219	"Illegal modulo rotary axis setpoint"
146220	"G%1 not allowed in this block"
146221	"Axis with act. transformation illegal"
146231	"MD%1: MD could not be read"*
146232	"MD%1: name of radius/chamfer not allowed"*
146233	"MD%1: name of angle not allowed"*
146234	"MD%1: name conflict: radius/chamfer <--> angle"*
146235	"MD%1: addr.ext. not allowed for radius/chamfr"*
146236	"MD%1: address extension not allowed for angle"*
146237	"MD%1: input resolution not allowed"*
146238	"MD%1: axis name not allowed"*
146239	"MD%1: axis not allowed in mode group"*
146240	"MD%1: axis name assigned several times"*
146241	"MD%1: IPO parameters not allowed"*
146242	"MD%1: axis name not allowed for plane"*
146243	"MD%1: G number not allowed as initial setting"*
146253	"Rapid traverse block was generated"
146254	"G15 is not simulated"

* Simulation must be cancelled and a corrected set of machine data activated with the load list by reselecting.

146255	"Spline interpolation G06 cannot be simulated"
146256	"Spline interpolation G06 cannot be simulated"
146261	"In-process measurement @720 is not simulated"
146262	"Program coord. [...] not being simulated"
146263	"Coupled motion is not simulated"
146264	"G200 will not be simulated"
146265	"G103 is not simulated"
146266	"G104 is not simulated"
146267	"G105 is not simulated"
146268	"G119 is not simulated"
146269	"G24 is not simulated "
146271	"Ramp-up time G92 T is not simulated"
146272	"Starting angle offset G92 A is not simulated"
146273	"Working area limitation G25 is not simulated"
146274	"Working area limitation G26 is not simulated"
146275	"M36/M37 is not simulated"
146276	"Exact stop G60 is not simulated"
146277	"Velocity reduction G62 is not simulated"
146278	"Velocity reduction G64 is not simulated"
146290	"Context: measurement function @720"
146291	"Context: G function of 7th group"
146292	"Context: scale modification G51"
146293	"Context: synchronized spindle stop M19S"
146294	"Context: program jump"
146295	"Context: block to be skipped"
146296	"Context: dwell"
146297	"Context: refpt preprocess f. stock rem. cycle"
146298	"Context: intersection calc.f.stock rem. cycle"
146299	"Context: plane selection with free axis sel."
146300	"Context: cylindrical interpolation G92P"
146301	"Context: transformation"
146302	"Context: approach reference point"
146303	"Context: pole specification"
146304	"Context: spline interpolation is selected"
146305	"Context: block preprocessing stop by @714"
146307	"Context: G200 block"

1.5.1 Alarm description

146310	"Context: G15 block expected"
146311	"Context: G220–G222 block expected"
146312	"Context: G420–G426 block expected"
146320	"Conflict: measuring function @720 not allowed"
146321	"Conflict: G function of 7th group not allowed"
146322	"Conflict: scale modification not allowed"
146323	"Conflict: synchr. spindle stop not allowed"
146324	"Conflict: jump not allowed but still performed"
146326	"Conflict: dwell not allowed"
146327	"Conflict: ref.pt preprocessing not allowed"
146328	"Conflict: intersection calc. not allowed"
146329	"Conflict: plane selection not allowed"
146330	"Conflict: cylindr. interpolation not allowed"
146331	"Conflict: transformation not allowed"
146332	"Conflict: ref. point approach not allowed"
146333	"Conflict: pole selection not allowed"
146335	"Conflict: @714 not allowed"
146337	"Conflict: G200 block not allowed"
146340	"Conflict: G15 block invalid"
146341	"Conflict: G200–G222 block invalid"
146342	"Conflict: G420–G426 block invalid"
146400	"G%1: more than 1 radius in block"
146401	"G%1: radius is missing -> value 0 added"
146402	"G%1 ignored because of soft approach/retract."
146403	"G%1: plane axis is missing in block"
146404	"G48 prog. w/o previous approach / distance 0"
146405	"G%1: radius 0 programmed"
146406	"G%1: amount formed for negative radius"
146407	"G%1: allowed with G0/G1/G2/G3 only"
146410	"G%1: interpolation parameter is missing"
146411	"G%1:several thread leads prog. ->1st is valid"
146412	"G%1: thread lead param. does not match axes"
146415	"G%1: 1 axis or 2 axes are expected"
146416	"G%1: thread lead must be positive"
146417	"G%1: no axis programmed"
146418	"G%1: thread lead change F is missing"

146420	"G%1: only one rotary axis allowed"
146421	"G%1: 2 or 3 axes are expected"
146422	"G%1: Thread pitch parameter = 0"
146423	"G36: C is plane axis but G%1 is selected"
146430	"G%1: no pole defined yet"
146431	"G%1: negative radius illegal"
146432	"G%1: programmed axis is not a pole axis"
146433	"G%1: more than 2 axes programmed"
146434	"G%1: program either axis or radius"
146435	"G%1: program either axis or angle"
146436	"G%1: pole definition with G90 is missing"
146437	"G%1: pole definition only with exactly 2 axes"
146438	"G%1: G91 only allowed for existing pole axes"
146439	"G%1: no radius in block"
146440	"G%1: negative radius illegal"
146441	"G%1: no angle in block"
146442	"G%1: G91 for angle only allowed after G90"
146443	"G%1: more than one radius programmed"
146444	"G%1: more than one angle programmed"
146450	"G%1: no axes programmed"
146451	"Rapid trav. for contour definit'n not allowed"
146452	"G%1: sequence/number of elements illegal"
146453	"Only positive radius allowed here"
146454	"Progr. elements do not form a trav. block"
146455	"Contour definition: no further axis possible"
146456	"Contour definition: more than 2 axes progr."
146457	"G%1: G935 must be programmed with G1"
146458	"Contour definition: faulty circle parameters"
146459	"Contour def.: circle param. progr. sev. times"
146460	"No further circular axis possible"
146461	"Faulty circle parameters"
146470	"G16: at least 2 axes expected"
146471	"G%1: plane axes are identical"
146472	"G16: max. 4 axes can be simulated"
146480	"Axis prog. -> C axis on/off ignored"
146481	"M19 S: other M functions ignored"

1.5.1 Alarm description

146482	"Only 1 spindle can be programmed in a block"
146483	"M19 not allowed here"
146484	"M groups not allowed in this block"
146490	"G06: inch/metric conversion not allowed"
146491	"G06: axes to IPO parameters are missing"
146492	"G06: here only IPO parameter I allowed"
146493	"G06: positive path length I expected"
146494	"G06: exactly 3 coefficients K expected"
146500	"L%1 ignored, because M2, M30 or M17 in block"
146501	"G%1 desel., because M2, M30 or M17 in block"
146502	"G%1 deselected, because L call in block"
146510	"@720 is only possible in traversing block"
146511	"@714 must be on its own in the block"
146512	"@%1 is not permitted in contour program"
146513	"Traversing block must be in its own block"
146520	"G96: cutting velocity S is missing"
146521	"Feed is missing"
146522	"G98 allowed with G0/G1/G36 only"
146523	"G96 not allowed together with M19"
146524	"G36: G98 is generated and G%1 is deselected"
146530	"Option for G%1 is missing"
146531	"Cylindrical interpolation option is missing"
146532	"Circle radius programming option is missing"
146533	"Contour definition SPRINT option missing"
146534	"Option 5D helical is missing"
146535	"Program coordination option is missing"
146536	"Reference point preprocessing option missing"
146537	"Option extended thread package is missing"
146550	"G%1 not allowed here -> ignored"
146551	"G04 block: dwell F, X or S is missing"
146552	"S/T/angle is missing -> G92 ignored"
146553	"G92 T: T value > 5 not allowed"
146554	"G92 P: exactly one axis expected"
146555	"G92 P: axis is not a rotary axis"
146556	"G%1: axes for working area limit. are missing"
146557	"G%1: axis or angle is missing"

146558	"G%1: exactly one axis expected"
146559	"G63 allowed with G01 only, not with G%1"
146560	"P factor is missing with G51"
146561	"G175 inserted internally because of G%1"
146562	"G175 inserted internally because of @706"
146563	"G175 inserted internally because of D word"
146564	"G%1: only absolute ZO possible with G51"
146565	"@711: Both plane axes are expected"
146566	"@711: G0, G1, G10 or G11 must be active"
146567	"G15: 3 linear and 2 rotary axes expected"
146568	"G%1 is not simulated"
146569	"G%1: No drives programmed"
146570	"G%1: Master drive missing"
146571	"G%1: Max. 1 spindle allowed on master drives"
146572	"G%1: Slave drive per MD invalid"
146573	"G%1: I,J,K,IKA,IKP for slave drive illegal"
146574	"G%1: Axes, IKA or IKP cannot be simulated"
146575	"G%1: No position for drives allowed"
146576	"G%1: No position for slave drives allowed"
146577	"G%1: Position for slave drive is missing"
146578	"G%1: Position for a master drive is missing"
146579	"G%1: I,J or IKP for master drives illegal"
146580	"G%1: Link. struct. K does not permit IKA word"
146581	"G%1: Linking structure K requires IKA word"
146582	"G%1: IKA word expected due to IKP word"
146583	"G%1: K word not allowed"
146600	"DIN: ... %1 ..."
146700	"G%1 block: too much information in block"
146701	"Block information before jump ignored"
146702	"Block with G92 P: too much info in block"
146703	"Too much information in spline coeff. block"
146704	"Block with G92 T: too much info in block"
146705	"Too much information in block with G92 angle"
146706	"Block with G92 S: too much info in block"
146707	"Block with M19 S: too much info in block"
146708	"Block with @710: too much info. in block"

1.5.1 Alarm description

146709	"Block with @711: too much info. in block"
146730	"Axis not allowed here → ignored"
146731	"IPO parameters not allowed here → ignored"
146732	"Radii not allowed here → ignored"
146733	"Angle not allowed here → ignored"
146734	"F word not allowed here → ignored"
146735	"M words not allowed here → ignored"
146736	"S word not allowed here → ignored"
146737	"T word not allowed here → ignored"
146738	"H word not allowed here → ignored"
146739	"D word is not allowed here → ignored"
146740	"Comments not allowed here"
146741	"-word not allowed here → ignored"
146742	"Only @714 allowed here. Other @ ignored"
146743	"@706/@715/@720 not allowed here → ignored"
146744	"Progr. coord. [...] illegal here → ignored"
146745	"L word not allowed here → ignored"
146746	"N word not allowed here → ignored"
146747	"P word not allowed here → ignored"

160001 Axis already assigned**OK softkey***Scan* On "START"*Effect* The selected function is not started*Explanation* No further startup functions can be started with the defined axis number*Remedy* Terminate the startup function already active for this axis**160002 Axis not configured or configured wrongly****OK softkey***Scan* Startup application*Effect* Startup function is not executed*Explanation* Selected axis is not available*Remedy* Select available axis**160003 Drive module is not configured or incorrectly****OK softkey***Scan* Startup application*Effect* Startup function is not executed*Explanation* Selected drive number is not available*Remedy* Select available drive module

160004	Data code ... , error ... , 0x ...	OK softkey
<i>Scan</i>	Startup application	
<i>Effect</i>	Undefined	
<i>Explanation</i>	Internal system error with stated error parameters	
<i>Remedy</i>	Terminate application and repeat procedure, notify service if necessary.	
160005	Function code ... , error ... , 0x ...	OK softkey
<i>Scan</i>	Startup application	
<i>Effect</i>	Undefined	
<i>Explanation</i>	Internal system error	
<i>Remedy</i>	Terminate application and repeat procedure, notify service if necessary.	
160006	File transfer ID ... , error ... , 0x ...	OK softkey
<i>Scan</i>	Startup application	
<i>Effect</i>	Undefined; measuring data lost	
<i>Explanation</i>	<ul style="list-style-type: none"> • Internal system error • File transfer error when reading out a measurement buffer with specified error parameters. 	
<i>Remedy</i>	Check MMC system configuration and hardware	
160007	Measurement/drive type combination not allowed	OK softkey
<i>Scan</i>	When starting measuring functions	
<i>Effect</i>	The selected function is not started	
<i>Explanation</i>	The selected function is not possible with the addressed drive type	
<i>Remedy</i>	None	
160008	Mode/drive type combination not allowed	OK softkey
<i>Scan</i>	When starting measuring functions	
<i>Effect</i>	The selected function is not started	
<i>Explanation</i>	The selected function is not possible with the addressed drive type.	
<i>Remedy</i>	None	
160009	Mode/signal type combination not allowed	OK softkey
<i>Scan</i>	When starting measuring functions	
<i>Effect</i>	The selected function is not started	
<i>Explanation</i>	The selected signal type is not available	
<i>Remedy</i>	Correct signal selection	
160010	Too many function generators operating	OK softkey
<i>Scan</i>	When function generator is started	
<i>Effect</i>	Function generator is not started	
<i>Explanation</i>	Only function generator at a time can be active	
<i>Remedy</i>	Stop active function generator and repeat procedure	

1.5.1 Alarm description

160011	File name ... invalid	OK softkey
<i>Scan</i>	When selecting file functions	
<i>Effect</i>	Entries rejected	
<i>Explanation</i>	File names can only contain alphanumeric characters	
<i>Remedy</i>	Correct input and repeat procedure	
160012	Invalid input resolution (...)	OK softkey
<i>Scan</i>	Parameterization/starting startup functions	
<i>Effect</i>	The startup function cannot be started	
<i>Explanation</i>	See machine data description	
<i>Remedy</i>	Check/correct machine data input resolution	
160013	Invalid position control resolution (...)	OK softkey
<i>Scan</i>	Parameterization/starting startup functions	
<i>Effect</i>	The startup function cannot be started	
<i>Explanation</i>	See machine data description	
<i>Remedy</i>	Check/correct machine data position control resolution	
160014	Invalid maximum current of power section	OK softkey
<i>Scan</i>	Parameterization/starting startup functions	
<i>Effect</i>	The startup function cannot be started	
<i>Explanation</i>	See machine data description	
<i>Remedy</i>	Check/correct machine data maximum current	
160015	Invalid maximum axis velocity/spindle speed	OK softkey
<i>Scan</i>	Parameterization/starting startup functions	
<i>Effect</i>	The startup function cannot be started	
<i>Explanation</i>	See machine data description	
<i>Remedy</i>	Check/correct machine data for maximum velocities	
160016	Invalid scan time of current controller	OK softkey
<i>Scan</i>	Parameterization/starting startup functions	
<i>Effect</i>	The startup function cannot be started	
<i>Explanation</i>	See machine data description	
<i>Remedy</i>	Check/correct machine data for current controller scan time	
160017	Invalid scan time of position controller	OK softkey
<i>Scan</i>	Parameterization/starting startup functions	
<i>Effect</i>	The startup function cannot be started	
<i>Explanation</i>	See machine data description	
<i>Remedy</i>	Check/correct machine data for position controller scan time	
160018	Invalid scan time of speed controller	OK softkey
<i>Scan</i>	Parameterization/starting startup functions	
<i>Effect</i>	The startup function cannot be started	
<i>Explanation</i>	See machine data description	
<i>Remedy</i>	Check/correct machine data for speed controller scan time	

160019	Invalid tacho adaptation	OK softkey
<i>Scan</i>	Parameterization/starting startup functions	
<i>Effect</i>	The startup function cannot be started	
<i>Explanation</i>	See machine data description	
<i>Remedy</i>	Check/correct machine data for tacho adaptation	
160020	A measuring function is already active	OK softkey
<i>Scan</i>	Starting startup functions	
<i>Effect</i>	The startup function cannot be started	
<i>Explanation</i>	Only one measuring function at a time can be active	
<i>Remedy</i>	Stop previous measuring function and repeat procedure	
160022	Illegal bus selection	OK softkey
<i>Scan</i>	When starting DAC output	
<i>Effect</i>	DAC output cannot be started	
<i>Explanation</i>	Startup application internal error; it is not possible to access 611D hardware	
<i>Remedy</i>	End application and repeat procedure	
160023	Illegal component	OK softkey
<i>Scan</i>	When starting DAC output	
<i>Effect</i>	DAC output cannot be started	
<i>Explanation</i>	Signal selection does not correspond to drive components	
<i>Remedy</i>	Correct parameterization	
160024	There is no signal	OK softkey
<i>Scan</i>	Starting DAC output	
<i>Effect</i>	DAC output cannot be started	
<i>Explanation</i>	The selected signal is not available	
<i>Remedy</i>	Correct signal selection	
160025	Protected data area selected (segment)	OK softkey
<i>Scan</i>	Starting DAC output from memory location	
<i>Effect</i>	DAC output cannot be started	
<i>Explanation</i>	Selected address area is not allowed	
<i>Remedy</i>	Correct segment parameterization	
160026	Protected data area selected (offset)	OK softkey
<i>Scan</i>	When starting DAC output from memory location	
<i>Effect</i>	DAC output cannot be started	
<i>Explanation</i>	Selected address area is not allowed	
<i>Remedy</i>	Correct offset parameterization	
160027	Illegal offset parameterized	OK softkey
<i>Scan</i>	When starting DAC output	
<i>Effect</i>	DAC output cannot be started	
<i>Explanation</i>	Offset value is outside the permissible range	
<i>Remedy</i>	Correct offset value	

1.5.1 Alarm description

160028	Illegal shift factor parameterized	OK softkey
<i>Scan</i>	When starting DAC output	
<i>Effect</i>	DAC output cannot be started	
<i>Explanation</i>	Shift factor is outside permissible range	
<i>Remedy</i>	Correct shift factor	
160029	Missing target hardware	OK softkey
<i>Scan</i>	When starting DAC output	
<i>Effect</i>	DAC output cannot be started	
<i>Explanation</i>	–	
<i>Remedy</i>	–	
160030	Non-available DAC started	OK softkey
<i>Scan</i>	When starting DAC output	
<i>Effect</i>	DAC output cannot be started	
<i>Explanation</i>	A drive module which is not configured has been selected	
<i>Remedy</i>	Select available drive module	
160031	Max. number of servo signals exceeded	OK softkey
<i>Scan</i>	When starting DAC output	
<i>Effect</i>	DAC output cannot be started	
<i>Explanation</i>	A maximum of 4 SERVO signals can be output through DAC channels	
<i>Remedy</i>	Reduce number of output SERVO signals	
160032	Max. number of active DACs exceeded	OK softkey
<i>Scan</i>	Parameterization/starting DAC output	
<i>Effect</i>	DAC output cannot be started	
<i>Explanation</i>	Internal startup application error	
<i>Remedy</i>	End application and repeat procedure	
160033	DAC busy from other half of two-axis module	OK softkey
<i>Scan</i>	Parameterization/starting DAC output	
<i>Effect</i>	DAC output cannot be started	
<i>Explanation</i>	Three DAC channels exist on two-axis modules for both axes	
<i>Remedy</i>	Select other output channel and repeat procedure or stop busy DAC	
160034	No axis configured	OK softkey
<i>Scan</i>	When selecting startup menus for axes	
<i>Effect</i>	Startup menu for axes disabled	
<i>Explanation</i>	Startup menu for axes needs at least one NC axis	
<i>Remedy</i>	Enter NC axis configuration	
160035	No drive module configured	OK softkey
<i>Scan</i>	Selecting menu for DAC output	
<i>Effect</i>	Startup menu for DAC is disabled	
<i>Explanation</i>	Menu for DAC output needs at least one 611D module	
<i>Remedy</i>	–	

160036	No mixed I/O module configured	OK softkey
<i>Scan</i>	When selecting menus for mixed I/O output	
<i>Effect</i>	Startup menu for mixed I/O output is disabled	
<i>Explanation</i>	Menu for mixed I/O output requires mixed I/O hardware	
<i>Remedy</i>	–	
160037	No spindle configured	OK softkey
<i>Scan</i>	When selecting startup menu for spindles	
<i>Effect</i>	Startup menu for spindles is disabled	
<i>Explanation</i>	Startup menu for spindles requires at least one NC spindle	
<i>Remedy</i>	Enter NC spindle configuration	
160038	Error on DAC initialization	OK softkey
<i>Scan</i>	When starting startup application	
<i>Effect</i>	DAC output cannot be started	
<i>Explanation</i>	Internal startup application error	
<i>Remedy</i>	Restart system and repeat procedure	
160039	Error in DAC selection for digital drives	OK softkey
<i>Scan</i>	When parameterizing DAC output	
<i>Effect</i>	DAC output cannot be started	
<i>Explanation</i>	Internal startup application error	
<i>Remedy</i>	Restart application and repeat procedure	
160040	Error in DAC selection for mixed I/Os	OK softkey
<i>Scan</i>	When parameterizing mixed I/O output	
<i>Effect</i>	Mixed I/O output cannot be started	
<i>Explanation</i>	Internal startup application error	
<i>Remedy</i>	Restart application and repeat procedure	
160041	No more memory space available	OK softkey
<i>Scan</i>	When starting startup application	
<i>Effect</i>	Startup functions cannot be executed	
<i>Explanation</i>	No more system memory available	
<i>Remedy</i>	End other area application and repeat procedure	
160042	Measured values invalid	OK softkey
<i>Scan</i>	Measuring functions	
<i>Effect</i>	Measuring function is aborted	
<i>Explanation</i>	Recorded measured values cannot be used	
<i>Remedy</i>	Check measuring parameters and repeat procedure. A higher amplitude must be selected most especially for path frequency response measurement	

1.5.1 Alarm description

160043	Illegal measurement/meas. value combination	OK softkey
<i>Scan</i>	Parameterization/starting measuring functions	
<i>Effect</i>	The measuring function cannot be started	
<i>Explanation</i>	The selected measurement is not accessible with the selected signal	
<i>Remedy</i>	Correct signal selection or measurement selection	
160044	Travel function cannot be started	OK softkey
<i>Scan</i>	When starting startup traversing movements	
<i>Effect</i>	Function cannot be started	
<i>Explanation</i>	Traversing function not possible because of an alarm, missing controller or feedrate enable	
<i>Remedy</i>	Check enables, acknowledge alarms and repeat procedure	
160045	Wrong axis/drive/channel number	OK softkey
<i>Scan</i>	Startup application	
<i>Effect</i>	Startup application cannot be started	
<i>Explanation</i>	Selected axis/drive number does not exist	
<i>Remedy</i>	Select available axis/drive number	
160046	Axis/spindle has an analog drive	OK softkey
<i>Scan</i>	When starting startup function	
<i>Effect</i>	Startup function is not started	
<i>Explanation</i>	A startup function which is not available for analog drives has been selected	
<i>Remedy</i>	Select a different startup function	
160047	Axis/spindle has an FDD drive	OK softkey
<i>Scan</i>	Softkey parameter FDD	
<i>Effect</i>	FDD parameters are not displayed	
<i>Explanation</i>	No FDD parameters exist for MSD drive	
<i>Remedy</i>	None	
160048	Axis/spindle has an FDD drive	OK softkey
<i>Scan</i>	Softkey parameter MSD	
<i>Effect</i>	MSD parameters are not displayed	
<i>Explanation</i>	No MSD parameters exist for FDD drive	
<i>Remedy</i>	None	
160049	Compare error	OK softkey
<i>Scan</i>	Startup application	
<i>Effect</i>	Function aborted	
<i>Explanation</i>	Error on internal consistency check	
<i>Remedy</i>	End application and restart	
160050	Data not available	OK softkey
<i>Scan</i>	Startup application	
<i>Effect</i>	Function aborted	
<i>Explanation</i>	Error on internal data access	
<i>Remedy</i>	End application and restart	

160051	Division by 0	OK softkey
<i>Scan</i>	Startup application	
<i>Effect</i>	Function aborted	
<i>Explanation</i>	Error on internal consistency check	
<i>Remedy</i>	End application and restart; check measuring parameters	
160052	Drive does not acknowledge messages	OK softkey
<i>Scan</i>	611D communication	
<i>Effect</i>	611D drives cannot be addressed	
<i>Explanation</i>	Communications partner on drive side is not available	
<i>Remedy</i>	Start up control/drive; deselect faulty module	
160053	Function generator already active	OK softkey
<i>Scan</i>	When starting function generator	
<i>Effect</i>	Start command is ignored if the function generator is already running	
<i>Explanation</i>	–	
<i>Remedy</i>	–	
160054	Wrong block number/file name	OK softkey
<i>Scan</i>	611D communication	
<i>Effect</i>	Function aborted	
<i>Explanation</i>	Error on internal consistency check	
<i>Remedy</i>	End application and restart	
160055	Absolutely no access rights	OK softkey
<i>Scan</i>	Startup application	
<i>Effect</i>	Startup function cannot be executed	
<i>Explanation</i>	Access to required data not possible	
<i>Remedy</i>	End application and restart	
160056	Error during job processing	OK softkey
<i>Scan</i>	611D communication	
<i>Effect</i>	Function aborted	
<i>Explanation</i>	Error on internal consistency check	
<i>Remedy</i>	End application and restart	
160057	Status does not permit job	OK softkey
<i>Scan</i>	611D communication	
<i>Effect</i>	Function aborted	
<i>Explanation</i>	Error on internal consistency check	
<i>Remedy</i>	End application and restart	
160058	Job could not be processed	OK softkey
<i>Scan</i>	Startup application	
<i>Effect</i>	Function aborted	
<i>Explanation</i>	Error on internal consistency check	
<i>Remedy</i>	End application and restart	

1.5.1 Alarm description

160059	Measurement function already active	OK softkey
<i>Scan</i>	When starting measuring function	
<i>Effect</i>	Start command is ignored if measuring function is already running.	
<i>Explanation</i>	–	
<i>Remedy</i>	–	
160060	Measurement in progress	OK softkey
<i>Scan</i>	Startup applications measuring functions	
<i>Effect</i>	–	
<i>Explanation</i>	Operational message during measuring function	
<i>Remedy</i>	–	
160061	PI function code ... , error 0x ...	OK softkey
<i>Scan</i>	Startup application	
<i>Effect</i>	Function aborted	
<i>Explanation</i>	Error on internal consistency check	
<i>Remedy</i>	End application and restart	
160062	Package sequence error	OK softkey
<i>Scan</i>	Startup application	
<i>Effect</i>	Function aborted	
<i>Explanation</i>	Error on internal consistency check	
<i>Remedy</i>	End application and restart	
160063	Press “Accept configuration” softkey	OK softkey
<i>Scan</i>	Startup application	
<i>Effect</i>	Application operating with inconsistent data	
<i>Explanation</i>	Drive configuration must be updated after NCK reset or 611D ramp-up	
<i>Remedy</i>	Press “OK” and “Accept configuration” softkeys	
160064	Log error	OK softkey
<i>Scan</i>	611D communication	
<i>Effect</i>	Function aborted	
<i>Explanation</i>	Error on internal consistency check	
<i>Remedy</i>	Start up control/drive; deselect faulty module	
160065	System error start-up application	OK softkey
<i>Scan</i>	Startup application	
<i>Effect</i>	Undefined	
<i>Explanation</i>	Startup application is no longer stable	
<i>Remedy</i>	MMC reset	
160066	Temporarily no access rights	OK softkey
<i>Scan</i>	Startup application	
<i>Effect</i>	Startup function is not executed	
<i>Explanation</i>	Application has no access rights for required data	
<i>Remedy</i>	Enter password/alter keyswitch position	

160067	Timeout	OK softkey
<i>Scan</i>	Startup application	
<i>Effect</i>	Startup function is not executed	
<i>Explanation</i>	Timeout error on internal communication	
<i>Remedy</i>	End application and restart	
160068	Illegal amplitude	OK softkey
<i>Scan</i>	Function generator or measuring function parameterization	
<i>Effect</i>	Function cannot be started	
<i>Explanation</i>	The defined amplitude is illegal	
<i>Remedy</i>	Enter sensible amplitude value	
160069	Illegal amplitude 1	OK softkey
<i>Scan</i>	Function generator parameterization (square wave)	
<i>Effect</i>	The function cannot be started	
<i>Explanation</i>	The stated amplitude is illegal	
<i>Remedy</i>	Enter sensible amplitude value	
160070	Illegal amplitude 2	OK softkey
<i>Scan</i>	Function generator parameterization (staircase)	
<i>Effect</i>	Function cannot be started	
<i>Explanation</i>	The stated amplitude is illegal	
<i>Remedy</i>	Enter sensible amplitude value	
160071	Illegal bandwidth	OK softkey
<i>Scan</i>	Function generator/measuring function parameterization	
<i>Effect</i>	Function cannot be started	
<i>Explanation</i>	The bandwidth must be \leq of half the sampling rate	
<i>Remedy</i>	Set permissible bandwidth	
160072	Illegal scaling	OK softkey
<i>Scan</i>	Function generator/measuring function parameterization	
<i>Effect</i>	The function cannot be started	
<i>Explanation</i>	–	
<i>Remedy</i>	Set permissible scaling	
160073	Illegal period duration	OK softkey
<i>Scan</i>	Function generator/measuring function parameterization	
<i>Effect</i>	The function cannot be started	
<i>Explanation</i>	–	
<i>Remedy</i>	Enter a sensible value not equal to zero	
160074	Illegal limitation	OK softkey
<i>Scan</i>	Function generator/measuring function parameterization	
<i>Effect</i>	The function cannot be started	
<i>Explanation</i>	–	
<i>Remedy</i>	Enter a lower value not equal to zero	

1.5.1 Alarm description

160075	Illegal measuring time	OK softkey
<i>Scan</i>	Measuring function parameterization	
<i>Effect</i>	The function cannot be started	
<i>Explanation</i>	The defined measuring time is too great	
<i>Remedy</i>	Enter a smaller value not equal to zero	
160076	Illegal operating mode	OK softkey
<i>Scan</i>	Function generator/measuring function parameterization	
<i>Effect</i>	The function cannot be started	
<i>Explanation</i>	Stated mode cannot be executed (check by servo/611D) Possible causes: <ul style="list-style-type: none"> • Start-up function of an axis in spindle operation • Start-up function of a spindle in C axis operation • Travel against fixed stop is active • The axis/spindle is a GI following axis/spindle • The axis/spindle is a slave axis/spindle • Start-up function of a spindle without encoder (MD 520*, bit 2) 	
<i>Remedy</i>	Enter a different operating mode	
160077	Illegal offset	OK softkey
<i>Scan</i>	Function generator/measuring function parameterization	
<i>Effect</i>	The function cannot be started	
<i>Explanation</i>	Stated value too high	
<i>Remedy</i>	Enter a smaller value	
160078	Illegal settling time	OK softkey
<i>Scan</i>	Measuring function parameterization	
<i>Effect</i>	The function cannot be started	
<i>Explanation</i>	Stated value too high	
<i>Remedy</i>	Enter smaller value	
160079	Illegal pulse width	OK softkey
<i>Scan</i>	Function generator parameterization	
<i>Effect</i>	Function cannot be started	
<i>Explanation</i>	–	
<i>Remedy</i>	Enter sensible value	
160080	Illegal ramp duration	OK softkey
<i>Scan</i>	Measuring function parameterization	
<i>Effect</i>	Function cannot be started	
<i>Explanation</i>	–	
<i>Remedy</i>	Enter smaller value	
160081	Illegal traversing range limits	OK softkey
<i>Scan</i>	Function generator/measuring function parameterization	
<i>Effect</i>	The function cannot be started	
<i>Explanation</i>	–	
<i>Remedy</i>	Enter lower value; "0" means no monitoring	

160082	Illegal signal type	OK softkey
<i>Scan</i>	Function generator parameterization	
<i>Effect</i>	The function cannot be started	
<i>Explanation</i>	The selected function is not possible with this signal	
<i>Remedy</i>	Change signal type	
160083	Value not allowed	OK softkey
<i>Scan</i>	Startup application	
<i>Effect</i>	The function is not executed	
<i>Explanation</i>	The value concerned is not within the permissible value range (negative acknowledgement with variables service)	
<i>Remedy</i>	Correct input	
160084	Value > maximum value	OK softkey
<i>Scan</i>	Function generator/measuring function parameterization	
<i>Effect</i>	The function cannot be started	
<i>Explanation</i>	The value in question exceeds the permissible maximum value	
<i>Remedy</i>	Enter lower value	
160085	Value < minimum value	OK softkey
<i>Scan</i>	Function generator/measuring function parameterization	
<i>Effect</i>	The function cannot be started	
<i>Explanation</i>	The value in question is below the permissible minimum value	
<i>Remedy</i>	Enter larger value	
160086	Max. acceleration too large Initialization value too large Fine quantization too large Number of learning runs too large	OK softkey
<i>Scan</i>	<ul style="list-style-type: none"> • Reparameterization of the maximum acceleration (function parameters of the neural quadrant error compensation) • Reparameterization of the initialization value (function parameters of the neural quadrant error compensation) • Reparameterization of the fine quantization (function parameters of the neural quadrant error compensation) • Reparameterization of the number of learning runs (function parameters of the neural quadrant error compensation) 	
<i>Effect</i>	Start-up function aborts	
<i>Explanation</i>	<ul style="list-style-type: none"> • a) The maximum working area has been entered as a value that is greater than allowed in MD 276* and the function generator has been started with this. • b) The maximum working area exceeds internal format limits (even without function generator start).. • The initialization value of the neural quadrant error compensation is limited to 1% of the maximum speed in order to prevent uncontrolled injections during the learning phase if the network has not yet established the characteristic. In the 1st learning run, this value is used as injection amplitude. • The fine quantization must be greater than/equal to 4 and less than/equal to 32. • The number of learning runs must not be less than 5 or greater than 40. 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Enter a smaller value in the function parameter max. acceleration. • Enter a value between 0 and 1% (resolution 0.001%). • Enter a valid value in the fine quantization. • Enter a valid value. 	

1.5.1 Alarm description

160087	Max. acceleration too small Fine quantization too small Coarse quantization too small Number of learning runs too small	OK softkey
<i>Scan</i>	<ul style="list-style-type: none"> • Reparameterization of the maximum acceleration (function parameter of the neural quadrant error compensation) • Reparameterization of the fine quantization (function parameter of the neural quadrant error compensation) • Reparameterization of the coarse quantization (function parameter of the neural quadrant error compensation) • Reparameterization of the number of learning runs (function parameter of the neural quadrant error compensation) 	
<i>Effect</i>	<ul style="list-style-type: none"> • Start-up function aborts 	
<i>Explanation</i>	<ul style="list-style-type: none"> • Input of maximum acceleration zero is not allowed. • Fine quantization must be greater than or equal to 4 and less than or equal to 32. • Coarse quantization must be greater than 1. • A number of learning runs less than 5 or greater than 40 is not allowed. 	
<i>Remedy</i>	<ul style="list-style-type: none"> • Enter a larger value in the function parameter max. acceleration. • Enter a valid value in the fine quantization. • Enter a valid value in the coarse quantization. • Enter a valid value. 	
160088	Axis/spindle name ... invalid	OK softkey
<i>Scan</i>	DAC function parameterization	
<i>Effect</i>	The function cannot be started	
<i>Explanation</i>	The stated axis/spindle does not exist	
<i>Remedy</i>	Correct input	
160089	Axis/spindle number ... invalid	OK softkey
<i>Scan</i>	DAC function parameterization	
<i>Effect</i>	The function cannot be started	
<i>Explanation</i>	The stated axis/spindle does not exist	
<i>Remedy</i>	Correct input	
160090	Hard disk full, create file ...	OK softkey
<i>Scan</i>	Startup application file services	
<i>Effect</i>	The data set in question is not stored	
<i>Explanation</i>	Note enough memory on hard disk	
<i>Remedy</i>	Remove file not required	
160091	Data block of ... file invalid	OK softkey
<i>Scan</i>	Startup application file services (read only)	
<i>Effect</i>	No data is read	
<i>Explanation</i>	The contents of the selected file are not consistent	
<i>Remedy</i>	None	
160092	File ... not loaded completely	OK softkey
<i>Scan</i>	Startup application file services (read only)	
<i>Effect</i>	The read data set is not complete	
<i>Explanation</i>	Contents of file were not transferred completely	
<i>Remedy</i>	Repeat procedure	

160093	File ... not saved completely	OK softkey
<i>Scan</i>	Startup application file services (write)	
<i>Effect</i>	Incomplete data set created	
<i>Explanation</i>	File contents not completely transferred	
<i>Remedy</i>	Repeat procedure	
160094	File ... does not exist	OK softkey
<i>Scan</i>	Startup application file services (read only)	
<i>Effect</i>	No data is read	
<i>Explanation</i>	The stated file does not exist	
<i>Remedy</i>	Correct file selection	
160095	Error on reading from file ...	OK softkey
<i>Scan</i>	Startup application file services (read only)	
<i>Effect</i>	No data or only inconsistent data are read	
<i>Explanation</i>	Bulk storage device access problems	
<i>Remedy</i>	Contact service	
160096	Error in file structure ...	OK softkey
<i>Scan</i>	Startup application file services (read only)	
<i>Effect</i>	No data read in	
<i>Explanation</i>	File does not have correct format	
<i>Remedy</i>	None	
160097	Hard disk full, write file ...	OK softkey
<i>Scan</i>	Startup application file services (write)	
<i>Effect</i>	No data or only inconsistent data are written	
<i>Explanation</i>	Bulk storage device access problems	
<i>Remedy</i>	Remove files not required	
160098	Data block of file ... not available	OK softkey
<i>Scan</i>	Startup application file services (read only)	
<i>Effect</i>	No data read in	
<i>Explanation</i>	The file does not contain any data for the selected axis/drive	
<i>Remedy</i>	None	
160099	File ... not loaded	OK softkey
<i>Scan</i>	Startup application file services (read only)	
<i>Effect</i>	No data is read in	
<i>Explanation</i>	–	
<i>Remedy</i>	Repeat procedure	
160100	File ... not saved	OK softkey
<i>Scan</i>	Startup application file services (write)	
<i>Effect</i>	Data set is not stored	
<i>Explanation</i>	–	
<i>Remedy</i>	Repeat procedure	

1.5.1 Alarm description

160101	Internal error, end startup	OK softkey
<i>Scan</i>	Startup application	
<i>Effect</i>	–	
<i>Explanation</i>	Startup application cannot be executed because of internal error	
<i>Remedy</i>	No startup application or end startup application	
160102	Memory area exceeded	OK softkey
<i>Scan</i>	Start-up application at start of neural quadrant error compensation	
<i>Effect</i>	The function cannot be started	
<i>Explanation</i>	Fine quantization * (coarse quantization +1) must be less than or equal to 1000	
<i>Remedy</i>	Reduce the size of fine and coarse quantization	
<i>Note</i>	Applies as from SW 4	
160103	Invalid address assignment	OK softkey
<i>Scan</i>	Start-up application at start of neural quadrant error compensation	
<i>Effect</i>	The function cannot be started	
<i>Explanation</i>	Error in the parameterization of limit lower or upper area	
<i>Remedy</i>	Correct inputs	
<i>Note</i>	Applies as from SW 4	
160104	Learning phase active file functions not possible	OK softkey
<i>Scan</i>	Start-up application at file functions in the neural quadrant error compensation	
<i>Effect</i>	Access to the file functions not possible	
<i>Explanation</i>	No file functions are allowed while measurement is taking place	
<i>Remedy</i>	Stop measurement or wait for end of measurement	
<i>Note</i>	Applies as from SW 4	
160105	QEC bits not set	OK softkey
<i>Scan</i>	Start-up application at start of neural quadrant error compensation	
<i>Effect</i>	The function cannot be started	
<i>Explanation</i>	The activation bit of the neural QEC (NC MD) is not set	
<i>Remedy</i>	Set QEC bits	
<i>Note</i>	Applies as from SW 4	
160106	Feedforward control not activated	OK softkey
<i>Scan</i>	Start-up application at start of neural quadrant error compensation	
<i>Effect</i>	The function cannot be started	
<i>Explanation</i>	The speed feedforward control must be activated	
<i>Remedy</i>	Activate speed feedforward control (option, NC MD, PLC bit)	
<i>Note</i>	Applies as from SW 4	
160107	Axes not configured	OK softkey
<i>Scan</i>	Start-up application at start of circle form test	
<i>Effect</i>	The function cannot be started	
<i>Explanation</i>	Two real axes must be configured	
<i>Remedy</i>	Configure axes	
<i>Note</i>	Applies as from SW 4	

160108	No trace activated	OK softkey
<i>Scan</i>	Start-up application at start of SERVO TRACE function	
<i>Effect</i>	SERVO trace is not started	
<i>Explanation</i>	All traces are switched passive or no signal selected	
<i>Remedy</i>	Switch at least one trace to active	
<i>Note</i>	Applies as from SW 4	
160109	Trace buffer already assigned ...	OK softkey
<i>Scan</i>	Start-up application at start of SERVO TRACE function	
<i>Effect</i>	SERVO trace is not started	
<i>Explanation</i>	Trace buffer assigned by measuring function	
<i>Remedy</i>	Stop measuring function and restart Trace	
<i>Note</i>	Applies as from SW 4	
160110	Illegal NC No. ...	OK softkey
<i>Scan</i>	Start-up application at start of SERVO TRACE function	
<i>Effect</i>	SERVO trace is not started	
<i>Explanation</i>	NC No. is illegal	
<i>Remedy</i>	Specify axis name for a valid NC axis/spindle	
<i>Note</i>	Applies as from SW 4	
160111	Illegal component ...	OK softkey
<i>Scan</i>	Start-up application at start of SERVO TRACE function	
<i>Effect</i>	SERVO trace is not started	
<i>Explanation</i>	Component is illegal	
<i>Remedy</i>	Specify valid component (SERVO)	
<i>Note</i>	Applies as from SW 4	
160112	Illegal signal selection ...	OK softkey
<i>Scan</i>	Start-up application at start of SERVO TRACE function	
<i>Effect</i>	SERVO trace is not started	
<i>Explanation</i>	Signal number is illegal	
<i>Remedy</i>	Specify valid signal number	
<i>Note</i>	Applies as from SW 4	
160113	Illegal segment address ...	OK softkey
<i>Scan</i>	Start-up application at start of SERVO TRACE function	
<i>Effect</i>	SERVO trace is not started	
<i>Explanation</i>	Segment address is illegal	
<i>Remedy</i>	Specify legal segment address	
<i>Note</i>	Applies as from SW 4	

1.5.1 Alarm description

160114	Illegal offset address ...	OK softkey
<i>Scan</i>	Start-up application at start of SERVO TRACE function	
<i>Effect</i>	SERVO trace is not started	
<i>Explanation</i>	Offset address is illegal	
<i>Remedy</i>	Specify legal offset address	
<i>Note</i>	Applies as from SW 4	
160115	Illegal measurement duration ...	OK softkey
<i>Scan</i>	Start-up application at start of SERVO TRACE function	
<i>Effect</i>	SERVO trace is not started	
<i>Explanation</i>	Measuring duration is illegal	
<i>Remedy</i>	Specify legal measuring duration	
<i>Note</i>	Applies as from SW 4	
160116	Illegal trigger time ...	OK softkey
<i>Scan</i>	Start-up application at start of SERVO TRACE function	
<i>Effect</i>	SERVO trace is not started	
<i>Explanation</i>	Trigger time is illegal	
<i>Remedy</i>	Specify legal trigger time	
<i>Note</i>	Applies as from SW 4	
160117	Illegal mode ...	OK softkey
<i>Scan</i>	Start-up application at start of SERVO TRACE function	
<i>Effect</i>	SERVO trace is not started	
<i>Explanation</i>	Mode is illegal	
<i>Remedy</i>	Specify legal mode (0)	
<i>Note</i>	Applies as from SW 4	
160118	Illegal trigger condition ...	OK softkey
<i>Scan</i>	Start-up application at start of SERVO TRACE function	
<i>Effect</i>	SERVO trace is not started	
<i>Explanation</i>	Trigger condition is illegal	
<i>Remedy</i>	Specify legal trigger condition	
<i>Note</i>	Applies as from SW 4	
160119	Conversion error ...	OK softkey
<i>Scan</i>	Start-up application when converting the TRACE buffer	
<i>Effect</i>	Signal values in the Trace buffer could not be converted	
<i>Explanation</i>	–	
<i>Remedy</i>	–	
<i>Note</i>	Applies as from SW 4	

160120	Wrong Trace number (domain) ...	OK softkey
<i>Scan</i>	Start-up application when reading out the TRACE buffer	
<i>Effect</i>	Trace buffer could not be displayed	
<i>Explanation</i>	–	
<i>Remedy</i>	–	
<i>Note</i>	Applies as from SW 4	
160121	Trace header not initialized (domain) ...	OK softkey
<i>Scan</i>	Start-up application when reading out the TRACE buffer	
<i>Effect</i>	Trace buffer could not be displayed	
<i>Explanation</i>	–	
<i>Remedy</i>	–	
<i>Note</i>	Applies as from SW 4	
160122	Trace active, no data (domain) ...	OK softkey
<i>Scan</i>	Start-up application when reading out the TRACE buffer while Trace function is running	
<i>Effect</i>	Trace buffer could not be displayed	
<i>Explanation</i>	–	
<i>Remedy</i>	–	
<i>Note</i>	Applies as from SW 4	
160123	Illegal trigger threshold ...	OK softkey
<i>Scan</i>	Start-up application at start of SERVO TRACE function	
<i>Effect</i>	SERVO trace is not started	
<i>Explanation</i>	–	
<i>Remedy</i>	–	
<i>Note</i>	Applies as from SW 4	
160124	Option is not available	OK softkey
<i>Scan</i>	Start-up application on selecting the circle form test function	
<i>Effect</i>	Circle form test cannot be selected	
<i>Explanation</i>	–	
<i>Remedy</i>	Set circle form test option	
<i>Note</i>	Applies as from SW 4	
160125	Trace buffer already assigned	OK softkey
<i>Scan</i>	Start-up application on starting a measurement function	
<i>Effect</i>	Measurement function is not started.	
<i>Explanation</i>	Trace buffer is already assigned by Servo Trace	
<i>Remedy</i>	Stop Servo Trace and restart measurement function	
<i>Note</i>	Applies as from SW 4	

1.5.1 Alarm description

160126 Data not available on Servo OK softkey

Scan Start-up application at SK display and SK file function. Save with neural QEC or SK stop at Servo Trace.

Effect The characteristic of the neural QEC for the selected axis is not loaded from the Servo side to the MMC side. With Servo Trace, the data are not loaded to the MMC side.

Explanation The data characteristic is not yet available on the Servo side.

Remedy Enter the function parameters of the neural QEC for the axis and start the learning process or press the parameter transfer softkey. The characteristic is then available. With Servo Trace, parameterize correctly (observe the trigger conditions) and restart.

Note Applies as from SW 4

160127 Illegal channel / IKA No.

Scan Start-up applications when starting the servo-trace function for NCK signals.

Effect Servo-trace is not started.

Explanation

Remedy Enter permissible channel/IKA No. and restart.

Note Alarm in SW 5 and higher

161001 Function abort by the operator**OK softkey**

Scan Startup function

Effect None

Explanation Operational message after operator action

Remedy Stop Servo Trace and restart measurement function

161002 Function abort by SERVO error ...

Scan Startup application

Effect Current startup function aborted

Explanation A system error has caused the active function to terminate

The following errors (No. and meaning) are possible:

- 81 "Axial alarm active"
- 82 "Above traversing range upper limit"
- 83 "Below traversing range lower limit"
- 84 "No axial SERVO enable"
- 85 "No PLC enable"
- 86 "SERVO mode change"
- 87 "MF on SERVO aborted"
- 88 "Reset"
- 89 "Axis/spindle not in stop state"
- 90 "Spindle ramp-up encoder stop from PLC"

Remedy End application and restart

161003 Function abort due to 611D error ...*Scan* Startup application*Effect* Current startup function aborted*Explanation* A system error has caused the active function to terminate.**Function abort function generator:**

- Function generator already active
- Wrong mode
- Selected servo cycle is 0
- Length of period is 0 or > 1000 s
- Scaling is negative
- Amplitude 1 is negative or greater than allowed
- Offset is beyond the allowed limits
- Limitation is greater than allowed
- Wrong curve form
- Pulse width is negative or greater than the length of period
- Bandwidth is < 1 or > 100000
- Calculation of a register length for the noise signal from length of period and bandwidth for which no provision has been made
- Scaling change with inactive function generator

Furthermore the following errors (No. and meaning) are possible:

- 97 "Measuring function 611D aborted with error"
- 98 "611D ends FG mode, was already active"
- 99 "No pulse enable"
- 100 "Timer expired, 611D does not respond"

Function abort measuring functions:

- Measuring function is already active
- Measuring type not in permitted range
- Measured value not input
- There is a gap in the measured values input

Remedy Start up control/drive again and repeat procedure**161004 Measurement aborted****OK softkey***Scan* Startup application*Effect* Current measurement aborted*Explanation* Current measurement aborted because of system error*Remedy* Start up control/drive again and repeat procedure

1.5.1 Alarm description

161005 Function abort by NC error ...

Scan Startup application traversing function

Effect The traversing function in question aborted

Explanation Traversing function aborted because of system error or operator action.

General error

- 1 "Emergency stop"
- 2 "Warm restart"

Mode Group error

- 17 "Mode change"

Channel error

- 33 "Not all channels in reset state"
- 34 "Reset"
- 35 "Feed hold" or "feed override = 0"
- 36 "NC-STOP"
- 37 "No channel defined"

Axis error

- 49 "Servo enable"
- 50 "Parking axis"
- 51 "Feed hold"
- 52 "Follow-up"
- 53 "Axis disable"
- 54 "Hardware limit switch"
- 55 "Working area limitation +"
- 56 "Working area limitation -"
- 57 "Traversing range +"
- 58 "Traversing range -"
- 59 "Error conversion actual value system"

Spindle error

- 65 "PLC control for spindle"
- 66 "Spindle reset"
- 67 "Spindle servo enable"
- 68 "Setpoint = 0"
- 69 "Park"
- 70 "Spindle stop"

Remedy If system error occurs, start up control again and repeat procedure

161006 Function generator is running

Scan Startup application function generator

Effect –

Explanation Function generator operational message

Remedy –

161007 Measurement current control loop in progress

Scan Startup application measuring function current

Effect –

Explanation Current controller measuring function operational message

Remedy –

161008 Measurement position control loop in progress

Scan Startup application position controller measuring function

Effect –

Explanation Position controller measuring function operational message

Remedy –

161009 Measurement speed control loop in progress

Scan Startup application speed controller measuring function
Effect –
Explanation Speed controller measuring function operational message
Remedy –

161010 Please press NC start

Scan Selecting traversing movement during startup application
Effect –
Explanation Control waits for traversing function enable with "NC START"
Remedy Press NC START

161011 Wait for PLC enable

Scan Selecting traversing movement during startup application
Effect –
Explanation Control waits for PLC safety signal
Remedy PLC safety signal scan can be deselected with "Enable: internal"

161012 Measuring for circularity test in progress

Scan Start-up application after start of circularity test
Effect –
Explanation The control performs circularity test
Remedy –
Note Applies as from SW 4

161013 Measuring for neural QEC in progress

Scan Start-up application after start of neural QEC
Effect –
Explanation The control performs neural QEC
Remedy –
Note Applies as from SW 4

161014 Trace function is started

Scan Start-up application after start of SERVO Trace function
Effect –
Explanation The control performs SERVO Trace
Remedy –
Note Applies as from SW 4

161015 Trace started ...

Scan Start-up application after recording has started within the control for all active Trace buffers
Effect –
Explanation The selected Trace signals are recorded
Remedy –
Note Applies as from SW 4

1.5.1 Alarm description

161016 Trace triggered ...

Scan Start-up application after trigger has occurred within the control for all active trace buffers.

Effect –

Explanation The selected triggers have been reached for all active Trace buffers

Remedy –

Note Applies as from SW 4

161017 Trace concluded ...

Scan Start-up application after end of recording within control for all active Trace buffers.

Effect –

Explanation The selected traces have all been concluded, i.e. the selected measuring time has expired.

Remedy –

Note Applies as from SW 4

161018 Trace function aborted ...

Scan Start-up application while Trace function in progress

Effect All active trace functions are aborted

Explanation The selected traces are aborted before expiry of the measuring time

Remedy –

Note Applies as from SW 4

165001 No drive is assigned to this slot**OK softkey**

Scan Storing, loading MD from an individual drive

Effect Function is not executed

Explanation Defined drive number is not assigned to any slot

Remedy Match drive configuration and accept

165002 No data has been transmitted**OK softkey**

Scan Loading MD files

Effect Function not executed

Explanation The selected file does not contain the required MD

Remedy Select another file

165003 There is no free memory left**OK softkey**

Scan –

Effect –

Explanation This message appears as a result of the previous operation and is self-explanatory

Remedy –

165004 The DPRAM is assigned – data was not transferred**OK softkey**

Scan Saving, loading MD files

Effect Function is not executed

Explanation The link PC to NC is busy.

Remedy Wait, startup end, NCK reset or Power On

165005	Error in data transfer	OK softkey
<i>Scan</i>	Loading drive standard data	
<i>Effect</i>	Some data in the drive are invalid	
<i>Explanation</i>	Data not completely transferred	
<i>Remedy</i>	Repeat operation	
165007	Data is stored with errors	OK softkey
<i>Scan</i>	Saving machine data	
<i>Effect</i>	An invalid file was stored	
<i>Explanation</i>	Data was not completely transferred	
<i>Remedy</i>	Delete file, repeat operation	
165008	Selected drive has no FDD module	OK softkey
<i>Scan</i>	Drive MD: select motor	
<i>Effect</i>	Function is not executed	
<i>Explanation</i>	No active FDD drive available	
<i>Remedy</i>	Enter FDD in drive configuration and accept	
165009	No valid slot selected	OK softkey
<i>Scan</i>	Drive configuration: select module or delete slot	
<i>Effect</i>	Function is not executed	
<i>Explanation</i>	No valid slot number was entered	
<i>Remedy</i>	Enter valid number (1–15), repeat operation	
165010	Drive not active	OK softkey
<i>Scan</i>	Saving or loading MD of an individual drive	
<i>Effect</i>	Function is not executed	
<i>Explanation</i>	There is no connection to the passive drives	
<i>Remedy</i>	Switch drive to active, accept configuration	
165011	Transmission error – data not transferred	OK softkey
<i>Scan</i>	Saving, loading machine data	
<i>Effect</i>	Function is not executed	
<i>Explanation</i>	Transmission not possible or transmission interference	
<i>Remedy</i>	Repeat operation	
165012	There is no file with FDD motors	OK softkey
<i>Scan</i>	Drive MD/FDD/motor selection	
<i>Effect</i>	No default possible for motor	
<i>Explanation</i>	There is no system file	
<i>Remedy</i>	Please notify Siemens Service	
<i>Note</i>	Applies as from SW 4	

1.5.1 Alarm description

165013	There is no file with spindle drive motors	OK softkey
<i>Scan</i>	Drive MD/MSD/motor selection	
<i>Effect</i>	No default possible for motor	
<i>Explanation</i>	There is no system file	
<i>Remedy</i>	Please notify Siemens Service	
<i>Note</i>	Applies as from SW 4	
165014	Selected drive has no spindle drive module	OK softkey
<i>Scan</i>	Drive MD: select motor	
<i>Effect</i>	Function is not executed	
<i>Explanation</i>	No active MSD drive available	
<i>Remedy</i>	Enter MSD in drive configuration and transfer.	
165015	Data transmission has been aborted	OK softkey
<i>Scan</i>	–	
<i>Effect</i>	–	
<i>Explanation</i>	This message always appears when the “Abort” softkey has been pressed during a file function and has also been effective. The file function has therefore been performed incompletely. Because an incomplete file function can lead to inconsistent data, an aborted loading operation, for example, should be repeated or the result of an incomplete save operation, for example, should not be used. If the operation could no longer be interrupted at the time of operating the Abort key, e.g. because it has already been completed to the maximum possible extent, then this message does not appear.	
<i>Remedy</i>	Repeat operation if necessary.	
165016	No file name entered	OK softkey
<i>Scan</i>	Save, load, delete, copy MD file functions	
<i>Effect</i>	Function is not executed	
<i>Explanation</i>	Call up function again, enter correct name	
<i>Remedy</i>	–	
165017	No valid file name entered	OK softkey
<i>Scan</i>	Save, load, delete, copy MD file functions	
<i>Effect</i>	Function is not executed	
<i>Explanation</i>	Name entered using illegal characters	
<i>Remedy</i>	Call function again, enter correct name	
165018	File must not be deleted	OK softkey
<i>Scan</i>	Deleting MD files	
<i>Effect</i>	Function is not executed	
<i>Explanation</i>	<online> and STANDARD data cannot be deleted	
<i>Remedy</i>	–	
165019	File cannot be edited	OK softkey
<i>Scan</i>	Selecting Edit or Edit new	
<i>Effect</i>	Function is not executed	
<i>Explanation</i>	BOOT files cannot be edited.	
<i>Remedy</i>	–	

165020	Error on selecting file	OK softkey
<i>Scan</i>	Selection of Edit or Edit new	
<i>Effect</i>	Function is not performed	
<i>Explanation</i>	Internal error on file selection	
<i>Remedy</i>	Please notify Siemens Service	
<i>Note</i>	Applies as from SW 4	
165021	Drive configuration has not been saved	OK softkey
<i>Scan</i>	Saving, loading drive MD	
<i>Effect</i>	Function is not executed	
<i>Explanation</i>	The configuration must first be saved	
<i>Remedy</i>	Press softkey "Accept conf.+NCKPO", repeat operation	
165022	Data has not been written on hard disk	OK softkey
<i>Scan</i>	Saving machine data	
<i>Effect</i>	Files incomplete	
<i>Explanation</i>	Hard disk is probably full	
<i>Remedy</i>	Check free memory on hard disk	
165023	Drive is not in configuration	OK softkey
<i>Scan</i>	Saving, loading drive MD	
<i>Effect</i>	Function is not executed	
<i>Explanation</i>	The configuration must first be accepted (saved)	
<i>Remedy</i>	Change configuration and accept, with repeat operation	
165024	Selected file cannot be copied	OK softkey
<i>Scan</i>	Copying MD files	
<i>Effect</i>	Function is not executed	
<i>Explanation</i>	BOOT or <online> data was selected	
<i>Remedy</i>	Select standard or user file	
165025	Error: file has not been copied	OK softkey
<i>Scan</i>	Copying MD files	
<i>Effect</i>	Function is not executed	
<i>Explanation</i>	The named file does not exist	
<i>Remedy</i>	–	
165026	Name is reserved for standard data	OK softkey
<i>Scan</i>	Edit new, saving, inserting MD files	
<i>Effect</i>	Function is not executed	
<i>Explanation</i>	This name cannot be used for user files	
<i>Remedy</i>	Enter a different name	

1.5.1 Alarm description

165027	Loading from on-line to on-line not possible	OK softkey
<i>Scan</i>	Loading MD files	
<i>Effect</i>	Function is not executed	
<i>Explanation</i>	Only user or STANDARD data can be loaded	
<i>Remedy</i>	–	
165028	BOOT is no valid file name	OK softkey
<i>Scan</i>	Edit new, editing, saving, inserting MD files	
<i>Effect</i>	Function is not executed	
<i>Explanation</i>	The name cannot be used for user files	
<i>Remedy</i>	Enter a different name.	
165029	Boot files cannot be loaded	OK softkey
<i>Scan</i>	Loading MD files	
<i>Effect</i>	–	
<i>Explanation</i>	Boot files are automatically loaded on NCK reset	
<i>Remedy</i>	–	
165030	There is no file with power section selection	OK softkey
<i>Scan</i>	Drive MD/module selection	
<i>Effect</i>	Power section cannot be selected	
<i>Explanation</i>	There is no system file	
<i>Remedy</i>	Please notify Siemens Service	
<i>Note</i>	Applies as from SW 4	
165031	No communication to the MSD	OK softkey
<i>Scan</i>	Saving, loading machine data	
<i>Effect</i>	Function is not executed	
<i>Explanation</i>	Transmission either not possible or transmission interference	
<i>Remedy</i>	Repeat operation	
<i>Note</i>	Applies for SW 3 only	
165032	MSD has not taken any standard values	OK softkey
<i>Scan</i>	Drive MD, spindle (MSD): select motor	
<i>Effect</i>	Drive is not parameterized	
<i>Explanation</i>	There are no standard data for this motor/PS combination	
<i>Remedy</i>	Select a different motor or motor from another manufacturer	
165033	Conversion has not been switched off	OK softkey
<i>Scan</i>	Loading drive machine data	
<i>Effect</i>	Illegal data in drive	
<i>Explanation</i>	–	
<i>Remedy</i>	Repeat operation	
<i>Note</i>	Applies as from SW 5.4.	

165034	Conversion has not been switched on	OK softkey
<i>Scan</i>	Loading drive machine data	
<i>Effect</i>	Illegal data in drive	
<i>Explanation</i>	–	
<i>Remedy</i>	Repeat operation	
<i>Note</i>	Applies as from SW 5.4.	
165035	MD for motor/p section comb. not preset	OK softkey
<i>Scan</i>	Drive MD, axis (FDD): select motor	
<i>Effect</i>	Drive is not parameterized	
<i>Explanation</i>	There are no standard data for this motor/PS combination	
<i>Remedy</i>	Select a different motor or motor from another manufacturer	
165036	Not a valid drive number	OK softkey
<i>Scan</i>	Saving and loading MD of one individual drive	
<i>Effect</i>	Selected function is not executed	
<i>Explanation</i>	An illegal drive number has been entered	
<i>Remedy</i>	Enter a legal drive number	
165037	Boot file drive n. not saved	OK softkey
<i>Scan</i>	Saving BOOT for one or all drives	
<i>Effect</i>	Current drive status lost after next reset	
<i>Explanation</i>	No communication with drive	
<i>Remedy</i>	Save BOOT configuration, NCK reset, repeat operation	
165038	Drive configuration has not been loaded	OK softkey
<i>Scan</i>	Loading user drive machine data	
<i>Effect</i>	No connection to drives	
<i>Explanation</i>	The loaded MD file does not contain a configuration	
<i>Remedy</i>	Load file with configuration data	
165039	No communication to the digital drives	OK softkey
<i>Scan</i>	Saving, loading drive MD	
<i>Effect</i>	Function is not executed	
<i>Explanation</i>	The stated configuration is accepted	
<i>Remedy</i>	Save BOOT configuration, NCK reset, repeat operation	
165040	Only user configuration can be changed	OK softkey
<i>Scan</i>	Softkey "Configure memory"	
<i>Effect</i>	Function is not performed	
<i>Explanation</i>	Standard or on-line configuration selected accidentally.	
<i>Remedy</i>	Select user setting under "File functions"	
<i>Note</i>	Applies as from SW 4	

1.5.1 Alarm description

165041	Only possible in general reset mode	OK softkey
<i>Scan</i>	Softkey "Configure memory"	
<i>Effect</i>	Function is not performed	
<i>Explanation</i>	To configure memory, the control must be in the general reset mode.	
<i>Remedy</i>	Activate the general reset mode under "Diagnosis/start-up"	
<i>Note</i>	Applies as from SW 4	
165042	Configuration not complete	OK softkey
<i>Scan</i>	Softkey "Configure memory", check DRAM and SRAM configuration	
<i>Effect</i>	Function is not performed	
<i>Explanation</i>	Not all data belonging to the configuration are available	
<i>Remedy</i>	First enter all data	
<i>Note</i>	Applies as from SW 4	
165043	Insufficient memory space	OK softkey
<i>Scan</i>	Softkey "Configure memory", check DRAM and SRAM configuration	
<i>Effect</i>	Function is not performed	
<i>Explanation</i>	The calculated free memory space available is negative	
<i>Remedy</i>	Change the configuration such that the remaining memory is positive	
<i>Note</i>	Applies as from SW 4	
165044	Controller data have not been calculated	OK softkey
<i>Scan</i>	Loading of standard drive machine data and also softkey "Calculate controller data"	
<i>Effect</i>	Invalid data in the drive	
<i>Explanation</i>	–	
<i>Remedy</i>	Repeat action	
<i>Note</i>	Applies as from SW 4	
165045	No power section selected	OK softkey
<i>Scan</i>	Softkey "OK" in the drive machine data/selection module screen	
<i>Effect</i>	Key is ignored	
<i>Explanation</i>	Line with intermediate heading has been selected accidentally. These lines serve only for the headings in the selection list.	
<i>Remedy</i>	Select the correct module and press the key again.	
<i>Note</i>	Applies as from SW 4	
165046	No input authorization	OK softkey
<i>Scan</i>	Insert from clipboard, drive selection	
<i>Effect</i>	Function is not performed	
<i>Explanation</i>	The data block just edited cannot be modified even if password is set (e.g. standard data block)	
<i>Remedy</i>	Select another data block	
<i>Note</i>	Applies as from SW 4	

165047	No curve parameterized	OK softkey
<i>Scan</i>	Copy to clipboard and paste from clipboard in the IKA relationships display selected "with" curve.	
<i>Effect</i>	Function is not performed	
<i>Explanation</i>	<ul style="list-style-type: none"> • The curve number is not parameterized • Start or end pointer of the curve is not parameterized • The start pointer is greater than the end pointer • This information cannot be read (e.g. <on-line>, NCK power-up) 	
<i>Remedy</i>	Select "without" curve using the toggle key or press the Abort key and parameterize the curve.	
<i>Note</i>	Applies as from SW 4	
165048	No drift compensation performed for axis ...	OK softkey
<i>Scan</i>	"Drift compensation" softkey in Service display	
<i>Effect</i>	Function not carried out.	
<i>Explanation</i>	Internal error	
<i>Remedy</i>	None	
<i>Note</i>	Alarm in SW 5 and higher	
165049	Axis ... not available	OK softkey
<i>Scan</i>	"Drift compensation" softkey in Service display	
<i>Effect</i>	Function not carried out.	
<i>Explanation</i>	The selected axis is not active, e.g. because it has just been set up.	
<i>Remedy</i>	Perform Power on, repeat action.	
<i>Note</i>	Alarm in SW 5 and higher	
165050	Axis ... to be stopped first	OK softkey
<i>Scan</i>	"Drift compensation" softkey in service display	
<i>Effect</i>	Function not carried out.	
<i>Explanation</i>	Drift compensation only possible in Reset.	
<i>Remedy</i>	Stop program, press Reset, repeat action.	
<i>Note</i>	Alarm in SW 5 and higher	
165051	NQFK data not backed up	OK softkey
<i>Scan</i>	"Save on hard disk" softkey in the File functions menu in the Diagnosis/Start-up/Machine data display	
<i>Effect</i>	The NQFK data have not been saved	
<i>Explanation</i>	System error	
<i>Remedy</i>	Please notify Siemens Service	
<i>Note</i>	Alarm in SW 5 and higher	
165052	NQFK data for axis ... not saved	OK softkey
<i>Scan</i>	"Save on hard disk" softkey in the File functions menu in the Diagnosis/Start-up/Machine data display	
<i>Effect</i>	The NQFK data for the stated axis have not been saved.	
<i>Explanation</i>	The stated axis may have been incorrectly parameterized.	
<i>Remedy</i>	Check parameterization and repeat procedure.	
<i>Note</i>	Alarm in SW 5 and higher	

1.5.1 Alarm description

165053	NQFK data... not loaded	OK softkey
<i>Scan</i>	"Load from hard disk" softkey in the File functions menu in the Diagnosis/Start-up/Machine data display	
<i>Effect</i>	The NQFK data have not been loaded.	
<i>Explanation</i>	System error	
<i>Remedy</i>	Please notify Siemens service.	
<i>Note</i>	Alarm in SW 5 and higher	
165054	NQFK data for axis ... not loaded	OK softkey
<i>Scan</i>	"Load from hard disk" softkey in the File functions menu in the Diagnosis/Start-up/Machine data display	
<i>Effect</i>	The NQFK data of the stated axis have not been loaded.	
<i>Explanation</i>	The NQFK ASCII file of the stated axis is defective or not compatible.	
<i>Remedy</i>	Delete or correct file, repeat procedure.	
<i>Note</i>	Alarm in SW 5 and higher	
165055	Equivalent circuit data have not been calculated	OK softkey
<i>Scan</i>	Softkey "Calculate equivalent circuit diagram"	
<i>Effect</i>	Invalid data in drive.	
<i>Explanation</i>	–	
<i>Remedy</i>	Repeat action	
<i>Note</i>	Alarm in SW 5 and higher	
165056	Carry out safety acceptance test	OK softkey
<i>Scan</i>	Softkey "Accept safe functions"	
<i>Effect</i>	–	
<i>Explanation</i>	Without acceptance test, the operator's life and limb are at risk.	
<i>Remedy</i>	The acceptance test must be performed in accordance with the valid safety regulations.	
<i>Note</i>	Applies as from SW 5.4	
165057	Sisitec data TEA1 axis read error	OK softkey
<i>Scan</i>	Softkey "Accept safe functions"	
<i>Effect</i>	The function has not been performed.	
<i>Explanation</i>	–	
<i>Remedy</i>	If necessary, first start up the axis.	
<i>Note</i>	Applies as from SW 5.4	
165058	Sisitec data TEA3 drive write error	OK softkey
<i>Scan</i>	Softkey "Accept safe functions"	
<i>Effect</i>	The function has possibly been performed incompletely, data may be inconsistent.	
<i>Explanation</i>	–	
<i>Remedy</i>	If necessary, first start up the drive.	
<i>Note</i>	Applies as from SW 5.4	

165059	Check input new SI password different	OK softkey
<i>Scan</i>	Softkey "Change password"	
<i>Effect</i>	The password has not been changed	
<i>Explanation</i>	The new password must be entered again in the third field to ensure that it has been entered correctly.	
<i>Remedy</i>	Repeat input.	
<i>Note</i>	Applies as from SW 5.4	
165060	Rated power too small (MD x130 \leq 0)	OK softkey
<i>Scan</i>	Softkey "Calculate equivalent circuit diagram data (MSD only)"	
<i>Effect</i>	The equivalent circuit diagram data have not been changed.	
<i>Explanation</i>	The rated power (in MD 1130 and MD 2130) must not be \leq 0.	
<i>Remedy</i>	Correct value, repeat function.	
<i>Note</i>	Applies as from SW 5.4	
165061	Rated voltage too small (MD x132 \leq 0)	OK softkey
<i>Scan</i>	Softkey "Calculate equivalent circuit diagram data (MSD only)"	
<i>Effect</i>	The equivalent circuit diagram data have not been changed.	
<i>Explanation</i>	The rated voltage (in MD 1132 and MD 2123) must not be \leq 0.	
<i>Remedy</i>	Correct value, repeat function.	
<i>Note</i>	Applies as from SW 5.4	
165062	Rated current too small (MD x103 \leq 0)	OK softkey
<i>Scan</i>	Softkey "Calculate equivalent circuit diagram data (MSD only)"	
<i>Effect</i>	The equivalent circuit diagram data have not been changed.	
<i>Explanation</i>	The rated current (in MD 1103 and MD 2103) must not be \leq 0.	
<i>Remedy</i>	Correct value, repeat function.	
<i>Note</i>	Applies as from SW 5.4	
165063	Cos Phi power factor wrong	OK softkey
<i>Scan</i>	Softkey "Calculate equivalent circuit diagram data (MSD only)"	
<i>Effect</i>	The equivalent circuit diagram data have not been changed.	
<i>Explanation</i>	The Cos Phi power factor (in MD 1129 and MD 2129) must not be \leq 0 and must not exceed 0.996.	
<i>Remedy</i>	Correct value, repeat function.	
<i>Note</i>	Applies as from SW 5.4	
165064	Pole pair no. (ratio MD x134/MD x400) illegal	OK softkey
<i>Scan</i>	Softkey "Calculate equivalent circuit diagram data (MSD only)"	
<i>Effect</i>	The equivalent circuit diagram data have not been changed.	
<i>Explanation</i>	The pole pair no. (ratio rated frequency (MD 1134 and MD 2134) /rated speed (MD 1400 and MD 2400)) is illegal.	
<i>Remedy</i>	Correct value, repeat function.	
<i>Note</i>	Applies as from SW 5.4	

1.5.1 Alarm description

165065	Result field weakening speed < rated speed	OK softkey
<i>Scan</i>	Softkey "Calculate equivalent circuit diagram data (MSD only)"	
<i>Effect</i>	The equivalent circuit diagram data have not been calculated, the field weakening speed (MD 1142 and 2142) can now be modified manually.	
<i>Explanation</i>	The calculated field weakening speed is smaller than the rated speed (MD 1400 and 2400). This WarnNote is displayed if rated voltage plus the voltage drop at the series reactor exceed 400V.	
<i>Remedy</i>	Correct value of "field weakening speed" manually.	
<i>Note</i>	Applies as from SW 5.4	
165066	Current controller gain (MD 1120) not calculable	OK softkey
<i>Scan</i>	Softkey "Calculate controller data (FDD only)"	
<i>Effect</i>	The controller data have been calculated, the machine data concerned has been given a suitable default value.	
<i>Explanation</i>	The calculated current controller gain is < 0.	
<i>Remedy</i>	If necessary, correct value and repeat function.	
<i>Note</i>	Applies as from SW 5.4	
165067	Default value (MD x15) cannot be calculated	OK softkey
<i>Scan</i>	Softkey "Calculate controller data (MSD only)"	
<i>Effect</i>	The controller data have been calculated, the machine data concerned has been given a suitable default value.	
<i>Explanation</i>	The result calculated was a default value ≤ 0 .	
<i>Remedy</i>	If necessary, correct value and repeat function.	
<i>Note</i>	Applies as from SW 5.4	
165068	Magnetizing reactance (MD x14) not allowed	OK softkey
<i>Scan</i>	Softkey "Calculate controller data (MSD only)"	
<i>Effect</i>	The controller data have been calculated, the machine data concerned has been given a suitable default value.	
<i>Explanation</i>	The value 0 has been entered for the magnetizing reactance (MD1141 and MD 2141).	
<i>Remedy</i>	If necessary, correct value and repeat function.	
<i>Note</i>	Applies as from SW 5.4	
165069	Leakage reactance (MD x139/MD x140) not allowed	OK softkey
<i>Scan</i>	Softkey "Calculate controller data (MSD only)"	
<i>Effect</i>	The controller data have been calculated, the machine data concerned has been given a suitable default value.	
<i>Explanation</i>	The value 0 has been entered for one of the leakage reactances (MD 1139, 1140, 2139, 2140).	
<i>Remedy</i>	If necessary, correct value and repeat function.	
<i>Note</i>	Applies as from SW 5.4	
165070	Rated frequency (MD x134) not allowed	OK softkey
<i>Scan</i>	Softkey "Calculate controller data (MSD only)"	
<i>Effect</i>	The controller data have been calculated, the machine data concerned has been given a suitable default value.	
<i>Explanation</i>	The value 0 has been entered for the rated frequency (MD 1134 and MD 2134).	
<i>Remedy</i>	If necessary, correct value and repeat function.	
<i>Note</i>	Applies as from SW 5.4	

165071	Rotor resistance (MD x138) illegal	OK softkey
<i>Scan</i>	Softkey "Calculate controller data (MSD only)"	
<i>Effect</i>	The controller data have been calculated, the machine data concerned has been given a suitable default value.	
<i>Explanation</i>	The value 0 has been entered for the rotor resistance (MD 1138 and MD 2138).	
<i>Remedy</i>	If necessary, correct value and repeat function.	
<i>Note</i>	Applies as from SW 5.4	
165072	Moment of inertia (MD x117) illegal	OK softkey
<i>Scan</i>	Softkey "Calculate controller data"	
<i>Effect</i>	The controller data have been calculated, the machine data concerned has been given a suitable default value.	
<i>Explanation</i>	The value 0 has been entered for the moment of inertia (MD 1117 and MD 2117).	
<i>Remedy</i>	If necessary, correct value and repeat function.	
<i>Note</i>	Applies as from SW 5.4	
165073	Maximum speed smaller than field weakening speed	OK softkey
<i>Scan</i>	Softkey "Calculate controller data (MSD only)"	
<i>Effect</i>	The controller data have been calculated, the machine data concerned has been given a suitable default value.	
<i>Explanation</i>	The maximum speed (MD 1146 and MD 2146) is smaller than the field weakening speed (MD 1142 and MD 2142).	
<i>Remedy</i>	If necessary, correct value and repeat function.	
<i>Note</i>	Applies as from SW 5.4	
165074	Field weakening speed (MD x142) not allowed	OK softkey
<i>Scan</i>	Softkey "Calculate controller data (MSD only)"	
<i>Effect</i>	The controller data have been calculated, the machine data concerned has been given a suitable default value.	
<i>Explanation</i>	The value 0 has been entered for the field weakening speed (MD 1142 and MD 2142).	
<i>Remedy</i>	If necessary, correct value and repeat function.	
<i>Note</i>	Applies as from SW 5.4	
165075	No-load current (MD 1118) not allowed	OK softkey
<i>Scan</i>	Softkey "Calculate controller data (FDD only)"	
<i>Effect</i>	The controller data have been calculated, the machine data concerned has been given a suitable default value.	
<i>Explanation</i>	The value 0 has been entered for the no-load current.	
<i>Remedy</i>	If necessary, correct value and repeat function.	
<i>Note</i>	Applies as from SW 5.4	
165076	Ratio maximum current / no-load current illegal	OK softkey
<i>Scan</i>	Softkey "Calculate controller data (FDD only)"	
<i>Effect</i>	The controller data have been calculated, the machine data concerned has been given a suitable default value.	
<i>Explanation</i>	The ratio maximum current (MD 1104) no-load current (MD 1118) exceeds 900.	
<i>Remedy</i>	If necessary, correct value and repeat function.	
<i>Note</i>	Applies as from SW 5.4	

1.5.1 Alarm description

165077 Pole pair no. (ratio MD x130/MD x400) illegal**OK softkey****Scan** Softkey "Calculate controller data (MSD only)"**Effect** The controller data have been calculated, the machine data concerned has been given a suitable default value.**Explanation** The pole pair no. (ratio rated frequency (MD 1134 and MD 2134) / rated speed (MD 1400 and MD 2400) is illegal.**Remedy** If necessary, correct value and repeat function.**Note** Applies as from SW 5.4**300000 System error****POWER ON****Scan** Cyclic after control startup**Effect** Machining stops, interlocking of NC Start and Mode Group Ready**Explanation**

Additional information 1 (error no.)	Additional information 2	Explanation	Remedy
0x0001	Task ID	Opcode received unknown	Contact service
0x0002	Task ID	Message received unknown	Contact service
0x0003	Task ID	Faulty buffer type	Contact service
0x0004	Task ID	No queues available	Contact service
0x0011	Protocol ID	Unknown protocol ID	Contact service
0x0012	Message frame type	Unknown protocol message type	Contact service
0x0013	Service ID	Unknown protocol service ID	Contact service
0x0014	Variable length	Unknown protocol variable length	Contact service
0x0022	Task ID	Incorrect NC/servo/drive address	Contact service
0x0023	Pointer (set/actual)	Put_message pointer error	Contact service
0x0102	Version (set/actual)	Version error of boot files	Create boot files again
0x0103	Length (set/actual)	Incorrect length of boot files	Create boot files again
0x0301	Status	PI service initialization error	Contact service
0x0302	Status	PI service execution error	Contact service
0x0303	Status	PI service message error	Contact service
0x0304	Status	PI service abort error	Contact service
0x0401	Drive no.	Command with illegal drive no.	Contact service
0x0402	Message frame type	Command with illegal header (transmission)	Contact service
0x0403	Message frame type	Command with illegal header (reception)	Contact service
0x0404	–	Management overflow on transmitting orders	Contact service
0x0405	–	Management overflow on transmitting of acknowledgements	Contact service
0x0406	–	Management overflow on receiving orders	Contact service
0x0407	–	Management overflow on receiving acknowledgements	Contact service
0x0408	Status	Queue transmission error	Contact service
0x0411	–	Checksum error on receiving	Replace hardware
0x0412	Message length	Message length exceeded on receiving	Replace hardware
0x0413	Task ID	Timeout on transmitting	Replace hardware Increase cycle times
0x0414	–	Timeout + message unknown on transmitting	Replace hardware, Increase cycle times
0x0415	Task ID	Timeout on receiving	Replace hardware, Increase cycle times
0x0416	–	Timeout +message unknown on receiving	Replace hardware, Increase cycle times

1.5.1 Alarm description

0x0417	Task ID	Abort on transmitting	Replace hardware
0x0418	Task ID	Abort on receiving	Replace hardware
0x0421	Protocol ID	Error in data transmission (unknown protocol ID)	Contact service
0x0422	Message type	Error in data transmission (unknown message type)	Contact service
0x0423	Service ID	Error in data transmission (unknown service ID)	Contact service
0x0424	Variable length	Error in data transmission (unknown variable length)	Contact service
0x0431	Drive type 1 = FDD 2 = MSD	Timeout on firmware booting	Replace hardware (control module 611D, drive bus or DCM), increase cycle times
0x0432	Filling level (time of 611D error)	Abort of firmware booting due to 611D system error	Replace hardware (control module 611D, drive bus or DCM)
0x0433	File ID	An error occurred while reloading the drive software from the MMC. This can happen if NCK Power On or PLC restart has been given during drive booting.	Switch control off/on. If the error then still occurs, the 611D firmware must be re-installed.
0x0434	File ID	Error in boot sequence	Re-install 611D firmware, contact Service
0x0435	File ID	Error in boot file	Re-install 611D firmware, contact Service
0x0501	Status	No ADS block available	Contact service
0x0502	Status	No ADS send possible	Contact service
0x0510	Order no.	Acknowledgement cannot be allocated	Contact service
0x0520	Task ID	Message to illegal software component	Contact service
0x0601		Error on drive bus formation or data transmission (write FIFO not empty)	Replace hardware: NC module, control module 611D, drive bus cable
0x0602		Reserved	
0x0603		Error on bus formation: timeout or CRC error during PCU initialization	Replace hardware: control module 611D, NC module
0x0604		Error on bus formation: timeout or CRC error on timer initialization in PCU	Replace hardware: control module 611D, NC module
0x0605		Reserved	
0x0606		Sign-of-life error 611D	Ring programming with GI or eliminate gantry axes, replace 611D control module, wrong default for speed controller clock pulse in standard control system with SW versions below SW 5
0x0607		Invalid DCM interrupt (no timeout, no CRC)	Replace NC hardware
0x0608		Reserved	
0x0610		Reserved	
0x0611		Digital drives configured although there is no DCM (drive bus interface) on the NC hardware	Replace NC hardware
0x0612		Illegal internal ramp-up status	Replace NC hardware Reinstall NC system software Contact service
0x0613		invalid smtk_task opcode	Replace NC hardware Reinstall NC system software Contact service
0x0614		invalid smtk_status	Replace NC hardware Reinstall NC system software Contact service

1.5.1 Alarm description

0x0615		invalid status var_meldung()	Replace NC hardware Reinstall NC system software Contact service
0x0616		invalid status send_msg() – no message buffer free – error with smtk_send()	Replace NC hardware Reinstall NC system software Contact service
0x0617		invalid status mk_tea30_check() (error during interpretation of drive configuration)	Delete drive configuration Reinstall NC system software Contact service
0x0618		invalid status mk_bus_init()	Replace hardware: control module 611D, NC module Contact service
0x0619		Invalid status zustand_antrieb() Default status–0	Replace hardware: control module 611D, NC module
0x0620		Invalid status zustand_antrieb() Acknowledgement status–0	Replace hardware: control module 611D, NC module
0x0621		Invalid status zustand_antrieb() Default status–1	Replace hardware: control module 611D, NC module
0x0622		Invalid status zustand_antrieb() Acknowledgement status–1	Replace hardware: control module 611D, NC module
0x0623		Invalid status zustand_antrieb() Default status–2	Replace hardware: control module 611D, NC module
0x0624		Invalid status zustand_antrieb() Acknowledgement status–2	Replace hardware: control module 611D, NC module
0x0625		Invalid status zustand_antrieb() Default status–3	Replace hardware: control module 611D, NC module
0x0626		Invalid status zustand_antrieb() Acknowledgement status–3	Replace hardware: control module 611D, NC module
0x0627		Invalid status zustand_antrieb() Default status–4	Replace hardware: control module 611D, NC module
0x0628		Invalid status zustand_antrieb() Acknowledgement status–4	Replace hardware: control module 611D, NC module
0x0629		Invalid status zustand_antrieb() Acknowledgement status–5	Replace hardware: control module 611D, NC module
0x0630		Invalid status anstoss_hintergrund()	Replace hardware: control module 611D, NC module
0x0631		Invalid status lese_alarm_status()	Replace hardware: control module 611D, NC module
0x0632		Invalid status with drive alarm processing (al_status)	Replace hardware: control module 611D, NC module
0x0633		Invalid init-task event	Replace NC module Reinstall NC system software
0x0634		Error in drive configuration	Delete drive configuration Reinstall NC system software
0x0635		Invalid drive type (gsi_anlaufart)	Replace hardware: control module 611D, NC module
0x0636		Invalid smtk_event	Replace hardware: control module 611D, NC module

1.5.1 Alarm description

0x0637		Illegal transmission parameter in taster_übernahme()	Replace hardware: control module 611D, NC module
0x0638		Timeout during drive ramp-up – status 0 is not acknowledged by the drive	Replace 611D control module Reinstall drive firmware
0x0639		Illegal transmission parameter in meldung_servo_6xx()	Replace hardware: control module 611D, NC module
0x0640		Illegal status test formation of drive bus (gsi_zust_businit)	Replace hardware: control module 611D, NC module
0x0641		Faulty length of boot block 1	Reinstall drive firmware check hard disk replace NC module
0x0642		Faulty length of boot block 2	Reinstall drive firmware check hard disk replace NC module
0x0643		Timeout during transmission of initial program loader	Replace hardware: control module 611D, NC module, Contact service
0x0644		Faulty transmission parameter for fw_611D_urladen()	Replace hardware, reinstall NC system software Contact service
0x0645		Faulty status fw_611D_urladen()	Replace NC module reinstall NC system software Contact service
0x0701	Function no.	Overflow with orders (internal communication servo, drive)	Contact service
0x0702	–	Overflow with acknowledgements (internal communication servo, drive)	Contact service
0x0703	Function no.	Timeout (internal communication servo, drive)	Only SW 4: Set identical axis-specific position control cycle multiplication for all axes or resort the axes so that they are sorted according to descending position control cycle (e.g. 1st axis 4 ms, 2nd axis 2 ms, 3rd axis 1 ms) Otherwise: Increase cycle times for drive to obtain more calculation time for the communication.
0x0704	Function no.	Handshake error (internal communication servo, drive)	Only SW 4: Set identical axis-specific position control cycle multiplication for all axes or resort the axes so that they are sorted according to descending position control cycle (e.g. 1st axis 4 ms, 2nd axis 2 ms, 3rd axis 1 ms) Otherwise: Contact service
0x0705	Function no.	Unknown order (internal communication servo, drive)	Contact service
0x0706	Function no.	Unknown acknowledgement (internal communication servo, drive)	Contact service

Note Applies as from SW 3.

300001 Configuration error drive number

POWER ON

Scan When 611D drive link is being established

Effect 611D link is not established

Explanation Illegal drive number entered

Remedy Enter a drive number between 1 and 15

Note Applies as from SW 3

1.5.1 Alarm description

300002	Configuration error module type	POWER ON
<i>Scan</i>	Establishing the 611D drive link	
<i>Effect</i>	611D link not established	
<i>Explanation</i>	The configured module type does not correspond to the actual module type	
<i>Remedy</i>	Correct 611D module type (1/2 axis module)	
<i>Note</i>	Applies as from SW 3	
300003	Configuration error bus configuration	POWER ON
<i>Scan</i>	Establishing the 611D drive link	
<i>Effect</i>	611D link not established	
<i>Explanation</i>	The configured bus configuration does not correspond to the actual bus configuration (more actual drives as configured)	
<i>Remedy</i>	Correct 611D configuration; check hardware	
<i>Note</i>	Applies as from SW 3	
300004	Configuration error meas. cct. components	POWER ON
<i>Scan</i>	Establishing the 611D drive link	
<i>Effect</i>	611D link not established	
<i>Explanation</i>	Measuring circuit modules wrongly assigned (submodules missing or incorrect submodule type) or faulty	
<i>Remedy</i>	Replace drive module	
<i>Note</i>	Applies as from SW 3	
300005	Configuration error drive type	POWER ON
<i>Scan</i>	Establishing the 611D drive link	
<i>Effect</i>	611D link not established	
<i>Explanation</i>	The configured drive type (FDD/MSD) does not correspond to the actual drive type	
<i>Remedy</i>	Correct configuration or replace modules	
<i>Note</i>	Applies as from SW 3	
300006	CRC error drive link	POWER ON
<i>Scan</i>	Cyclic	
<i>Effect</i>	Machining stops, interlocking of NC START and Mode Group Ready	
<i>Explanation</i>	Interference on 611D drive link	
<i>Remedy</i>	Check control cabinet wiring; consult EMC regulations	
<i>Note</i>	Applies as from SW 3 As from SW 6, the alarm 300006 "CRC error drive link" is displayed only by the drive on which read access could not be executed. In addition, both error registers from the DCM are displayed for further information on the alarm. If the information from the error registers is not sufficient to determine a drive number, the alarm is output for the first drive available.	
300007	Number of defective axes, spindles, drives	POWER ON
<i>Scan</i>	Control startup	
<i>Effect</i>	Interlocking of NC START and Mode Group Ready	
<i>Explanation</i>	The NC axes, NC spindles and digital drives sum without setpoint assignment is larger than 15	
<i>Remedy</i>	Check setpoint assignment on digital drives and complete and match NC axis and spindle configuration if necessary	
<i>Note</i>	Applies as from SW 3	

300008	FDD software not loaded	POWER ON
<i>Scan</i>	Control power-up – establishment of drive link	
<i>Effect</i>	Power-up aborts	
<i>Explanation</i>	Drive configuration and NCK memory configuration are inconsistent.	
<i>Remedy</i>	In the NCK memory configuration, select the "FDD yes" setting or remove FDD from drive configuration. Check the system software.	
<i>Note</i>	Applies as from SW 4	
300009	MSD software not loaded	POWER ON
<i>Scan</i>	Control power-up – establishment of drive link	
<i>Effect</i>	Power-up aborts	
<i>Explanation</i>	Drive configuration and NCK memory configuration are inconsistent.	
<i>Remedy</i>	In the NCK memory configuration, select the "MSD yes" setting or remove MSD from drive configuration. Check the system software.	
<i>Note</i>	Applies as from SW 4	
300100	Drive link off	Reset key
<i>Scan</i>	Cyclic	
<i>Effect</i>	Interlocking of NC START and Mode Group Ready	
<i>Explanation</i>	Alarm appears when power supply to electronics of 611D in operation is switched off	
<i>Remedy</i>	Return power supply to drive electronics and press reset key	
<i>Note</i>	Applies as from SW 3 As from SW 6, the alarm 300100 "Drive link off" is displayed only by the drive on which read access could not be executed. In addition, both error registers from the DCM are displayed for further information on the alarm. If the information from the error registers is not sufficient to determine a drive number, the alarm is output for the first drive available.	
300300	Drive link off	Reset key
<i>Scan</i>	Startup	
<i>Effect</i>	Interlocking of NC start and Mode Group Ready	
<i>Explanation</i>	Alarm appears if there is no supply to the electronics for the 611D currently ramping up	
<i>Remedy</i>	Return power supply to drive electronics	
<i>Note</i>	Applies as from SW 3; as from SW 6, the two error registers are displayed for further information on the alarm.	
300301	"Drive software" being loaded	Message
<i>Scan</i>	When starting up the control or after switching on the drives.	
<i>Effect</i>	None	
<i>Explanation</i>	The message "Drive software being loaded" is displayed as long as the software of the drives is being loaded.	
<i>Remedy</i>	The message is automatically cleared after loading of the drive software.	
<i>Note</i>	Applies as from SW 6	

1.5.1 Alarm description

300500 System error drive**POWER ON***Scan*

Cyclic after control power-up

Effect

a) Error occurs during the ramp-up phase

- Ramp-up phase is stopped
- Pulse or servo disable
- SIMODRIVE_READY and DRIVE_READY are cancelled

Explanation

Error No. F...	Additional information (xx = for diagnostic purposes)	Explanation	Remedy	Relevant for
F001 (only for drive SW 1.x). For drive software > SW 2.x, see F034 or F035.	Incorrect address / xx	In the program memory test, it was found during power-up that the written bit pattern could not be read back. Cause: Hardware error on the servo control module.	Replace servo control module.	FDD
F002	Incorrect address / xx	In the data memory test, it was found during power-up that the written bit pattern could not be read back. Cause: Hardware error on the servo control module.	Replace servo control module.	FDD / MSD
F007	xx / xx	In the clock pulse synchronization between NC and drive, an illegal state has been read from the hardware. Synchronization could not be performed.	Replace servo control module.	FDD / MSD
F01B	xx / Axis No. xx = 0: Error	<ul style="list-style-type: none"> • A current of 0 is expected during power-up of the current actual value measurement and during cyclic operation on a pulse disable, since the system assures that no current can flow. It is possible that the hardware for the current actual value measurement is defective. 	<ul style="list-style-type: none"> • Replace the control module. Check the connections. Connect the power section 	FDD / MSD

Note

In the event of a fault, record additional information and inform hotline.

Error No. F...	Additional information (xx = for diagnostic purposes)	Explanation	Remedy	Relevant for
	xx = 1: Power section not connected	<ul style="list-style-type: none"> • A current of 0 is expected during power-up of the current actual value measurement and during cyclic operation on a pulse disable. If a 1-axis power section is addressed via the module selection (software configuration of the power section) as a 2-axis power section, the current actual value measurement outputs this system error, since a current > 0 is measured (NB: the software configuration and the installed hardware (power section and/or control module) do not match). 	<ul style="list-style-type: none"> – Change the software configuration of the power section (2-axis power section → 1-axis power section), or – Deactivate the 2nd axis, or – Install the 2-axis power section 	
F020	xx / xx	On a single-axis module, an attempt is made by the NC to activate the second axis. Possibly faults in communication via the drive bus or servo control module defective.	Replace servo control module. Check plug-on connections, take measures to eliminate noise (screening, check ground connections).	FDD / MSD
F021	xx / xx	On a single-axis module, an attempt is made by the NC to activate two axes. Possibly faults in communication via the drive bus or servo control module defective.	Replace servo control module. Check plug-on connections, take measures to eliminate noise (screening, check ground connections).	FDD / MSD
F022	xx / xx	In at least one axis of the drive module, the motor measuring system is not implemented or it is defective. Since the components used in the measuring systems are detected by the NC and this information is passed on to the drive, faults in communication by the drive bus could be the cause.	Replace servo control module. Check plug-on connections, take measures to eliminate noise (screening, check ground connections).	FDD / MSD

1.5.1 Alarm description

Error No. F...	Additional information (xx = for diagnostic purposes)	Explanation	Remedy	Relevant for
F023	xx / Axis No. Read K1C register of the relevant PCU ASIC NC drive number	The motor measuring system has a motor encoder with voltage output. This calls for an IPU submodule with voltage input. A submodule other than that expected has been detected.	Replace servo control module. Check plug-on connections, take measures to eliminate noise (screening, check ground connections).	FDD / MSD
F024	xx / xx	In executing the software, an illegal internal axis number has been found. Possible causes: Defective servo control module, electromagnetic compatibility faults.	Replace servo control module. Take measures to eliminate noise (screening, check ground connections).	FDD / MSD
F025	xx / xx	In executing the software, an illegal internal physical axis number has been found. Possible causes: Defective servo control module, electromagnetic compatibility faults.	Replace servo control module. Take measures to eliminate noise (screening, check ground connections).	FDD / MSD
F026	xx / Axis No.	The NC attempts to log on an FDD module as MSD. There are possibly faults in the communication via the drive bus or servo control module is defective.	Replace servo control module. Check plug-on connections, take measures to eliminate noise (screening, check ground connections).	FDD
F027	xx / Axis No.	The NC attempts to log on an MSD module as FDD. There are possibly faults in the communication via the drive bus or servo control module is defective.	Replace servo control module. Check plug-on connections, take measures to eliminate noise (screening, check ground connections).	MSD
F028	xx / Axis No. Read K1C register of the relevant PCU ASIC NC drive number	For the direct measuring system, only certain submodules are allowed. A submodule has been detected that is not allowed.	Replace servo control module. Check plug-on connections, take measures to eliminate noise (screening, check ground connections).	FDD / MSD
F031	Error code / Axis No. 0x40; illegal PDU length 0x41; axes do not have the same PDU length 0x42; PDU length not a word multiple 0x43; axes do not have the same NC type	The NC has not transferred permissible corner data to the drive for communication via the drive bus. This is presumably caused by faults on the drive bus or a defective servo control module.	Replace servo control module. Check plug-on connections, take measures to eliminate noise (screening, check ground connections).	FDD / MSD
F033	Error code / xx 0x51; wrong data format in element list 0x52; wrong conversion group specified in Refresh	The drive software is no longer consistent. This is presumably caused by a hardware fault on the servo control module.	Reload drive software Replace servo control module.	FDD / MSD
F034 F035 Error numbers have different load sequences	Error code / incorrect address 0 or incorrect address 0x60; incorrect response of SERVO on STF handshake 0x61; error during RAM check 0x62; transport checksum does not correspond to that of SERVO	Errors have been found on loading the drive software. This is caused either by errors in transmission on the drive bus or a defective servo control module.	Check drive bus cable and connectors, take measures to eliminate noise (screening, check ground connections), replace servo control module.	FDD / MSD

1.5.1 Alarm description

Effect

b) In cyclic mode

For MSD:

- Pulse suppression, motor runs down
- SIMODRIVE_READY and DRIVE_READY are cancelled
- Power On fault
- Pulse and controller disable corresponds to STOP A with SINUMERIK Safety Integrated.

For FDD:

- Controllers are disabled. Motor is braked.
- SIMODRIVE_READY and DRIVE_READY are cancelled
- Power On fault
- Regenerative stop (corresponds to STOP B) with SINUMERIK Safety Integrated.

Response via MD 1612.0, can be configured as from SW 4

Explanation

Error No. F...	Additional information (xx = for diagnostic purposes)	Explanation	Remedy	Relevant for
F003	Time slice / xx 20=current controller cycle (MD 1000) 10=speed controller cycle (MD 1001) 8=position controller cycle (NC MD) 4=1 ms (permanent) 2=4 ms (permanent) 1=monitoring cycle (MD 1102) A0=start-up synchronization B0=background computing time 40=SI monitoring cycle (MD 1300)	The computation time of the drive processor is no longer sufficient for the selected functions in the given clock pulse times. This error normally occurs only in conjunction with start-up functions (FFT measurement, step response). SINUMERIK Safety Integrated: Monitoring cycle too small.	During start-up with FFT or measurement of the step response – Switch off emergency retraction – Switch off feedforward control (MD 1004.0) – Switch off min-max memory (MD 1650.0) – Reduce number of DAC output channels (max. 1 channel) – Switch off variable signalling function (MD1620.0) – Switch off encoder phase error compensation (MD1011.1) – Select larger position controller cycle for the NC. – Increase the corresponding cycle or the subordinate cycle (e.g. current, speed or position control cycle) or deselect functions which are not required.	FDD / MSD
F004	xx / xx	With controller enable, the NC must update the sign-of-life in each position controller cycle. If an error occurs, there has been no sign-of-life for at least two consecutive position controller cycles. Causes: NC failure, communication failure via the drive bus. Hardware fault on the drive module or HW error on NC CPU if error occurs sporadically at intervals of several hours. A further reason: ring programming with GI or gantry axes.	Check plug-on connections, take measures to eliminate noise (screening, check ground connections). Replace NC hardware, replace servo control module.	FDD / MSD
F005	xx / xx 1A: SZ <> 1 for IZ=0 2A: SZ <> 1, 2, 3, 4, 5 2B: SZ IZ <> 0, 1 2C: SZ=3 for PO parameterization error 3A: SZ <> 1, 2, 3, 4, 5 3B: SZ IZ <> 0, 1	Ramping up of the drive modules is broken down into 5 states (steps). The states are provided in sequence by the NC and acknowledged by the drive. If an error occurs, an invalid setpoint state has been detected in the drive. Causes: Faults in communication via the drive bus. Hardware fault on the drive module, hardware fault on the NC.	Check plug-on connections, take measures to eliminate noise (screening, check ground connections). Replace NC hardware, replace servo control module.	FDD / MSD
F006	xx / xx	The endless loop for processing communication has been exited. Presumably caused by a hardware fault on the servo control module.	Replace servo control module.	FDD / MSD

1.5.1 Alarm description

Error No. F...	Additional information (xx = for diagnostic purposes)	Explanation	Remedy	Relevant for
F010	x / xx x = 1: HW underflow 2: HW overflow 3: SW underflow 4: SW overflow	The boundaries of the processor-internal hardware stack or of the software-stack in the data memory have been violated.	Reload drive software. Replace servo control module.	FDD / MSD
F011	xx / xx	The watchdog timer on the servo control module has expired. Caused by a hardware fault in the time base on the servo control module.	Replace servo control module.	FDD / MSD
F012	xx / xx	The NC basic clock pulse generated on the NC and transferred via the drive bus cable to the drive has failed. Possible causes: NCK Reset, EMC faults, hardware fault NC, cable break drive bus, hardware fault servo control module.	Check drive bus cable and plug-on connectors, take measures to eliminate noise (screening, check ground connections), replace NC hardware, replace servo control module.	FDD / MSD
F013	xx / xx	The NC basic clock pulse generated on the NC and transmitted via the drive bus cable to the drive did not supply a pulse that fits in the clock pulse grid. Possible causes: EMC faults drive bus, hardware fault NC, hardware fault servo control module.	Check drive bus cable and plug-on connectors, take measures to eliminate noise (screening, check ground connections), replace NC hardware, replace servo control module.	FDD / MSD
F014	Incorrect address / xx	The processor has detected an illegal command in the program memory.	Replace servo control module.	FDD / MSD
F015	xx / xx As from version 4.0: start address of the incorrect code data area As from version 4.0: segment of the incorrect code data area, with: 0: P memory 1: X memory 2: Y memory	In the continuous checking of the checksum in the program memory, a difference has been found between the set and actual checksums. Presumably caused by a hardware fault on the servo control module.	Replace servo control module.	FDD / MSD
F016	xx / xx	An illegal interrupt of the processor has occurred.	Check drive bus cable and connector. Replace servo control module.	FDD / MSD
F017	xx / xx	An illegal interrupt of the processor has occurred.	Check drive bus cable and connector. Replace servo control module.	FDD / MSD
F018	xx / xx	An illegal interrupt of the processor has occurred.	Check drive bus cable and connector. Replace servo control module.	FDD / MSD
F019	xx / xx	An illegal interrupt of the processor has occurred.	Check drive bus cable and connector. Replace servo control module.	FDD / MSD

1.5.1 Alarm description

Error No. F...	Additional information (xx = for diagno- stic purposes)	Explanation	Remedy	Relevant for
F030	Error code / Axis No. 0x01; non-sup- ported ROSCTR 0x02; illegal ROSCTR 0x03; job man- agement "defec- tive" 0x04; wrong PDUREF for ac- knowledgegment 0x05; acknowl- edgement illegal at that time 0x06; acknowl- edgement is not supported 0x07; illegal PROTID 0x08; illegal PERLG (odd) 0x09; buffer man- agement "defec- tive" 0x0A; illegal PI code (internal) 0x0B; internal status of PI re- start illegal 0x0C; status pro- cessor in WRITE- DATA "defective" 0x0D; illegal transmission pa- rameter for RE- FRESH_PI ZUST NC drive number	Either irrecoverable errors have been found in the communication via the drive bus, or the drive soft- ware is no longer consistent. Cause is either a defective drive bus inter- face or a hardware fault on the servo control group.	Check drive bus cable and plug-on connectors, take measures to elimi- nate noise (screening, check ground connections), replace servo control module.	FDD / MSD
F032	Error code / Axis No. 0x20; job man- agement "defec- tive" 0x21; illegal sta- tus in SET_TRANSP 0x22; checksum test incorrect more than 3 times 0x23; receive PDU too long 0x24; status 6XX abort illegal NC drive number	Either irrecoverable errors have been found in the communication via the drive bus, or the drive soft- ware is no longer consistent. Cause is either a defective drive bus inter- face or a hardware fault on the servo control group.	Check drive bus cable and plug-on connectors, take measures to elimi- nate noise (screening, check ground connections), replace servo control module.	FDD / MSD
F040	xx / xx	An illegal number of current setpoint filters (>4) has been entered.	Correct number of current setpoint filters MD1200.	FDD / MSD
F041	xx / xx	An illegal number of speed setpoint filters (>2) has been entered.	Correct number of speed setpoint filters MD1500.	FDD / MSD

1.5.1 Alarm description

Error No. F...	Additional information (xx = for diagnostic purposes)	Explanation	Remedy	Relevant for
F044 (drive SW 2.5 and higher)	xx /axis no.	<ul style="list-style-type: none"> The rotor position synchronization is faulty. The difference between the first part of rotor position synchronization (coarse synchronization) and the second part (fine synchronization to the active encoder zero mark) exceeds 45° electrical. A too large difference may be caused by the following: incorrect encoder adjustment EMC problem on zero mark signal too high voltage level of CD track 	<ul style="list-style-type: none"> Check encoder adjustment and EMC measures new sequence check mode replace motor 	FDD
F045	Error code / Axis No.	Either an encoder with distance-coded reference marks has been entered by the NC or a BERO switch in the register \$1D of the motor measuring system of the PCU ASIC. This is not allowed during fine synchronization which is activated by powering up, by zero monitoring error or by deselecting the parking axis.	After powering up, in the event of zero monitoring errors or after deselection of the parking axis, the NC/ PLC must not enter encoders with distance-coded reference marks or a BERO switch into the register \$1D of the motor measuring system of the PCU ASIC.	FDD / MSD
F046	xx / xx	As from drive software SW 4.02, startup of the drive is only possible with the drive software loaded	Re-load drive software	FDD/MSD

Note

Applies as from SW 3

300501**Current monitoring****POWER ON****Scan**

Cyclically after the control is switched on

Effect

Pulse reset, motor coasts down
SIMODRIVE READY and DRIVE_READY are reset.
Power On error.

Explanation

- The smoothed current amount (smoothing time: MD 1254) is greater than or equal to a current threshold. A serious error has occurred in the current actual value acquisition.
- With active rotor position identification (FDD only), the permissible current threshold has been exceeded.
 - Up to SW 2.6 (611–D): only MSD; additionally to alarms 300502 / 300503
Current threshold = $1,2 \cdot \text{max. permissible power section current (MD1107)}$
 - With SW 2.6 and higher: FDD and MSD; replacing alarms 300502 / 300503
Current threshold = $1,2 \cdot 1,05 \cdot \text{max. permissible power section current (MD1107)}$

Remedy

Check maximum power section current MD1107; replace 611D hardware if necessary

Note

Applies with SW 3 and higher

300502**Meas. circuit error phase current R****POWER ON****Scan**

Cyclic after control power up

Effect

- Pulse suppression, motor runs down
- SIMODRIVE_READY and DRIVE_READY are cancelled.
- Power On error

Explanation

Phase current R is greater than or equal to 1.05 times the value of the maximum permissible power section current MD 1107. Serious error has occurred in the actual current value circuit.

- Check maximum power section current MD1107
- Defective actual current value circuit

Remedy

Check maximum power section current MD1107; replace 611D hardware if necessary

Note

Applies up to SW 4 (611–D: up to SW 2.6)

1.5.1 Alarm description

300503	Meas. circuit error phase current S	POWER ON
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	<ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Power On error 	
<i>Explanation</i>	Phase current S is greater than or equal to 1.05 times the value of the maximum permissible power section current MD 1107. Serious error has occurred in the actual current value circuit. <ul style="list-style-type: none"> • Check maximum power section current MD1107 • Defective actual current value circuit 	
<i>Remedy</i>	Check maximum power section current MD1107; replace 611D hardware if necessary	
<i>Note</i>	Applies up to SW 4 (611–D: up to SW 2.6)	
300504	Meas. circuit error motor (inc.)	POWER ON
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	<ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Power On error 	
<i>Explanation</i>	<ul style="list-style-type: none"> • Encoder faulty • Motor encoder not connected • Motor encoder cable faulty • Module faulty 	
<i>Remedy</i>	Eliminate cause; replace motor/611D hardware if necessary	
<i>Note</i>	Applies as from SW 3	
300505	Measuring circuit error abs. track	POWER ON
<i>Scan</i>	Control power up or cancellation of the Parking Axis function	
<i>Effect</i>	<ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Power On error 	
<i>Explanation</i>	Error on the absolute track or measured value acquisition of optical encoder <ul style="list-style-type: none"> • Absolute value encoder defective • Motor encoder not connected • Motor encoder cable faulty • Module faulty • Consider MD1023 (IMS) and MD1033 (DMS) 	
<i>Remedy</i>	Eliminate cause; replace motor/611D hardware if necessary	
<i>Note</i>	Applies as from SW 3	

300506	Sign of life: NC failed	POWER ON
<i>Scan</i>	Cyclic after servo enable	
<i>Effect</i>	for MSD: <ul style="list-style-type: none"> • Pulse suppression, motor coasts down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Power On – error for FDD: <ul style="list-style-type: none"> • Controllers are disabled, motor is braked • SIMODRIVE_READY and DRIVE_READY are cancelled. • As from drive SW 2, response can be configured via MD 1612.6 	
<i>Explanation</i>	With servos enabled, the NC must update the sign of life in every position control cycle. If an error occurs, the sign of life has not been updated. Cause: a) NC does not update the sign of life as response to an alarm (e.g. 611D alarm) b) Failure of communication via drive bus c) Hardware fault of drive module d) NC failure	
<i>Remedy</i>	Re a) Check to see whether the sign of life failure is a secondary error. It is a secondary error if, for example: Axis x is faulty / outputs an alarm in an n-axes structure. If this error situation is present, the above error message is given for all n axes, although there is a fault/alarm present only on axis x. ⇒ Correct fault of axis x ⇒ Sign of life of other axes is irrelevant Re b) Check connector, take radio interference suppression measures (check shielding and ground) Re c) Exchange servo module Re d) See NC error diagnosis, replace NC hardware, if necessary.	
<i>Note</i>	Applies as from SW 6	
300507	Synchronization error rotor position	POWER ON
<i>Scan</i>	Control power up or cancellation of the Parking Axis function	
<i>Effect</i>	for FDD: <ul style="list-style-type: none"> • Controllers are disabled, motor is braked • SIMODRIVE_READY and DRIVE_READY are cancelled • As from drive SW 2, response can be configured via MD 1612.7 	
<i>Explanation</i>	Difference angle between the actual rotor position and the recalculated rotor position is too great. Faults might have occurred on the encoder or zero marker signals.	
<i>Remedy</i>	Reference with BERO deselect. Check encoder cable, encoder cable connection or grounding, because EMC problems might have occurred. Replace motor/611D if necessary.	
<i>Note</i>	Applies as from SW 4 As from SW 5, alarm cannot be configured	

1.5.1 Alarm description

300508	Zero mark error motor	POWER ON
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	for MSD: <ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Power On error for FDD: <ul style="list-style-type: none"> • Controllers are disabled, motor is braked • SIMODRIVE_READY and DRIVE_READY are cancelled As from drive SW 2, response can be configured via MD 1612.8	
<i>Explanation</i>	The counted number of encoder marks is incorrect on passing through the zero marker. <ul style="list-style-type: none"> • Defective encoder • EMC problems • Defective IPU submodule 	
<i>Remedy</i>	Eliminate cause; replace motor/611D hardware if necessary.	
<i>Note</i>	Applies as from SW 3	
300509	Converter limit frequency exceeded	POWER ON
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	for MSD: <ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Power On error for FDD: <ul style="list-style-type: none"> • Controllers are disabled, motor is braked • SIMODRIVE_READY and DRIVE_READY are cancelled • Power On error 	
<i>Explanation</i>	As from drive SW 2, response can be configured via MD 1612.9 Motor frequency has exceeded the limit frequency f_g . Possible causes: Number of encoder marks in MD 1005 does not correspond to actual number of encoder marks. Speed limitation MD 1147 or number of motor pole pairs MD 1112 in FDD or motor nominal frequency MD 1134 and motor nominal speed MD 1400 for MSD are equal to zero or not correct. Limit frequency f_g : FDD $f_g = 1.12 * \text{minimum}(1.2 * \text{MD } 1400, \text{MD } 1147) * \text{MD } 1112 / 60$ MSD $f_g = 1.12 * \text{minimum}(\text{MD } 1146, \text{MD } 1147) * \text{number of pole pairs} / 60$ $\text{number of pole pairs} = \text{nominal motor frequency (MD } 1134) * 60 / \text{nominal motor speed (MD } 1400)$	
<i>Remedy</i>	Check MD 1005 against actual number of encoder marks. If necessary, check MD 1147 (speed limitation), MD 1400 (nominal motor speed) and additionally for MSD: MD 1134 (nominal motor frequency) FDD: MD 1112 (number of motor poles).	
<i>Note</i>	Applies as from SW 4	
300510	Fault in center frequency measurement	POWER ON
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	<ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Power On error 	
<i>Explanation</i>	Speed too high at center frequency measurement	
<i>Remedy</i>	Reduce speed	
<i>Note</i>	Applies as from SW 4	

300511	Meas. value memory active	POWER ON
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	<ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Power On error 	
<i>Explanation</i>	Measured value memory is active during power up	
<i>Remedy</i>	Start up again!	
<i>Note</i>	Applies as from SW 4	
300515	Heat sink temperature alarm	POWER ON
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	<p>for MSD:</p> <ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Power On error <p>for FDD:</p> <ul style="list-style-type: none"> • Controllers are disabled, motor is braked • SIMODRIVE_READY and DRIVE_READY are cancelled • Power On error <p>As from drive SW 2, response can be configured via MD 1612.15</p>	
<i>Explanation</i>	<p>Heat sink temperature in "hot" state and time of 20 s expired.</p> <ul style="list-style-type: none"> • Converter overload • Ambient temperature too high • Fan not working • Temperature encoder faulty 	
<i>Remedy</i>	Eliminate cause	
<i>Note</i>	Applies as from SW 3	
300606	Flux controller at end stop	Reset key
<i>Scan</i>	Cyclically after the control is switched on	
<i>Effect</i>	<ul style="list-style-type: none"> • Pulse reset, motor coasts down • SIMODRIVE_READY and DRIVE_READY are reset. • Reset error 	
<i>Explanation</i>	<p>The specified flux setpoint cannot be achieved although the maximum current is specified.</p> <p>Causes:</p> <ul style="list-style-type: none"> • Motor data (equivalent circuit diagram data) are incorrect • Motor data and type of connection of motor (start/delta) do not match • Motor is unstable because motor data are completely wrong • Current limit is too low for motor ($0.9 \cdot MD\ 1238 \cdot MD\ 1103 < MD\ 1136$) 	
<i>Remedy</i>	Eliminate cause	
<i>Note</i>	Alarm in SW 5 and higher	
300607	Current controller at end stop	Reset key
<i>Scan</i>	Cyclically after the control is switched on	
<i>Effect</i>	<ul style="list-style-type: none"> • Pulse reset, motor coasts down • SIMODRIVE_READY and DRIVE_READY are reset. • Reset error 	
<i>Explanation</i>	<p>The specified current setpoint cannot be injected in the motor although the maximum voltage is defined.</p> <p>Possible causes:</p> <ul style="list-style-type: none"> • Motor either not connected or phase missing 	
<i>Remedy</i>	Check motor – converter connecting cable.	
<i>Note</i>	Alarm in SW 5 and higher (611–D: SW 3.1 and higher)	

1.5.1 Alarm description

300608	Speed controller against stop	Reset key
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	<ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error 	
<i>Explanation</i>	<p>Set torque value exceeds limit torque value, set speed value is less than speed threshold MD 1606 and the time of MD 1603 (FDD) has expired.</p> <p>Causes:</p> <ul style="list-style-type: none"> • Motor encoder not connected • Motor encoder cable faulty • Module faulty • Encoder faulty • Motor earth not connected • Motor encoder cable shield not connected • Motor not connected or phase not connected • Motor blocked 	
<i>Remedy</i>	Eliminate cause	
<i>Note</i>	Applies as from SW 3	
300609	Temperature probe break	Reset key
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	<ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error 	
<i>Explanation</i>	<ul style="list-style-type: none"> • Temperature encoder faulty (motor) • Connection to encoder faulty • Module faulty 	
<i>Remedy</i>	Eliminate cause or operate at fixed temperature Note: Temperature monitoring not active with fixed temperature	
<i>Note</i>	Applies as from SW 3	
300609	Encoder limit frequency exceeded	Reset key
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	<p>for MSD:</p> <ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Power On error <p>for FDD:</p> <ul style="list-style-type: none"> • Controllers are disabled, motor is braked • SIMODRIVE_READY and DRIVE_READY are cancelled • Power On error <p>Response via MD 1613.9 configurable as from SW 4</p>	
<i>Explanation</i>	<p>Actual speed value exceeds the encoder limit frequency:</p> <ul style="list-style-type: none"> • Wrong encoder • MD 1005 does not correspond to number of encoder marks • Encoder defective • Motor encoder cable defective or not fastened properly • Motor encoder cable screen not connected • Drive module defective 	
<i>Remedy</i>	Eliminate cause	
<i>Note</i>	Applies as from SW 4	

300610	Rotor position identification failed	Reset key
<i>Scan</i>	During the function "Rotor position identification"	
<i>Effect</i>	FDD only: <ul style="list-style-type: none"> – Controllers are disabled, motor is braked – SIMODRIVE_READY and DRIVE_READY are cancelled. – Reset error Response via MD 1613.13 configurable as from SW 4	
<i>Explanation</i>	Rotor position could not be determined from the measuring signals, because no significant saturation effects occurred.	
<i>Remedy</i>	Increase current via MD 1019 or check whether motor is connected.	
<i>Note</i>	Applies as from SW 6	
300611	Illegal motion during rotor position identification	Reset key
<i>Scan</i>	During the function "Rotor position identification"	
<i>Effect</i>	for MSD only: <ul style="list-style-type: none"> • Controllers are disabled, motor is braked • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error 	
<i>Explanation</i>	During the measurement, the motor has rotated by a value greater than that entered in MD 1020. The torsion may have been caused by switching the motor onto a rotating motor or through the identification.	
<i>Remedy</i>	If the torsion has been caused by the identification and if the error occurs repeatedly, reduce MD 1019 or increase MD 1020.	
<i>Note</i>	Applies as from SW 6	
300613	Motor temperature alarm	Reset key
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	for MSD: <ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error for FDD: <ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled • Reset error Response via MD 1613.13 configurable as from SW 4	
<i>Explanation</i>	Beyond the motor temperature threshold MD 1607 <ul style="list-style-type: none"> • Motor overloaded • Machine current too great, e.g. because of incorrect motor data • Temperature sensor defective (motor) • Motor fan defective • Module defective • Fault between turns motor 	
<i>Remedy</i>	Eliminate cause or operate at MSD fixed temperature Note: Temperature monitoring not active with fixed temperature	
<i>Note</i>	Applies as from SW 4	

1.5.1 Alarm description

300614	Motor temperature cut-off limit	Reset key
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	for MSD: <ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error for FDD: <ul style="list-style-type: none"> • Controllers are disabled, motor is braked • SIMODRIVE_READY and DRIVE_READY are cancelled • Reset error As from drive SW 2, response can be configured via MD 1613.14	
<i>Explanation</i>	Beyond motor temperature threshold MD 1602 and timer MD 1603 has expired <ul style="list-style-type: none"> • Motor overloaded • Machine current too great, e.g. because of incorrect motor data (P-96/P-238) • Temperature sensor defective (motor) • Motor fan defective • Module defective • Fault between turns motor 	
<i>Remedy</i>	Eliminate cause or operate at MSD fixed temperature Note: Temperature monitoring not active with fixed temperature	
<i>Note</i>	Applies as from SW 3	
300701	Start-up required	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	Drive does not have correct parameter set	
<i>Remedy</i>	<ul style="list-style-type: none"> • Boot strap via motor selection or load TEA3 file • Save BOOT drive • Power up again 	
<i>Note</i>	Applies as from SW 3	
300702	Drive basic clock pulse invalid	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	A drive basic clock pulse has been set at the NC that is too high for the drive	
<i>Remedy</i>	Change the basic clock pulse at the NC	
<i>Note</i>	Applies as from SW 3	
300703	Current controller clock pulse invalid	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	A current controller clock pulse MD 1000 has been set that is not allowable for the drive.	
<i>Remedy</i>	Change current controller clock pulse	
<i>Note</i>	Applies as from SW 3	
300704	Speed controller clock pulse invalid	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	Speed controller clock pulse MD 1001 is invalid.	
<i>Remedy</i>	Change speed controller clock pulse	
<i>Note</i>	Applies as from SW 3	

300705	Position controller clock pulse invalid	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	A position controller clock cycle has been set at the NC that is not allowed for the drive	
<i>Remedy</i>	Change position controller clock cycle at the NC	
<i>Note</i>	Applies as from SW 3	
300706	Monitoring clock pulse invalid	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	Monitoring clock pulse MD 1002 is invalid	
<i>Remedy</i>	Change monitoring clock cycle	
<i>Note</i>	Applies as from SW 3	
300707	Drive basic clock pulse axially not equal	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	On 2-axis modules, the drive basic clock cycle must be identical for both axes.	
<i>Remedy</i>	On 2-axis modules, the drive basic clock pulse must be set to be identical for both axes.	
<i>Note</i>	Applies as from SW 3	
300708	Current controller clock cycle axially not equal	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	On 2-axis modules, the current controller clock pulse MD 1000 must be identical for both axes.	
<i>Remedy</i>	Set the current controller clock cycle to be identical for both axes.	
<i>Note</i>	Applies as from SW 3	
300709	Speed controller clock pulse axially not equal	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	On 2-axis modules, the speed controller clock pulse MD 1001 must be identical for both axes.	
<i>Remedy</i>	Set speed controller clock pulse to be identical for both axes.	
<i>Note</i>	Applies as from SW 3	
300710	Position controller clock pulse axially not equal	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	On 2-axis modules, the position controller clock pulse must be identical for both axes.	
<i>Remedy</i>	Set the position controller clock pulse to be identical for both axes.	
<i>Note</i>	Applies as from SW 3	

1.5.1 Alarm description

300711	Monitoring clock pulse axially not equal	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	On 2-axis modules, the monitoring clock pulse MD 1002 must be identical for both axes.	
<i>Remedy</i>	Set the monitoring clock pulse to be identical for both axes.	
<i>Note</i>	Applies as from SW 3	
300712	Dynamic response setting not possible (2 axes)	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	For two active axes on a module, it is not possible to change the controller structure via MD 1004.	
<i>Remedy</i>	With two active axes on a module, configuration structure MD 1004 must be set to i before n.	
<i>Note</i>	Applies as from SW 3	
300713	Shift of position controller clock pulse invalid	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	The position controller clock pulse shift specified by the NC is greater than or equal to the position controller clock pulse.	
<i>Remedy</i>	NC Hotline	
<i>Note</i>	Applies as from SW 4	
300714	Power section code wrong	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	<ul style="list-style-type: none"> The module order number entered in the NC for the drive is not permissible Additional information for MSD (drive SW 1 only): Illegal power section code The drive has already been booted with a module order number which does not correspond with the module order number currently set in the NC. Additional information for MSD (drive SW 1 only): Actual power section code in MSD and actual power section code in NC 	
<i>Remedy</i>	Reselect module in the NC or cancel reboot procedure	
<i>Note</i>	Applies as from SW 3	
300715	Maximum power section current <= 0	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	The maximum current of the power section MD 1107 has a value that is less than or equal to 0.	
<i>Remedy</i>	Enter a valid value in machine data MD 1107 "Maximum current of power section".	
<i>Note</i>	Applies as from SW 3	

300716	Torque constant invalid	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	1. Torque constant MD 1113 has a value that is less than or equal to 0. 2. The ratio of torque constant MD 1113/number of pole pairs MD 1112 is greater than 70.	
<i>Remedy</i>	Enter a valid value in machine data MD 1113 "Torque constant".	
<i>Note</i>	Applies as from SW 3	
300717	Motor moment of inertia <= 0	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	Motor moment of inertia MD 1117 has a value that is less than or equal to 0.	
<i>Remedy</i>	Enter a valid value in machine data MD 1117 "Motor moment of inertia".	
<i>Note</i>	Applies as from SW 3	
300718	Calculation delay error, I controller	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	Input error in calculation delay timer MD 1101	
<i>Remedy</i>	Correct input error in calculation delay timer MD 1101.	
<i>Note</i>	Applies for SW 3 only	
300719	Error motor code number	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	One of the motor code numbers is illegal (P-96 or P-238) Additional information Motor fault (1 or 2)	
<i>Remedy</i>	<ul style="list-style-type: none"> • Change motor code number • Save BOOT drive • Repeat ramp-up 	
<i>Note</i>	Applies for SW 3 only	
300719	Motor delta not parameterized	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	During activation of the star-delta changeover by drive MD1013, the motor delta (motor2) is not parameterized.	
<i>Remedy</i>	Check or enter machine data for motor delta (motor 2).	
<i>Note</i>	Applies as from SW 4	
300720	Maximum motor speed too high	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	Maximum motor speed MD 1401 of speed controller clock pulse MD 1001 have too great a value.	
<i>Remedy</i>	Reduce maximum motor speed MD 1401 or set a smaller speed controller clock pulse MD 1001.	
<i>Note</i>	Applies for SW 3 only	

1.5.1 Alarm description

300721	I0 motor > i-rated motor	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	Motor no-load current (MD 1136) is greater than the rated current (MD 1103) of the motor.	
<i>Remedy</i>	<ul style="list-style-type: none"> • Change motor data • Save BOOT drive • Repeat ramp-up 	
<i>Note</i>	Applies for SW 3 only	
300722	I0 motor > I-rated power section	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	Connected motor too large for power section being used (continuous current MD 1108) because of its no-load current (MD 1136).	
<i>Remedy</i>	Change power section or motor	
<i>Note</i>	Applies for SW 3 only	
300723	STS configuration axially unequal	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	On 2-axis modules, the configuration of the control set MD 1003 must be identical for both axes.	
<i>Remedy</i>	Make the configuration of the control set identical for both axes.	
<i>Note</i>	Applies as from SW 3	
300724	Invalid pole pair number	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	FDD: MD 1112 is not correct. MSD: MD 1134 or MD 1400 is not correct.	
<i>Remedy</i>	Eliminate error on inputting the above machine data.	
<i>Note</i>	Applies as from SW 4	
300725	Number of encoder marks = 0	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	The number of encoder marks MD 1005 has the value 0.	
<i>Remedy</i>	Eliminate error when entering the number of encoder marks MD 1005.	
<i>Note</i>	Applies as from SW 3	
300726	Voltage constant = 0	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	The voltage constant MD 1114 has a value less than or equal to zero.	
<i>Remedy</i>	Eliminate error on inputting the voltage constant MD 1114.	
<i>Note</i>	Applies as from SW 4	

300727	Reactance <= 0	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	The stator reactance MD 1139 or rotor reactance MD 1140 or magnetizing reactance MD 1141 is less than or equal to zero.	
<i>Remedy</i>	Eliminate error on inputting MD 1139, MD 1140 or MD 1141.	
<i>Note</i>	Applies as from SW 4	
300728	Torque/current matching factor too large	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	The matching factor (set torque → cross current) in the speed controller is too large.	
<i>Remedy</i>	Eliminate error when inputting <ul style="list-style-type: none"> Rated motor current MD 1103, or Limit current transistor MD 1107, or Torque constant MD 1113. 	
<i>Note</i>	Applies as from SW 4	
300729	Motor zero-speed current <= 0	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	Motor zero-speed current MD 1118 is less than or equal to zero.	
<i>Remedy</i>	Eliminate error on inputting the motor zero-speed current MD 1118	
<i>Note</i>	Applies as from SW 4	
300730	Rotor resistance invalid	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	Rotor resistance is less than or equal to zero or format overflow has occurred.	
<i>Remedy</i>	The following machine data can have an incorrect value: <ul style="list-style-type: none"> Torque controller clock pulse MD 1001 Rated motor frequency MD 1134 Rotor resistance cold MD 1138 Stator stray reactance MD 1139 Rotor stray reactance MD 1140 	
<i>Note</i>	Applies as from SW 4	
300731	Rated power <= 0	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	Rated power MD 1130 is less than or equal to zero.	
<i>Remedy</i>	Eliminate error on inputting the rated power MD 1130.	
<i>Note</i>	Applies as from SW 4	
300732	Rated motor speed <= 0	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	Rated motor speed MD 1140 is less than or equal to zero.	
<i>Remedy</i>	Eliminate error on inputting the rated motor speed MD 1140.	
<i>Note</i>	Applies as from SW 4	

1.5.1 Alarm description

300733	Motor no-load voltage invalid	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	The motor no-load voltage MD 1135 is less than or equal to zero or greater than rated motor voltage MD 1132 or greater than 450 x MD 1400/MD 1142. With MD 1400: Rated motor speed MD 1142: Speed at start of field weakening	
<i>Remedy</i>	Eliminate error on inputting <ul style="list-style-type: none"> Rated motor voltage MD 1132 Rotor zero-speed voltage MD 1135 Rated motor speed MD 1400 Threshold speed field weakening MD 1142. Motor no-load current MD 1136 	
<i>Note</i>	Applies as from SW 4	
300734	Motor no-load current <= 0	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	Motor no-load current MD 1136 is less than or equal to zero.	
<i>Remedy</i>	Eliminate error on inputting the motor no-load current MD 1136.	
<i>Note</i>	Applies as from SW 4	
300735	Field weakening speed <= 0	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	Field weakening speed MD 1142 is less than or equal to zero.	
<i>Remedy</i>	Eliminate error on inputting the field weakening speed MD 1142.	
<i>Note</i>	Applies as from SW 4	
300736	Lh characteristic invalid	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	Upper speed on the Lh characteristic MD 1143 is less than or equal to field weakening speed MD 1142 or gain of Lh characteristic MD 1144 is less than 100.	
<i>Remedy</i>	Eliminate error on inputting <ul style="list-style-type: none"> Upper speed of the Lh characteristic MD 1143 Gain of the Lh characteristic MD 1144 Field weakening speed MD 1142. 	
<i>Note</i>	Applies as from SW 4	
300740	Parameterization error	POWER ON
<i>Scan</i>	POWER ON and cyclic	
<i>Effect</i>	Drive only ramps up to ramp-up state 2 or pulse suppression and motor runs down	
<i>Explanation</i>	Division error has occurred because of illegal parameter combination Additional information: none	
<i>Remedy</i>	<ul style="list-style-type: none"> Check parameters and correct Save BOOT Repeat ramp-up 	
<i>Note</i>	Applies as from SW 3	

300741	Upper limit violated MD	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	During ramp-up control detects that machine data has violated input limits. This occurs with parameters with motor-dependent limits if the motor maximum speed is reduced and maintained after booting. Another cause might be the switching off of the input limits (P-90, bit 0). Alter parameter and switch on input limits again. Additional information: Number of incorrect machine data	
<i>Remedy</i>	<ul style="list-style-type: none"> • Correct parameter • Check all parameters with motor-dependent limits • Save BOOT drive • Repeat ramp-up 	
<i>Note</i>	Applies as from SW 3	
300742	Lower limit violated MD	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	During ramp-up control detects that machine data has violated input limits. This occurs with parameters with motor-dependent limits if the motor maximum speed is reduced and maintained after booting. Another cause might be the switching off of the input limits (P-90, bit 0). Alter parameter and switch on input limits again. Additional information: Number of incorrect machine data	
<i>Remedy</i>	<ul style="list-style-type: none"> • Correct parameter • Check all parameters with motor-dependent limits • Save BOOT drive • Repeat ramp-up 	
<i>Note</i>	Applies for SW 3 only	
300742	Converter frequency U/f	POWER ON
<i>Scan</i>	Power On	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	In V/f mode (selection via MD 1014), only converter frequencies (MD 1100) of 4 kHz and 8 kHz are permissible.	
<i>Remedy</i>	Eliminate error during input of converter frequency MD 1100 or by deselecting V/f mode MD 1014.	
<i>Note</i>	Applies as from SW 5.1	
300743	Error on saving FEPRM	POWER ON
<i>Scan</i>	POWER ON	
<i>Effect</i>	Drive only ramps up to ramp-up state 2	
<i>Explanation</i>	Error occurred when last saved; data from last save operation are used. Additional information: none	
<i>Remedy</i>	<ul style="list-style-type: none"> • Check parameters and save BOOT again 	
<i>Note</i>	Applies for SW 3 only	

1.5.1 Alarm description

300743	Function not with this 611D control module	POWER ON
<i>Scan</i>	When powering up the control.	
<i>Effect</i>	The power-up procedure is interrupted, the pulses remain disabled.	
<i>Explanation</i>	The 611D performance control module is required for SINUMERIK Safety Integrated (see SINUMERIK Safety Integrated documentation). This alarm is output if the hardware is not installed. This alarm also occurs if 1PH2/4/6 motors are connected and no 611D performance control module is installed.	
<i>Remedy</i>	Replace the 611D control module.	
<i>Note</i>	Applies as from SW 5.4.	
300744	Checksum error safe monitorings	POWER ON
<i>Scan</i>	When powering up the control.	
<i>Effect</i>	The power-up procedure is interrupted, the pulses remain disabled.	
<i>Explanation</i>	The actual checksum calculated by the drive and stored in MD 1398 via the safety-related MDs has a different value to the reference checksum stored in MD 1399 on the last machine acceptance. The safety-related data have been modified or an error has occurred.	
<i>Remedy</i>	Check all safety-related MDs and make any necessary corrections. Then execute a POWER ON. Carry out an acceptance test.	
<i>Note</i>	Applies as from SW 5.4.	
300745	Limit values for safe end position interchanged	POWER ON
<i>Scan</i>	When powering up the control.	
<i>Effect</i>	The power-up procedure is interrupted, the pulses remain disabled.	
<i>Explanation</i>	The data for the upper limit for SE monitoring contains a value less than that stored in the data for the lower limit.	
<i>Remedy</i>	Check machine data MD 1334 upper limit value for safe end position and MD 1335 lower limit value for safe end position, and change them such that the upper limit is greater than the lower limit. Then execute a POWER ON.	
<i>Note</i>	Applies as from SW 5.4.	
300746	No SBH/SG enable	POWER ON
<i>Scan</i>	When powering up the control.	
<i>Effect</i>	The power-up procedure is interrupted, the pulses remain disabled.	
<i>Explanation</i>	The SBH/SG function is not enabled in MD 1301, although the SE/SN function is selected in this MD.	
<i>Remedy</i>	Enable the SBH/SG function in MD 1301.	
<i>Note</i>	Applies as from SW 5.4.	
300747	Monitoring cycle MD 1300 invalid	POWER ON
<i>Scan</i>	When powering up the control.	
<i>Effect</i>	The power-up procedure is interrupted, the pulses remain disabled.	
<i>Explanation</i>	MD 1300 was not set to a multiple of the NC position control cycle.	
<i>Remedy</i>	Set the monitoring cycle in MD 1300 to $n \cdot \text{NC position control cycle}$, where n must be 1.	
<i>Note</i>	Applies as from SW 5.4.	

300748 Monitoring cycle of both axes not identical POWER ON

Scan When powering up the control.

Effect The power-up procedure is interrupted, the pulses remain disabled.

Explanation The monitoring cycle in MD 1300 was not set to an identical value for both axes of a two-axis module.

Remedy Set MD 1300 to the same value on all drives of the module.

Note Applies as from SW 5.4.

300749 Conversion factor between motor and load too POWER ON

Scan When powering up the control.

Effect The power-up procedure is interrupted, the pulses remain disabled.

Explanation The conversion factor from the motor system [increments] to the load system [$\mu\text{m}/\text{mdegrees}$] is greater than 1, or the factor that converts the load system to the motor system is greater than 65535.

Conditions The condition for the load to motor system factor is: $\mu\text{m_to_incr} \leq 65535$
 The condition for the motor to load system factor is: $\text{incr_to_}\mu\text{m} \leq 1$
 mit $\mu\text{m_to_incr} = \frac{1}{\text{incr_to_}\mu\text{m}}$

Equation for rotary axis With a rotary motor encoder and a rotary axis:

$$\text{incr_to_}\mu\text{m}(n) = \frac{\text{MD1321}}{\text{MD1322}} * \text{incr_to_}\mu\text{m_rot_rot}$$

where $n = 0 \dots 7$ (gear stage) and

$$\text{incr_to_}\mu\text{m_rot_rot} = \frac{360000}{8192} * \frac{1}{\text{MD1318}}$$

Equation for linear axis With a rotary motor encoder and a linear axis:

$$\text{incr_to_}\mu\text{m}(n) = \frac{\text{MD1321}}{\text{MD1322}} * \text{incr_to_}\mu\text{m_rot_lin}$$

where $n = 0 \dots 7$ (gear stage) and

$$\text{incr_to_}\mu\text{m_rot_lin} = \frac{1000}{8192} * \frac{1}{\text{MD1318}} * \text{MD1320}$$

Remedy Check the following safety-related MDs, depending on the motor encoder type and axis type, and correct if necessary.

- MD 1317
Grid spacing linear scale (for a linear encoder)
- MD 1318
Encoder marks per revolution (for a rotary encoder)
- MD 1318
MD 1320
(for a rotary encoder and linear axis)
- MD 1321
MD 1322
(for the use of a gearbox)

The motor type and axis type are defined in MD 1302.

Note Applies as from SW 5.4

1.5.1 Alarm description

300750	Speed controller adapt.: $n_{\text{max}} < n_{\text{min}}$	Reset key
300850		
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	<p>for MSD:</p> <ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error <p>for FDD:</p> <ul style="list-style-type: none"> • Controllers are disabled, motor is braked • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error <p>Response via MD 1613.0 can be configured as from drive SW 2. Alarm output can be activated via MD 1012.4 as from V. 5.2 (611D: SW 3).</p> <ul style="list-style-type: none"> • MD 1012.4 = 0: 300750 • MD 1012.4 = 1: 300850 	
<i>Explanation</i>	The upper adaptation speed MD 1412 is less than the lower adaptation speed MD 1411.	
<i>Remedy</i>	Enter a larger value for upper adaptation speed MD 1412 than for lower adaptation speed MD 1411.	
<i>Note</i>	Applies as from SW 3	
300751	Speed controller amplification too high	Reset key
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	<p>for MSD:</p> <ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error <p>for FDD:</p> <ul style="list-style-type: none"> • Controllers are disabled, motor is braked • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error <p>Response via MD 1613.0 can be configured as from drive SW 2.</p>	
<i>Explanation</i>	The P gain of the speed controller MD 1407 or MD 1408 is too large.	
<i>Remedy</i>	Enter lower value for P gain MD 1407 or MD 1408 for speed controller; or the motor zero-speed current MD 1118 must be greater than zero.	
<i>Note</i>	Applies as from SW 3	
300752	Blocking freq. I-set filter wrong	Reset key
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	<p>for MSD:</p> <ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error <p>for FDD:</p> <ul style="list-style-type: none"> • Controllers are disabled, motor is braked • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error <p>Response via MD 1613.0 can be configured as from drive SW 2.</p>	
<i>Explanation</i>	Sampling theorem violated.	
<i>Remedy</i>	The blocking frequency MD 1210, MD 1213, MD 1216, MD 1219 for each current filter must be greater than the reciprocal value of two current controller clock pulses MD 1000.	
<i>Note</i>	Applies as from SW 3	

300753 Timer n-controller at stop wrong**Reset key***Scan* Cyclic after control power up

Effect

- Controllers disabled, motor braked
- SIMODRIVE_READY and DRIVE_READY are cancelled.
- Reset error

Explanation –

Remedy Speed controller timer at stop MD 1605 must always be larger or the same as the pulse suppression cutoff speed MD 1403.

Note Applies as from SW 3

300754 Signal number invalid**Reset key****300854***Scan* Cyclic after control power up

Effect

for MSD:

- Pulse suppression, motor runs down
- SIMODRIVE_READY and DRIVE_READY are cancelled.
- Reset error

for FDD:

- Controllers are disabled, motor is braked
- SIMODRIVE_READY and DRIVE_READY are cancelled.
- Reset error

Response via MD 1613.0 can be configured as from drive SW 2.
Alarm output can be activated via MD 1012.4 as from V. 5.2 (611D: SW 3).

- MD 1012.4 = 0: 300754
- MD 1012.4 = 1: 300854

Explanation Signal number invalid in the variables signalling function and min-max memory.

Remedy Enter correct signal number.

Note Applies as from SW 4

300755 V/f operation: motor running**Reset key****300855***Scan* Cyclic after control power up

Effect

for MSD:

- Pulse suppression, motor runs down
- SIMODRIVE_READY and DRIVE_READY are cancelled.
- Reset error

for FDD:

- Controllers are disabled, motor is braked
- SIMODRIVE_READY and DRIVE_READY are cancelled.
- Reset error

Response via MD 1613.0 can be configured as from drive SW 2.
Alarm output can be activated via MD 1012.4 as from V. 5.2 (611D: SW 3).

- MD 1012.4 = 0: 300755
- MD 1012.4 = 1: 300855

Explanation V/f operation: at initialization, the motor turns.

Remedy Stop the motor.

Note Applies as from SW 4

1.5.1 Alarm description

300756	Hysteresis of torque setpoint smoothing too large	Reset key
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	for MSD: <ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error for FDD: <ul style="list-style-type: none"> • Controllers are disabled, motor is braked • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error Response via MD 1613.0 can be configured as from drive SW 2.	
<i>Explanation</i>	Hysteresis of the torque setpoint smoothing MD 1246 is greater than or equal to the threshold of the torque setpoint smoothing MD 1245.	
<i>Remedy</i>	Eliminate error on inputting MD 1246 and MD 1245.	
<i>Note</i>	Applies as from SW 4	
300757	Torque matching factor too great	Reset key
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	for MSD: <ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error for FDD: <ul style="list-style-type: none"> • Controllers are disabled, motor is braked • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error Response via MD 1613.0 can be configured as from drive SW 2.	
<i>Explanation</i>	The torque matching factor MD 1191 is beyond the format limit.	
<i>Remedy</i>	Eliminate error on inputting MD 1191.	
<i>Note</i>	Applies as from SW 4	
300758 300858	Upper generator threshold too high	Reset key
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	for MSD: <ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error for FDD: <ul style="list-style-type: none"> • Controllers are disabled, motor is braked • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error Response via MD 1613.0 can be configured as from drive SW 2. Alarm output can be activated via MD 1012.4 as from V. 5.2 (611D: SW 3). <ul style="list-style-type: none"> • MD 1012.4 = 0: 300758 • MD 1012.4 = 1: 300858 	
<i>Explanation</i>	Upper threshold of the two-point controller is too high in the generator mode i.e. the sum of the values in MD1631 + MD1632 exceeds that in MD1633.	
<i>Remedy</i>	Eliminate error on inputting MD 1631, MD 1632 and MD 1633.	
<i>Note</i>	Applies as from SW 4	

300759 300859	Generator cut-off threshold too high	Reset key
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	<p>for MSD:</p> <ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error <p>for FDD:</p> <ul style="list-style-type: none"> • Controllers are disabled, motor is braked • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error <p>Response via MD 1613.0 can be configured as from drive SW 2. Alarm output can be activated via MD 1012.4 as from V. 5.2 (611D: SW 3).</p> <ul style="list-style-type: none"> • MD 1012.4 = 0: 300759 • MD 1012.4 = 1: 300859 	
<i>Explanation</i>	Generator cut-off voltage MD 1633 is greater than or equal to the response threshold for the d.c. link monitoring MD 1630.	
<i>Remedy</i>	Eliminate error on inputting MD 1633 or MD 1630.	
<i>Note</i>	Applies as from SW 4	
300760 300860	Excessive emergency retraction speed	Reset key
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	<p>for MSD:</p> <ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error <p>for FDD:</p> <ul style="list-style-type: none"> • Controllers are disabled, motor is braked • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error <p>Response via MD 1613.0 can be configured as from drive SW 2. Alarm output can be activated via MD 1012.4 as from V. 5.2 (611D: SW 3).</p> <ul style="list-style-type: none"> • MD 1012.4 = 0: 300760 • MD 1012.4 = 1: 300860 	
<i>Explanation</i>	Emergency retraction speed MD 1639 is greater than or equal to the maximum speed MD 1146.	
<i>Remedy</i>	Eliminate error on inputting MD 1639 or MD 1146.	
<i>Note</i>	Applies as from SW 4	
300761 300861	Min. generator speed too high	Reset key
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	<p>for MSD:</p> <ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error <p>for FDD:</p> <ul style="list-style-type: none"> • Controllers are disabled, motor is braked • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error <p>Response via MD 1613.0 can be configured as from drive SW 2. Alarm output can be activated via MD 1012.4 as from V. 5.2 (611D: SW 3).</p> <ul style="list-style-type: none"> • MD 1012.4 = 0: 300761 • MD 1012.4 = 1: 300861 	
<i>Explanation</i>	Minimum speed generator axis MD 1635 is greater than or equal to the maximum speed MD 1146.	
<i>Remedy</i>	Eliminate error on inputting MD 1635 or MD 1146.	
<i>Note</i>	Applies as from SW 4	

1.5.1 Alarm description

300762 300862	Emergency retract/generator active	Reset key
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	<p>for MSD:</p> <ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error <p>for FDD:</p> <ul style="list-style-type: none"> • Controllers are disabled, motor is braked • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error <p>Response via MD 1613.0 can be configured as from drive SW 2. Alarm output can be activated via MD 1012.4 as from V. 5.2 (611D: SW 3).</p> <ul style="list-style-type: none"> • MD 1012.4 = 0: 300762 • MD 1012.4 = 1: 300862 	
<i>Explanation</i>	Emergency retraction or generator is already active.	
<i>Remedy</i>	Check parameterization/machine data.	
<i>Note</i>	Applies as from SW 4	
300763 300863	Generator/emergency retraction mode invalid	Reset key
<i>Scan</i>	Cyclic	
<i>Effect</i>	<p>for MSD:</p> <ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error <p>for FDD:</p> <ul style="list-style-type: none"> • Controllers are disabled, motor is braked • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error <p>Response via MD 1613.0 can be configured as from drive SW 2. Alarm output can be activated via MD 1012.4 as from V. 5.2 (611D: SW 3).</p> <ul style="list-style-type: none"> • MD 1012.4 = 0: 300763 • MD 1012.4 = 1: 300863 	
<i>Explanation</i>	Value given by the NC via a G command must be in the range 0 ... 7.	
<i>Remedy</i>	Check parameterization (G command in the NC).	
<i>Note</i>	Applies as from SW 4	
300764 300864	No emergency retraction/generator mode possible	Reset key
<i>Scan</i>	Cyclic	
<i>Effect</i>	<p>for MSD:</p> <ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error <p>for FDD:</p> <ul style="list-style-type: none"> • Controllers are disabled, motor is braked • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error <p>Response via MD 1613.0 can be configured as from drive SW 2. Alarm output can be activated via MD 1012.4 as from V. 5.2 (611D: SW 3).</p> <ul style="list-style-type: none"> • MD 1012.4 = 0: 300764 • MD 1012.4 = 1: 300864 	
<i>Explanation</i>	Emergency retraction/generator mode is possible only with active d.c. link measurement (MD 1161 = 0) in an old hardware version, no d.c. link measurement is possible and therefore the error message 300765 might also be issued if in an old hardware version MD 1161 is set to zero.	
<i>Remedy</i>	Enter the value zero into machine data MD 1161 or order new hardware version (hardware components: drive control with Order No. 6SN1 118-0Dx1x-0AA0).	
<i>Note</i>	Applies as from SW 4	

300765	No link measurement possible	Reset key
300865		
<i>Scan</i>	Cyclic	
<i>Effect</i>	<p>for MSD:</p> <ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error <p>for FDD:</p> <ul style="list-style-type: none"> • Controllers are disabled, motor is braked • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error <p>Response via MD 1613.0 can be configured as from drive SW 2.</p> <p>Alarm output can be activated via MD 1012.4 as from V. 5.2 (611D: SW 3).</p> <ul style="list-style-type: none"> • MD 1012.4 = 0: 300765 • MD 1012.4 = 1: 300865 	
<i>Explanation</i>	If the fixed voltage MD 1161 is equal to zero, no d.c. link measurement is possible because of the incorrect hardware version.	
<i>Remedy</i>	In the machine data fixed voltage MD 1161, enter a value greater than zero or order new hardware version (hardware components: drive control with the Order No. 6SN1 118-0Dx1x-0AA0).	
<i>Note</i>	Applies as from SW 4	
300766	Blocking frequency greater than Shannon frequency	Reset key
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	<p>With MSD:</p> <ul style="list-style-type: none"> • Pulse reset, motor coasts down • SIMODRIVE_READY and DRIVE_READY are reset. • Reset error <p>With FDD:</p> <ul style="list-style-type: none"> • Controllers disabled, motor braked • SIMODRIVE_READY and DRIVE_READY are reset. • Reset error <p>Response via MD 1613.0 can be configured as from drive SW 2.</p>	
<i>Explanation</i>	The band-stop frequency of a speed setpoint filter is greater than the Shannon sampling frequency from the sampling theorem.	
<i>Remedy</i>	<p>The band-stop frequency of a speed setpoint filter must be smaller than the reciprocal value of two speed controller pulserates.</p> <p>Speed setpoint filter 1: $MD\ 1210 < 1 / (2 \cdot MD\ 1000 \cdot 31.25\ \mu\text{sec})$</p> <p>Speed setpoint filter 2: $MD\ 1213 < 1 / (2 \cdot MD\ 1000 \cdot 31.25\ \mu\text{sec})$</p> <p>Speed setpoint filter 3: $MD\ 1216 < 1 / (2 \cdot MD\ 1000 \cdot 31.25\ \mu\text{sec})$</p> <p>Speed setpoint filter 4: $MD\ 1219 < 1 / (2 \cdot MD\ 1000 \cdot 31.25\ \mu\text{sec})$</p> <p>The band-stop frequency of a current setpoint filter must be smaller than the reciprocal value of two current controller pulserates.</p> <p>Current setpoint filter 1: $MD\ 1214 < 1 / (2 \cdot MD\ 1000 \cdot 31.25\ \mu\text{sec})$</p> <p>Current setpoint filter 2: $MD\ 1217 < 1 / (2 \cdot MD\ 1000 \cdot 31.25\ \mu\text{sec})$</p>	
<i>Note</i>	Alarm in SW 5 and higher	

1.5.1 Alarm description

300767	Natural frequency greater than Shannon frequency	Reset key
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	<p>With MSD:</p> <ul style="list-style-type: none"> • Pulse reset, motor coasts down • SIMODRIVE_READY and DRIVE_READY are reset. • Reset error <p>With FDD:</p> <ul style="list-style-type: none"> • Controllers disabled, motor braked • SIMODRIVE_READY and DRIVE_READY are reset. • Reset error <p>Response via MD 1613.0 can be configured as from drive SW 2.</p>	
<i>Explanation</i>	The natural frequency of a speed setpoint filter is greater than the Shannon sampling frequency from the sampling theorem.	
<i>Remedy</i>	<p>The natural frequency of a speed setpoint filter must be lower than the reciprocal value of two speed controller pulserates.</p> <p>Speed setpoint filter 1: $MD\ 1520 \bullet 0.01 \bullet MD\ 1514 < 1 / (2 \bullet MD\ 1001 \bullet 31.25\ \mu\text{sec})$</p> <p>Speed setpoint filter 2: $MD\ 1521 \bullet 0.01 \bullet MD\ 1517 < 1 / (2 \bullet MD\ 1001 \bullet 31.25\ \mu\text{sec})$</p>	
<i>Note</i>	Alarm in SW 5 and higher	
300768	Counter bandwidth greater than double blocking frequency	Reset key
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	<p>With MSD:</p> <ul style="list-style-type: none"> • Pulse reset, motor coasts down • SIMODRIVE_READY and DRIVE_READY are reset. • Reset error <p>With FDD:</p> <ul style="list-style-type: none"> • Controllers disabled, motor braked • SIMODRIVE_READY and DRIVE_READY are reset. • Reset error <p>Response via MD 1613.0 can be configured as from drive SW 2.</p>	
<i>Explanation</i>	<p>The counter bandwidth of a current or speed setpoint filter is greater than twice the blocking frequency.</p> <p>This error message is generated for the general band blocking only if:</p> <p>Speed setpoint filter 1: $MD\ 1516 > 0.0$ or $MD\ 1520 \neq 100.0$</p> <p>Speed setpoint filter 2: $MD\ 1519 > 0.0$ or $MD\ 1521 \neq 100.0$</p> <p>Current setpoint filter 1: $MD\ 1212 > 0.0$</p> <p>Current setpoint filter 2: $MD\ 1215 > 0.0$</p> <p>Current setpoint filter 3: $MD\ 1218 > 0.0$</p> <p>Current setpoint filter 4: $MD\ 1221 > 0.0$</p>	
<i>Remedy</i>	<p>The counter bandwidth must be smaller than double the blocking frequency.</p> <p>Current setpoint filter 1: $MD\ 1212 \leq 2 \bullet MD\ 1210$</p> <p>Current setpoint filter 2: $MD\ 1215 \leq 2 \bullet MD\ 1213$</p> <p>Current setpoint filter 3: $MD\ 1218 \leq 2 \bullet MD\ 1216$</p> <p>Current setpoint filter 4: $MD\ 1221 \leq 2 \bullet MD\ 1219$</p> <p>Speed setpoint filter 1: $MD\ 1516 \leq 2 \bullet MD\ 1514$</p> <p>Speed setpoint filter 2: $MD\ 1519 \leq 2 \bullet MD\ 1517$</p>	
<i>Note</i>	Alarm in SW 5 and higher	

300769	Denominator bandwidth greater than double natural frequency	Reset key
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	<p>With MSD:</p> <ul style="list-style-type: none"> • Pulse reset, motor coasts down • SIMODRIVE_READY and DRIVE_READY are reset. • Reset error <p>With FDD:</p> <ul style="list-style-type: none"> • Controllers disabled, motor braked • SIMODRIVE_READY and DRIVE_READY are reset. • Reset error <p>Response via MD 1613.0 can be configured as from drive SW 2.</p>	
<i>Explanation</i>	<p>The denominator bandwidth of a current or speed setpoint filter is greater than twice the natural frequency.</p> <p>This error message is generated for the general band blocking only if:</p> <p>Speed setpoint filter 1: MD 1516 > 0.0 or MD 1520 \neq 100.0</p> <p>Speed setpoint filter 2: MD 1519 > 0.0 or MD 1521 \neq 100.0</p> <p>Current setpoint filter 1: MD 1212 > 0.0</p> <p>Current setpoint filter 2: MD 1215 > 0.0</p> <p>Current setpoint filter 3: MD 1218 > 0.0</p> <p>Current setpoint filter 4: MD 1221 > 0.0</p>	
<i>Remedy</i>	<p>The denominator bandwidth of a current or speed setpoint filter must be greater than double the natural frequency.</p> <p>Speed setpoint filter 1: $MD\ 1515 \leq 2 \cdot MD\ 1514 \cdot 0.01 \cdot MD\ 1520$</p> <p>Speed setpoint filter 2: $MD\ 1518 \leq 2 \cdot MD\ 1517 \cdot 0.01 \cdot MD\ 1521$</p> <p>Current setpoint filter 1: $MD\ 1211 \leq 2 \cdot MD\ 1210$</p> <p>Current setpoint filter 2: $MD\ 1214 \leq 2 \cdot MD\ 1213$</p> <p>Current setpoint filter 3: $MD\ 1217 \leq 2 \cdot MD\ 1216$</p> <p>Current setpoint filter 4: $MD\ 1220 \leq 2 \cdot MD\ 1219$</p>	
<i>Note</i>	Alarm in SW 5 and higher	

300770	Filter factor cannot be represented	Reset key
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	<p>With MSD:</p> <ul style="list-style-type: none"> • Pulse reset, motor coasts down • SIMODRIVE_READY and DRIVE_READY are reset. • Reset error <p>With FDD:</p> <ul style="list-style-type: none"> • Controllers disabled, motor braked • SIMODRIVE_READY and DRIVE_READY are reset. • Reset error <p>Response via MD 1613.0 can be configured as from drive SW 2.</p>	
<i>Explanation</i>	The calculated filter coefficients for a band-stop filter cannot be represented in the internal format.	
<i>Remedy</i>	Alter filter setting	
<i>Note</i>	Alarm in SW 5 and higher	

1.5.1 Alarm description

300775	Fixed voltage axially unequal	Reset key
300875		
<i>Scan</i>	Cyclic	
<i>Effect</i>	<ul style="list-style-type: none"> • Error 300775: <ul style="list-style-type: none"> – for MSD: Pulse deletion, motor idles to a stop SIMODRIVE_READY and DRIVE_READY are canceled. – for FDD: Controllers are disabled, motor brakes SIMODRIVE_READY and DRIVE_READY are canceled. Response configurable via MD 1613.0 as from drive SW 2. • Error 300875: No impact on current operation. The old state is retained as long as the fixed axial voltages on the module axes are different. <p>Alarm output can be activated via MD 1012.4 as from SW 5.2 (611D: SW 3).</p> <ul style="list-style-type: none"> • MD 1012.4 = 0: 300775 • MD 1012.4 = 1: 300875 	
<i>Explanation</i>	<p>The fixed voltage for the intermediate circuit entered in each MD 1161 is different for the axes of a two-axis module. When a fixed voltage not equal to 0 is entered in MD 1161, it replaces the measured voltage of the intermediate circuit. The fixed voltages in MD 1161 for the axes on a module must be equal before they can be used.</p> <p>MD 1161 for both axes = 0</p> <ul style="list-style-type: none"> • Measured voltage of the intermediate circuit is used in internal calculations. <p>MD 1161 for both axes = 580 V</p> <ul style="list-style-type: none"> • The entered fixed voltage is used in internal calculations. 	
<i>Remedy</i>	Set the same fixed voltage or enter "0" on all module axes in order to use the measured intermediate circuit voltage for internal calculations.	
<i>Note</i>	Applies as from SW 5	
300776	Meas. circ. monitor. motor (inc.) inact.	Reset key
<i>Scan</i>	Power-up and cyclic	
<i>Effect</i>	<p>for MSD:</p> <ul style="list-style-type: none"> • Pulse deletion, motor idles to a stop • SIMODRIVE_READY and DRIVE_READY are canceled. • Reset error <p>for FDD:</p> <ul style="list-style-type: none"> • Controllers are disabled, motor brakes • SIMODRIVE_READY And DRIVE_READY are canceled • Reset error <p>Response configurable via MD 1613.0 as from drive SW 2.</p>	
<i>Explanation</i>	When SINUMERIK Safety Integrated function MD 1301 is active, the measuring circuit monitoring motor (inc.) MD 1600.4 must be active.	
<i>Remedy</i>	Activate the measuring circuit monitoring motor (inc.) by setting MD 1600.4 = 0.	
<i>Note</i>	Applies as from SW 5.4	
300777	Current for rotor position identification	Reset key
<i>Scan</i>	Power-up and cyclic	
<i>Effect</i>	<p>FDD only:</p> <ul style="list-style-type: none"> • Controllers are disabled, motor brakes • SIMODRIVE_READY and DRIVE_READY are canceled. <p>Response configurable via MD 1613.0 as from drive SW 4.</p>	
<i>Explanation</i>	A current higher than that permissible for the motor and for the power section used has been parameterized in MD 1019.	
<i>Remedy</i>	Reduce current via MD 1019.	
<i>Note</i>	Applies as from SW 6	

300778	Illegal converter frequency rotor position identification	Reset key
<i>Scan</i>	Power-up and cyclic	
<i>Effect</i>	FDD only: <ul style="list-style-type: none"> – Controllers are disabled, motor brakes – SIMODRIVE_READY and DRIVE_READY are canceled. 	
<i>Explanation</i>	When selecting the rotor position identification (MD 1018), only converter frequencies (MD 1100) of 4 kHz or 8 kHz are permissible.	
<i>Remedy</i>	Change converter frequency or deselect rotor position identification.	
<i>Note</i>	Applies as from SW 6	
300779	Motor moment of inertia ≤ 0	Reset key
<i>Scan</i>	Power-up and cyclic	
<i>Effect</i>	for MSD: <ul style="list-style-type: none"> – Pulse suppression, motor coasts down – SIMODRIVE_READY and DRIVE_READY are canceled for FDD: <ul style="list-style-type: none"> – Controllers are disabled, motor brakes – SIMODRIVE_READY and DRIVE_READY are canceled. 	
<i>Explanation</i>	Motor moment of inertia MD 1117 has a value that is smaller or equal to zero.	
<i>Remedy</i>	Enter a correct value in machine data MD 1117 "Motor moment of inertia".	
<i>Note</i>	Applies as from SW 6	
300780	IO motor > I-rated motor	Reset key
<i>Scan</i>	Power-up and cyclic	
<i>Effect</i>	MSD only: <ul style="list-style-type: none"> – Pulse suppression, motor coasts down – SIMODRIVE_READY and DRIVE_READY are canceled. 	
<i>Explanation</i>	The no-load current of the motor (MD 1136) is greater than the rated current (MD 1103) of the motor.	
<i>Remedy</i>	<ul style="list-style-type: none"> – Change motor data – Save Boot drive – Power up again 	
<i>Note</i>	Applies as from SW 6	
300781	IO motor > I-rated power section	Reset key
<i>Scan</i>	Power-up and cyclic	
<i>Effect</i>	MSD only: <ul style="list-style-type: none"> – Pulse suppression, motor coasts down – SIMODRIVE_READY and DRIVE_READY are canceled. 	
<i>Explanation</i>	Because of its no-load current (MD 1136), the motor connected is too large for the power section used (continuous current MD 1108).	
<i>Remedy</i>	Replace power section or motor	
<i>Note</i>	Applies as from SW 6	
300782	Reactance ≤ 0	Reset key
<i>Scan</i>	Power-up and cyclic	
<i>Effect</i>	FDD only: <ul style="list-style-type: none"> – Controllers are disabled, motor brakes – SIMODRIVE_READY and DRIVE_READY are canceled. Response configurable via MD 1613.0 as from drive SW 4.	
<i>Explanation</i>	The stator reactance MD 1139 or rotor reactance MD 1140 or main field reactance MD 1141 is smaller than or equal to zero.	
<i>Remedy</i>	Correct error when entering MD 1139, MD 1140 or MD 1141.	
<i>Note</i>	Applies as from SW 6	

1.5.1 Alarm description

300783 Rotor resistance invalid**Reset key***Scan* Power-up and cyclic

Effect MSD only:

- Pulse suppression, motor coasts down
- SIMODRIVE_READY and DRIVE_READY are canceled.

Explanation The rotor resistance is less than or equal to zero or a format overflow has occurred.

Remedy The following machine data may have an incorrect value:

- Speed controller cycle MD 1001
- Motor rated frequency MD 1134
- Rotor resistance cold MD 1138
- Stator leakage reactance MD 1139
- Rotor leakage reactance MD 1140.

Note Applies as from SW 6

300784 Motor no-load voltage invalid**Reset key***Scan* Power-up and cyclic

Effect MSD only:

- Pulse suppression, motor coasts down
- SIMODRIVE_READY and DRIVE_READY are canceled.

Explanation Error in no-load voltage (MD 1135):

- $MD\ 1135 \leq 0$ or
- $MD\ 1135 > MD\ 1132$ or
- $MD\ 1135 \times MD\ 1142 / MD\ 1400 + V_{pre} > 450\ V$

With
 $V_{pre} = 0.181 \times MD\ 1136 \times MD\ 1142 \times MD\ 1119$

MD 1132: Rated motor voltage

MD 1400: Rated motor speed

MD 1142: Threshold speed field weakening

MD 1136: No-load motor current

MD 1119: Inductance series reactor

Remedy Correct error when entering

- Rated motor voltage MD 1132 or:
- No-load motor voltage MD 1135 or
- Rated motor speed MD 1400 or
- Rotor resistance cold MD 1138
- Threshold speed field weakening MD 1142 or
- No-load motor current MD 1136.

Note Applies as from SW 6

300785 Motor no-load current ≤ 0 **Reset key***Scan* Power-up and cyclic

Effect MSD only:

- Pulse suppression, motor coasts down
- SIMODRIVE_READY and DRIVE_READY are canceled.

Explanation Motor no-load current MD 1136 is smaller than or equal to zero.

Remedy Correct the error when entering the motor no-load current MD 1136.

Note Applies as from SW 6

300786 Field weakening speed ≤ 0 **Reset key***Scan* Power-up and cyclic

Effect MSD only:

- Pulse suppression, motor coasts down
- SIMODRIVE_READY and DRIVE_READY are canceled.

Explanation Field weakening speed MD 1142 is smaller than or equal to zero.

Remedy Correct the error when entering the field weakening speed MD 1142.

Note Applies as from SW 6

300799	Save and boot required	Power On
<i>Scan</i>	Cyclic after control power up	
<i>Effect</i>	for MSD: <ul style="list-style-type: none"> • Pulse suppression, motor runs down • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error for FDD: <ul style="list-style-type: none"> • Controllers are disabled, motor is braked • SIMODRIVE_READY and DRIVE_READY are cancelled. • Reset error Response via MD 1613.0 can be configured as from drive SW 2.	
<i>Explanation</i>	After automatic calculation of the controller parameters, it is necessary to save the machine data and to perform a power up.	
<i>Remedy</i>	Perform above measures.	
<i>Note</i>	Applies as from SW 4	
300850	Speed controller adaptation: n-max < n-min	
<i>Note</i>	Alarm description see 300750	
300854	Signal number invalid	
<i>Note</i>	Alarm description see 300754	
300855	u/f operation: motor running	
<i>Note</i>	Alarm description see 300755	
300858	Upper generator threshold too high	
<i>Note</i>	Alarm description see 300758	
300859	Generator cut-off threshold too high	
<i>Note</i>	Alarm description see 300759	
300860	Excessive emergency retraction speed	
<i>Note</i>	Alarm description see 300760	
300861	Minimum generator speed too high	
<i>Note</i>	Alarm description see 300761	
300862	Emergency retraction/generator active	
<i>Note</i>	Alarm description see 300762	
300863	Generator/emergency retraction mode invalid	
<i>Note</i>	Alarm description see 300763	
300864	No emergency retraction/generator mode possible	
<i>Note</i>	Alarm description see 300764	

1.5.1 Alarm description

300865 No link measurement possible

Note Alarm description see 300765

300875 Fixed voltage axially unequal

Note Alarm description see 300775

300899 Save and boot necessary

Note Alarm description see 300799

300900 Stop A triggered**POWER ON**

Scan In monitoring cycle.

Effect The drive is stopped with STOP A.
 – Pulses are disabled via relay "Drive_IMP".
 – Motor runs down
 – Power on error

Explanation There can be several reasons for triggering STOP A:

- The time frame in MD 1356 of STOP B has expired.
- The speed has fallen below the threshold in MD 1360 of STOP B.
- The shut-down path test has been requested by the user by SGE "test stop selection", but the pulses were not deleted after expiry of the time frame in MD 1357.

Remedy The user must find the cause and initiate appropriate measures.

Note Applies as from SW 5.4

300901 Stop B triggered**POWER ON**

Scan Cyclic in SI monitoring cycle.

Effect The drive is stopped with STOP B. The pulses are then disabled via relay "Drive_IMP".

Explanation There can be several reasons for triggering STOP B:

- The safe standstill monitoring has responded.
- STOP B was requested after STOP F, i.e. an error has occurred during cross-comparison.

Remedy The user must find the cause and initiate appropriate measures.

Note Applies as from SW 5.4

300906 Safe braking ramp exceeded**POWER ON**

Scan Cyclic in SI monitoring cycle.

Effect The drive is stopped with STOP A. The pulses are then disabled via relay "Drive_IMP".

Explanation Die Istgeschwindigkeit der Achse ist beim Bremsen mit "nsoll=0" (Stop B oder Stop C) nicht verringert worden, sondern ist über die beim Bremsen nachgeführte Geschwindigkeitsgrenze und die in MMD_MD_SB_STOP_N_TOL (Toleranz Istgeschwindigkeit für SBR) eingetragene Toleranz angestiegen.

Remedy Eingabewert des Maschinendatums MD_SB_STOP_N_TOL überprüfen.

Note Applies as from SW 6

300907 Tolerance for safe operational stop exceeded**POWER ON**

Scan Cyclic in SI monitoring cycle.

Effect The drive is stopped with STOP A or STOP B. The pulses are disabled via relay "Drive_IMP".

Explanation The actual position has migrated too far from the set/standstill position (outside the standstill window). The standstill window is configured in MD 1330.

Remedy The user must find the cause and initiate appropriate measures.

Note Applies as from SW 5.4

300908	Stop C triggered	Reset key
<i>Scan</i>	Cyclic in SI monitoring cycle.	
<i>Effect</i>	The drive is stopped with STOP C. After completion of the stop reaction, the drive remains under control, and the axis is monitored for SBH.	
<i>Explanation</i>	There can be several reasons for triggering STOP C (depending on the configuration): <ul style="list-style-type: none"> • The safe speed monitoring has responded (MD 1361). • The safe end position monitoring has responded (MD 1362). 	
<i>Remedy</i>	The user must find the cause and initiate appropriate measures.	
<i>Note</i>	Applies as from SW 5.4	
300909	Stop D triggered	Reset key
<i>Scan</i>	Cyclic in SI monitoring cycle.	
<i>Effect</i>	The NC has stopped the drive with STOP D. After completion of the stop reaction, the drive remains under control, and the axis is monitored for SBH.	
<i>Explanation</i>	There can be several reasons for triggering STOP D (depending on the configuration): <ul style="list-style-type: none"> • The safe speed monitoring has responded (MD 1361). • The safe end position monitoring has responded (MD 1362). 	
<i>Remedy</i>	The user must find the cause and initiate appropriate measures.	
<i>Note</i>	Applies as from SW 5.4	
300910	Stop E triggered	Reset key
<i>Scan</i>	Cyclic in SI monitoring cycle.	
<i>Effect</i>	The NC has stopped the drive with STOP E. After completion of the stop reaction, the drive remains under control, and the axis is monitored for SBH.	
<i>Explanation</i>	There can be several reasons for triggering STOP E (depending on the configuration): <ul style="list-style-type: none"> • The safe speed monitoring has responded (MD 1361). • The safe end position monitoring has responded (MD 1362). 	
<i>Remedy</i>	The user must find the cause and initiate appropriate measures.	
<i>Note</i>	Applies as from SW 5.4	
300911	Failure in a monitoring channel	Reset key
<i>Scan</i>	Cyclic in SI monitoring cycle.	
<i>Effect</i>	If no Safety Integrated monitoring system is active, STOP F does not initiate a stop response, but displays the message "Failure in a monitoring channel". If SBH/SG, SE or SN are active, the drive is stopped with the stop response STOP A/B.	
<i>Explanation</i>	Cross-comparison between NC and drive has revealed a difference, and STOP F has been initiated.	
<i>Remedy</i>	Find the difference between the monitoring channels. The error code which indicates the cause appears as follows: <ul style="list-style-type: none"> • on 840C MD 301: Diagnostics for STOP F • on 611D MD 1395 The meaning of the error code can be found in the SINUMERIK Safety Integrated documentation. It is possible that the safety-related machine data are no longer identical or that the SGEs do not have the same signal level (measure again or check in the SI service display). If no such error is found, an error may have occurred in the CPU, such as a corrupt memory cell. This error can be transient (remedied by POWER ON) or permanent (reoccurs after POWER ON, in this case replace the hardware).	
<i>Note</i>	Applies as from SW 5.4	

1.5.1 Alarm description


300914	Safe speed exceeded	Reset key
<i>Scan</i>	Cyclic in SI monitoring cycle.	
<i>Effect</i>	The drive is stopped by the response configured in MD 1361. After completion of the stop reaction, the drive remains under control, and the axis is monitored for SBH.	
<i>Explanation</i>	The axis has moved faster than defined in MD 1331, i.e. the axis has exceeded the permissible speed limit.	
<i>Remedy</i>	The user must find the cause and initiate appropriate measures.	
<i>Note</i>	Applies as from SW 5.4	
300915	Safe end position exceeded	Reset key
<i>Scan</i>	In monitoring cycle.	
<i>Effect</i>	The drive is stopped by the response configured in MD 1361. After completion of the stop reaction, the drive remains under control, and the axis is monitored for SBH.	
<i>Explanation</i>	The axis has traveled beyond the end position entered in data MD 1334 and MD 1335.	
<i>Remedy</i>	If no apparent operating error has occurred: Check the input value of the machine data, check the SGEs: of the 2 end positions, was the correct one selected? If MDs and SGEs are correct, inspect the machine for damage and repair the damage.	
<i>Note</i>	Applies as from SW 5.4	
300950	Axis is not safely referenced	
<i>Scan</i>	In monitoring cycle.	
<i>Effect</i>	No stop response was initiated. The alarm remains active, when the SN/SE functions are enabled, until the axis state "axis safely referenced" is attained.	
<i>Explanation</i>	The standstill position stored before the machine was switched off does not match the actual position (reference position) detected on power-up. This alarm requests the user to confirm the present actual position. The position should be established as follows <ul style="list-style-type: none"> • Measure the position • Travel to a known position 	
<i>Remedy</i>	If safe automatic referencing is not possible, the user must issue a user authorization for the new position with the softkey. This user authorization identifies the above position as safe, i.e. the axis state "axis safely referenced" is attained.	
<i>Warning</i>	If the axis has not been referenced safely, and the user authorization is not active: <ul style="list-style-type: none"> • The safe cams are active but not yet safe • The safe end positions are not yet active 	
<i>Note</i>	Applies as from SW 5.4	
300951	Teststop running	
<i>Scan</i>	In monitoring cycle.	
<i>Effect</i>	The pulses are deleted. <ul style="list-style-type: none"> • If, following the time configured in MD 1357 (time for checking pulse deletion), the positive acknowledgement of pulse deletion has not been detected, STOP A is triggered. • If the pulse deletion is acknowledged internally in the drive within the configured time, a stop response is not initiated. The alarm remains active, on selection via SGE "test stop selection", until the selection is canceled. 	
<i>Explanation</i>	The test stop has been activated by the user by setting SGE "test stop selection". When the user cancels the "test stop selection" SGE, the alarm is deactivated.	
<i>Remedy</i>	If STOP A was triggered, it is only possible to restart by POWER ON.	
<i>Note</i>	Applies as from SW 5.4	

301701	Limit value SG too large	POWER ON
<i>Scan</i>	Power On	
<i>Effect</i>	The startup process is interrupted. The pulses remain disabled.	
<i>Explanation</i>	<p>The limit value of the safe speed is higher than the speed that corresponds to a limit frequency of 300 kHz. The maximum permissible speed to be monitored is calculated as follows:</p> $n_{\max} \left[\frac{\text{rev}}{\text{min}} \right] = \frac{300000[\text{Hz}] * 60}{\text{no. of encoder marks}}$ <p>Monitoring condition: $MD1331 \leq \frac{1}{\ddot{u}} * n_{\max}$ with \ddot{u} = speed ratio</p>	
<i>Remedy</i>	Check the input in MD 1331, correct if necessary and execute a POWER ON.	
<i>Note</i>	Applies as from SW 6	
301706	Parameterization of cam position invalid	POWER ON
<i>Scan</i>	Power On	
<i>Effect</i>	The startup process is interrupted. The pulses remain disabled.	
<i>Explanation</i>	<p>At least one of the cam positions parameterized and enabled via MD_SB_ENABLE contravenes the rule that cam positions must not lie within the tolerance range around the modulo position.</p> <p>The tolerance range is defined as follows:</p> <p>a) With inactive cam synchronization (MD 1301 bit 7=0):</p> <p>Upper modulo value – MD 1342 < cam position</p> <p>Lower modulo value+MD 1342 ≤ cam position</p> <p>b) With active cam synchronization (MD 1301 bit 7=1):</p> <p>Upper modulo value – MD 1340 – MD 1342 > cam position</p> <p>Lower modulo value+MD 1342 ≤ cam position</p> <p>Upper/lower modulo value= ± 737 280 000</p>	
<i>Remedy</i>	<p>Check the parameterization of the cam positions MD 1336[0–3] and MD 1337[0–3] and the entry in MD 1305, correct if necessary and execute a POWER ON.</p> <p>Check the input in MD 1305, correct if necessary and execute a POWER ON.</p>	
<i>Note</i>	Applies as from SW 6	
301707	Parameterization module value for invalid	POWER ON
<i>Scan</i>	Power On	
<i>Effect</i>	The startup process is interrupted. The pulses remain disabled.	
<i>Explanation</i>	The parameterized modulo value for the function "Cams for endlessly rotating rotary axes" in MD 1305 is not a multiple of 360 000 mdegrees.	
<i>Remedy</i>	Check the modulo value for SN in MD 1305, correct if necessary and execute a POWER ON.	
<i>Note</i>	Applies as from SW 6	

1.6 Dialog text

1.6.1 Notes for the operator

With many operator inputs, texts are displayed in the left two thirds of the input line for support and for error diagnostics.



1.6.2 Listing of dialog texts

All notes for the operator are listed in the following table in alphabetical order.

Dialog text	Appears with the following event	What must be done or What is wrong
BLOCK NOT AVAILABLE	When searching for blocks in the part program	—
BLOCK NUMBER TOO LARGE	Generating block number	Block number cannot be greater than N9999
BLOCK STRUCTURE WRONG	With "Correction block" function	Cursor is at the start of the wrong block
BLOCK TOO LONG	When editing part programs, a block must not be longer than 120 characters	Conclude block with "LF"
CHARACTER NOT ALLOWED	Taking over an input value (e.g. with the input key)	Input value has the wrong format
CHARACTER NOT AVAILABLE	When searching for characters in part programs	—
COMMENTS ERROR	Occurs when editing if the brackets do not match up	Check the number of brackets set
CYCLE DISABLE	When handling cycles (editing, copying, etc.)	Remove "Cycle disable" interface signal
CYCLE IN THE EPROM	Information while handling cycles	—
DATA TRANSMISSION RUNNING	Editing part programs	Stop interface

Dialog text	Appears with the following event	What must be done or What is wrong
DECIMAL POINT NOT ALLOWED	Taking over an input value (e.g. with the input key)	—
DELETE DATA?	“Delete” key has been pressed	If pressed again the data area specified will be deleted
DIFFERENT PROGRAM TYPES	When copying or renaming part programs	Only identical program types (L to L, % to %, etc.) can be handled
DRIFT COMPENSATION DATA ERROR	With semi-automatic drift compensation	Repeat compensation
EDITING NOT ALLOWED	When editing part programs	Repeat input
ENTER PASSWORD	When trying to enter protected data	Enter password
FORMAT ERROR	Taking over an input value (e.g. with the input key)	The control can do nothing with the value in this position. See Operator's Guide.
FORMAT ERROR IN DISPLAY DESCRIPTION	Cannot occur with the user. (Only possible with the machine manufacturer during UMS testing.)	A format has been specified in the display description which does not agree with that to be displayed
GENERAL DATA ERROR	Taking over an input value (e.g. with the input key)	The value cannot be taken over. Taking over the value would cause an error: change value
GENERAL INPUT ERROR	Taking over an input value (e.g. with the input key)	The value was wrong. Change value
HELP NOT AVAILABLE	Operating the “Help” key	No help is available for the display selected
INPUT DISABLED	Taking over an input value (e.g. with the input key)	Operate keyswitch
INPUT ERROR (PROGRAM)	When editing part programs	The character selected cannot be entered in the part program
INPUT LINE OVERFLOW	Character input	Max. 25 characters
INTERFACE ASSIGNED	When starting data input/output	Selected interface is already operating
KEY NOT ALLOWED	Taking over an input value (e.g. with the input key)	Refers to input key and delete keys
KEYSWITCH MISSING	Selecting machine data tree or with general reset	Operate keyswitch
“MB” NOT CONFIGURED	When paging the menu tree	The menu block/tree is incorrectly configured
MD TRANSFER ERROR	Data error when fetching machine data	—
MDA CHANNEL ASSIGNED	MDA has already been started in another channel	Change channel or press “Reset”
MDA MEMORY OVERFLOW	In “MDA” mode	Max. 500 characters may be entered
NO CORRECTION BLOCK	With “Correction block” function	Correction block cannot be selected

1.6.2 Listing of dialog texts

Dialog text	Appears with the following event	What must be done or What is wrong
NO RENAME FOR CYCLES	Renaming cycles is not possible	—
NO VALUE ENTERED	Taking over an input value (e.g. with the input key)	Input value has the wrong format
ONLY 1 PROG. NO. ALLOWED	With MOVE or RENAME or EXECUTE YES/NO, of a part program	—
ONLY POSSIBLE AFTER "RESET"	When entering program numbers into the automatic basic display	The NC must be in the RESET state for safety reasons. Press RESET or wait until the current program is completed
"OPERATOR PROMPT MACRO BLOCK" SEVERAL VALUES	When editing via screen forms using operator prompt macros	If several fields are bracketed together in the display, then only one of the values can be entered
"OPERATOR PROMPT MACRO BLOCK" TOO LONG	When editing using the screen form with the aid of the operator prompt macros	Operator prompt macro has been incorrectly configured
"OPERATOR PROMPT MACRO BLOCK" VALUE MISSING	When editing via screen forms using operator prompt macros	No value has been entered
OVERSTORAGE ACTIVE	When overstoreing	Wait until previous overstore operation has been completed
PROGRAM ALREADY AVAILABLE	When opening part programs, copying, renaming	Select different number
PROGRAM ERASE PROTECTED	Renaming part program number Opening Reading in via RS232C (V.24) if already present and being executed	Complete execution or reading in
PROGRAM MEMORY FULL	Inputting part programs manually or via RS232C (V.24)	On appearance of the message programs must be deleted
PROGRAM NOT AVAILABLE	Taking over a part program number during part program handling	Correct number
PROGRAM NUMBER NOT ALLOWED	Part program handling	Change part program number
PROGRAM PRESELECTION FORBIDDEN (MODE)	Selecting program for editing in MDA mode	Change mode
PROGRAM PRESELECTION NOT ALLOWED	Part program selection during TEACH IN	Abort TEACH IN (RESET)
SELECT PROGRAM	Something is to be entered in a part program	Select part program
SOURCE PROGRAM DEFECTIVE	Appears when reading out a part program	A bit has flipped in the part program just read (parity error).

Dialog text	Appears with the following event	What must be done or What is wrong
SPECIFY 2 PROGRAM NUMBERS	When copying or renaming part programs	—
STOP AXES	The actual axis value is to be read	Axis values must not change.
STOP PROGRAM	Editing the program being processed	Interrupt program (NC STOP)
TOO MANY CHARACTERS ENTERED	Taking over an input value (e.g. with the input key)	Input value has the wrong format
TOOL NUMBER NOT ALLOWED	With functions operating with tool offsets	e.g. PRESET with a rotary axis: In the PRESET display "0" must be entered for the tool offset number
RS232C (V.24) CHANNEL ALREADY IN RESET	On stop or stop all in display Data input/output	A RESET request has already been sent. When the softkey is pressed again it is ignored.
RS232C (V.24) CHANNEL NUMBER NOT CORRECT	When starting data input/output	The RS232C (V.24) interface number is too large or too small
WRONG AXIS SPECIFIED	With axis-specific functions (e.g. Preset)	Axis does not exist
WRONG DATA NUMBER	When deleting data	Data item (e.g. R parameter) with the number entered does not exist
WRONG G FUNCTION	With technology-dependent functions	Correct G function
WRONG MODE GROUP	For functions which are assigned to a mode group (e.g. channel selection)	Select an alternative mode group
WRONG PASSWORD	Password input	—
WRONG RS232C (V.24) CHANNEL NUMBER	Starting data output	The RS232C (V.24) interface number is too large or too small
WRONG VALUE ENTERED	When inputting into display screen forms (e.g. contour definition)	Change value
"_" NOT ALLOWED	Taking over an input value (e.g. with the input key)	Input value has wrong format
"=", "CR" IN WRONG PLACE	Taking over an input value (e.g. with the input key)	Input value has the wrong format
1ST NUMBER > 2ND NUMBER	Deleting data areas	The 1st number must be smaller than the 2nd
2ND DECIMAL POINT	Taking over an input value (e.g. with the input key)	Input value has the wrong format

END OF SECTION

2 Diagnostics on the PLC

2.1 Error numbers (ACCU 3 high byte, DB 1 DW 160)

General

The error number FEHLCODE gives a detailed coding of the cause of error.

The error numbers are hexadecimal and therefore correspond to the representation in the function:

AUSGABE ADR:AG,F0000

with which FEHLCODE and the additional error information can be read.

The error numbers and the additional information are also stored in the diagnostics DB (DB 1) DW 160–164.

If the PLC goes into the stop state with an error number identified by a *W*, a warm restart will be effected after the next RESET (unless cold restart or installation has been selected).

All other error numbers cause a cold restart.

If no error has occurred the error number is 00.

Error messages of the interpreter

Error messages of the interpreter	
01	Non-interpretable command *)
02	Illegal parameter *)
03	Data transfer into non-existent data (DB) *)
04	Substitution error *)
05	Call for a block that has not been loaded *)
06	Call for a non-existent data block *)
07	Segment not permitted with LIR/TIR *)
08	Segment error in a block transfer command *)
09	Overflow in block stack *)
0A	Overflow in interrupt stack *)
0B	Immediate system stop due to "STS" command *)
0C	Stop request by user ("STP" command) *)
0D	Processing delay *)
0E	Call for an illegal OB (OB No. 0...39) *)
0F	Call for a non-existent page (command "ACR") *)

*) Additional information is given on this error in additional fields (see Section 2.2)

2.1 Error numbers (ACCU 3 high byte, DB 1 DW 160)

*Error messages on
system startup*

Cold restart	
27	MD 137: Illegal address for OEM info bits ¹⁾
28	Compress function ("Push block") interrupt ¹⁾ *) Note: PLC General Reset required after this error; blocks can first be saved via the programmer
29	MD8/9/10: Impermissible number of channels/spindles/axes *)
2A	Data loss
2B	Installation of NCK/MMC/COM requested
2C	MD17: Impermissible quantity of wait cycles for enabling the computer link user interface
2D	MD18: Impermissible user interface number for outputting a message to the host computer on synchronization
2E	MD19: Impermissible quantity of function nos. for core sequence initiation
2F	MD20–29: Impermissible function number for core sequences
30	MD128: Address 1st machine control panel too high (max. 120)
31	MD129: Address 2nd machine control panel too high (max. 120)
32	Reserved
33	MD error with DMP assignment lists (overlapping) *)
34	Interface-DMP incorrectly started (system start) *)
35	Reserved
36	Reserved
37	Distributed interrupt byte does not exist *)
38	Number of interrupt byte already exists (double addressing)
39	Number for interrupt byte has been assigned more than once
3A	Impermissible input value for number of the interrupt byte
3B	Reserved
3C	Reserved
3D	Reserved
3E	Reserved
3F	Interrupt byte declared more than once (with the same address) *)
40	RAM user memory: Memory capacity too small for inserted EPROM submodules
41	RAM user memory: Memory capacity set in MD too small for user program memory
42	RAM user memory: Physical capacity of user program memory too small for machine data setting
43	RAM user memory: Memory capacity set in MD too small for user data memory
44	RAM user memory: Physical capacity of user data memory too small for machine data setting
45	Invalid version of interface DMP firmware *)
46	I/O configuration: Impermissible number of interfaces plugged in
47	I/O configuration: Multiple addressing for inputs *)
48	I/O configuration: Multiple addressing for outputs *)
W49	I/O modules changed
4A	Unassigned

*) Additional information is given on this error in additional fields (see Section 2.2)

Cold restart	
4B	System parameters: Incorrect ms time frame
4C	System parameters: Incorrect 10 ms time frame
4D	System parameters: Incorrect 100 ms time frame
4E	System parameters: Incorrect MC5 time (programmer cannot be used for diagnosis in PLC)
4F	Unassigned
51	Impermissible input value for byte number of the alarm byte
51	Byte number for alarm byte assigned more than once
52	Alarm byte number specified but byte does not exist or impermissible machine control panel
53	Irregular block type: PLM block not allowed in user program memory
54	Irregular block type: C block not allowed in user program memory
55	Synchronization error in EPROM basic program memory *)
56	Synchronization error in EPROM user program memory *)
57	Synchronization error in RAM user program memory *)
58	Synchronization error in RAM user data memory *)
59	Irregular block type in EPROM basic program memory *)
5A	Irregular block type in EPROM user program memory *)
5B	Irregular block type in RAM user program memory *)
5C	Irregular block type in RAM user data memory *)
5D	Summation error with RAM for OB, FB, DB, FX, SB, PB *)
5E	Summation error with EPROM for OB, FB, DB, FX, SB, PB *)

Restart	
5F	Impermissible warm restart *)
60	Check sum error in RAM for OB, FB, DB, FX, SB, PB *)
61	Check sum error in EPROM for OB, FB, DB, FX, SB, PB *)

Cold restart and/or warm restart	
62	No RAM user program memory available
63	No user data memory available
64	Operator panel input byte in impermissible area
65	Operator panel output byte in impermissible area
66	No synchronization pattern from master in cold restart *)
67	No synchronization pattern from master in warm restart *)
68	Process image of the inputs: impermissible value for delete limit
69	Input is in retentive area of the process image
6A	Process image of the outputs: impermissible value for delete limit
6B	Output is in retentive area of the process image
6C	Function URLADE not executed, submodule not inserted or empty ¹⁾
6D	Error during function: Save user program on MMC hard disk ¹⁾
6E	Machine data error equivalent to FB25 on the 850 *) (see special section)
W 6F	EUs or DMP modules not switched on or incorrectly jumpered (rotary switch) *)

*) Additional information is given on this error in additional fields (see Section 2.2)

1) SW 3 and higher

2.1 Error numbers (ACCU 3 high byte, DB 1 DW 160)

*Operational and
user errors*

Dynamic system monitoring	
70	Check sum error in RAM for OB, FB, DB, FX, SB, PB *)
71	Check sum error in EPROM for OB, FB, DB, FX, SB, PB *)
72	RAM error in user data memory
73	RAM error in system data memory

Cyclic system monitoring	
74	NC (master) CPU in the system failed
75	PLC CPU in the system failed
76	Reserved for 840
77	Reserved
W 78	PLC STOP by request from programmer
W 79	PLC STOP by operating mode switch
W 7A	Reserved for 840
W 7C	No ready signal from interface DMP or interface PLC or 135 WD <ul style="list-style-type: none"> Interface may be blocked Connector missing

*Error messages from
interrupt routines*

System errors	
80	Division error
81	Overflow error
82	"Array Bounds" error
83	Incorrect OP Code
84	Error in ESC-OP code
85	Non-interpretable interrupt (NII)
86	Error in the save routine (SAVE-UP)
87	Stack overflow
88	Semaphore buffer overflow
89	Semaphore buffer not reached
8A	Addressing error by access to an input/output not existing in the process image

Timeouts	
90	Unassigned
91	Unassigned
92	Timeout with buffered access to link/local bus *)
93	Timeout with system program processing *)
94	Timeout with LIR/TIR commands *)
95	Timeout with TNB/TNW commands *)
96	Timeout with LPB/LPW/TPB/TPW commands *)
97	Timeout with a substitution command *)

*) Additional information is given on this error in additional fields (see Section 2.2)

Timeouts	
98	Timeout with transfer in/out (see errors B0 and B1)
99	Timeout cannot be interpreted with active interpreter *)
9A	Timeout with processing a function macro *)
9B	Timeout with processing high-level language blocks *)
9C	Timeout with access to pabe commands LB CB, LB CW, LB CD, TB CB, TB CW, TB CD

Error messages of distributed I/Os	
W A0	Transfer error to an expansion unit
W A1	Overttemperature in an expansion unit or bouncing enable input with SIMATIC I/O devices
W A2	Interface DMP outputs a command output disable during operation
W A3	Transmission link to EU 185U (SIMATIC EU) has failed
W AF	Message "OUTDS" from power supply unit
W B0	Input module failed or changed and STOP set for PLC for this module via MD *)
W B1	Output module failed or changed and STOP set for PLC for this module via MD *)

Cycle time monitoring	
C0	Cycle time exceeded
C1	Cycle time exceeded; FB12 called more than twice per cycle

*Error messages when
using the PLM and C
high-level languages*

HLL call in the interpreter	
D0	Unknown type identifier in parameter declaration of the FB called
D1	Illegal type identifier block
D2	Unknown code in the parameter block of the FB called: input parameter
D3	Unknown code in the parameter block of the FB called: output parameter

HLL_HLL function	
D4	Unknown pseudo parameter in STACK
D5	Block not available
D6	HLL block not in line with paragraph
D7	Block called is not a HLL block

HLL_ADB function	
D8	DB to be opened in HLL: wrong pseudo parameter
D9	DB to be opened not available
DA	DB to be opened not in line with paragraph

*) Additional information is given on this error in additional fields (see Section 2.2)

2.1 Error numbers (ACCU 3 high byte, DB 1 DW 160)

HLL_MACRO function	
DC	Core to be called not available or cannot be called by HLL

HLL_STOP function	
DD	Sytem STOP by HLL user *)

HLL_S5 function	
DE	Unknown pseudo parameter in STACK
DF	S5 block called not available
E0	S5 block not in line with paragraph
E1	Block called is not a S5 block

Other operational and user errors	
F7	M decoding: byte number for DB30>63
F8	PROTES system error: error with P link *)
F9	Interrupts from interrupt-generating I/O devices not acknowledged by OB2

Errors in addressing decoding data blocks	
FA	Decoding data block not available
FB	Data block word length without header not divisible by 3
FC	Wrong number of decoding units
FD	Decoding data block too short
FE	Assignment list DB99 not available or too short

Error message with function macros	
FF	Group error with function macros *) Display of individual errors with function macros is via ACCU1 and ACCU2. The ACCUs can be read out at the programmer via OUTPUT ISTACK. For more details on errors see FB descriptions.

*) Additional information is given on this error in additional fields (see Section 2.2)

2.2 Additional error information (ACCU 3 low byte, DB 1 DW 161–163)

For all errors marked with an *) in the above list, further information is given in the additional fields. This information can be read out using the programmer from addresses F0001 to F0004 or from DW161 to 164 in the diagnostics DB (DB1).

In the additional error information marked by ++ the representation of F0001 - F0004 on the operator panel and in DB1 high/low is swapped.

This information is summarized below:

Error No.	Address	Contents/Designation
01	F0000 F0001 F0002 F0003	01: Error number incorrect MC5 operation code OB number where incorrect operation code occurred — —
02, 03, 04, 05, 06, 07, 08, 09, 0E, 0F	F0000 F0001 F0001 F0002 F0003	Error number of interpreter High byte: Identifier for preceding command Low byte: OB number where the error occurred Operation code of the MC5 command which led to error Parameter of MC5 command in BCD code Identifier for preceding command: ++) 0: No command modification 1: Preceding command was B MW, B DW, B BS or substitution command
0A	F0000 F0001 F0002 F0003	0A: Overflow in interruption stack OB number where overflow occurred — —
0B	F0000 F0001 F0002 F0003	0B: Stop caused by STS command OB number where STS occurred — —
0D	F0000 F0001 F0002 F0003	0D: Error number processing time delay OB number where processing time delay occurred — —

2.2 Additional error information (ACCU 3 low byte, DB 1 DW 161–163)

Error No.	Address	Contents/Designation
28	F0000 F0001 F0002	28: Compress function interrupted The interrupted block is pushed completely (if possible) during runup 0000: Block completely pushed 0100: Interrupted block could not be completely pushed (s. F0002) where F0001 = 0100: nn: Block number and block type nn: Block number (hexadecimal) tt: Block type (hexadecimal) 01 = DB, 02 = SB, 04 = PB, 05 = FX, 08 = FB, 0C = DX, 10 = OB ++)
29	F0000 F0001	29: MD8/9/10: Impermissible number of channels/spindles/axes 01: MD8: Too many channels 02: MD9: Too many spindles 03: MD10: Too many axes
33	F0000 F0001 F0002 F0003	33: MD error in DMP assignment lists or error in the DMP configuration DB/DX 00: Error in DMP assignment lists (overlapping) 04: I/O type identifier: DMP I/O device configuration does not correspond to configuration DB/DX Otherwise: Error in the configuration lists DB/DX Number of the DB/DX from MD 136 (BCD format) When F0001=4: 0I or 0Q identifier input/output Otherwise: Number of the incorrect/missing data word within the configuration DB/DX (BCD format) When F0001=4: Byte number (BCD format) Otherwise: Unassigned ++)
34	F0000 F0001 F0002 F0003 F0004	34: Interface DMP/interface PLC not started correctly or EU incorrectly jumpered 00: Interface DMP/interface PLC not started correctly (system startup) 01: Identifier for incorrect EU jumpering Number of the interface module (at F0001=01) Submodule number (when F0001=01) Line number (when F0001=01) ++)
37	F0000 F0001 F0002 F0003	37: Distributed interrupt byte not available Byte number (BCD format) — — ++)

2.2 Additional error information (ACCU 3 low byte, DB 1 DW 161–163)

Error No.	Address	Contents/Designation
3C	F0000 F0001 F0002 F0003	3C: Error number MD double addressing inputs Group number (BCD format) — —
3D	F0000 F0001 F0002 F0003	3D: Error number MD double addressing outputs Group number (BCD format) — —
3E	F0000 F0001 F0002 F0003	3E: Error number output group per MD for several PLCs Group number (BCD format) — —
45	F0000 F0001 F0002 F0003	45: Error number illegal version of interface DMP firmware Number of interface module Illegal (fitted) firmware interface-DMP Required firmware interface-DMP ++)
47	F0000 F0001 F0002 F0003	47: Error number double addressing inputs Byte number (BCD format) — —
48	F0000 F0001 F0002 F0003	48: Error number double addressing outputs Byte number (BCD format) — —
49	F0000 F0001 F0002 F0003	49: Error number modification of I/O modules 3C: Changed address location of I/O byte 00: I/O failure 0I or 0Q identifier input/output Byte number (BCD format)
55, 56, 57, 58, 59, 5A, 5B, 5C, 5D, 5E, 60, 61, 70, 71	F0000 F0001 F0002 F0003	Respective error number Segment address of fault block Offset address (byte-oriented) of fault block (segment and offset point to the synchronization pattern) ++) —

2.2 Additional error information (ACCU 3 low byte, DB 1 DW 161–163)

Error No.	Address	Contents/Designation
5F		<p>I/O failure during the cycle or a set cold restart because of IP/WF modules (MD 6049, bit 1 = 1) causes PLC to stay in the stop state after the first RESET. A warm restart gives the described error; the cold restart set in the machine data prevents a warm restart from being executed and message 5FH appears (warm restart not allowed). After repeating RESET, the cold restart set in the MD is executed together with a redefinition of the I/Os.</p> <p>If one of the modules fails on Power off, the PLC executes a cold restart and goes into cyclic operation; the failed module is ignored.</p> <p>F0000 5F: Error number illegal warm restart</p> <p>F0001 00: No entry in ISTACK or power supply failure not only reason for interruption or PLC machine data 6049 bit 1 (cold restart bit) set and warm restart initiated by programmer or PLC mode selector switch.</p> <p>3C: Changed address location of I/O byte, otherwise I/O type identifier:</p> <p>01: Centralized I/Os, TPx, LPx</p> <p>03: 16-bit link</p> <p>04: DMP</p> <p>F0002 0I or 0Q identifier input/output</p> <p>F0003 Byte number (BCD format) ++)</p>
6C ¹⁾	F0000 F0001	<p>6C: Error when booting the user program</p> <p>0001: Memory dump (file on MMC hard disk) does not exist or is empty</p> <p>0002: Illegal user program file</p> <p>000B: ICODE error</p> <p>000C: ADS error (e.g. no communication with MMC) ++)</p>
6D ¹⁾	F0000 F0001 F0002	<p>6D: Error while saving the user program</p> <p>0001: Save not possible (reason see F0002)</p> <p>000A: System error</p> <p>000B: ICODE error</p> <p>000C: ADS error (e.g. no communication with MMC)</p> <p>When F0001 = 0001:</p> <p>0001: User program memory empty</p> <p>0002: Boot not completely finished or data loss ++)</p>

1) SW 3 and higher

Error No.	Address	Contents/Designation
6F	F0000 F0001 F0002 F0003 F0004	6F: Error number I/O fault on start-up Type of link: 03: 16-bit 04: DMP Number of the interface module EU number or DMP module number Line (MPC) number for DMP ++)
92	F0000 F0001 F0002 F0003	92: Error number timeout for buffered access to link (local bus Bus address (segment), where timeout occurs Bus address (offset), where timeout occurs Type identifier of the timeout **) ++)
93	F0000 F0001 F0002 F0003	93: Error number timeout with system progr. processing CS when timeout occurs IP when timeout occurs Type identifier of the timeout **) ++)
94	F0000 F0001 F0002 F0003	94: Error number timeout with LIR/TIR OPCODE command Offset address Segment number ++)
95	F0000 F0001 F0002 F0003	95: Error number timeout with TNB/TNW OPCODE command Offset address Segment number ++)
96	F0000 F0001 F0002 F0003	96: Error number timeout with LPB/LPW/TPB/TPW OPCODE command Specification of input or output Byte number (BCD format) ++)
99	F0000 F0001 F0002 F0003	99: Error number Error number timeout not interpretable when interpreter active CX when timeout occurs IP when timeout occurs Type identifier of the timeout **) ++)
9A	F0000 F0001 F0002 F0003	9A: Error number timeout when processing a function macro OPCODE of the command that called the function macro Command parameter (with FX only, otherwise 0000) Type identifier of the timeout **) ++)

**) Type identifier of timeout:
0001 = Internal timeout
0002 = Link bus timeout
0003 = Local bus timeout

2.2 Additional error information (ACCU 3 low byte, DB 1 DW 161–163)

Error No.	Address	Contents/Designation
9B	F0000 F0001 F0002 F0003 F0004	9B: Error number timeout when processing high-level language CS when timeout occurs IP when timeout occurs Type identifier of the timeout **) Identifier indicating whether DB has been opened 0000: DB opened 0001: No DB opened (in this case timeout is initiated on access to timeout DB)
A0	F0000 F0001 F0002 F0003	Error number A0 I/O type identifier 01: Centralized I/O devices, TPx, LPx 03: 16-bit link 04: DMP 0I or 0Q identifier inputs/outputs Byte number (BCD format) ++)
B0, B1	F0000 F0001 F0002 F0003	Error number B0/B1 I/O type identifier 01: Centralized I/O devices, TPx, LPx 03: 16-bit link 04: DMP 0I or 0Q identifier inputs/outputs Byte number (BCD format) ++) In compact terminal blocks, it is not possible to enter the individually defective module in the error fine coding (the terminal block always fails as a complete unit); i.e. the first defective byte (the byte with the lowest address) found in the image is always the one given in the error fine coding. If the terminals are mixed (inputs and outputs), this is always an input byte.
DD	F0000 F0001 F0002 F0003	DD: Error number system STOP by HLL user User STOP number HLL call address (offset) HLL call address (segment)
FF	F0000 F0001 F0002 F0003	FF: Group error with function macro Current OB No. (No. of processing level) — —

**) Type identifier of timeout:
0001 = Internal timeout
0002 = Link bus timeout
0003 = Local bus timeout

PLC machine data test

1. The machine data test is performed in the code restart branch.
2. If the machine data are invalid, the group error number 110D (6EH) is transferred in the error field (address F0000 with programmer, cell FEHLCOD for system program). The detailed error identifiers for each test are entered in the additional error field (address F0001 with programmer, cell EADOPAD + 1 for system program).
3. Detailed error identifiers

Address		Error
F0000	F0001	
6E	0	Reserved
	3	Reserved
	4	Reserved
	5	Reserved
	6	Reserved
	7	PLC MD for error and operational messages (channel-specific) set
	8	PLC MD for error and operational messages (spindle-specific) set
	9	PLC MD for error and operational messages (axis-specific) set
	10	PLC MD for M decoding with extended addresses set. At least one decoding list is missing.
	11	PLC MD "1st machine control panel" set – input missing
	12	PLC MD "2nd machine control panel" set – input missing
	13	Reserved
	14	Reserved
	15	PLC MD "1st machine control panel" set – output missing
	16	PLC MD "2nd machine control panel" set – output missing
	17	Reserved
	18	Reserved
	19	PLC MD for error and operational messages (DB58) set
	20	Reserved
	21	Reserved
	22	Reserved
	23	Reserved

*Synchronization error
on power-up*

Address		Error
F0000	F0001	
66	1	Cold restart: synchronization error master CPU
67	1	Restart: synchronization error master CPU

*Error in
programmer link*

This error is an internal software error.

Address		Error
F0000	F0001	
F8	0100	Error on fetching a receive buffer
	0200	Error on returning a receive buffer
	0300	Error on reserving a transmit buffer
	0400	Error on transmitting a receive buffer
	0500	Reserved
	0600	ADS interface between PLC and IF PLC faulty

END OF SECTION

3 Error Display on CPU

Errors that prevent normal operation of the PLC or the IF PLC, are displayed by a flashing LED on the front panel of the module in question.

Error list of the PLC

LEDs for PLC	Meaning (SINUMERIK 840C)
Steady light (green only)	PLC cyclic mode
Steady light (red only)	PLC in STOP state
Steady light (red and green)	OVERALL RESET necessary (initial power-up or data loss)
Light flashing (red) once	Error on cross-check sum over system program submodule
3 times	Timer 0 error (process-internal timer) or watchdog error
4 times	SW3: Module is a PLC 135 WB (can no longer be used)
5 times	Access to link RAM not possible
6 times	Error with test access to link RAM
7 times	SW1 and SW2: Error in system initialization program (synchronization pattern)
9 times	SW3: No communication with MMC
10 times	SW3: Error when booting
11 times	1 ACOP error (group error)
12 times	IF PLC cannot be addressed from PLC
13 times	RAM of the IF PLC defective (program memory or CPU RAM)
14 times	Dual port RAM of the IF PLC defective
15 times	ADS link to the NC defective
16 times	ADS link to the IF PLC defective
17 times	ADS link (reserved); SW3 and higher: ADS link to MMC defective
18 times	ADS link (reserved)
LED for IF PLC	Meaning
Steady light (green only)	IF PLC in cyclic operation (no error), MPC transmission running
Steady light (red only)	IF PLC in the STOP state
Light flashing (red) 12 times	RAM of the IF PLC defective (CPU-RAM)
13 times	Dual port RAM of the IF PLC defective
LED off	No MPC transmission, processor running

Note If the PLC 135 WB2 is used, the LEDs for the PLC and IF PLC are situated on the PLC 135 WB2 or interface PLC module. If the PLC 135 WD is used, all the LEDs are situated on the front panel of this module.

Error display on the MMC CPU

Figure	Meaning
0	Driver not loaded
1	Driver loaded but ADS power-up not yet performed
2	Jump ADS interface power-up
3	ADS interface power-up, MMC waits for '0' from NC

Figure	Meaning
4	ADS interface power-up, MMC waits for '1' from NC
5	ADS interface power-up state
6	ADS interface power-up state
7	Interface active (OKAY)
8	MMC powered without NC
9	State which causes removal of the driver

Error detection NCK CPU

The cause of errors in the NCK area are displayed on the 386 NCK CPU as far as possible by the flashing rhythm of the red LED at the front of the NCK CPU. On the 486 CPU, these error detections are now displayed on the 7-segment display at the front of the CPU module (2 digits, both numbers alternating). If the NC continues to run and simply intends to indicate failure of the link to the MMC, this is still signalled by the red LED flashing 11 times. In the case of errors designated by R! it is essential to read out from the alarm log of the MMC which register contents of the NCK CPU were logged at the time of failure (this makes it much easier to identify the cause of error).

Error code	Cause
1	The selected boot bank (switch position on the 486 CPU) is either not programmed or incorrectly programmed. Switch position 0 must always function otherwise the module is defective.
2	DRAM error on NCK CPU, defective during memory test after Power On
4	!R Parity error in the DRAM
7	!R Undefined NMI
8	!R NMI caused by push button on CSB or CPU (486) or V24 (486)
9	!R NMI caused by timeout (CPU local)
10	!R NMI caused by timeout on link or local bus
11	Failure of link to the MMC (this is indicated simply by flashing, also on 486 CPU)
14	!R NC processor exception (commonly known as software crash)
15	!R Internal hardware fault
16	Boot transfer error (ADS transport)
17	Boot transfer error (I code protocol)
18	Faulty file booted (OMF format)
19	Faulty file booted (illegal address area)
20	Wrong file started as last in the loading list (no starting information)
21	Link area between boot EPROM and loaded system was illegally overwritten (presumably software error in the loaded system program). Remedy: Reboot

END OF SECTION

4 Errors with Function Macros

ACCU 1 (FB No.)	ACCU 2 (Error No.)	Error occurred at	Error description
11	1	Setting up data blocks	DB No. impermissible
	2		DB No. > 255
	3		Specified DW No. < 0
	4		Length of DB to be set up is not the same as the length of the DB already in the PLC
	5		Memory space in the PLC no longer sufficient
	6		Existing DW No. > 255
	7		DB No. = 0
	8		DB type different from DB or DX
12	1	Retriggering of cycle time monitoring	PLC Stop with error detection 0C1H on 3rd call of FB12 within one PLC cycle
52	1	Block transfer	Illegal mode
	2		Number of DWs to be transferred > 127
	3		Number of DWs to be transferred < 0
	4		Segment No. of 8-bit memory < 1 or > 13
	5		Segment No. of 16-bit memory < 1 or > 13
	6		Offset of 1st DW in 8-bit memory > 7FFFH
	7		Offset of 1st DW in 16-bit memory > 7FFFH
	8		Selected 8-bit memory area exceeds lower segment limit (not with segment Nos. 6, 10, 11,12)
	9		Selected 16-bit memory area exceeds lower segment limit (not with segment Nos. 6, 10, 11,12)
60	1	Block transfer	Number of DWs to be transferred > 2043
	2		Number of DWs to be transferred = 0
	3		Target DB No. = 0
	4		Target or source DB not available
	5		Target DB too short
	6		Target DB in EPROM
	7		Source DB too short
	8		Incorrect TYQU parameter
	9		Incorrect TYZI parameter

ACCU 1 (FB No.)	ACCU 2 (Error No.)	Error occurred at	Error description
61	v0 v1 v2 v3 v4 v5 v6 v7 v8	Read NC data	ANZ > 1 not permitted NSBY not permitted DB missing or DB No. not permitted or MW not permitted Data type not permitted *ANZ = 0 or > 128 Reading / writing not permitted Number format not permitted Value 3 for ZOA or ZOFA not equal or 1 Type data target/data source in PLC not permitted
62		Write NC data	See FB 61 (reading NC data)
65	1	Transfer flags → flag stacks	Stackpoint overflow
66	1	Transfer flag stack → flags	Stackpoint not reached
67	2 1	Transfer machine control panel signals → DB axes	Parameter axis No. > 30 PLC machine data not set for signals from/to axis
68	1	Aperiodic user program call	Parameter tool < 0
69	1 2 3	G decoding	Channel number not permitted G group incorrect PLC MD: signals from/to NC channel or signals from NC channel not set
70	1 2 3 4 5 6 7	Transfer interfa- ces DB to I/Q/F	Source or target type incorrect (illegal ASCII character) Source DB does not exist in PLC Parameter limits of source or target parameter not re- ached or exceeded Source or target DB too short Parameter limit of flag area exceeded PII or PIQ limits exceeded Illegal source or target parameter type (not I, Q, F)

ACCU 1 (FB No.)	ACCU 2 (Error No.)	Error occurred during	Error description
71		Transfer interface DB to I/Q/F (see FB 70)	
72	1	Transfer NC channel to DB channel-specific signals	Channel address not permitted
73	1	Transfer DB channel-specific signals to NC channel	Channel address not permitted
74	1	Transfer spindle to DB spindle-specific signals	Spindle address not permitted
75	1	Transfer DB spindle-specific signals to spindle	Spindle address not permitted
76	1	Transfer axis to DB axis-specific signals	Axis address not permitted
77	1	Transfer DB axis-specific signals to axis	Axis address not permitted
78	1 2 3	Transfer machine control panel signals → channels/spindles	PLC machine data not set for signals from/to channel PLC machine data not set for signals from/to spindle Parameterized channel No. or spindle No. too large
79	1 2	Transfer machine control panel signals → DB axes	PLC machine data not set for signals from/to axis Number of parameterized axes > 30
88	1 2	Mode lamp	PLC MD signals from/to channel not set Parameterized channel No. >4
89	1 2 3	Reading of block start address	Block type not permitted Address list does not exist Address list insufficient
113		Symmetrical tool search	No messages

END OF SECTION

5 Parameterization Errors Spindle/Axis



The Safety Integrated service data are described in the SINUMERIK Safety Integrated documentation (Description of Functions).



The Service numbers can be found under DIAGNOSIS in the Service display Axes/Spindles menu.

Service number	Significance	Remedy		
		General	Axis	Spindle
	Parameterization errors spindle/axis			
300	Sampling ratio incorrect	MD 155 160 163 168	MD 1396*	MD 466*
	and/or with SW 5.4 and higher: The monitoring cycle set for Safety Integrated via MD 40010 is not a multiple of the position control cycle for this axis.		MD 40010	MD 40010
301 to 307	(reserved)			
308	Incorrect increment weighting		MD 364* 368* 1208* 1212*	466* 456* 524* 468*
309	Incorrect actual-value resolution		MD 1116* 1204*	458*
310 311	(reserved)			
312	a) Error in encoder speed ratios (MD value = 0) b) Speed ratios not 1:1 for axis with distance-coded measuring system		MD 3032* to 3060* MD 3064* to 3092*	MD 2400* to 2407* MD 2408* to 2415*
313	(reserved)			
314	Illegal servo gain K_v factor		MD 252* 260* 256*	MD 435* to 442* 468*
315	(reserved)			
316	Illegal modulo value/axis is not a rotary axis		MD 344* 564*	
317 ¹⁾	Position control cycle LA/LS is not the same Position control cycle FA/FS		MD 1396*	MD 466*
318 ¹⁾	Incorrect LA/LS/FA/FS number parameterized			

¹⁾ SW 3 and higher

Service number	Significance	Remedy		
		General	Axis	Spindle
319	Illegal maximum speed (scaling overrun)		MD 264* 256* 268* 260* 1736*	MD 403* to 410* MD 419* to 426* 468* 2522*
320	(reserved)			
321	Feedforward control parameterization incorrect		MD 312* 1124* 1260*	MD 465*
322	Incorrect clock cycle setting	MD 168*		
323	Illegal position control resolution ¹⁾		MD 1800*	MD 524*
324	Incorrect C axis assignment: (axis does not exist) no spindle encoder available ²⁾		MD 200*	MD 400* 461* 520*
325	Position control sampling time for C axis \neq position control sampling time for spindle		MD 1396*	MD 466*
326	Incorrect measuring gear		MD 364* 368* 1208* 1212*	MD 455* 456* 524*
327	Measuring systems 1 and 2 of an axis are assigned to one distance-coded linear scale or an absolute encoder has also been defined. SW5 and higher: An EnDat absolute encoder without zero marker has been defined.		MD 1808* Bit 4 Bit 5	
328	On reparameterization of the machine data of the QEC, invalid values have been found. Possible causes are: <ul style="list-style-type: none"> The characteristic of the conventional QEC has been incorrectly parameterized. <ul style="list-style-type: none"> The MD 1244* must be less than MD 1248*. The MD 1248* must be less than 100 x MD 1252*. Internal formats have been exceeded with the characteristic parameterization. In the neural QEC, the following errors have been found. <ul style="list-style-type: none"> The learning rate MD 1368* must not be 0. The measuring time MD 1376* must not be 0. The neural QEC has been activated (MD 1812*, bit 0 = 1) although there is no valid parameterization of the function parameters. This can also occur at POWER ON if the person responsible for installation and start-up has forgotten to save to a boot file. 		MD 1244* 1248* 1252* 1368* 1376* 1812*	MD 1368* 1376* 1812* Bit 0

1) or position control resolution (spindle) = position control resolution (axis)

2) or mode group (spindle) = mode group (axis)

Service number	Significance	Remedy		
		General	Axis	Spindle
329 (SW 3 and higher)	Errors in setpoint/actual value assignment. Double assignment of measuring circuit input/output.		MD 200* 384* 1388* 1824* Bit 2	MD 400* 460* 522* Bit 2
	and/or With SW 5.4 and higher: The measuring circuit connection (MD 4100*) allocated to SI has already been assigned to another axis/spindle. Note: If SI is operated with an encoder, the second measuring circuit can no longer be allocated freely.		MD 4100*	MD 4100*
330 (SW 4 and higher)	Invalid values have been entered in the machine data for Master/Slave mode (MD 1336*/2700* oder 1340*/2701*): <ul style="list-style-type: none"> The axis/spindle entered there does not exist. A rotary axis has been assigned to a linear axis or vice versa. Only the following are allowed: 2 rotary axes or 2 spindles or 2 linear axes or 1 rotary axis to a spindle. In a specific/C-axis combination, different axes/spindles have been assigned. An axis has been entered in the MD 1340*/2701*. The entered axis/spindle has a different position controller cycle. Parameterized axis/spindle is contained in a different mode group 		MD 1336* 1340*	MD 2700* 2701*
331 (SW 5.4 and higher)	Errors have occurred during conversion of SI-MD.		MD 4184* to 4196* 4200* to 4244* 4248* to 4260* 4180*	MD 4184* to 4196* 4200* to 4244* 4248* to 4260* 4180*
			Evaluate detailed information in the SI SERVICE SCREEN (service data 1000).	

END OF SECTION

